

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

13 October 2019

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

JADA SRINVASA RAD
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 26 September 2019 at Aperia Mall 10 Kallang Avenue, involving vehicle SBF6823Y / SKW1744D

Quotation for Repair Vehicle No: SKW1744DY, MAZDA 3(Third Party Claim)

| Quantity | Nett Item | | |
|----------|-----------------------------------|----------|-------------|
| 1 | Front Grille ? | | |
| 1 | Front Side Chrome LH <i>Cra</i> ✓ | \$ | 611.00 |
| 1 | Front Bumper Sponge ? | \$ | 286.00 |
| 1 | Front Bumper Retainer LH X | \$ | 186.00 |
| 1 | Front Tow Cover <i>MIS</i> ✓ | \$ | 44.00 |
| 1 | Front Reinforcement ? | \$ | 31.00 |
| 1 | Head lamp LH ? | \$ | 594.00 |
| 1 | Head Lamp Clip ? | \$ | 2,358.00 |
| 1 | Front Bumper <i>de</i> ✓ | \$ | 5.00 |
| | | \$ | 1,084.00 |
| | | \$ | 5,199.00 |
| | | Less 15% | \$ 779.85 |
| | | | \$ 4,419.15 |

Labour

| | | |
|---------------------|---|-----------------------------|
| 1 | To repair Front Panel, Head Lamp Panel, remove and re-fix damaged parts, straighten and realign affected areas. | \$ 200 500.00 |
| 2 | To spray affected areas | \$ 250 480.00 |
| 3 | To programming and diagnosis head lamp | \$ 30 150.00 |
| Total Amount | | <u>\$ 5,549.15</u> |

Kindly arrange your surveyor to survey my vehicle.
We look forward to hear from you soon.
Thank you.

Yours Faithfully
Mr Wong
81122116

Paul
Hp 90010068
3 days
L/S
16/10/19 @ 11:55
Resurvey after
repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be approved and is subject to final approval from insurer's company

Acknowledged by Repairer
Signature:
Date: