

LOH Cynthia
6568804843

CC4/ASM19018070/Uga3

LKK:
IDAC: 141991

ASSIGNMENT

Surveyor: MARCUS

DOI: 14/10/2019

Date / Time: 14/10/2019

Registered in Merimen: —

Pre-assign / CCU / FTE



Insured Vehicle No.: SJX 6641R

Claim No.: S9M023IW

Name of Insured: TEO BEE CHOO PAULA

Policy No.: GA045597/1

Insured Tel No.: HP: +65-98160416

Make / Model: KIA

Excess Sec II :SS D.O.A: 11/10/2019 17:30

Place of Accident: PIE > JURONG NEAR JLN EUNOS EXIT

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SLP 2230M

INSRS:
WSP: ASIA
Tel: MOTORSPORTS
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SLP 2230M	Non-Reporting ltr (1st):	
	SJX 6641R	Non-Reporting ltr (2nd):	
	NA/AIG19018003/r3; DOA: 11/10/19	Non-Reporting ltr (Final):	
	- CS3/AIG14005957/Pa3q2; DOA: 25/03/14	Notification ltr (if non-pickup):	
	- CC6/AIG12011643/Kst2w2; DOA: 11/06/12	Call OI:	
14/12	Email WOI, TO SEEK MANDATE.	After call ltr to OI:	7 CPL 14/12/19
21/12	Pending mandate approval.	Documentation Check List: Handler Typist	
12/1	offw \$5407.45 (pending acceptance).	Notification ltr (if non-pickup)	☒
15/1	SCHU @ \$5407.45, DV send (pending DV in).	After call ltr to OI:	☒
2/1	DV in, PIC call me to close.	Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by: MARCUS
FINALIZATION	US	SS 5000/-	(5 days) Reduction: \$5881.80 @ 5%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 25/11/2020	Confirm with: Asia Motorsports	Email ☐ Call ☐	
Final Liability:	%: 100	(Agreed / Assessed) BOLA S/N No.: 21	If NO or B 28, Ass. Lia:	
Repair Cost:	SS 5000.00			
Loss of Rental (LOR):	SS 400.00	(4 days) x \$100		
Loss of Use (LOU):	SS -	(5 x days)		
Loss of Income (LOI):	SS -	(5 x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)		
GIA/LTA Search:	SS 7.45			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost:	SS -			
Total:	SS 5407.45	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	SS 5407.45	Name 1: Asia Motorsports Solution Pte Ltd		
Payee 2: (Strike if N.A.)	SS -	Name 2: -		
Payee 3: (Strike if N.A.)	SS -	Name 3: -		

X GIA

LH4 Cecilia

S
4/5 \$5000/?not Authorized
LH4
14/10/19
4/5 \$5000
Sdy

Page No. 1

Vehicle No. SLP 2230M

GKE

HONDA SHUTTLE

Take the Repair

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Tailgate 1195.20	Body	1425.00	
1	Tailgate centre chrome garnish	11	425.00	X
1set	Tailgate centre chrome garnish clips	11	40.00	X
1	Tailgate inner lock	twi/ser	278.00	
1	Tailgate inner trim board 345.50	de/cra	547.00	
2	Tailgate damper @298.20	11	596.40	X
2	Tailgate rubber stopper @5.80	11	11.60	X
1	Tailgate Honda badge 38.50	nu	92.00	
1	Tailgate SHUTTLE emblem 58.00	nu	98.00	
2	Tailgate reflector @395.00	11	790.00	X
2	RHS & LHS Taillamp @782.00 468.40	mscra	1564.00	120
1	Rear windscreen inner seal	nu	172.00	
1	Rear bumper 1150.00	rd/de	1242.00	
2	Rear bumper side retainers 45x2.90	ser	144.00	
2	Rear bumper reflectors @152.00	11	304.00	X
2	Rear bumper reflector covers @98.00	twi/ser	196.00	
1	Rear bumper inner sponge	pin	42.00	
1	Rear end panel 487.40	3.00	762.00	
1	Rear end panel top garnish 171.40	pin	298.00	
1	Rear spare tyre panel tool tray	cra	248.00	
1	Rear boot edge weatherstrip	twi	184.00	
			9459.00	
50% less			20%	20%
			1891.80	
			7567.20	
<u>SPECIAL NETT ITEMS</u>				
1 set	Rear Bumper clips	nu	60.00	40
1	Rear windscreen sealant	nu	100.00	40
1	Reverse camera	REFIX	0.00	X
1 set	Reverse sensor	short	280.00	200
1	Rear licence plate	11	75.00	X
2	Rear licence plate lamps @52.00	11	104.00	X
1 set	Tailgate inner trim clips	nu	60.00	40
1	Rear end panel sealant	nu	100.00	50
TOTAL PARTS			8346.20	

Supplementary Item to add in Finalise Cost of Repair

1) RHS fender trim \$382 de/cra
less 20% = \$305.60
50%

5806.40
502
2803.2

411881.80

Vehicle No. SLP 2230M

HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1400.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	900
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	180.00	30
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear	180.00	80
5	To remove and replace reverse sensors/ refix camera and check for proper function	150.00	50
6	To remove and refix rear tailgate windscreen	140.00	120
7	To provide anti-rust treatment on affected areas	180.00	60
	Labour Total :	3230.00	
	TOTAL (PARTS & LABOUR):	11576.20	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

I, KK Auto Consultants hence notify
 the Repairer of the following:
 • before/after spray painting
 • damaged part(s) during resurvey
 • subject to confirmation
 • is on a "Without Prejudice" basis
 • (action(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer:
 Signature:
 Date:

P - 2803.20
 S.N - 370.00
 L - 1840.00
 5013.20

**2-HR
FREE
WEEKDAY PARKING**



**Spend \$30 to qualify
NOW TILL 15 NOV 2019**
[MON - FRI, 6PM - 10PM]

CLICK TO FIND OUT MORE

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Dyna Box



Owner Selling since Day 1 at
Borneo. Super Good condition.
Take with no worry!
Contact

ABWIN

ONE-STOP



Browse by Category

Sort by Date Posted

13 vehicles

honda shuttle

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	honda shuttle		Any	Any	2017	Any	Any	Any
		Honda Shuttle 1.5A G (OPC)	\$52,800	\$6,600 /yr	15-Feb-2017	1,496 cc	16,345 km	Stationwag
		100% Loan Available, OPC Cannot Be A Previous Grab Car! Super Low Mileage Done! Like New, Superb Condition, Well Maintained Interior Condition, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!						
		Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda						
		Posted: 15-Oct-2019						
		Honda Shuttle Hybrid 1.5A	\$73,888	\$8,820 /yr	17-Nov-2017	1,496 cc	20,000 km	Stationwag
		Fuel Type: Petrol-Electric						
		1 Owner. Low Mileage Done At 20000km.Original Paintwork. Clean And Neat Condition. Used As 2nd Car. Accident Free. High Loan. Trade In Available. Most Practical Wagon, Low Maintenance, With Good Fuel Efficiency. What Are You Waiting For? Call Our Friendly Salesman...						
		Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda						
		Posted: 14-Oct-2019						
		Honda Shuttle Hybrid 1.5A X	\$72,800	\$9,150 /yr	19-Jun-2017	1,496 cc	35,339 km	Stationwag
		Graded A by STP						
		Fuel Type: Petrol-Electric						
		Promo 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing. View...						
		Cosmo Automobiles						
		Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda						
		Posted: 13-Oct-2019						
		Honda Shuttle Hybrid 1.5A	\$73,500	\$8,950 /yr	20-Sep-2017	1,496 cc	-	Stationwag
		Fuel Type: Petrol-Electric						
		Elegant Silver, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.						
		Prime Motor & Leasing						
		Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda						
		Posted: 12-Oct-2019						
		Honda Fit Shuttle goes on sale in Japan						
		Honda has announced the launch of the much-awaited Fit Shuttle in Japan, which was delayed due to problems arising from the Japanese earthquake in March						
		article						

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 339K

Vehicle Details

Vehicle No.: SLP2230M

Vehicle to be Exported: No

Intended Deregistration Date: 15 Oct 2019

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: L15B3539052

Chassis No.: GK81007735

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$19,413.00

Original Registration Date: 29 May 2017

First Registration Date: 29 May 2017

Transfer Count: 0

Actual ARF Paid: \$9,413.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 May 2027

PARF Rebate Amount: \$7,059.00

Intended COE Rebate Details

COE Expiry Date: 28 May 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,489.00

COE Rebate Amount: \$35,416.00

Total Rebate Amount: \$42,475.00

The information contained herein is correct as at 15 Oct 2019

OK

18070/9



Service Request Details

Claim

S9M023IW

Reference

None

Loss Date

October 11, 2019

Report Date

Oct 14, 2019 12:51:00 PM

Request Date

October 14, 2019

Due Date

October 21, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

p: Les

T: 2.57p.m

V: 17

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLP2230M

Model
SHUTTLE

Service Address

...

Primary Contact/Insured

TEO BEE CHOO PAULA
2 PEAK VILLE, 487771, Singapore
98160416
chooieteo@hotmail.com

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
Asia Motorsports Solution Pte Ltd

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Summer Lee (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Monday, 14 October, 2019 12:19 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey; customer.service@axa.com.sg
Subject: [EXTERNAL] NOTICE OF ACCIDENT: ACCIDENT INVOLVING SLP 2230 M & SJX 6641 R ON 11 OCTOBER 2019

Categories: Shekhar

Your Ref:
Our Ref: SLP 2230 M

14 October 2019

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING SLP 2230 M & SJX 6641 R ON 11 OCTOBER 2019

We are instructed to notify you of a road traffic accident on **11 October 2019** at about **1715H** at **PIE twds City** involving our client's vehicle registration number **SLP 2230 M** and vehicle registration number **SJX 6641 R** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **16 October 2019 (Wednesday), 1230H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

In the meantime, please note that **with effect from 1st June 2019**, we have shifted to and are now operating from the following address:

**37A Everitt Road
Singapore 428586**

Please update your records accordingly and send all future correspondence to the new address above.



Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27/12/2019

Survey Details:

Date of loss	11-Oct-19
Date of appointment	14-Oct-19
Date of survey	14-Oct-19
Location of survey	ASIA MOTORSPORTS SOLUTION PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLP2230M
Make and Model	HONDA SHUTTLE 1.5G CVT
Date of registration	29-May-17
Parf Rebate	
Market Value	\$ 68,000.00
Parf Rebate	\$ 42,488.00
Nett Loss	\$ 25,512.00

Repair details:

Initial Estimate	\$ 11,576.20
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,173.20
Check items (estimate)	\$ -
Labour	\$ 1,840.00
Total	\$ 5,013.20
Lump Sum(if applicable)	\$ 5,000.00

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	5,000.00
Loss of use	\$	-
Loss of rental	\$	400.00
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	-
Proposed Total	\$	5,407.45

 <MANDATE IA> - S9M023IW {ACCIDENT INVOLVING SJX 6641R & SLP 2230M ON 11/10/2019}

Type

 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5407.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 27/12/2019

[Reply](#)



ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

JIN & WEI ENTERPRISES
52998339K

INVOICE NO: 2017/C188

DATE: 05/11/2019

VEHICLE NO: SLP 2230 M

MAKE	: HONDA	ENGINE NO : L15B3539052
MODEL	: SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR	CHASSIS NO : GK81007735

DESCRIPTION

AMOUNT

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$5,000.00

Total amount payable

S\$5,000.00



Asia Motorsports Solution Pte Ltd



Re:<MANDATE IA> - S9M023IW {ACCIDENT INVOLVING SJX 6641R & SLP 2230M ON 11/10/2019}

Type

🔗 Question

Message

APPROVE MAX \$5407.45

Reply

Cecilia Chong (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Tuesday, 5 November 2019 2:50 PM
To: Admin A; Cecilia Chong (LKK Auto)
Subject: Re: ACCIDENT INVOLVING SLP 2230 M & SJX 6641 R ON 11 OCTOBER 2019 - CALL FOR DIRECT SETTLEMENT
Attachments: SLP2230M_estimate_finalisation.pdf; SLP2230M_invoice.pdf; SLP2230M_report.pdf; SLP2230M_rental_invoice.pdf; SJX6641R_ins_search.pdf

Your Ref:
Our Ref : SLP 2230 M

5 November 2019

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1,
#02-25
Singapore 408933

Attn: Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SLP 2230 M & SJX 6641 R ON 11 OCTOBER 2019 - CALL FOR DIRECT SETTLEMENT

Kindly find attached the finalized report for SLP 2230 M, as proposed by our Single Joint Expert. We are pleased to inform that we are agreeable to the amount proposed.

As such, we are writing to your kind office to call for a direct settlement, in relation to the accident involving SLP 2230 M & SJX 6641 R on 11 October 2019. We will like to know if your company is prepared to settle for the amount as stated below:

Cost of Repair (amount as proposed by SJE)	: \$ 5,000.00
Cost of Rental	: \$ 480.00
LTA Search	: \$ 7.45
Total:	: \$ 5,487.45

We seek your kindest assistance in letting us know whether your kind office is agreeable to the above within the next 7 days and we look forward to you forwarding us the DV (without prejudice to any personal injury claims), if required, so that we can expedite on its return for an amicable settlement to the matter.

We have also attached a copy of our company's invoice for SLP 2230 M, the Singapore Accident Statement of SLP 2230 M, rental invoice and LTA Search, for your easy reference.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19018070/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA

Date : 03-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 6641R	Veh. Inspected	SLP 2230M
Policy No.	GA045597/1	Coverage (\$)	0.00
Claim No.	S9M023IW	Excess (\$)	0.00
Assign From		Assign Date	14/10/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81007735	Colour	SILVER
Odometer	194922	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	CST	6 mm
L/H Front Tyre	195/60 R15	CST	6 mm
R/H Rear Tyre	195/60 R15	CST	6 mm
L/H Rear Tyre	195/60 R15	CST	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/10/2019	Inspection Date	14/10/2019
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2230M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE (CONSISTENT)	BADLY DENTED	1,425.00	1,195.20
1	TAILGATE CENTRE CHROME GARNISH (CONSISTENT)	NOT NECESSARY	425.00	-
1	SET TAILGATE CENTRE CHROME GARNISH CLIPS (CONSISTENT)	NOT NECESSARY	40.00	-
1	TAILGATE INNER LOCK (CONSISTENT)	TWISTED / BENT	278.00	278.00
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	DEFORMED / CRACKED	547.00	345.50
2	TAILGATE DAMPER @\$298.20 (CONSISTENT)	NOT NECESSARY	596.40	-
2	TAILGATE RUBBER STOPPER @\$5.80 (CONSISTENT)	NOT NECESSARY	11.60	-
1	TAILGATE HONDA BADGE (CONSISTENT)	NECESSARY	92.00	38.50
1	TAILGATE SHUTTLE EMBLEM (CONSISTENT)	NECESSARY	98.00	58.00
2	TAILGATE REFLECTOR @\$395.00 (CONSISTENT)	NOT NECESSARY	790.00	-
2	RHS & LHS TAILLAMP @\$782.00 (CONSISTENT)	N/S CRACKED	1,564.00	568.40
1	REAR WINDSCREEN INNER SEAL (CONSISTENT)	NECESSARY	172.00	172.00
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	1,242.00	1,150.00
2	REAR BUMPER SIDE RETAINERS (CONSISTENT)	BENT	144.00	90.00
2	REAR BUMPER REFLECTORS @\$152.00 (CONSISTENT)	NOT NECESSARY	304.00	-
2	REAR BUMPER REFLECTOR COVERS @\$98.00 (CONSISTENT)	TWISTED / TORN	196.00	196.00
1	REAR BUMPER INNER SPONGE (CONSISTENT)	TORN	42.00	42.00
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	762.00	487.40
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TORN	298.00	171.40
1	REAR SPARE TYRE PANEL TOOL TRAY (CONSISTENT)	CRACKED	248.00	248.00
1	REAR BOOT BADGE WEATHERSTRIP (CONSISTENT)	TWISTED	184.00	184.00
1	RHS FENDER TRIM (CONSISTENT)	DEFORMED / CRACKED	382.00	382.00
	LESS 20% DISCOUNT		-1,968.20	-
	LESS 50% DISCOUNT		-	-2,803.20
			7,872.80	2,803.20

Report Ref No. CC4/ASM19018070/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	40.00
1	REVERSE CAMERA (NPA) (SN) (CONSISTENT)	SERVICEABLE	-	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE (SN) (CONSISTENT)	NOT NECESSARY	75.00	-
2	REAR LICENCE PLATE LAMPS @\$52.00 (SN) (CONSISTENT)	NOT NECESSARY	104.00	-
1	SET TAILGATE INNER TRIM CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	50.00
			779.00	370.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS.		1,400.00	600.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED .		1,000.00	900.00
	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		180.00	30.00
	TO REMOVE AND REFIX/REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR.		180.00	80.00
	TO REMOVE AND REPLACE REVERSE SENSORS/REFIX CAMERA AND CHECK FOR PROPER FUNCTION .		150.00	50.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		140.00	120.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		180.00	60.00
			3,230.00	1,840.00
GRAND TOTAL			11,881.80	5,013.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/ASM19018070/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59N0231W

Reference

CC4IASM19018070/Uga2a2

Loss Date

11 October 2019

Report Date

14 Oct 2019 12:51:00 PM

Request Date

14 October 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLP2220M

Make

TRWD HONDA

Model

SHUTTLE

Service Address

...

Primary Contact/Insured

TEO BEE CHOO PAULA

2 PEAK VILLE, 487771, Singapore

98160416

chooiefv@hotmail.com

Claim Handler

LOH Cynthia

6568804643

cynthia.loh@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Additional Instructions

Asia Motorsports Solution Pte Ltd

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Merimen

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	PQA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LETTER TO OJ.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 RENTAL INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 MANDATE JA DD 27122019 .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 TP FINAL EST LIST .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
TAX INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
PASIF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
LTA SEARCH INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 October 2019
TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	15 October 2019
LIST TO SURVEYOR SENT.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	14 October 2019
SURVEYOR APPOINTED.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	14 October 2019
GIA SLP2220M TP.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	14 October 2019
GA045597-Policy Schedule.pdf	Legal	Letter of Demand/Notice of Proceedings	VISHNU BATHAM Shekhar	14 October 2019
GA045597-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shekhar	14 October 2019
EMAIL TP PRL.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	14 October 2019
EMAIL TP PRL.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	14 October 2019