

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

30-10-19

Date Of Accident : 12-10-2019

OUR REF : SJV 9236T/T/19

Lkk - Adrian

PRECISE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-34 (BLK D)

Singapore 417883

Date In/out: 14/10/19 to 24/10/19

TP FWD.

Xiao Tony

ESTIMATE BILL ON VEH. NO. : SJV 9236T

MODEL : TOYOTA ALTIS

CHASSIS NO. : MR053ZEE106168100

LIST ITEM

Rear Bumper Fascia	Deformed		✓	372.85
Rear Bumper Side Retainer - LH & RH	new	2pcs @ 132.25	114	264.50
Rear Bumper Side Attachment - LH & RH	new	2pcs @ 141.40	X	282.80
Rear Bumper Clips	Nec	10pcs @ 12.90	30	129.00
Rear Bumper Sponge	crushed		✓	182.60
Rear Bumper Beam	new		X	372.25
Rear Bumper Stay - LH & RH	LH Bent	2pcs @ 141.40	85.60	282.80
Boot Lid	Buckled		✓	781.75
Boot Lid Weather Stripe	cut		✓	182.25
Boot Lid Rubber Stopper	new		X	43.10
Boot Lid Emblum "1.6"			✓	41.90
Boot Lid Emblum "Corolla"			✓	41.35
Boot Lid Emblum "Altis"			✓	43.10
Boor Lid Badge			✓	41.10
Rear End Panel	Dented		✓	781.10
Rear End Panel Top Trim	Deformed		✓	289.90
Rear End Panel Top Trim Clips	new	4pcs @ 12.90	10	51.60

	4,183.95
Less Discount 25%:	<u>1,045.99</u>
	3,137.96

SPECIAL NETT ITEMS

Reverse Sensor with Control Unit	200	200 380.00
----------------------------------	-----	-----------------------

LABOUR CHARGE

To Check Wiring System.		30 50.00
To Tuff Coat Affected Areas.		60 180.00
To Remove & Refix Interior Upholstery.		60 120.00
To Remove & Refix Reverse Sensor.	1750	50 120.00
To Remove & Refix Boot Lid Mechanism.		50 180.00
To Respray Affected Areas.		PW 1,000.00
To Renew Damages Parts, Straighten & Repair & Aligned All Parts.		700 900.00

	<u>6,067.96</u>
GST 7% :	<u>424.76</u>
TOTAL AMOUNT :	<u>6,492.72</u>

total : 4188.12
 h/s : 3.31K ✓
 07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____