

Surveyor:

LTG

DOI:

ASSIGNMENT
15/10/2019

Date / Time:

14/10/2019

Registered in Merimen:

14/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SDS 9292S

Claim No. : 9020887332SG

Name of Insured : ENG MUI SIAH

Policy No. : 1900011899

Insured Tel No. : HP: +65-97551225

Make / Model : LEXUS GS300

Excess Sec II : \$5 D.O.A : 21/09/2019 13:10

Place of Accident : JUNCT OF ORCHARD RD & CAIRNHILL RD

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SMG 7680A

INSRS:
WSP: TEAM AUTOPRO
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SMG 7680A - X	Non-Reporting ltr (1st):	
	SDS 9292S- CS/TMI17015767/K1qbn2; DOA: 14/8/17	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OE:	
		After call ltr to OE:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OE:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	% Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 3/2/2020	Confirm with: Ade	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : NIL	If NO or B 28, Ass. Lia :
Repair Cost:	\$5 5350.00	02 GOING STRAIGHT ON "ONLY LEFT" LANG	
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 880.00	(5 110 x 8 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search	\$5 29.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 6259.00	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5 6259.00	Name 1: Team Auto Pro Pte Ltd	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

COPY SENT
26/1/2020

SJE : _____ Vehicle Nos : **SMG 7680 A**
 Date of Survey : _____ Model : **VELLIRE**
 Date of ReSurvey: _____ After-Paint: _____ Year : _____
 Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear door	1	\$ 2,692.00	\$2,500.00 2,692.00	DDV
2	Rear door lower panel	1	\$ 328.40	\$ 328.40	NDM XA
3	Rear door lower panel garnish	1	\$ 121.60	✓ 121.60	CUTV
4	Rear door inner garnish	1	\$ 288.60	\$ 288.60	NDM XA
5	Rear door regulator assy	1	\$ 462.20	\$ 462.20	NDM XA
6	Rear door sensor strip	1	\$ 288.30	\$ 288.30	
7	Rear door weather strip	1	\$ 234.20	\$ 234.20	
8	Auto door mechanism	1	\$ 1,680.00	\$ 1,680.00	MV
9	Rear door roller upper	1	\$ 239.50	\$ 239.50	NDM XA
10	Rear door roller centre	1	\$ 265.50	\$ 265.50	
11	Rear door roller lower	1	\$ 238.50	\$ 238.50	
12	Rear door lock mechanism	1	\$ 942.00	\$ 942.00	
13	Rear fender	1	\$ 689.10	✓ 689.10	DDV
14	Rear fender inner shield	1	\$ 342.80	\$ 342.80	NDM XA
15	Rear wheel ^{8.5x15} hub garnish	1	\$ 109.00	✓ 109.00	DLV
16	Rear absorber	1	\$ 649.50	\$ 649.50	
17	Rear absorber bearing	1	\$ 289.00	\$ 289.00	
18	Rear bumper	1	\$ 978.00	\$ 978.00	RX
19	Front door	1	\$ 1,567.80	✓ 1,567.80	DDV
20	Front door lower panel	1	\$ 328.40	✓ 328.40	SCRV
21	Front door lower panel ^{8.5x15} garnish	1	\$ 121.60	✓ 121.60	SCRV
22	Front fender ^{LH}	1	\$ 689.10	✓ 689.10	DDV
23	Front fender inner shield	1	\$ 342.80	\$ 342.80	NDM XA
Parts Sub Total :				\$ 13,887.90	6126.61
Discount 25% :				\$ 2,777.58	1531.65
PARTS TOTAL :				\$ 11,110.32	4594.95

4/5 5356/2

TORQUE WHEEL

16/10/17

1400 hrs

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	734R
Vehicle Details	
Vehicle No.:	SMG7680A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE ELEGANCE MOONROOF (AUTO)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ARJ210376
Chassis No.:	JTNGF3DH508019994
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$48,189.00
Original Registration Date:	31 Dec 2018
First Registration Date:	31 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$59,465.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2028
PARF Rebate Amount:	\$44,598.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,000.00
COE Rebate Amount:	\$29,453.00
Total Rebate Amount:	\$74,051.00

The information contained herein is correct as at 16 Oct 2019

OK

Dep 16,530 / 1yr
1,386 / 1141w

MV 181,880 / 2
PV 74,551 / 2
NV 106,949 / 2

Tedim
16/10/19

osome
Incorporation
in Singapore

SS **35** + SS **315**
Filing agent fee Government fees

Learn

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

"MITSUBISHI" Fuso Canter FB3BEO5RDEA Lorry With ...



Please Call Us Or Email For More
Details.
Direct Owner [Send Ad](#)

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Reg. Date

20 results/page

12 vehicles

Toyota Vellfire

Advanced Search

Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Vellfire	Any	Any	2018	Any	Any	Any	All
	Toyota Vellfire 2.5A Elegance	\$179,600	\$16,630 /yr	19-Oct-2018	2,494 cc	9,712 km	MPV	Available
Regular Service Toyota Service Centre, Non PHV Car, Last Service May 2019, 5 Yrs Warranty Till Oct 2023, Agent Car, Mesmerizing 3 Digit Car Plate Number Goes With The Car, Underutilized Original Low Mileage, Pearl White/Full Leather Interior, 18 Inch Rim, 1 Owner, Sellin...								
360 VR Cars								
Posted: 10-Oct-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	Toyota Vellfire 2.5A X	\$158,999	\$15,220 /yr	19-Oct-2018	2,493 cc	-	MPV	Available
Latest FaceLifted Toyota Vellfire, Non Smoking Driver, View To Believe, Call Now To View Today.								
Posted: 03-Oct-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	Toyota Vellfire 2.5A Elegance	-	N.A	19-Oct-2018	2,494 cc	-	MPV	SOLD
Interest Rate 2.48% Only! 3 Years Warranty, Secured And Well Maintained By Fussy Owner. Immaculate Condition Inside And Outside. Give Yourself A Peace Of Mind! Buy It From Us! A Company With Professional Sales Serviced Assured. Call Our Sales Team And Arrange...								
Car Search								
Posted: 27-Sep-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	Toyota Vellfire 2.5A Z G-Edition	-	N.A	27-Sep-2018	2,493 cc	-	MPV	SOLD
Elegant White MPV, Facelift Model, 7 Seater Unit, With High Specifications, One Owner Only, Low Mileage, Owner Decide To Let Go As Too Many Cars, Brand New Condition, Easy Financing, Flexible In-house Loan Packages Available, Alpine Head Unit For Vellfire.								
Posted: 24-Aug-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	LTA Compliant Exhaust For Toyota CHR							
Toyota CHR 1.8CC KAKIMOTO Exhaust SYSTEM !!								
More info about this product								
	Toyota Vellfire 2.5A X	\$149,888	\$14,400 /yr	10-Sep-2018	2,493 cc	-	MPV	Available
New Latest Facelifted Toyota Vellfire 2.5A x 8-Seater. (Ready Stocks) Guaranteed COE. Call Us For More Information / Details.								
Posted: 12-Aug-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	Toyota Vellfire 2.5A Z G-Edition	\$181,800	\$17,250 /yr	28-Aug-2018	2,493 cc	-	MPV	Available
Latest Highest Specification Model Facelifted Toyota Vellfire With 3 LED Headlight, A Rare Elegant Pearl White MPV, 7 Seater Unit, 2nd Row Ottoman Seat With Footrest, 100% Accident Free, One Owner With Low Mileage, Owner Decide To Let Go As Upgrading To Anothe...								
Posted: 14-Oct-2019 Tags: 2018 Toyota Vellfire, 2018 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota								
	Toyota Vellfire 2.5A Z G-Edition	-	N.A	01-Aug-2018	2,493 cc	-	MPV	SOLD
Elegant White MPV, Latest Model, 7 Seater Unit, With High Specifications, One Owner Only, Almost New Condition, Easy Financing, Flexible In-House Loan Packages Available.								
Compare								

MOTOR CAR (LH)

Vehicle No: SALT 7650A

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door		DL ✓	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH-Door Garnish (corner)		LUT ✓	
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender		DD ✓	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector (side garnish)		DL ✓	

[illegible]

No of Items:

7

Assessore

 $\mathcal{L}_{\mathcal{L}_1, \mathcal{L}_2}$

16/10/19

PRE-REPAIR INSPECTION REQUEST – SMG7680A vs SDS9292S (OI) on D.O.A.: 21/09/2019

18000 / d

From: Hor, Yinnul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Marissa, Azlan, Syazairidina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashveenjeekaur, Parthiban, Theerthan, Subramaniam, Divyashri
Sent: 10/14/2019 3:35:58 PM
Attachments:  pgs 7680 SDS9292S.pdf

Hi,

Please refer to the enclosed request from Team AutoPro Pte Ltd.

Claim no : 9020887332SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yit Rul (Vivian)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

4.05 pm @ 14/10/2019
VNI
Peach

From: TeamAutoPro North [mailto:teamautopl@gmail.com]
Sent: Monday, October 14, 2019 3:05 PM
To: Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Abu Kassim, Noor Marissa; Supramaniam, Darshene; Tan, Lily (AIG); Hor, Yinnul
Subject: [EXTERNAL] 2 Days Notice: SMG 7680 A (Our Ref) and SDS 9292 S (Your Ref) Dated 21st October 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Road Traffic Accident Involving SMG 7680 A (Our Ref) and SDS 9292 S (Your Ref)

Dated 21st October 2019, Time around 12:30HRS
@ JUNCTION OF CARINHILL RD IN FRONT OF H&M

We represent our client; MKM CAR LEASING PTE LTD, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SMG 7680 A and your insured's vehicle registration number: SDS 9292 S.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of Mr Lim - LKK as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Peach
Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SMG7680A (9020887332SG)
[SDS92925]**

TP

MKM CAR LEASING PTE LTD

Sep 21 2019 12:00PM

[ENG MUI SIAH]

Team Autopro Pte Ltd - Sin Ming

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/01/2020 08:11 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6339.00) - SMG7680A - Claim Handler: Loh, Chee-Heng

Approved:6339.00:LOU try to settle at \$110, else \$120 for amicable settlement

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019 Edit Reg		14 Oct 2019 00:00 Edit Adj Rpt	\$5,350.00 Edit Estimates	\$5,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ENG MUI STAH, ID: S0212604D, Tel: +6599999999								
Main Claimant:	MKM CAR LEASING PTE LTD, Co. Reg. No.: 201224734R								
Vehicle Reg. No.:	SMG7680A	Date of Loss:	21/09/2019 12:00 - :59 (8 Months and 21 Days From LTA Reg Date (Man Yr))						
Claim Type:	TP / 9020887332SG	Policy/Cover Note No.:	1900011899 (Comprehensive)						
Vehicle Reg. No. (Insured):	SD592925	Policy No. (Claimant):	SD19V09968/VPZ/R00						
		Excess:							
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 23/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (24/01/2020): Alert - Adj Mandate Approved (\$56339.00) - SMG7680A - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMG7680A (9020887332SG)

[SDS9292S]

TP

MKM CAR LEASING PTE LTD

Sep 21 2019 12:00PM

[ENG MUI SIAH]

Team Autopro Pte Ltd - Sin Ming

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/20 17:26	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/20 17:11	General View	1	Load JPG	
2	23/01/20 17:11	General View	1	Load JPG	
3	23/01/20 17:11	General View	1	Load JPG	
4	23/01/20 17:11	General View	1	Load JPG	
5	23/01/20 17:11	General View	1	Load JPG	
6	23/01/20 17:11	General View	1	Load JPG	
7	23/01/20 17:11	General View	1	Load JPG	
8	23/01/20 17:11	General View	1	Load JPG	
9	23/01/20 17:11	General View	1	Load JPG	
10	23/01/20 17:11	General View	1	Load JPG	
11	23/01/20 17:11	General View	1	Load JPG	
12	23/01/20 17:11	General View	1	Load JPG	
13	23/01/20 17:11	General View	1	Load JPG	
14	23/01/20 17:11	General View	1	Load JPG	
15	23/01/20 17:11	General View	1	Load JPG	
16	23/01/20 17:11	General View	1	Load JPG	
17	23/01/20 17:11	General View	1	Load JPG	
18	23/01/20 17:11	General View	1	Load JPG	
19	23/01/20 17:11	General View	1	Load JPG	
20	23/01/20 17:11	General View	1	Load JPG	
21	23/01/20 17:11	General View	1	Load JPG	
22	23/01/20 17:11	General View	1	Load JPG	
23	23/01/20 17:11	General View	1	Load JPG	
24	23/01/20 17:11	General View	1	Load JPG	
25	23/01/20 17:11	General View	1	Load JPG	
26	23/01/20 17:11	General View	1	Load JPG	
27	23/01/20 17:11	General View	1	Load JPG	
28	23/01/20 17:11	General View	1	Load JPG	
29	23/01/20 17:11	General View	1	Load JPG	
30	23/01/20 17:11	General View	1	Load JPG	
31	23/01/20 17:11	General View	1	Load JPG	
32	23/01/20 17:11	General View	1	Load JPG	
33	23/01/20 17:11	General View	1	Load JPG	
34	23/01/20 17:11	General View	1	Load JPG	
35	23/01/20 17:11	General View	1	Load JPG	
36	23/01/20 17:11	General View	1	Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	23/01/20 17:11	General View		☒
38	23/01/20 17:11	General View		☒
39	23/01/20 17:11	General View		☒
40	23/01/20 17:11	General View		☒
41	23/01/20 17:11	General View		☒
42	23/01/20 17:11	General View		☒
43	23/01/20 17:11	General View		☒
44	23/01/20 17:11	General View		☒
45	23/01/20 17:11	Chassis Number		☒
46	23/01/20 17:11	Odometer Reading		☒
47	23/01/20 17:11	General View		☒
48	23/01/20 17:11	General View		☒
49	23/01/20 17:11	General View		☒
50	23/01/20 17:11	General View		☒
51	23/01/20 17:11	General View		☒
52	23/01/20 17:11	General View		☒
53	23/01/20 17:11	General View		☒
54	23/01/20 17:11	General View		☒
55	23/01/20 17:11	General View		☒
56	23/01/20 17:11	General View		☒
57	23/01/20 17:11	General View		☒
58	23/01/20 17:11	General View		☒
59	23/01/20 17:11	General View		☒
60	23/01/20 17:11	General View		☒
61	23/01/20 17:11	General View		☒
62	23/01/20 17:11	General View		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 17:48	ACKNOWLEDGEMENT EMAIL TO AIG DD 14.10.19		☒
2	14/10/19 17:48	EMAIL FROM AIG DD 14.10.19		☒
3	14/10/19 17:48	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		☒
4	23/10/19 11:34	TP ESTIMATE - MARKED		☒
5	23/01/20 17:09	LOD		☒
6	23/01/20 17:09	GIA SEARCH FEE		☒
7	27/02/20 09:31	WORKSHOP INVOICE		☒
8	27/02/20 09:31	AUTHORISATION TO ACT FORM		☒
9	27/02/20 09:31	Release Voucher		☒
10	27/02/20 09:31	LETTER TO OI		☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/10/19 08:28	OI GIA REPORT		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SDS9292S (Insd veh)	Model:	TOYOTA VELLFIRE 2.5
	SMG7680A (TP veh)		ELEGANCE MOONROOF (A)
Date of Accident:	21/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	16,155.92	
Final Repair Cost	:	\$	5,350.00	
Loss of Use	:	\$	880.00	8.00 days at \$110.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	29.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,259.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 6,259.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

27 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018080/BDA3Q2

Date: 27/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900011899
 Claimant SMG7680A Insured Vehicle No: SDS9292S
 Vehicle No: SMG7680A
 Date of Loss: 21/09/2019 Nature of Claim: TP Claim No: 9020887332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG7680A
 Make & Model: TOYOTA VELLFIRE, 2.5 ELEGANCE Engine No: 2ARJ210376
 MOONROOF (A)
 Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: JTNGF3DH508019994
 Colour: Black Odometer: 103655 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,645.92	4,884.95	6,760.97	58.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	1,820.00	2,690.00	59.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,155.92	6,704.95	9,450.97	58.50
Approved Total (Overridden) (S\$)		5,350.00		
Nett Amount (S\$)	16,155.92	5,350.00	10,805.92	66.89
+ Loss of Use (8.0 x S\$110.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		6,259.00		

INSPECTION

Date of Assignment: 14/10/2019
 Date Inspected: 15/10/2019 Inspected At: 160 SIN MING DR #01-14
 SIN MING AUTO CITY SINGAPORE
 575722
 Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)
 Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR	Dented	2,692.00 FL	*2,500.00 FL
2	1		*REAR DOOR LOWER PANEL	Not Necessary	328.40 FL	*- FL
3	1		*REAR DOOR LOWER PANEL GARNISH	Cut	121.60 FL	*121.60 FL
4	1		*REAR DOOR INNER GARNISH	Not Necessary	288.60 FL	*- FL
5	1		*REAR DOOR REGULATOR ASSY	Not Necessary	462.20 FL	*- FL
6	1		*REAR DOOR SENSOR STRIP	Not Necessary	288.30 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP	Not Necessary	234.20 FL	*- FL
8	1		*AUTO DOOR MECHANISM	Not Necessary	1,680.00 FL	*- FL
9	1		*REAR DOOR ROLLER UPPER	Not Necessary	239.50 FL	*- FL
10	1		*REAR DOOR ROLLER CENTRE	Not Necessary	265.50 FL	*- FL
11	1		*REAR DOOR ROLLER LOWER	Not Necessary	238.50 FL	*- FL
12	1		*REAR DOOR LOCK MECHANISM	Not Necessary	942.00 FL	*- FL
13	1		*REAR FENDER	Dented	689.10 FL	*689.10 FL
14	1		*REAR FENDER INNER SHIELD	Not Necessary	342.80 FL	*- FL
15	1		*REAR WHEEL ARCH GARNISH	Dislodged	109.00 FL	*109.00 FL
16	1		*REAR ABSORBER	Not Necessary	649.50 FL	*- FL
17	1		*REAR ABSORBER BEARING	Not Necessary	289.00 FL	*- FL
18	1		*REAR BUMPER	Repair	978.00 FL	*- FL
19	1		*FRONT DOOR	Dented	1,567.80 FL	*1,567.80 FL
20	1		*FRONT DOOR LOWER PANEL	Scratched	328.40 FL	*328.40 FL
21	1		*FRONT DOOR LOWER PANEL CORNER GARNISH	Scratched	121.60 FL	*121.60 FL
22	1		*FRONT FENDER LH	Dented	689.10 FL	*689.10 FL
23	1		*FRONT FENDER INNER SHIELD	Not Necessary	342.80 FL	*- FL
24	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
25	1		*REAR DOOR LOWER PANEL CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
28	1		*ALLOY RIM	Necessary	800.00 FS	*200.00 FS
29	1		*FRONT DOOR SEALANT)	Necessary	80.00 FS	*60.00 FS
30	1		*REAR DOOR SEALANT)	Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,117.90	6,416.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,471.98	1,531.65
Total Parts (\$\$)	11,645.92	4,884.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR DOOR COMPONENT	New	200.00	80.00
2	R&R REAR UNDER CARRIAGE	New	150.00	0.00
3	R&R FRONT SIDE GLASS	New	120.00	0.00
4	R&R REAR SIDE GLASS	New	120.00	0.00
5	R&R FUEL TANK	New	150.00	0.00
6	R&R FRONT DOOR COMPONENT	New	200.00	80.00
7	R&R RIM AND TYRE	New	250.00	0.00
8	WHEEL ALIGNMENT	New	120.00	0.00
9	PANEL BEAT	New	1,500.00	800.00
10	RUST PROOFING	New	200.00	60.00
11	SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,510.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >