

90306548

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5346J

AAD1910-063

Not Authorised
C/Sing @

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 OCT 2019

SHC 5346J

VF1ABL15AUC279355

RENAULT

LATITUDE

8.10.19

AIG

30/9/2014

PART		LIST	
1	BUMPER COVER FRT	\$	747.20
1	BUMPER SPOILER FRT	\$	344.70
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	101.40
1	BUMPER SUPPORT FRT	\$	10.70
1	BUMPER UNDERTRAY FRT	\$	292.50
1	BUMPER GRILLE LOWER FRT	\$	147.00
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	663.70
1	HEADLAMP LH	\$	743.60
1	HEADLAMP PANEL FRT LH	\$	127.70
1	FENDER PANEL FRT LH	\$	414.40
1	WHEELARCH FRT LH	\$	112.30
1	FENDER BRACKET LOWER LH	\$	11.80
1	FENDER INSULATOR LH	\$	65.50
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	686.00
1	FRAME FULL SUPPORT PANEL	\$	592.70
1	FRAME FULL SUPPORT BRACKET	\$	41.60
1	BONNET	\$	1,312.70
1	BONNET INSULATOR	\$	294.30
1	BONNET STRUT LH	\$	53.30
1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE LH	\$	236.50
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	BONNET CABLE	\$	55.20

X

Trans-cab Auto Services Pte Ltd**AAD1910-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5346J

1	BONNET CABLE COVER	\$	80.60	}	X
1	BONNET SEAL OUTER	\$	83.20		
1	BONNET SEAL INNER	\$	70.10		
1	AIR CLEANER BOX	\$	464.20		
1	AIR CLEANER HOSE	\$	175.85		
1	AIR CLEANER LOWER	\$	271.26		
TOTAL		\$	10,617.88		
10%		\$	1,061.79		
		\$	9,556.09		

Special Nett

1	BUMPER CLIP FRT	\$	nn	66.00	}	X
1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
1	WHEELARCH CLIP FRT LH	\$	nn	30.50		
1	FRONT LEFT TYRE	\$	SL	300.00		
1	FRONT LEFT TYRE RIM	\$	SL	380.00		
1SET	Front licence plate with holder	\$	SL	80.00		
1	WINDSCREEN SEALANT	\$	nn	253.80		
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30		
2	BONNET CABLE CLIP L70Y	\$	nn	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85		
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00		
1SET	RADIATOR GRILLE SCREW	\$	nn	16.00		
TOTAL		\$	1,634.27			

TOTAL PARTS \$ 11,190.36**LABOUR**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts, adjust
and realign the same

\$ 6,000.00 X

Trans-cab Auto Services Pte Ltd**AAD1910-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5346J

To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2201</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	X
TOTAL	\$	14,800.00	
Over All Total	\$	25,990.36	

LKK Auto Consultants hence notify the following:

LUMP SUM (REPAIR DAY)

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

20 days
1 day