



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)

0

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/10/2019
Vehicle Reg. No.:	SJW7417X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	JOHARI BIN JAMIL		
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	10/08/2007
Vehicle Colour:	GREY	Chassis No:	ZNE100360097
Engine No:	1ZZ2874054		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	1,008.75
Miscellaneous Items	11.00
Labour	400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,419.75
+ GST 7.00% (\$\$)	99.38
Nett Amount (\$\$)	1,519.13

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2019)**Parts:** M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJW7417X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH	25.00	0.00	*1,345.00 FL
Sub Total (\$\$)						1,345.00
- List Item Discount on L Items (\$\$)						336.25
Total Parts (\$\$)						1,008.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00 ✓

Sub Total (\$\$) 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION.

New

200.00 ✓

2 SPRAY PAINT FRONT DOOR RH

New

200.00 ✓

Gross Labour Cost (\$\$) 400.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749
'wp'

04/11/19 @ 1145

Lumpsum

Resurvey after repair.

02 days

sure / handle with

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: