## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

То : AIG Asia Pacific Insurance Pte. Ltd.

Attn : Tan. Bennie-WZ

Your Ref : 0026932034SG

Our Ref : CC6/AIG19018151/AHB3

Date : 17 Jan 2020 "WITHOUT PREJUDICE"

## ACCIDENT INVOLVING SLT5466J & SLJ9301C ON 07/10/2019

Refer to the above accident.

The accident occurred when Insured Vehicle was involved in a 3 vehicle chain collision and was the 2nd car and was pushed forward from behind (BOLA 28). A letter was sent out to the Insured to notify TP clain and that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have successfully / not successfully carried out TP Express Settlement between your insured (vehicle no. SLT5466J) and third party claimant (vehicle no. SLJ9301C).

Summary of offer made to workshop Kang Car Repairers Pte Ltd is as follows:

	Claimed	Revised
Cost of Repairs (w/gst)	\$ 9,897.98	\$ 4,387.00
Loss of Use (\$120 x 4 Days)	\$ 480.00	\$ 240.00 (\$60 x 4 days)
GIA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 10,379.98	\$ 4,629.00

Amount of claim at Liability 100% 4,629.00

## TOTAL NO. OF DAYS = 4 Recommended Days

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards, VIC ALPEH

LKK Auto Consultants Pte Ltd