Interview (%

Tech, Into 6

Employ 1181: 6 (0557.36

OB MG Whicle: SGW 6612R CC3/MG19018183/Agd352 00pr. 11/10/2019

19/02/2005,40ps confirmed with Mr Boo form fig \$ 10557.36, 4 sups by email. (Red \$ 16665.64, 61%)

# Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 19 February 2020 5:40 PM

To:

Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;

jiayee.yap@premiumauto.com.sg

Subject:

RE: FINAL REVISION - SGW6612R - OD AIG - SURVEYED 15 OCT 19

Dear Mr Boo,

#### WITHOUT PREJUDICE

Confirm final fig \$10,557.36 before excess \$800.00 & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 18 November 2019 3:39 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR

<sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing

<claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SGW6612R - OD AIG - SURVEYED 15 OCT 19

Hi Adrian and all,

Revised estimate is attached. Photographs of headlamp was taken by you in our Ubi Office

Please confirm repair cost of \$10,557.36 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

# Claim Audit

AUDIT TR	AIL		Ву
o. On A	Audit I	Remarks	
	Clm Veh		[] Merimen
	Model		Administrator
	Changed	Reg No: SGW6612R, Policy No: 2100503942-02. Acct Date: 2019/10/11, Claim Type: SC. Insurer:	[I] Merimen
12 Oct	Clus Created	AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA11913	Administrator
2 2019 <b>(</b>		5330	ranning ord
	Clm	MILE SEES AND ROSE	[] Nivitha
2019 F	Registration :	Setl.Type:3->0, Claim Type:SC->OD.	Govindasamy
	Modified		
15 Oct	Cl		[] Nivitha
	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	Govindasamy
16:13	Ketrieveu		
15 Oct	Adj Co	NAME AND CONTRACTOR OF THE CHOOSE	[A] Nivitha
2019 16:13	Assigned	LKK Auto Consultants Pte Ltd (HQ):	Govindasamy
	Adj Next		[A] Nivitha
	Rpt	Next Rpt:Final Rpt.Due Date: 2019/10/24	Govindasamy
	Changed		0.000
1E Oct			[A] Nivitha
7 2019	Adj Mandata Sat	Approved:8000.00.Reinsp:Adj decides.	Govindasamy
16:13	manuate set		
	Clm		[A] Nivitha
		Rep:1137->200611.	Govindasamy
	Modified		
	Clm Veh	(202420) AUDI O2 1 4 TECI /A)	[A] Nivitha
		(203438) AUDI Q3 1.4 TFSI (A).	Govindasamy
	Changed		[A] LEE SU
	Assignment 1st		THING
G B C	Accessed		
	Adj		[A] Nivitha
		[None] -> ADRIAN LING	Govindasamy
	Assigned	Total Control of the	
15 Oct	Adj Rpt		[A] SHIAU CHAN
	Initiated		[A] SHIAU CHAI
17:02	2111010100		
15 Oct	Clm Dtl		[A] SHIAU CHAN
13 2019	Modified	JPJ Reg. Date: -> 2017/03/16.	
17:02			
15 Oct 14 2019	Clm Details		[A] SHIAU CHAI
17:02	Notified		
	Adj Im.		
	Advice	Next Rpt:Final Rpt.Due Date:2019/10/24	[A] SHIAU CHAI
17:15	Submitted		
15 Oct	Adj	Cur.Req: 20936.00: DAMAGES CONSISTENT. REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORIS	[A] SHIAU CHAI
5 (T	Mandate	E REPAIR.	[A] SHIAO CHA
	Request		[I] Mithoo Singh
16 Oct	Clm	7.00 September 2 000 Ferrors > 200 00 35 Pemarks; > Not Applicable GST; >> 7.00.	Aashweenjeet
	Registration Modified	Init.Est.:->6,000 - 7,000. Excess: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	Kaur
10:05 16 Oct	modified		[A] Merimen
18 2019	Label Added	(20226):Coverage Confirmed.	Administrator
10:05	Lubbi Muudu	역하다 국도소에 전혀 10년 전에 대한다. (10년 12년 13년 13년 13년 13년 13년 13년 13년 13년 13년 13	. ioiiiiiou ucui
	Adj Next	Next Rpt:Final Rpt.Due Date: 2019/10/24. Mandate Remarks: Re-inspection to be done for damag	*** ** **
19 2019	Rpt	e check and supplementary items / labour.	[I] Koh, Victor-C
	Changed	e check and supplementary resins ( about	
16 Oct	Adj	Approved:5080.00:Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-C
20 2019	Mandate Set		[+] NOIT, VICTOR-C
10:55	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		BREETSE WAL
	Clm	A Time - 20:00:00 -> 00:00:00	[I] AIG OneClai
		Acct Time:20:00:00->00:00:00.	Integration Use
09:36	Modified		
	Adj Mandate	Cur.Req:10557.36:KINDLY APPROVE REPAIR COST OF \$10,557.36.	[A] SHIAU CHA
22 2019 12:02	Request	SAMILISAL SASSEL SALIMINES COLUMN 2 1 STATE SALES AND	SENTENCES (SELECTION (CARE))
	Adj Next		
23 2020	Rpt	Cur Rpt:Final Rpt, Cur Due Date: 2019/10/24. Mandate Remarks:	[I] Koh, Victor-
13:53	Changed	45 51 4 52 TO 10 CHANGE THE SECRET SECTION OF SECRET SECTIONS SECTION	
10 Eab			
24 2020	Mandata Cal	Approved:10557.36:	[I] Koh, Victor-0
13:53	manuate Se		
15.55	e From	■ Date To ■ Audit Type None	▼ Go

ACTIVITY No record

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 24 October 2019 5:02 PM

To:

Paramchand, Varsha

Cc:

Rumli, Sharizah; Chua, Tienzhu (SG); Quek, Joyceline-CH; Mithoosingh,

Aashweenjeetkaur

Subject:

RE: - SID 13756094 & CLM NO 5418401861SG - INSD ASKING WHY BONNET IS

NOT APPROVED FOR REPAIRS

Dear Varsha,

Our surveyor had already adviced insured that the damage to bonnet is not due to accident.

Insured has since collected her vehicle without any incident.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paramchand, Varsha < Varsha. Paramchand@aig.com>

Sent: Wednesday, 23 October 2019 4:43 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Cc: Rumli, Sharizah <Sharizah.Rumli@aig.com>; Chua, Tienzhu (SG) <Tienzhu.Chua1@aig.com>; Quek, Joyceline-CH <JoycelineCH.Quek@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Subject: RE: - SID 13756094 & CLM NO 5418401861SG - INSD ASKING WHY BONNET IS NOT APPROVED FOR REPAIRS





This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息,请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

# - SID 13756094 & CLM NO 5418401861SG - INSD ASKING WHY BONNET IS NO...

From: Paramchand, Varsha siewsc@lkkauto.com To:

Rumli, Sharizah, Chua, Tienzhu (SG), Quek, Joyceline-CH, Mithoosingh, Aashweenjeetkaur Cc:

21/10/2019 11:46:08 AM Sent:

#### Hi LKK,

Insd asking why the bonnet is not replaced as the dent was caused by the accident. Pls ctc insd & advise @ 96956286.

Tq

Varsha

\*\*\*\* Entered By: SSPMJL (Manibalan, Jaya Lachme) @ 21/10/2019 11:04 AM \*\*\*\* Hi Team.

Cm call in request to speak to Surveyor who is in charge for her claim.

Cm claim bonnet is not replace due to surveyor not approve for it. This dent is cause by the current accident.

Cm request callback from surveyor. Cm contact 96956286.

Varsha Claims / AIG Asia Pacific Insurance Pte Ltd Claims Care Associate AIG Building, 78 Shenton Way #08-16 Singapore 079120 www.aig.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. Click here to find out more.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hove already adviced insured that the bornet is danged to bonnet is not due to accident. Insured how since collected her webside without any incident.

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 17 October 2019 9:29 AM

To:

Claims; SUR

Subject:

RE: OD CLAIM SGW 6612 R VEH IN

Dear Kelvin,

As instructed by our client, please proceed to repair the insured vehicle SGW 6612R (Excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Wednesday, 16 October 2019 9:02 AM

To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: OD CLAIM SGW 6612 R VEH IN

Dear Kelvin,

Please be informed that we are pending approval from insurance.

The office-in-charge is Mr Khoo Kay Eng and his email: Kay-Eng.Khoo@aig.com

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims < claims@premiumauto.com.sg > Sent: Wednesday, 16 October 2019 8:27 AM

To: SUR <sur@lkkauto.com>

Cc: 'Claims' < claims@premiumauto.com.sg>
Subject: RE: OD CLAIM SGW 6612 R VEH IN

Importance: High

Dear all,

# Claim Audit

1	UDIT TRAIL			By
lo.	On	Audit	Remarks	[] Merimen
1	12 Oct 2019	Clm Veh Model Changed		Administrator
2	11:11 12 Oct 2019 11:11	Clm Created	Reg No: SGW6612R. Policy No: 2100503942-02, Acct Date: 2019/10/11. Claim Ty pe: SC. Insurer: AIG Asia Pacific Insurance Pte, Ltd. (SG). Ins.Status => Notificati on, Created from SAS:MPA119135330	[I] Merimen Administrator
3	15 Oct 2019 16:13	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Nivitha Govindasamy [] Nivitha
4	15 Oct 2019 16:13	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	Govindasamy [A] Nivitha
5	15 Oct 2019 16:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	Govindasamy
6	15 Oct 2019 16:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/24	[A] Nivitha Govindasamy
7	15 Oct 2019 16:13	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	15 Oct 2019 16:13	Clm Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	15 Oct 2019 16:13		(203438) AUDI Q3 1.4 TFSI (A).	[A] Nivitha Govindasamy
10	15 Oct 2019 16:13	Assignment 1st Accessed		[A] LEE SU THING
11	15 Oct 2019 16:13	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
12	15 Oct 2019 17:02	Adj Rpt Initiated		[A] SHIAU CHAN
13	15 Oct 2019	Clm Dtl Modified	JPJ Reg. Date: -> 2017/03/16.	[A] SHIAU CHAN
14	17:02 15 Oct 2019	Clm Details Notified		[A] SHIAU CHAN
15	17:02 15 Oct 2019	Adj Im. Advice	Next Rpt:Final Rpt.Due Date:2019/10/24	[A] SHIAU CHAN
16	17:15 15 Oct 2019	Submitted  Adi Mandate Request	Cur.Req:20936.00: DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
	17:15	CIm Registration	Init, Est.:->6,000 - 7,000. Excess: -> 800.00. 2F Remarks: -> Not Applicable. GS	[I] Mithoo Singh,
17	16 Oct 2019 10:05	Modified	T: -> 7.00.	Aashweenjee Kaur
18	16 Oct 2019 10:05	Label Added	(20226):Coverage Confirmed.	[A] Merimer Administrato
19	16 Oct 2019 10:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/24. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	VICTOR-CK
20	16 Oct 2019	Adj Mandate Set	Approved:5080.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record								
Merimen Bill	ing for this cas	se - Transactio			Ca Name	Ref I	Ref 2	Amount
Bill Ref No	Bill Date	Bill Type	Асс Туре	Acc Name	(Branch)	PMS (4)	THE CASE	STATE STATE
2313999	15 Oct 2019	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants	Consultants	SGW6612R		11.77

## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Date: 15 Oct 2019

## Preliminary Advice

Vehicle No

: SGW6612R

Accident Date

: 11/10/2019

Make

: AUDI Q3

Policy No.

: 2100503942-02

Assignment Date

: 15/10/2019

Excess

: \$\$0.00

Date of Inspection : 15/10/2019

Est. Duration of Repair

: 3.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,223.00
Revised Amount	:S\$	5,080.00
Check Items (Estimated)	:S\$	15,856.00
Total	:S\$	20,936.00

Lump Sum Repair

:S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	106,000.00
COE / PARF Rebate	:S\$	62,811.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,189.00

#### Remarks

The vehicle is repairable at our adjusted amount, let us have your authorisation.	We have also confirmed excess and policy coverage. Kindly
	8.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

•	2	$\sim$ 1	ロヒ	IT ST	МΤ	<b>III</b> 100	ΕM	т
А	9	u	DEI			Ī		ч

12/10/2019 10:57 Date Of Report 11/10/2019 20:00 Date Of Accident

PIE TOWARDS CHANGI BEFORE EXIT 9 EUNOS **Exact Location Of Accident** 

SINGAPORE Country/State of Loss

### DETAILS OF OWN VEHICLE

SGW6612R Vehicle Registration Number

Insured/Policyholder

DUA BEE YEN Name Of Registered Owner S7809891J NRIC No

ALEXISDUA@YAHOO.COM **Email Address** (LOCAL) +65-96956286 Mobile Phone No OTHERS-90111338 Alternative Phone No

Vehicle Particulars

AUDI Manufacturer

Q3 1.4 TFSI S TRONIC Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle?

If No. Please state action to be taken

PRIVATE CAR Vehicle Category

**Insurance Company** 

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

2100503942-02 Policy Number

Cover Note Number

Driver

DUA BEE YEN Name of Driver S7809891J NRIC No 07/04/1978 Date Of Birth INDOOR Occupation 19/01/2005 Date Of Driving Pass

14 YEARS AND 8 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-96956286 Mobile Number

Fax Number

OTHERS-90111338 Contact Number

ALEXISDUA@YAHOO.COM **EMail Address** 

149 PETIR ROAD Address

#10-182

670149 Postcode

Was driver an employee of the Insured's Company NO

OWNER If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

3

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO ambulance?

Was any other material or property damaged?

YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

0

Number of Passengers (Including Driver)

**Details of Police Action** 

YES Was the accident reported to the police?

If Yes, Please state which Police Station

10 UBI AVENUE 3 Police Station Name

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

Police Station Address SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT Are accident photos available for attachment?

NO

Was there any video captured by Car Camera?

NO Was there any audio recorded?

NO

Page 2 of 30

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the assident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: Kelica Khou

NRIC/FIN NO. GESTESSON

## Sketch Plan #2

				SGW 6613
			1 f - 1	29111 1961 3
		111		
		LAI1		
		151		
SCRIBE CIRCUMSTAN	CES OF THE ACCIDENT			
Dafor to	Palice Report			
Keter To	Police Report			
CLARATION				Gold 2
	articulars are true in every resp	ect	120	
CLARATION We declare the foregoing p	articulars are true in every resp Driver's Signature	ect	Reporting Centre Pers Name: Kelly's K NRIC/FIN No.: GFS 7	

### POLICE REPORT





Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3 Report No. T/20191011/7023

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2019 22:01			Vide Report No.: Station Diary No.: G/20191011/0194			
Informan	t's Partic	ulars				
Name of DUA BEE	Informant YEN		Address: 149 PETIR ROAD #10-182 SINGAPORE 670149			
ID Type / ID No.: NRIC NO / S7809891J			Contact No.: Home/Office: Mobile: 96956286			
Nationalit SINGAPO	y: ORE CITIZ	'EN	Email: ALEXISDUA@YAHOO.COM			
Sex: Age: Date of Birth: Female 41 07/04/1978			Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation		nent manager	Driving Licence Information: Class: 3  Date of Expiry:			

Type of Accident:	Non-Injury Conveyed By Ambu		ink ive:	Date/Time of Accident: 11/10/2019 20:00	Type of Location Straight Road	
Location: PIE towards (	Changi, before exit 9 Euro	os, below ov	verhead	bridge		
Weather: R		Road Surface:			Road Speed Limit:	
Traffic Flow: Traffi		Traffic Co	Traffic Control:		Traffic Volume: Heavy	
One way					Anyone conveyed by	

Details of Vehicle Involved								
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge		
SGW6612R	Car	AUDI	Q3	Brown	Slightly Damaged	0		
SLJ3502D	Car	HONDA	CITY	White	Seriously Damaged	1		
SMG2042A	Car	VOLKSWAGO N	PASSAT	Grey	Slightly Damaged	1		

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SGW6612R	AIG ASIA PACIFIC INSURANCE PTE. LTD.				

## POLICE REPORT



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20191011/7023

#### CONTINUATION OF REPORT

Details of Perso						
Any Pedestrian Ir				_		
No. of Pedestrian	s Injured: NIL	Use of Pe	destriar	Cross	ing: NA	
Driver				1868		
Name	DUA BEE YEN		ID No		S7809891J	
Related Vehicle	SGW6612R (Car)		Conta	ct No.	96956286	
Hospital/Clinic	NIL			of g ce & / Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL	Date Disc	charge	NIL		
	ted Medical Leave NIL	Degree o		NIL		
Driver	Too medical core	1 2				
Name	CLEMENT TAN		ID No		S8505410D	
Related Vehicle	SLJ3502D (Car)		Conta	ct No.	97316955	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Disc	charne	NIL		
	ted Medical Leave NIL	Degree o				
Driver	Ted Wedical Leave 1412	- Dogree v	11,111		AND THE SECOND	
Name	CHUN SEHYUN		ID No	6	S8368942J	
Related Vehicle	SMG2042A (Car)		Contact No.		86224304	
Hospital/Clinic	NIL			of g ce & Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Disc	charge	NIL		
	ted Medical Leave NIL	Degree o		NIL		

### Brief Details.

Driving on PiE towards Changi, heavy traffic and was moving, vehicle infront stepped and I brake and hit the rear of vehicle in front

#### POLICE REPORT





Police Station Of Origin Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20191011/7023

CONTINUATION OF REPORT

Sketch Plan

Authentication Stamp

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Informant:
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
11/10/2019 22:01

Officer In Charge Of Case:
TP / TPIB /
THABAGESH JEYATHESH
Contact No.: 65476232

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	AL LINE
Owner ID Type:	Singapore NRIC
Owner ID:	891J
Vehicle Details	
Vehicle No.:	SGW6612R
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	Q3 1.4 TFSI S TRONIC
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CZD259364
Chassis No.:	WAUZZZ8U3HR040442
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$27,887.00
Original Registration Date:	16 Mar 2017
First Registration Date:	16 Mar 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$31,042.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2027
PARF Rebate Amount:	\$23,281.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,300.00
COE Rebate Amount:	\$39,530.00
Total Rebate Amount:	\$62,811.00

The information contained herein is correct as at 15 Oct 2019



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : DUA BEE YEN (LAI MEIYAN)

Period of Insurance : 16 Mar 2019 To 15 Mar 2020

Engine No. Chassis No. : CZD259364 : WAUZZZ8U3HR040442 Policy No.

Vehicle No. : SGW6612R : 2100503942-02

Endorsement No. :

Issued Date

: 01 Mar 2019

#### ABOUT THE COVER

Make/Model

: AUDI Q3 1.4 TFSI (150 BHP)

Engine Capacity/Tonnage 1,395.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholdre b) Any other person who is driving on the Policyholder's older or with bischer permission. This Policy will incominely the Policyholder or any authoritied driver only if height meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than your improvement.

Age Condition

: All Age Condition

Limitation as to use\*

the only for excital develop and pleasure purposes and for the Policyholder's business. This Policy does not cover use for him or reward, driving tustion, driving test, raispectioning, the comage of pools other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\*\*Limitations rendered inoporative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cop. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### EXCESS

11

Section 1 Fire - S0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2 Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

DUA BEE YEN (LAI MEIYAN) + \$800 (Own Damage)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED R

1 Aug. Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63682323

For other Approved Reporting Centres(A)G Authorised Repairers, prease contact our 24 hour actident emergency hotine at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg. or AIG SQ Mobile App. Simply search and download "AIG SQ" from iTunes or Google Play.

#### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We havely denty that the policy to when this Certificate of insurance release is assert in accordance with the provisions of the Motor Vehicles (Third Party Risks and Company Rose). (See (Manager) and Motor Vehicles (Third Party Risks) Rules, 1979 (Manager).

281 ALEXANDRA ROAD AUDI GUSTOMER SERVICE CENTRE

Underwritten by AiG Asia Pacific insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE SSPOCE





AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #07-16

# MOTOR ACCIDENT INTERVIEW FORM

NAME	Dua Bee Yen
VEHICLE NUMBER	56w 6612R
DATE/ TIME OF ACCIDENT	: 11 oct 2019/8pm
PLACE OF ACCIDENT	: PIE towards Changi, before Euros exit
THIRD PARTY VEHICLE (IF ANY)	
	**************************************
Start Jonney from Bu	kit Panjang, item intend to go to Jalan Rambai
DID YOU DRINK ANY ALCOHOLIC DRINKS I POLICE CONDUCT ANY BREATHE-ANALYSES No	BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC R TEST ON YOU? IF YES, WHAT WAS THE RESULTS?
I collided with the but the car in front	extensiveness of the DAMAGES TO ALL VEHICLES INVOLVED?  vehicle in front. My car was slightly damaged  was seriously dented. The car in front of the  was also slightly dented (M)
WERE YOU OR YOUR PASSENGER/S INJURE FOR INVESTIGATION?	ED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE
trua Bee Yen	

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

# UNDERTAKING

1, Dua Bee	Yen, (NRIC No. <u>\$78098915</u> ), hereby
confirm that the Singapore	Accident Statement lodged by me on 120ct 2010
at\O a ~_ hours pe	rtaining to the accident involving motor car Reg. No: h I was the driver are true and accurate to the best of my
I acknowledge that my insu a breach of policy terms and	rers are not liable under the contract of insurance if there is d conditions.
there is evidence emerges irrevocably undertake to a insurance and I undertake	ted/unreported third party property or injury claim arises or is that there is a breach of policy terms and conditions, I absolve my insurer from all liability under the contract of to re-pay any sums paid by my insurers pursuant to the receipt of written demand by my insurers.
Signature	: Dra Bee yen
Name of Insured / Driver	:
Nric No.	: S7809891J
Date	S7809891J : 12/10/19.
Signature	:1
Name of Policyholder	:
Nric No.	:
Date	:

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## WIP: 15673

#### Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323

Fax No : 6841 1183

Reference : PA/OD/1231/2019/NS

Date : 14-0ct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Dua Bee Yen Address : 149 petir road

#10-182

Singapore 670149

 Telephone
 : HP +65 96956286

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 2100503942-02

Vehicle No : SGW 6612 R

Model Code : Audi Q3 1.4 TFSI S TRONIC

Model / Year : 16/3/2017 Engine No : CZD 259364

Chassis No : WAUZZZ8U3HR040442

Mileage :

Date In :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 11-Oct-19

Place of Accident : Pie Towards Changi Before Exit 9 Eunos

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

# Telefax

# Estimated Labour Charges for Accident Vehicle. SGW 6612 R

S/n	Nature of Jobs	Š	Estimated Charges	Surveyor's Recommendation	
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	/
2	To dismantle and renew front bumper and both headlights. To repair bonnet. Re-organise crash management components. Reinstall all parts		\$	2,800.00	500.
3	To respray front bumper and bonnet		\$	2,400.00	550/
4	To carry out diagnostic checks.	S/N	\$	192.00	
	TOTAL LABOUR CHARGES	:	\$	5,752.00	2

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

# Telefax

# Material List for Accident Vehicle Regn No. SGW 6612 R

S/N	Parts Description		Damaged Parts & Prices S/Nett Remarks
1	FRONT BUMPER Delad	\$	1,788.00 -1430.40
2	FRONT BUMPER FIXING PARTS	\$	99.00 +
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH 2	\$	278.00 *
4	FRONT BUMPER GRILLE - CENTRE	\$	197.00 + 159,60
5	FRONT BUMPER CLOSING ELEMENT - LOWER	\$	160.00 +
6	FRONT BUMPER SPOILER 7458 NEC	\$	349.00 7
7	RADIATOR GRILLE CONC.	\$	1,053.00
, 8	RADIATOR GRILLE STRIKER PLATE	ds.	111.00 4 7 88.80
9	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$	770.00 ? X
10	FRONT BUMPER FOAM FILLER PIECE THE NUL	\$	93.00 <sup>7</sup> ×
11	FOAM FILLER PIECE COVER Nee	\$	59.00 7 ×
12	FRONT BUMPER COVER	\$	112.00 - 89.70
13	CAUTION SIGN STICKER / Vac NEC	\$	13.00 - 9.76
14	SIGNAL HORN - LH LOW TONE 2	\$	182.00+
15	SIGNAL HORN - RH HIGH TONE	\$	182.00 *
16	HEADLIGHT MOUNTING - LH / RH 2 New 2	\$	214.00 *
17	HEADLIGHT SUPPORT - LH / RH	\$	46.00 ⊀
18	HEADLIGHT RETAINING PLATE - LH / RH 2 2	\$	158.00 🖈
- 19	LED HEADLIGHT - LH / RH RH WAT. 1/2 2	\$	14,174.00 2 3649.60
20	HEADLIGHT LIFT CYLINDER - LH / RH N4 N4 2	\$	384.00 +
	SUB TOTAL SPARE PARTS :	\$	20,422.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SGW 6612 R

		Damaged Parts & Prices			
S/N	Parts Description			S/Nett	Remarks
21	HEADLIGHT HOSE Men		\$	170.00	
22	RADIATOR AIR GUIDE - LH / RH ZHU	2	\$	46.00 +	
23	RADIATOR SEALING STRIP - CENTRE		\$	21.00 +	
24	FRONT WHEEL COVER - LH / RH Hu	2	\$	472.00 L	- 377.60
25	FRONT NO PLATE Dente	S/N	\$	40.00	40
26	SUNDRIES Not Nec.		\$	300.00	X
	TOTAL SPARE PARTS		\$	21,471.00	
	TOTAL LABOUR CHARGES		\$	5,752.00	
	GRAND TOTAL		\$	27,223.00	
	All charges are not inclusive of GST.				
	I I Demode (OK) - Appeared Remarks (V) = Not any	bayone			

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

166 Butlovised, 03 Days

Adoin him

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 15673

Hi Adrian

jb 18 Nov 19

4 days include HL replacement

## Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1231/2019/NS

Date : 14-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Dua Bee Yen

Address : 149 petir road #10-182

#10-182 Singapore 670149

 Telephone
 : HP +65 96956286

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 2100503942-02

Vehicle No : SGW 6612 R

Model Code : Audi Q3 1.4 TFSI S TRONIC

Model / Year : 16/3/2017 Engine No : CZD 259364

Chassis No : WAUZZZ8U3HR040442

Mileage Date In

Estimated By : Johnny Boo / Allan Wu

Accident Date : 11-Oct-19

Place of Accident : Pie Towards Changi Before Exit 9 Eunos

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Estimated Labour Charges for Accident Vehicle. SGW 6612 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendatio			
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$	360.00
2	To dismantle and renew front bumper and both headlights. To repair bonnet. Re-organise crash management components. Reinstall all parts removed.		\$	2,800.00	\$	750.00
3	To respray front bumper and bonnet		\$	2,400.00	\$	550.00
4	To carry out diagnostic checks.	S/N	\$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$	5,752.00	\$	1,852.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

# Material List for Accident Vehicle Regn No. SGW 6612 R

	List for Accident Venior reg			Damaged Part S/Nett		emarks
5/N	Parts Description			S/Nett	111	11101111
5/IN		5	5	1,788.00	\$	1,430.40
1	FRONT BUMPER		5	99.00		
2	FRONT BUMPER FIXING PARTS		\$	278.00		
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH		en e	197.00	\$	157.60
4	FRONT BUMPER GRILLE - CENTRE		\$		•	0.700
5	FRONT BUMPER CLOSING ELEMENT - LOWER		\$	160.00		
6	FRONT BUMPER SPOILER		\$	349.00	•	842.40
7	RADIATOR GRILLE		\$	1,053.00	\$	88.80
8	RADIATOR GRILLE STRIKER PLATE		\$	111.00	\$	80.00
9	FRONT BUMPER SIDE REINFORCEMENT BEAM	Λ	\$	770.00		
10	FRONT BUMPER FOAM FILLER PIECE		\$	93.00		
11	FOAM FILLER PIECE COVER		\$	59.00	1	89.20
12	FRONT BUMPER COVER		\$	112.00		9.76
13	THE STONE CTICKED	NEC	\$	13.00		9.76
14	TONE		\$	182.00		
15	DU LICH TONE		\$	182.00		
16	THE INTINC IN I PH	2	\$	214.00		
	CHEROPE LH / RH	2	\$	46.00	)	
17	THE PETAINING PLATE - LH / RH	2	\$	158.00	)	
18		2	\$	14,174.00	\$	5,669.60
19		2	\$	384.00	0	
20		340	\$	20,422.0	0 \$	8,287.7
	SUB TOTAL SPARE PARTS	13.58	100			

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Material List for Accident Vehicle Regn No. SGW 6612 R

		Damaged Parts & Prices				
S/N	Parts Description			S/Nett	F	Remarks
Ont	Tutto bootingston	c/f			\$	8,287.76
21	HEADLIGHT HOSE		8	\$ 170.00		
22	RADIATOR AIR GUIDE - LH / RH		2	\$ 46.00		
23	RADIATOR SEALING STRIP - CENTRE			\$ 21.00		
24	FRONT WHEEL COVER - LH / RH		2	\$ 472.00	\$	377.60
25	FRONT NO PLATE	S	S/N	\$ 40.00	\$	40.00
26	SUNDRIES			\$ 300.00		
	TOTAL SPARE PARTS		: -	\$ 21,471.00	\$	8,705.36
	TOTAL LABOUR CHARGES			\$ 5,752.00	\$	1,852.00
	GRAND TOTAL			\$ 27,223.00	\$	10,557.36

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

**Please Note** 

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SGW 6612 R Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept

4th March 2020

PA/OD/1231/2019/NH

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref

Your Ref Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SGW 6612 R, Audi Q3 1.4 TFSI S-TRONIC.

With reference to the above-mentioned vehicle, no. SGW 6612 R, claimant, Ms. Dua Bee Yen, please find the related document per attached.

- A copy of the Original invoice no. 85014933 S\$ 10,440.38.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG – SGW 6612 R Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

**Ubi Service Centre** 55 Ubi Road 1 Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1183 **Customer Service** 6366 2323 Service Appointment 24-hour Breakdown Service 9828 1233 customer care@premiumauto.com.sg Email

#### INS TAX INVOICE

Page 1

10:27

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice No: 85014933

Account: A0006

(T

0)

Date : 03/03/2020

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY

Term : 30

SINGAPORE 079120

Regn No: SGW6612R

32373) (V

Regn Date: 16/03/2017

Mileage: 44925

WIP No.: 15673

Model: Q3 1.4 TFSI S tronic 8UGAKX

Chassis: WAUZZZ8U3HR040442

Order: SGW6612R

Engine: CZD 259364

Dept: U

You have been assisted by :- UB-Kelvin Khoo

(138)

		Deta	ils	Qty	Unit Price	Amount
s	SUBLET		M:	40.00	1.00	40.00
3	122200000	TO SUPPLY VEHICLE NUMBER P	LATE	2202 100		000 00
2	EXC		M: 8888	-800.00	1.00	-800.00
S	BODYWORK	Insurance Excess/Liability TO REMOVE, CHECK AND REINST. HARNESS FOR HEADLIGHT, HORN.	M: ALL FRONT WIRE	360.00	1.00	360.00
S	BODYWORK	TEMPERATURE SENSOR AND HEAL	DLIGHT WASHER	750.00	1.00	750.00
8	BODINORR	TO DISMANTLE AND RENEW FROM HEADLIGHT.TO REPAIR BONNET MANAGEMENT COMPONENTS.REINS REMOVED	NT BUMPER AND REORGANISE CRASH			
S	BODYWORK		M:	550.00	1.00	550.00
	120000 E88000	TO RESPRAY FRONT BUMPER	22:07	100 00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CH	M:	192,00	1.00	152.00
X	A8U0807065L GRU	COVER(LAST)	Less 020%	1.00	1788.00	1,430.40
ž.	A8U0807683C 4U8	(SK) GRILLE AP	Less 020%	1.00	197.00	157.60
X	A8U0853651M 1QP	GRILLE	Less 020%	1.00	1053.00	842.40
į.	A8U0853692C	PLATE (LAST)	Less 020%	1.00	111.00	88.80
\$	A8U0807081C	COVER (LAST)	Less 020%	1,00	111.50	89.20
ζ.	A8K0010520C	STICKER	Less 020%	1.00	12.20	9.76
X	A8U0941774A	HEADLIGHT (LAST) AP	Less 020%	1.00	7087.00	5,669.60
X	A8U0853717 4U8	(SK) COVER	Less 020% Less 020%	1.00	236.00	188.80
X	A8U0853718 4U8	COVER	Less 020%	1.00	230.00	100,00
_	Parts 8,665.36				Sub-Total	9,757.3

0.00 Labour 1,892.00 0.00 0.00 Sublet Menus Lubricant

683.02 7% GST 10,440.38 **Grand Total** 

Received by

For & on behalf of Premium Automobiles Pte Ltd

:

:

:

# Telefax

to AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building

Singapore 079120 Motor Claims Dept Yr Ref: SGW 6612 R Norah Khai 6768 9828 6841 1183

Body Repair

from Telephone +65-

83 Telefax +65-Mobile +65-

Our department Your Claim Ref

Our Ref

PA/OD/1231/2019/KK 22 October 2019

total pages

Showroom

9 Leng Kee Road Singapore 159090

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

55 Ubi Road 1 Singapore 408699

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

Audi Q3 1.4 TFSI S-TRO

Vehicle Chassis No.

WAUZZZ8U3HR040442

Vehicle Regn No.

SGW 6612 R

Vehicle Mileage

44930 KM

Vehicle Owner

Ms Dua Bee Yen

Certificate No

2100503942-02

Own Damage Excess:

\$ 856.00 (Inclusive GST)

Accident Date

11 Oct 2019

Place

PIE Towards Changi Before Exit 9 Eunos

Repair Cost

: \$ 10,440-28

WIP No.

: 15673

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Ad) Assigned	Adi Rot		Adj Subr	mitted	Ins Auth'ed	Pending for Sur Report Cancel Case		
Main	16 Oct 2019	and Submitted	15 Oct 2019 16:13 Edit Adj Rpt	S\$10,557 Edit Estima	3 CH ST 1 1	<b>S\$10,5</b> ! View Rp	Series Control				rvey
	Main	Re	eference		Claim	Details		Documents		<u></u>	how All
CLAIM S	UBFOLDER DE	TAILS	And the party of the last of t			N. S. Carly Labor.	I have been been been been been been been be	by insurer]			
Insured:	DUA BEE	YEN, ID: S7809	891J, Tel: +65	96956286,	Email:	ALEXISDI	UA@YAHOO				
Vehicle Re No.:	g. sgw66	SGW6612R Date						19 00:00 - :59 hs and <b>25</b> Days Fr	om LTA Re	eg Date (N	fan Yr)]
Claim Type	e: OD / 54	OD / 5418401861SG					(Comprehensive)				
					Exce		S\$800.00				V1500-0
Repairer:	Premium	Automobiles Pt	e Ltd (UBI) 55 l	Jbi Road 1,	408699	Ubi - Tel:	67689828	/9827/9911	0		
Handling Insurer:	Aashween	ieetkaur. Mithoosir	igh@aig.com					ithoo Singh, Aas			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Har	ndled by A	ADRIAN LI	NG] [Final R	pt due 2	24/10/20	)19]
Driver/Cus dian:	DUA BEE	rEN (41 / Female)	, NRIC: S7809	891J, Tel:	+6596	956286 E	mail: ALEX	ISDUA@YAHOO.C	М		
ASSOCIA	TED MAIL RE	CEIVED						V	lew All	Compose	Case Mai
AIG_SC     AIG_SC	(16/10/2019) (16/10/2019) OCIATED TAS	: Alert - Adj Mar : SGW6612R / C	date Approved	(\$\$5080.0 19 / Covera	0) - 50	GW6612F	View All	Handler: Mithoo Sandler: Mithoo S	Create N	ew Task	Complete
No results		C#555 05550	900cm(275) 5.00M	receis (1981)		10000000	servet/fig.th	50000000000000000000000000000000000000			

## **Claim Documents**

\*SGW6612R (5418401861SG)
OD
Oct 11 2019 12:00AM
[DUA BEE YEN]
Premium Automobiles Pte Ltd

Up	load Documents Uple	and Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	1
Assessment Reports			1 per		•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	15/10/19 17:15	Adjuster Immediate Advice	0	Load HTM	_
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	15/10/19 16:54	General View	0	Load JPG	•
2	15/10/19 16:54	Chassis Number	0	Load JPG	•
3	15/10/19 16:54	General View	0	Load JPG	•
4	15/10/19 16:54	General View	0	Load JPG	•
5	15/10/19 16:54	General View	0	Load JPG	•
6	15/10/19 16:54	General View	0	Load JPG	•
7	15/10/19 16:54	General View	0	Load JPG	•
8	15/10/19 16:54	General View	0	Load JPG	•
9	15/10/19 16:54	General View	0	Load JPG	
10	15/10/19 16:54	General View	0	Load JPG	•
11	15/10/19 16:54	General View	0	Load JPG	
12	15/10/19 16:54	General View	0	Load JPG	•
13	15/10/19 16:54	General View	0	Load JPG	•
14	15/10/19 16:54	General View	0	Load JPG	•
15	15/10/19 16:54	General View	0	Load JPG	•
16	15/10/19 16:54	General View	0	Load JPG	•
17	15/10/19 16:54	General View	0	Load JPG	•
18	15/10/19 16:54	General View	0	Load JPG	9
19	15/10/19 16:54	General View	0	Load JPG	•
20	15/10/19 16:54	General View	0	Load JPG	•
21	15/10/19 16:54	General View	0	Load JPG	•
22	15/10/19 16:54	General View	0	Load JPG	•
23	15/10/19 16:54	General View	0	Load JPG	•
24	15/10/19 16:54	General View	0	Load JPG	•
25	15/10/19 16:54	General View	0	Load JPG	•
26	15/10/19 16:54	General View	0	Load JPG	•
27	15/10/19 16:54	General View	0	Load JPG	•
28	15/10/19 16:54	General View	0	Load JPG	•
29	15/10/19 16:54	General View	0	Load JPG	•
30	15/10/19 16:54	General View	0	Load JPG	•
31	15/10/19 16:54	General View	0	Load JPG	•
32	15/10/19 16:54	General View	0	Load JPG	2
33	15/10/19 16:54	General View	0	Load JPG	

Ass	essment Reports		1 per page	v 2
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbn	ail Print
34	15/10/19 16:54	General View	1 Load JP	5 <b></b>
35	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
36	06/12/19 09:03	Reinspection Photo	<b>1</b> Load JP	G 🗹
37	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
38	06/12/19 09:03	Reinspection Photo	1 Load JP	5 <b>2</b>
39	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
40	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
41	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
42	06/12/19 09:03	Reinspection Photo	1 Load JP	G 🗹
43	06/12/19 09:03	Reinspection Photo	1 Load JP	3
44	06/12/19 09:03	Reinspection Photo	1 Load JP	3 <b>2</b>
45	06/12/19 09:03	Reinspection Photo	1 Load JP	3
46	06/12/19 09:03	Reinspection Photo	● Load JP	<b>9</b>
Doc	umentation		1 per page	v 2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbn	ail Print
1	15/10/19 16:53	Singapore Accident Statement	① Load PD	F
2	15/10/19 16:53	Police Report	① Load PD	F
3	15/10/19 16:53	Certificate of Insurance	1 Load PD	F
4	15/10/19 16:53	Driver's Driving License	① Load PD	F
5	15/10/19 16:53	INTERVIEW FORM	<b>●</b> Load PD	F
6	15/10/19 16:53	UNDERTAKING FORM	1 Load PD	F
7	15/10/19 16:53	ESTIMATE	● Load PD	F
8	12/12/19 12:02	REVISED ESTIMATE	Load PD	F
9	09/03/20 14:01	DISCHARGE VOUCHER	1 Load PD	F
10	09/03/20 14:01	WORKSHOP INVOICE	■ Load PD	F

# **Linked Accident Report Documents**

			View	View in Brow	vser ▼
Assessment Reports			1 per	page 🔻	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	21/10/19 11:32	Addendum Sheet	0	Load JPG	•
2	06/12/19 18:53	Accident Statement	0	Load HTM	
3	06/12/19 18:55	Accident Statement	0	Load HTM	
4	06/12/19 18:56	Accident Statement	0	Load HTM	1
5	06/12/19 18:57	Accident Statement	•	Load HTM	
6	06/12/19 19:07	Accident Statement	•	Load HTM	
7	06/12/19 19:08	Accident Statement	•	Load HTM	
8	06/12/19 19:10	Accident Statement	•	Load HTM	
9	06/12/19 19:10	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page ▼	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/10/19 11:10	Accident Photo	0	Load JPG	•
2	12/10/19 11:10	Accident Photo	0	Load JPG	•
3	12/10/19 11:10	Accident Photo	0	Load JPG	•
4	12/10/19 11:10	Accident Photo	0	Load JPG	•
5	12/10/19 11:10	Accident Photo	0	Load JPG	•
6	12/10/19 11:10	Accident Photo	0	Load JPG	Ø
7	12/10/19 11:10	Accident Photo	0	Load JPG	•
8	12/10/19 11:10	Accident Photo	0	Load JPG	•

020		1 per p	1 per page ▼		
Assessment Reports			Thumbnail	Print	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	•	Load JPG	•
9	12/10/19 11:10	Accident Photo	0	Load JPG	•
10	12/10/19 11:10	Accident Photo	0	Load JPG	•
11	12/10/19 11:10	Accident Photo	0	Load JPG	•
12	12/10/19 11:10	Accident Photo			•
13	12/10/19 11:10	Accident Photo	0	Load JPG	•
14	12/10/19 11:10	Accident Photo	0	Load JPG	
15	12/10/19 11:10	Accident Photo	0	Load JPG	2
16	12/10/19 11:10	Accident Photo	0	Load JPG	•
17	12/10/19 11:10	Accident Photo	0	Load JPG	•
-	100000000000000000000000000000000000000	Accident Photo	0	Load JPG	•
18	12/10/19 11:10	Accident Photo	0	Load JPG	•
19	12/10/19 11:10	Accident Photo	0	Load JPG	•
20	12/10/19 11:10		0	Load JPG	
21	12/10/19 11:10	Accident Photo	0	Load JPG	•
22	12/10/19 11:10	Accident Photo	0	Load JPG	•
23	12/10/19 11:10	Accident Photo			-
	100 Control   10		1 per	page v	•
Do	cumentation	Premium Automobiles Pte Ltd (UBI)		Thumbnai	Print
No	Finalized On		0	Load JPG	•
1	12/10/19 11:06	Sketch Plan	0	Load JPG	•
2	12/10/19 11:07	POLICE REPORT	0	Load JPG	•
3	12/10/19 11:07	POLICE REPORT	0	Load JPG	•
4	12/10/19 11:07	POLICE REPORT	0	Load JPG	
5	21/10/19 11:34	Accident Sketch Plan	•	LUGG JF G	457

# **Documents Checklist**

	Reset   Save   Print
DOCUMENTS CHECKLIST	
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG19018183/AQD3S2

Date:

09/03/2020

REFERENCE

Insured/Claimant: Date of Loss:

DUA BEE YEN

11/10/2019

Policy No:

Nature of Claim:

OD Claim No:

Engine No:

Chassis No:

Odometer:

5418401861SG

CZD259364

44923 km

WAUZZZ8U3HR040442

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SGW6612R

Make & Model:

AUDI Q3, 1.4 TFSI (A) 16/03/2017 (Man. Year: 2016)

Reg. Date: Colour:

Bronze

Engine Capacity:

1395 cc

Market Value/New Car Price:

\$\$106,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

235/55 R17 Michelin 6 mm Rear Tyre Size: Rear Left Side:

Rear Right Side:

235/55 R17

Michelin 6 mm Michelin 6 mm

Michelin 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,471.00	8,705.36	12,765.64	59.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,752.00	1,852.00	3,900.00	67.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,223.00	10,557.36	16,665,64	61.22
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	26,423.00	9,757.36	16,665.64	63.07
+ GST 7.00/7.00% (S\$)	1,849.61	683.02	1,166.59	63.07
Nett Amount (S\$)	28,272.61	10,440.38	17,832.23	63.07

INSPECTION

Date of Assignment:

Date Inspected:

15/10/2019

15/10/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=876239&extid=320051&CFID=68364923&C... 1/4

# REPAIR DETAILS

0.130.000	commende Qty Part No.		Condition	Repairer's	Amount
		*FRONT BUMPER	Deformed	1,788.00 FS	*1,430.40 FS
1	1	*FRONT BUMPER FIXING PARTS	Not Necessary	99.00 FS	*-FS
2	1	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	278.00 FS	*-FS
3	2	*FRONT BUMPER GRILLE - CENTRE	Not Necessary	197.00 FS	*157.60 FS
4	1	*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	160.00 FS	*-FS
5	1	*FRONT BUMPER SPONGE	Not Necessary	349.00 FS	*-FS
6	1		Cracked	1,053.00 FS	*842.40 FS
7	1	*RADIATOR GRILLE *RADIATOR GRILLE STRIKER PLATE	Cracked	111.00 FS	*88.80 FS
8	1		Not Necessary	770.00 FS	*-FS
9	1	*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	93.00 FS	*-FS
10	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	59.00 FS	*-FS
11	1	*FOAM FILLER PIECE COVER	Deformed	112.00 FS	*89.20 FS
12	1	*FRONT BUMPER COVER	Necessary	13.00 FS	*9.76 FS
13	1	*CAUTION SIGN STICKER *SIGNAL HORN - LH LOW TONE	Not Necessary	182.00 FS	*-FS
14	1	*SIGNAL HORN - RH HIGH TONE	Not Necessary	182.00 FS	*-FS
15	1	*HEADLIGHT MOUNTING - LH / RH	Not Necessary	214.00 FS	*-FS
16	2	*HEADLIGHT SUPPORT - LH / RH	Not Necessary	46.00 FS	*-FS
17	2	*HEADLIGHT SUPPORT - LH / RH	Not Necessary	158.00 FS	*-FS
18	1	*LED HEADLIGHT - LH / RH	O/s Cut	14,174.00 FS	*5,669.60 FS
19	1	*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	384.00 FS	*-FS
20	2	*HEADLIGHT HOSE	Not Necessary	170.00 FS	*-FS
21	1	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	46.00 FS	*- FS
22	2	*RADIATOR SEALING STRIP - CENTRE	Not Necessary	21.00 FS	*- FS
23	1	*FRONT WHEEL COVER - LH / RH	Necessary	472.00 FS	*377.60 FS
24	2		Dented	40.00 FS	*40.00 FS
25	1	*FRONT NO PLATE	Not Necessary	300.00 FS	*- FS
26	1	*SUNDRIES	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	27.72.72.72.72.72.72.72.72.72.72.72.72.7	
F=Fr	anchise part. S=Spo	Nett.	Total Parts (S\$)	21,471.00	8,705.36

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

iculars	Lab.Type	Repairer's	Amount
ems		200.00	360.00
REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR ADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND ADLIGHT WASHER ASSY.	New		/ A A A A A A A A A A A A A A A A A A A
REPAIR BONNET, RE-ORGANISE CRASH MANAGEMENT	New	2,800.00	750.00
	New	2,400.00	550.00
CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour	r Cost (S\$)	5,752.00	1,852.00
	REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR ADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND ADLIGHT WASHER ASSY. DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT MPONENTS. REINSTALL ALL PARTS REMOVED. RESPRAY FRONT BUMPER AND BONNET. CARRY OUT DIAGNOSTIC CHECKS.	REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR New ADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND ADLIGHT WASHER ASSY.  DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. New REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT MPONENTS. REINSTALL ALL PARTS REMOVED.  RESPRAY FRONT BUMPER AND BONNET. New	REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR New 360.00 IDLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND IDLIGHT WASHER ASSY.  DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. New 2,800.00 REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT MPONENTS. REINSTALL ALL PARTS REMOVED.  RESPRAY FRONT BUMPER AND BONNET. New 2,400.00 New 192.00

< END OF ESTIMATES >