

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Oct 2019

Preliminary Advice

Insured Vehicle No : GBA3679T
TP Vehicle No : SJY8983K Accident Date : 08/10/2019
Make : PORSCHE 911 CARRERA Assignment Date : 15/10/2019
Date of Inspection : 17/10/2019 Est. Duration of Repair : 4 days
Inspection At : TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ)
27A TANJONG PENJURU
SINGAPORE 609025

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,571.17
Revised Amount	:S\$	4,390.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,390.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP