

ASS. REC. BY:

Assignment: Rasul

ASSIGNMENT (Office)

From (Person): Pauline Soh

of EGI

Date/Time: 15/10/2019 @ 4:36pm

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 8983K

Insured:

GBA 36797

at Workshop n/s

TRANSUROKAS

Tel:

6331 0683

of

27A Tanjung Penjun

Policy No:

Claim No:

CDMCG19001905

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:12pm 15/10/19

Person Contacted:

EM

Vehicle IN/OUT

Date/Time

Action/Instruction Estimated ✓

SJY 8983K-X

GBA 36797-X

18/10/19

@ 14:31 pm revised PA to Pauline Soh via message


ASS. REC. BY: Rasul

4236
WEXPRY: 2029/APR

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: SJY 8983K
 at Workshop m/s TRANS EUROKARS
 of 27A Tarzook Peninsula
 Insured: ERHO
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJY 8983K Yr Regn: 2010 / JWA
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: PORSCHE CARRERA 911 c.c. 3614
 Colour: GRKY A/C: Insured / Std / NI / NA
 Sp. Reading: 46519 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WPO22299ZAS701007
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 235/40ZR18
 R: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
 TOYO/YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 08/10/19 D.O.I. 17/10/19
 Survey held at TRANS EUROKARS
 Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/11/19	Confirmed P/R \$ 4,390.00 @ 4 days with Rasul (\$ 3,181.17 Red - 42%)
	RECEIVED 12 NOV 2019
	12/11/2019

Date/Time, File Pass to? : Preli. Report
 1) 12/11/19 : Final Report
 Date/Time, File Return to?
 2) _____
 Report Formed:
 Lump Sum 4,390/- P/R

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (%))

Survey Fee:	
Transportation:	250
S + RS - SI	11
Fines:	
Others:	
TOTAL	261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBA3679T	Accident Date	: 08/10/2019
TP Vehicle No	: SJY8983K	Assignment Date	: 15/10/2019
Make	: PORSCHE 911 CARRERA	Est. Duration of Repair	: 4 days
Date of Inspection	: 17/10/2019		
Inspection At	: TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ) 27A TANJONG PENJURU SINGAPORE 609025		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,571.17
Revised Amount	:S\$	4,390.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,390.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

Nivitha (LKK Auto)

From: Pauline Soh <pauline.soh@ergo.com.sg>
Sent: Tuesday, 15 October 2019 4:36 PM
To: Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Ivy Yong; Phoebe Xie; eva.kok@eurokars.com.sg
Subject: FW: Claims ref no. (P) CDMCG19001905 TP CLAIMS- SJY8983K &V GBA3679T DOA 8/10/2019
Attachments: SAS2682583.PDF; ESTIMATE ERGO TP - SJY8983K.pdf

Hi LKK,

Please conduct this survey request.
(Note: Survey vehicle only)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]
Sent: Thursday, October 10, 2019 2:12 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg
Subject: TP CLAIMS- SJY8983K &V GBA3679T DOA 8/10/2019

YOUR REF: GBA3679T / OUR REF: SJY8983K THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 12 November 2019 4:29 pm
To: jessicahs@eurokars.com.sg
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; SUR
Subject: RE: FINALIZATION ERGO TP - SJY8983K.xlsx

Dear Jessica,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to ERGO Insurance Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Monday, 11 November 2019 2:59 pm
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg
Subject: FINALIZATION ERGO TP - SJY8983K.xlsx

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$4,390.00 before GST
04 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2019 16:05
Date Of Accident	08/10/2019 10:15
Exact Location Of Accident	ALONG TEMPLE STREET PARALLEL PARKING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY8983K
Insured/Policyholder	
Name Of Registered Owner	TAY JIH-HSIN
NRIC No	S7113423G
Email Address	TAYJIHHSIN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91529443
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	PORSCHE
Model	911 CARRERA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA282428/1
Cover Note Number	

Driver

Name of Driver	TAY JIH-HSIN
NRIC No	S7113423G
Date Of Birth	27/04/1971
Occupation	INDOOR
Date Of Driving Pass	15/05/1990
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91529443
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	TAYJIHHSIN@HOTMAIL.COM

Address 5 SPRINGLEAF GARDEN SINGAPORE 788167
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA3679T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver CHNG TENG HOE
 NRIC/Passport Number S1464247A
 Contact Number 90886861
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renew/late policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

△
B


△
A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/10/2019 around 1015hrs my car was parked along Temple Street parallel parking. When I returned to collect my car, driver of vehicle B informed me that he had collided onto the front portion of my car while doing reversing.


DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

ERGO INSURANCE PTE LTD 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Tay Jih-Hsin ADDRESS : 5 Springleaf Garden Singapore 788167 TEL :	WIP : 51360 EXCESS : DATE: 10.10.2019
VEH NO : SJY8983K	DATE IN :	CONTACT PERSON : EVA	63310683
CHASSIS NO : WP0ZZ99ZAS701007	MILEAGE :	TYPE OF CLAIM :	TP
MODEL : 911 Carrera	DATE REG.: 30.06.2010	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY		REVISED	PRICES
1	FRONT BUMPER <i>repair</i>	1	P997-505-191-05-G2L		\$ 2,100.70
2	NOZZLE HOLDER LH <i>X SUC</i>	1	P997-505-761-02-		\$ 50.30
3	NOZZLE HOLDER RH <i>X SUC</i>	1	P997-505-762-02-		\$ 50.30
4		0	0		\$ -
5		0	0		\$ -
TOTAL PARTS					\$ 2,201.30
LESS 10%					\$ 220.13
TOTAL PARTS COST					\$ 1,981.17

Labour Description

1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			1560	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER .			1300	\$ 1,500.00
3	TO INSTALL THE FRONT BUMPER PROTECTIVE FILM (1 WORKING DAY)			NETT	\$ 900.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT <i>nr</i>	\$ X 200.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
6	SUNDRIES. <i>Resue</i>		<i>net</i>	NETT	\$ 30 50.00

Signature
18/10/19
Hp 90010068
4 days
17/10/19 @1535
Resue after paint

TOTAL LABOUR	\$ -	\$ 5,590.00
TOTAL PARTS	\$ -	\$ 1,981.17
TOTAL	\$ -	\$ 7,571.17
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

*DISCLAIMER

1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

ERGO INSURANCE PTE LTD		NAME : Mr Tay Jih-Hsin	WIP : 51360
5 Temasek Boulevard		ADDRESS : 5 Springleaf Garden	EXCESS :
#04-01 Suntec Tower Five		Singapore 788167	DATE : 10.10.2019
Singapore 038985		TEL :	
ATTN. :	MOTOR CLAIMS		
FAX :			
VEH NO :	SJY8983K	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WPOZZZ99ZAS701007	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	911 Carrera	DATE REG. : 30.06.2010	POLICY NO. :

NATURE OF WORKS

S/NO		Parts Description		REVISED	PRICES
		QTY			
1	FRONT BUMPER	1	P997-505-191-05-G2L	\$ -	\$ 2,100.70
2	NOZZLE HOLDER LH	1	P997-505-761-02-	\$ -	\$ 50.30
3	NOZZLE HOLDER RH	1	P997-505-762-02-	\$ -	\$ 50.30
4		0	0		\$ -
5		0	0		\$ -
TOTAL PARTS				\$ -	\$ 2,201.30
LESS 10%				\$ -	\$ 220.13
TOTAL PARTS COST				\$ -	\$ 1,981.17
		Labour Description			
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,560.00	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER .			\$ 1,300.00	\$ 1,500.00
3	TO INSTALL THE FRONT BUMPER PROTECTIVE FILM (1 WORKING DAY)			\$ 900.00	\$ 900.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ -	\$ 200.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 600.00	\$ 600.00
6	SUNDRIES.			\$ 30.00	\$ 50.00
TOTAL LABOUR				\$ 4,390.00	\$ 5,590.00
TOTAL PARTS				\$ -	\$ 1,981.17
TOTAL				\$ 4,390.00	\$ 7,571.17
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ 4,390.00	
GST 7%				\$ 307.30	\$ -
TOTAL				\$ 4,697.30	\$ -

NUMBER OF DAYS: 4 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE

SINGAPORE 038985

INV No. AC1911669
INV Date 15/11/2019
Reference CS/EGI19018201/R1sd3n2
Code EGI



PROFESSIONAL SERVICE FEE

Vehicle No. SJY 8983K
Insured Veh. GBA 3679T
Claim No. CDMCG19001905
Policy No.
Accident Date 08/10/2019
Inspection Date 17/10/2019

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19018201/R1SD3N2
Date: 15/11/2019**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No: SJY8983K Insured Vehicle No: GBA3679T
 Date of Loss: 08/10/2019 Nature of Claim: TP Claim No: CDMCG19001905

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY8983K Engine No: A02824
 Make & Model: PORSCHE 911 CARRERA, 3.4 COUP PDK E5 (A) Chassis No: WP0ZZZ99ZAS701007
 Reg. Date: 30/06/2010 (Man. Year: 2010) Odometer: 48519 km
 Colour: Grey
 Engine Capacity: 3614 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40ZR18 Rear Tyre Size: 235/40ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,031.17	30.00	2,001.17	98.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	4,360.00	1,180.00	21.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,571.17	4,390.00	3,181.17	42.02
+ GST 7.00/7.00% (S\$)	529.98	307.30	222.68	42.02
Nett Amount (S\$)	8,101.15	4,697.30	3,403.85	42.02

INSPECTION

Date of Assignment: 15/10/2019
 Date Inspected: 17/10/2019 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
 27A Tanjong Penjuru
 Singapore 609025

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2019)
Parts: M1-COUPE	PORSCHE 911 CARRERA 3.4 COUP PDK E5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY8983K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,100.70 FL	*- FL
2	1		*NOZZLE HOLDER LH	Serviceable	50.30 FL	*- FL
3	1		*NOZZLE HOLDER RH	Serviceable	50.30 FL	*- FL
4	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
Sub Total (S\$)					2,251.30	30.00
- List Item Discount on L Items 10.00/10.00% (S\$)					220.13	0.00
Total Parts (S\$)					2,031.17	30.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,340.00	1,560.00
2	TO RESPRAY FRONT BUMPER	New	1,500.00	1,300.00
3	TO INSTALL THE FRONT BUMPER PROTECTIVE FILM (1 WORKING DAY)	New	900.00	900.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	0.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (S\$)			5,540.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >