

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM19018243/Gcf3s2

8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811

Date: 12-11-2019



ATTN: CYNTHIA LOH

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKQ 7313G	Veh. Inspected	SLF 9568X
Policy No.		Coverage (\$)	0.00
Claim No.	S9M023O4	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	16/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GGH300010063	Colour	BLACK
Odometer	50774 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/60 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
----------------------------------------------------	--

5. General Information

Accident Date	14/10/2019	Inspect Date / Time	16/10/2019 (12:00 PM)
Survey held at	160 SIN MING DRIVE AUTO CITY #07-11/07		
Repairer	JP CONCEPTZ		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/ASM19018243/Gcf3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.