

2000000

ASS. REC. BY:

REF: CS/INC19018272/R19d3m2

Special Instruction:

Surveyor: Rafsy

ASSIGNMENT (Office)

From (Person): Theresia Vimala

of INC

Date/Time: 16/10/19 @ 10:03am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 5276Y

Insured: SKE 3191A

at Workshop m/s Trans Eurokors

Tel: 8128 9802 / 6331 0685

of 27A Tanjung Perungu

Policy No:

Claim No: MT/1065612-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/10/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11am @ 16/10/19

Person Contacted: Jess

Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Tolungda ✓</u>
	<u>SMG 5276Y-X</u>
	<u>SKE 3191A-X</u>
<u>28/11/19 @ 10.06am</u>	<u>confirmed with Jess final fig to 4614.88, 4 days.</u>
	<u>ceded \$ 4708.04, 50%)</u>

15C

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 16 October 2019 1:23 PM
To: assignments
Cc: Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/10/2019

Hi Lkk , pse take note of the OIC details.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Theresa Vimala D/O Balagangadharan
Sent: Wednesday, 16 October 2019 10:03 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/10/2019

Dear LKK,

Please assist to survey the following vehicles.

SN	Surveyor	Claim No.	Appt Type	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	DI VEH	doa	Additional Remarks
1	ERIC	MT/1060821-001	TP	16/10/2019	SLW8321H	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	Kerlyn Ong / 91865113	Physical Survey		Cb6661e	2/9	After 10am
2			TP	16/10/2019	SKH7563Z	HOME ADDRESS	58A SUNGEI KADUT LOOP RYOBI INDUSTRIAL BUILDING SINGAPORE 729505	Glynn Neo / 8383 2726	Physical Survey	14:00-16:00			Workshop : JXC Pte Ltd
3	serene	MT/1065612-002	TP	16/10/2019	SMG5276Y	TRANS EUROKARS PTE LTD	27A TANJONG PERJURU SINGAPORE 609042	Jess Francis Carlos / 8128 9802	Physical Survey	14:00-16:00	SKF3191a	6/10	
4	charlotte	MT/1066127-002	TP	16/10/2019	SLS2617R	TRANS EUROKARS PTE LTD	27A TANJONG PERJURU SINGAPORE 609042	Jess Francis Carlos / 8128 9802	Physical Survey	14:00-16:00	SKK3686m	7/10	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 November 2019 10:06 AM
To: jess.francis@eurokars.com.sg
Cc: jessicahs@eurokars.com.sg; samuel.ng@eurokars.com.sg;
ronald.yap@eurokars.com.sg; SUR
Subject: RE: FINALIZATION NTUC TP SMG5276Y (MAZDA) // BEFORE PAINT PHOTOS

Dear Jess,

WITHOUT PREJUDICE

Confirm final fig \$4,614.88 before GST and 4 repair days.

Kindly send the relevant documents to NTUC Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jess.francis@eurokars.com.sg <jess.francis@eurokars.com.sg>
Sent: Wednesday, 27 November 2019 12:02 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: jessicahs@eurokars.com.sg; samuel.ng@eurokars.com.sg; ronald.yap@eurokars.com.sg
Subject: RE: FINALIZATION NTUC TP SMG5276Y (MAZDA) // BEFORE PAINT PHOTOS

Dear Rasul,

Kindly refer to the before paint photos.

Regards.

Jess Francis Carlos
Insurance Claims Executive
Trans Eurokars Pte Ltd
27A Tanjong Penjuru
Singapore 609042
Tel no.: 8128 9802

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Jessica Harry Shastri <jessicahs@eurokars.com.sg>
Sent: 27 November 2019 11:10 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Samuel Ng <samuel.ng@eurokars.com.sg>
Cc: Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>
Subject: RE: FINALIZATION NTUC TP SMG5276Y (MAZDA)

Dear Jess,

Shiau Chan (LKKAUTO)

From: catherinechua@eurokars.com.sg
Sent: Wednesday, 6 November 2019 11:48 AM
To: Shiau Chan (LKKAUTO)
Cc: jess.francis@eurokars.com.sg; eva.kok@eurokars.com.sg
Subject: RE: KINDLY ADVISE THE STATUS OF VEHICLES AND FINALISE

Dear Shiau Chan

Please refer to the remarks added to your list.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: 06 November 2019 11:30 AM
To: Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>; Catherine Chua <catherinechua@eurokars.com.sg>
Subject: KINDLY ADVISE THE STATUS OF VEHICLES AND FINALISE

Dear Sir/Madam,

Kindly advise the status of below vehicles:

- | | | |
|-------------------------|-----------------|--|
| 1. SGE 2606E (ECICS-TP) | DOA: 30/09/2019 | Not repaired yet as liability is unclear |
| 2. SMG 5276Y (NTUC-TP) | DOA: 06/10/2019 | Not repaired yet |
| 3. SLU 1056E (FIRST-TP) | DOA: 18/10/2019 | Will finalise soon |
| 4. SLZ 8242L (MSIG-TP) | DOA: 19/10/2019 | Not repaired yet |

If done of repair, kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Incident report

Date: 6th October 2019

Time: 14:30pm

Location: slip road leading from Alexandra Road onto West Coast Highway (in the direction towards Vivo City)

Incident: I had turned onto the slip road from Alexandra Road, and had stopped at the junction to look out for oncoming traffic before turning onto the main road (West Coast Highway) when I heard a loud "crash" and felt my vehicle lurch forward (i.e. I had been rear-ended by the vehicle behind—vehicle number SKF 3191A). No one was injured in the incident. My vehicle sustained a few dents to its bumper but was able to drive off afterwards.



Location of incident:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available abroad.

ACCIDENT STATEMENT

Date Of Report 07/10/2019 10:50
 Date Of Accident 06/10/2019 14:25
 Exact Location Of Accident SLIP RD FROM ALEXANDRA RD TO WEST COAST HIGHWAY
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG5276Y
Insured/Policyholder
 Name Of Registered Owner ONG GEK LIAN DEBORAH
 NRIC No S1652217A
 Email Address COSDEB1964@GMAIL.COM
 Mobile Phone No (LOCAL) +65-96357249
 Alternative Phone No OFFICE-96812603

Vehicle Particulars

Manufacturer MAZDA
 Model MAZDA3 1.5L SDN
 Exact Purpose for which vehicle was being used at time of accident PRIVATE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1900006395
 Cover Note Number

Driver

Name of Driver CHEN LEE YOONG ELIZABETH
 NRIC No S9220710B
 Date Of Birth 17/06/1992
 Occupation INDOOR
 Date Of Driving Pass 29/04/2011
 Driving Experience 8 YEARS AND 5 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-96812603
 Fax Number
 Contact Number
 Email Address ELIZABETHCHEN17@GMAIL.COM

Address	133 THOMSON RIDGE
Postcode	574715
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHEN YUN YIT COSMAS GENDER: : MALE
Passenger 2	NAME: : CHEN CHUN YIT MATTHEW GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF3191A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANNE
NRIC/Passport Number	
Contact Number	90082848
Address	
Postcode	

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 7/10/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: ~~SHH~~ Catharine Chua
NRIC/FIN No.: S1449251H

Please refer to the statement provided by Elizabeth Chen. attached.

I/We declare the foregoing particulars are true in every respect.

Date & Time: 7/10/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.: S1449251H



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Ong Gek Lian Deborah
Period of Insurance : 24 Dec 2018 To 23 Dec 2020
Engine No. : P520567427
Chassis No. : JM6BN22A8K0266310

Vehicle No. : SMG5276Y
Policy No. : 1900006395
Endorsement No. :
Issued Date : 15 Jan 2019

ABOUT THE COVER

Make/Model : MAZDA 3 1.5 SKYACTIV
Engine Capacity/Tonnage : 1,496.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, game-making, reliability trial or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use \$500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ong Gek Lian Deborah - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurocars Pte Ltd Add: 27A Tanjong Pagar, Singapore 608042 63310608

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599190

ARF (AP) PTE LTD - MAZDA
7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX
SINGAPORE 068111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

883474



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**Third Party Insurer Enquiry**Our Ref No: GR-19-164057
Date of Request: 07/10/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date: 07/10/2019
Enquiry By: Catherine Chua Siew Quek
TP Vehicle No.: SKF3191A
Accident Date: 06/10/2019**Enquiry Result**

Mazda: SMG5J6Y

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKF3191A	NTUC Income Insurance Co-operative Ltd	06/06/2019-05/06/2020	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE		NAME : Mdm Ong Gek Lian Deborah	WIP : 38264
1 MARITIME SQUARE		ADDRESS : 133 Thomson Ridge	EXCESS :
#10-01 HARBOURFRONT CENTRE		Singapore 574715	DATE: 8-Oct-19
SINGAPORE 099253		TEL : 96357249	
ATTN. :	MOTOR CLAIMS		
FAX :			
VEH NO :	SMG5276Y	DATE IN :	CONTACT PERSON : Jess 63957874
CHASSIS NO :	JM6BN22A8K0266310	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.: 24-Dec-18	POLICY NO. :

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER <i>de /</i>	1	MBPD8-50-221ABB		\$ 1,128.60
2	BRACKET CENTER <i>? 450</i>	1	MKD53-50-251		\$ 5.40
3	TOWING COVER LHS <i>mis /</i>	1	MBHN1-50-EL1 BB		\$ 16.50
4	TOWING COVER RHS <i>mis /</i>	1	MBHN1-50-EK1 BB		\$ 17.10
5	REFLECTOR LHS <i>X</i>	1	MD350-51-5L0E		\$ 53.00
6	RETAINER CENTER, SENSOR <i>X } 450</i>	2	MKD47-67-UC5A53		\$ 36.40
7	SENSOR CENTER, ULTRASONIC <i>? X</i>	2	MGMK6-67-UC1 53		\$ 361.80
8	TAPE PROTECTOR, SENSOR <i>me /</i>	3	MBCKA-50-EM1		\$ 14.10
9	REAR REINFORCEMENT <i>? 64 /</i>	1	MB45A-50-260		\$ 564.20
10	GROMMET, REAR BUMPER <i>me /</i>	2	M9991-00-501		\$ 6.00
11	GROMMET, REAR BUMPER <i>me /</i>	4	MBHN1-50-021A		\$ 10.80
12	RIVET, REAR BUMPER <i>me /</i>	4	MBBM4-50-355		\$ 18.00
13	FASTENER, REAR BUMPER <i>me /</i>	4	MB45A-56-146A		\$ 12.00
14	CLIP, REAR BUMPER <i>me /</i>	2	MGJ21-50-049		\$ 6.80
15	ORNAMENT, MAZDA <i>me /</i>	1	MBHN1-51-721		\$ 56.10
16	MASCOT, REAR <i>me /</i>	1	MBHN1-51-730		\$ 78.20
17	ORNAMENT, SKYACTIVE <i>me /</i>	1	MBHN1-51-771		\$ 66.80
18	FASTENER, BOOTLID <i>X 450</i>	2	MEG21-51-146		\$ 12.40
19	GROMMET, BOOTLID <i>X 450</i>	2	MGA7B-51-146		\$ 6.60
20	GASKET LHS, BOOTLID <i>me /</i>	1	MB45A-51-3J8		\$ 22.00
21	GASKET RHS, BOOTLID <i>me /</i>	1	MB45A-51-3H8		\$ 22.00
22	GASKET LHS, TAILLAMP <i>me /</i>	1	MBHN1-51-163		\$ 22.00
23	GASKET RHS, TAILLAMP <i>me /</i>	1	MBHN1-51-153		\$ 22.00
			TOTAL PARTS		\$ 2,558.80
			LESS 10%		\$ 255.88
			TOTAL PARTS COST		\$ 2,302.92

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, TO REPAIR BOOTLID, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 2,640.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	nm X	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	nm X	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	nm X	\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING. <i>Ciavetta</i>	NETT 150	\$ 250.00
9	MZ-BR-SUNDRI	SUNDRIES. <i>nel</i>	NETT 10	\$ 100.00
			TOTAL LABOUR	\$ - \$ 7,020.00
			TOTAL PARTS	\$ - \$ 2,302.92
			TOTAL	\$ - \$ 9,322.92
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS

TRANS EUROKARS PTE LTD

Authorised Signature

[Signature]
18/10/19

Rasul

Hp 90010068

4 days

16/10/19 @ 1455

Ready before paint

LPG Auto Consultants hence notify the Repairer of the following:

- To recovery before/after paint
- To display damaged panel during recovery
- Parts prices are subject to confirmation
- Third party survey is to be a "Witness Threaded" item
- No legal responsibility is accepted
- Supplemental Survey may be required and is subject to final approved item/quantity

Accepted by Repairer
Signature:
Date:



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE		NAME : Mdm Ong Gek Lian Deborah		WIP : 38264	
1 MARITIME SQUARE		ADDRESS : 133 Thomson Ridge		EXCESS :	
#10-01 HARBOURFRONT CENTRE		Singapore 574715		DATE: 8-Oct-19	
SINGAPORE 099253					
ATTN. : MOTOR CLAIMS		TEL : 96357249			
FAX :					
VEH NO :	SMG5276Y	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BN22ABK0266310	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	24-Dec-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO		QTY		REVISED	PRICES
1	REAR BUMPER <i>del</i>	1	MBPD8-50-221ABB		\$ 1,128.60
2	BRACKET CENTER <i>?</i>	1	MKD53-50-251		\$ 5.40
3	TOWING COVER LHS <i>MIS</i>	1	MBHN1-50-EL1 BB		\$ 16.50
4	TOWING COVER RHS <i>MIS</i>	1	MBHN1-50-EK1 BB		\$ 17.10
5	REFLECTOR LHS <i>X</i>	1	MD350-51-5L0E		\$ 53.00
6	RETAINER CENTER, SENSOR <i>X</i>	2	MKD47-67-UC5A53		\$ 36.40
7	SENSOR CENTER, ULTRASONIC <i>?</i>	2	MGMK6-67-UC1 53		\$ 361.80
8	TAPE PROTECTOR, SENSOR <i>me</i>	3	MBCKA-50-EM1		\$ 14.10
9	REAR REINFORCEMENT <i>?</i>	1	MB45A-50-260		\$ 564.20
10	GROMMET, REAR BUMPER <i>me</i>	2	M9991-00-501		\$ 6.00
11	GROMMET, REAR BUMPER <i>me</i>	4	MBHN1-50-0Z1A		\$ 10.80
12	RIVET, REAR BUMPER <i>me</i>	4	MBBM4-50-355		\$ 18.00
13	FASTENER, REAR BUMPER <i>me</i>	4	MB45A-56-146A		\$ 12.00
14	CLIP, REAR BUMPER <i>me</i>		MGJ21-50-049		\$ 6.80
15	ORNAMENT, MAZDA <i>me</i>		MBHN1-51-721		\$ 56.10
16	MASCOT, REAR <i>me</i>		MBHN1-51-730		\$ 78.20
17	ORNAMENT, SKYACTIVE <i>me</i>		MBHN1-51-771		\$ 66.80
18	FASTENER, BOOTLID <i>me X</i>		MEG21-51-146		\$ 12.40
19	GROMMET, BOOTLID <i>X</i>		MGA7B-51-146		\$ 6.60
20	GASKET LHS, BOOTLID <i>me</i>		MB45A-51-3J8		\$ 22.00
21	GASKET RHS, BOOTLID <i>me</i>	1	MB45A-51-3H8		\$ 22.00
22	GASKET LHS, TAILLAMP <i>me</i>	1	MBHN1-51-163		\$ 22.00
23	GASKET RHS, TAILLAMP <i>me</i>	1	MBHN1-51-153		\$ 22.00
TOTAL PARTS					\$ 2,558.80
LESS 10%					\$ 255.88
TOTAL PARTS COST					\$ 2,302.92
Labour Description					

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, TO REPAIR BOOTLID, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 2,640.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	X NETT	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X NETT	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING. <i>Cinemat</i>	NETT 150	\$ 250.00
9	MZ-BR-SUNDRI	SUNDRIES.	NETT 10	\$ 100.00

TOTAL LABOUR	\$ -	\$ 7,020.00
TOTAL PARTS	\$ -	\$ 2,302.92
TOTAL	\$ -	\$ 9,322.92
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS

Authorised Signature

Rasul
Hp 90010068
4 days
16/10/19 @ 1455
Ready before paint



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

NTUC INCOME INSURANCE		NAME : Mdm Ong Gek Lian Deborah		WIP : 38264	
1 MARITIME SQUARE		ADDRESS : 133 Thomson Ridge		EXCESS :	
#10-01 HARBOURFRONT CENTRE		Singapore 574715		DATE: 8-Oct-19	
SINGAPORE 099253		TEL : 96357249			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SMG5276Y	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BN22A8K0266310	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	24-Dec-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	\$ 1,128.60	\$ 1,128.60
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
3	TOWING COVER LHS	1	MBHN1-50-EL1 BB	\$ 16.50	\$ 16.50
4	TOWING COVER RHS	1	MBHN1-50-EK1 BB	\$ 17.10	\$ 17.10
5	REFLECTOR LHS	1	MD350-51-5L0E		\$ 53.00
6	RETAINER CENTER, SENSOR	2	MKD47-67-UC5A53		\$ 36.40
7	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 53		\$ 361.80
8	TAPE PROTECTOR, SENSOR	3	MBCKA-50-EM1	\$ 14.10	\$ 14.10
9	REAR REINFORCEMENT	1	MB45A-50-260	\$ 564.20	\$ 564.20
10	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
11	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
12	RIVET, REAR BUMPER	4	MB8M4-50-355	\$ 18.00	\$ 18.00
13	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 12.00	\$ 12.00
14	CLIP, REAR BUMPER	2	MGJ21-50-049	\$ 6.80	\$ 6.80
15	ORNAMENT, MAZDA	1	MBHN1-51-721	\$ 56.10	\$ 56.10
16	MASCOT, REAR	1	MBHN1-51-730	\$ 78.20	\$ 78.20
17	ORNAMENT, SKYACTIVE	1	MBHN1-51-771	\$ 66.80	\$ 66.80
18	FASTENER, BOOTLID	2	MEG21-51-146		\$ 12.40
19	GROMMET, BOOTLID	2	MGA7B-51-146		\$ 6.60
20	GASKET LHS, BOOTLID	1	MB45A-51-3J8	\$ 22.00	\$ 22.00
21	GASKET RHS, BOOTLID	1	MB45A-51-3H8	\$ 22.00	\$ 22.00
22	GASKET LHS, TAILLAMP	1	MBHN1-51-163	\$ 22.00	\$ 22.00
23	GASKET RHS, TAILLAMP	1	MBHN1-51-153	\$ 22.00	\$ 22.00
TOTAL PARTS				\$ 2,083.20	\$ 2,558.80
LESS 10%				\$ 208.32	\$ 255.88
TOTAL PARTS COST				\$ 1,874.88	\$ 2,302.92
Labour Description					

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR BOOTLID, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 990.00	\$ 2,640.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	\$ 1,260.00	\$ 2,520.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ -	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ -	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING.	\$ 150.00	\$ 250.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 10.00	\$ 100.00
			TOTAL LABOUR	\$ 2,740.00 \$ 7,020.00
			TOTAL PARTS	\$ 1,874.88 \$ 2,302.92
			TOTAL	\$ 4,614.88 \$ 9,322.92
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 4,614.88
			GST 7%	\$ 323.04 \$ -
			GRAND TOTAL	\$ 4,937.92 \$ -

NUMBER OF DAYS: 4 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19018272/R1qd3n2
73 BRAS BASAH ROAD Date: 29-11-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: SERENE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 3191A	Veh. Inspected	SMG 5276Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1065612-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	16/10/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 SEDAN 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6BN22A8K0266310	Colour	BROWN
Odometer	9516 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/10/2019	Inspect Date / Time	16/10/2019 (03:02 PM)
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 5276Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,128.60	1,128.60
1	BRACKET CENTER	SERVICEABLE	5.40	-
1	TOWING COVER LHS	MISSING	16.50	16.50
1	TOWING COVER RHS	MISSING	17.10	17.10
1	REFLECTOR LHS	SERVICEABLE	53.00	-
2	RETAINER CENTER,SENSOR	SERVICEABLE	36.40	-
2	SENSOR CENTER,ULTRASONIC	SERVICEABLE	361.80	-
3	TAPE PROTECTOR,SENSOR	NECESSARY	14.10	14.10
1	REAR REINFORCEMENT	BENT	564.20	564.20
2	GROMMET,REAR BUMPER	NECESSARY	6.00	6.00
4	GROMMET,REAR BUMPER	NECESSARY	10.80	10.80
4	RIVET,REAR BUMPER	NECESSARY	18.00	18.00
4	FASTENER,REAR BUMPER	NECESSARY	12.00	12.00
2	CLIP,REAR BUMPER	NECESSARY	6.80	6.80
1	ORNAMENT,MAZDA	NECESSARY	56.10	56.10
1	MASCOT,REAR	NECESSARY	78.20	78.20
1	ORNAMENT,SKYACTIVE	NECESSARY	66.80	66.80
2	FASTENER,BOOTLID	SERVICEABLE	12.40	-
2	GROMMET,BOOTLID	SERVICEABLE	6.60	-
1	GASKET LHS,BOOTLID	NECESSARY	22.00	22.00
1	GASKET RHS,BOOTLID	NECESSARY	22.00	22.00
1	GASKET LHS,TAILLAMP	NECESSARY	22.00	22.00
1	GASKET RHS,TAILLAMP	NECESSARY	22.00	22.00
	LESS 10% DISCOUNT		-255.88	-208.32
			2,302.92	1,874.88
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	10.00
			100.00	10.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR		2,640.00	990.00
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, TO REPAIR BOOTLID, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.		2,520.00	1,260.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	NOT NECESSARY	330.00	-
	TO TRANSFER REVERSE SENSORS.	NOT NECESSARY	330.00	-
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	250.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		350.00	180.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		250.00	150.00
	TO SUPPLY BRILA PREMIUM COATING.		6,920.00	2,730.00
			9,322.92	4,614.88
	GRAND TOTAL			
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			4,614.88

Report Ref No. CS/INC19018272/R1qd3n2

MRB

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.