



23/10 2.00-2.30pm

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail THIRD PARTY CLAIM <i>LPK</i> <i>Nivitha</i> <i>68411972</i>	Account No S1000020 / TPCLAIM	Customer Detail M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No 0	
	Document Date 15/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	ACR50R	03/03/2017	SLL6447A	0	49402 :5DS/SLL6447A/11101!

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>Lompac Inc</i> T/P VEH. : YL9292E ACC DATE : 11.10.19 BY :				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
5	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				360.00
6	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR.				360.00
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				450.00
8	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.				350.00
9	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary Parts Labour Materials Lubrication/Fluid Others .	Total
			Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4039830

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 15/10/2019
TIME 14:26

4039830

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No 0	
	Document Date 15/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-LAMP PANEL, TAIL-GATE AND AFFECTED PORTION OF CAR.				2880 3608.00
11	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1770 3540.00
12	1	T52159-28959 COVER, RR BUMPER <i>de</i>	1.00	596.90		596.90
13	2	T52156-28050 L/R SIDE BPR SUPPORT, <i>ne</i>	1.00	57.70		57.70
14	3	T52156-28060 L/RR BUMPER SUPPORT, <i>ne</i>	1.00	40.40		40.40
15	4	S52161-0K040 PIECE, RR BUMPER <i>ne</i>	4.00	4.10		16.40
16	5	T68105-28680 GLASS SUB-ASSY, BACK <i>ne (photo)</i>	1.00	1265.90		1265.90
17	6	T67005-28D10 BACK DOOR <i>bt</i>	1.00	1753.60		1753.60
18	7	T76801-28460 GARNISH SUB-ASSY, <i>? ca</i>	1.00	336.80		336.80
19	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>ne</i>	2.00	108.00		216.00
20	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>ne</i>	1.00	200.00		200.00
21	0	T04562-12010 W/SCREEN GLS DAM KIT, <i>ne</i>	1.00	121.00		121.00
22	1	T58307-28110 REAR LOWER FLR PANEL, <i>bt - photo</i>	1.00	755.40		755.40
23	2	T76802-28070 GARNISH SUB-ASSY <i>?</i>	1.00	229.40		229.40
24	3	T81591-28300 LENS & BODY, RR <i>?</i>	1.00	784.90		784.90
25	4	T90975-02064 EMBLEM, SYMBOL <i>ne</i>	1.00	72.20		72.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4039831

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 15/10/2019
TIME 14:26

4039831

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Beni Warehousing Pte Ltd
	Document No 0	29 Tuas Avenue 11
	Document Date 15/10/2019	Singapore 639089
		Home: 68724358

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	03/03/2017	SLL6447A	0	49402	5DS/SLL6447A/11101!
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	5	T75441-28730 REAR "TOYOTA" EMBLEM, <i>new</i>	1.00	44.10		44.10
27	6	T75441-28720 "PREVIA" EMBLEM, <i>new</i>	1.00	57.20		57.20
<div><p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer Signature: Date:</p></div> <div><p><i>Resur</i> <i>Hp 20010088</i> <i>8 days</i> <i>23/10/19 @ 1420</i> <i>Resur before paint</i></p></div>						
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,547.90 Labour 9,150.00 Materials 350.00 Lubrication/Fluid 0.00 Others 0.00	16,047.90
			GST 7.00% 1,123.35
			Less 0.00
			Amount Due 17,171.25

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLL6447A

CUSTOMER

DATE 15/10/2019
TIME 14:26SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

4039832

4039832