

JALE



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Attn: Rasul

8 days Final Bill

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
Longpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLPI1 Document No 38044636 Document Date 16/12/2019	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	03/03/2017	SLL6447A	117850	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	11/12/2019	9.37	11/12/2019	9.3

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : LOMPAC INS. T/P VEH. : YL9292E ACC DATE : 11.10.19 BY : RASUL (LKK)	*			50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)	*			200.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.	*			180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.	*			180.00
5	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.	*			360.00
6	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR.	*			360.00
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.	*			450.00
8	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM. PO 25227	M30			350.00
9	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
		Amount Due	

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462 4136195

TO SECURITY GUARD

4136195

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/12/2019
TIME 15:34

VEHICLE NO

SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

TAX INVOICE

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/s Beni Warehousing Pte Ltd 29 Tuas Avenue 11 Singapore 639089 Home: 68724358
	Document No 38044636	
	Document Date 16/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GFXSK	E1	03/03/2017	SLL6447A	117850	49402	5DS/SLL6447A/11101
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M307146485	2AZ4A74877	60	Francis Cher T S	11/12/2019	9.37	11/12/2019	9.37

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-LAMP PANEL, TAIL-GATE AND AFFECTED PORTION OF CAR.	*			2880.00
11	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1770.00
12	1	T76801-28460 GARNISH SUB-ASSY,	1.00	336.80		336.80
13	2	T21000-22 SIKA 210002-2 G+P-207 ADHESIVE, PRIN	1.00	200.00		200.00
14	3	T52159-28959 COVER, RR BUMPER AERAS	1.00	596.90		596.90
15	4	T52156-28050 L/REAR BUMPER SUPPORT,	1.00	57.70		57.70
16	5	T52156-28060 L/REAR SIDE BUMPER SUPPORT,	1.00	40.40		40.40
17	6	S52161-OK040 PIECE, RR BUMPER	4.00	4.10		16.40
18	7	T67005-28D10 PANEL ASSY, BACK DOOR	1.00	1753.60		1753.60
19	8	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00
20	9	T04562-12010 DAM KIT, WINDOW GLASS	1.00	121.00		121.00
21	0	T58307-28110 PANEL, LAMP LOWER	1.00	755.40		755.40
22	1	T90975-02064 EMBLEM, SYMBOL	1.00	72.20		72.20
23	2	T75441-28730 PLATE, LUGGAGE	1.00	44.10		44.10
24	3	T68105-28680 GLASS, BACK DOOR	1.00	1265.90		1265.90
25	4	T75441-28720 PLATE, LUGGAGE	1.00	57.20		57.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 5,533.60 Labour 6,610.00 Materials 350.00 Lubrication/Fluid 0.00 Others 0.00	12,493.60 GST 7.00% 874.5 Less 0.00 Amount Due 13,368.10

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/12/2019
TIME 15:34

VEHICLE NO SLL6447A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto