

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Kenneth
17/10/19
1309PM

S 9m023TKMC/RA

16,OCT 2019

AXA Insurance Pte Ltd
143 Cecil Street #01-01 GB Building
S 069542

Not Authorized
L1 Lp 87
Phanny After Paint
3 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SCE8063D
Accident involving vehicle no: SKS6809P/SCE8063D
DOA: 14/10/2019 AT Along Thomson Road

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SKS6809P

To supply--

Description	Qty	Amount
Front bumper	1	Ben 458.10 ✓
Bumper retainer	1	Pr 82.33 ✓
Bumper clip		Ma 42.00 ✓
Headlamp	1	mg 2,804.00 ✓
Foglamp cover	1	Pr 112.90 X
Foglamp	1	Pr 248.20 X
Fender,Rh	1	Pr 761.45 ✓
Fender cowl	1	Pr 163.40 X
Cowling clip		Ma 38.00 X
Parts		4,710.38
Parts less 25%		1,177.59
		3,532.79

To remove damaged parts and attachments.

Repair/reshape dented areas

Replace/align all parts into position.

To spray paint

800.00

600.00

4,932.79

4000
4000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before other spray painting
- To display damaged part(s) waiting resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal allocation(s) is allowed
- Supplier (s) must be insured and is subject to approval from insurance company

Acknowledged by Repairer
Signature
Date