

ASS. REC. BY

REF: CS/CT 19018398 / Rinfz Special Instructions:

Surveyor: RASHI

ASSIGNMENT (Office)

From (Person): Ong chin kiat

CTL

Date/Time: 18-10-19 9:55 a.m

Estimated Cost

Bill to:

OD(TP) WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No: GBB 1037D

Insured: PC 8348P

nt Workshop m/s **MORA Automotive**

Tel: 6262 3317

of 15 Fan yu Road

Policy No: DMBSA 30708019000

Claim No: SNM190704917C02

Sum Insured:

Experiments

Make of Veh.

D.O.A. 14.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endocrinology

Date/Time: 18.10.19 10:24 a.m.

Person Contacted: Ah kit

Vehicle IN/OUT

[illegible]

ASSIGNMENT

COXPIRY: 2023/July

From:

Date:

29/10/2019

Veh No:

G8B 1037D

Yr Regn:

2008 / July

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Com / Taxi / Prime Mover /

Truck / Trailer or

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

G8B 1037D

Make:

MITSUBISHI FB 70

C.C.

at Workshop n/s

MOVA Automotive

Colour:

WHITE

A/C:

Insured / Std / NI / NA

of

15 Fan Young Road

Sp Reading

818569

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

FB 70BBA 6498

Claims No:

Gen. Cond: Good (Fair) / Poor / Burnt

Sum Insured:

Excess:

Steering: (norder) / Jammed / Leaked / Burnt or

(Client's Record)


Brake: (norder) / Jammed / Leaked / Burnt or

Make of Veh:

11am (nowalking)

Modi: (Nil) / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

17K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F:

195 R15C

R:

21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / (YOKO) or

Front

Rear

R/Bal:

7

mm

R/Bal:

7/7

mm

L/Bal:

7

mm

L/Bal:

7/7

mm

D.O.A:

14/10/19

D.O.I:

29/10/19

Survey held at

MOVA (FY)

Des. of Damages: Frt (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11

repair / mt 5K

Rasul continued to 25000; 8 days with Billy. (Red 3128.17, 382)

RECEIVED 13 JAN 2020

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

8

1)



: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S = RS 139

Fishes:

Others:

Report Format:

TP

Error:

0m / 1.1: 5000

(1/1)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019		18 Oct 2019 09:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YYC TRANSPORT PTE LTD, Co. Reg. No.: 200917054K		
Main Claimant:	SIAC PTE LTD, Co. Reg. No.: 199100842R		
Vehicle Reg. No.:	GB81037D	Date of Loss:	14/10/2019 21:00 - :59 [135 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204917C02	Policy/Cover Note No.:	DMB15N30708019000
Vehicle Reg. No. (Insured):	PC8348P	Policy No. (Claimant):	5110234579
		Excess:	S\$1,000.00
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2019]		
Driver/Custodian (Insured):	ZHANG QIANG (35 / Male), NRIC: G2594811X Email:		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	842R

Vehicle Details

Vehicle No.:	GBB1037D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FB70BB15RDEA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4M42A57918
Chassis No.:	FB70BBA10498
Maximum Power Output:	-
Open Market Value:	\$23,402.00
Original Registration Date:	02 Jul 2008
First Registration Date:	02 Jul 2008
Transfer Count:	0
Actual ARF Paid:	\$1,171.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$11,949.00
Total Rebate Amount:	\$11,949.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 15 Oct 2019

OK

VUEBET STATUS - OK

17,000
11,949
5,051

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2019 09:58
Date Of Accident	14/10/2019 21:00
Exact Location Of Accident	WOODLANDS AVE 2 INTO SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB1037D
Insured/Policyholder	
Name Of Registered Owner	SIAC PTE LTD
Co Reg No	199100842R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62622977

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FB70BB1SRDEA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110234579
Cover Note Number	

Driver

Name of Driver	HASAN ANAMUL
Passport No/FIN	G2318480Q
Date Of Birth	20/10/1992
Occupation	OUTDOOR
Date Of Driving Pass	27/10/2017
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98533470
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	17 FAN YOONG ROAD
Postcode	629794
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC83489
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	ZHANG QIANG
NRIC/Passport Number	G2594811X
Contact Number	91308911
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Amal

Driver's Signature
(if driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Natrah
15/10/2019

Sketch Plan Pg. 2

SKETCH PLAN

WOODLANDS AVE 2 INTO SLE

A= GBB1037D

B= PC 8348P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: GBB1037D	ACCIDENT DATE & TIME: 14/10/2019 @ 2100hrs
CONTACT NUMBER: 98533490	E-MAIL ADDRESS:
LOCATION: Woodlands Ave 2 - Attending into SLE	
I was travelling in Woodlands Ave 2 attending into SLE. When suddenly Veh B came from behind and hit onto the rear portion of my vehicle. That's all.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
☐ Claim Own Policy	☒ Claim Third Party
☐ Claim OD/TP at other workshop	☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No:

Rasul (LKKAuto)

From: Billy <billy@nova.com.sg>
Sent: Monday, 11 November, 2019 9:15 AM
To: Rasul (LKKAuto)
Cc: 'Jia Yu'
Subject: RE: GBB 1037D DOA : 14/10/19

Hi Sir,

Confirm Limit Lump Sum \$5000.00, Thank you.

Best Regard's
Billy Liaw

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: 11 November 2019 09:10
To: Billy
Subject: RE: GBB 1037D DOA : 14/10/19

Hi Billy,

Repair limit as we confirm is 5K Only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Billy [mailto:billy@nova.com.sg]
Sent: Friday, 1 November, 2019 8:39 AM
To: Rasul (LKKAuto)
Subject: RE: GBB 1037D DOA : 14/10/19

Hi Sir,

Noted Thank You.

Best Regard's
Billy Liaw

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: 31 October 2019 09:17
To: Billy
Subject: GBB 1037D DOA : 14/10/19

Hi Billy,

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5801
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/08/09/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0068664-2

Estimate

17/10/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- GBB1037D

Veh Model :- MITSUBISHI FB70BB1SRDEA

Estimate# :- CK419845

Claim # :-

ACC. Date :- 14/10/19

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE <i>bt</i>	1	PC 2,641.80	2,641.80 ✓
2.	TAILGATE STICKER - MITSUBISHI <i>re</i>	1	PC 139.70	139.70 ✓
3.	TAILGATE LOCK LATCH LH <i>bt</i>	1	PC 79.85	79.85 ✓
4.	TAILGATE HINGE LH <i>bt</i>	1	PC 112.38	112.38 ✓
5.	TAIL LAMP ASSY LH <i>Cr</i>	1	PC 232.10	232.10 ✓
6.	REAR CHASSIS MEMBER RH (REPAIR)	1	PC	
7.	REAR CROSS MEMBER (REPAIR)	1	PC	
8.	REAR NUMBER PLATE BRACKET <i>bt</i>	1	SET 58.40	58.40 ✓
LIST TOTAL S\$				3,264.23
25% DISCOUNT S\$				-816.06
				<u>1) 2,448.17</u>
SPECIAL NET ITEMS :				
1.	TAILGATE STICKER - 60KM/H <i>re</i>	1	PC 10.00	10.00 ✓
2.	TAILGATE STICKER - 13 PAX <i>re</i>	1	PC 10.00	10.00 ✓
3.	REAR STEP PANEL <i>repair</i>	1	PC 300.00	300.00 X
4.	REAR WOODEN PLATFORM <i>price</i>	1	SET 3,200.00	3,200.00 ✓
5.	REAR NUMBER PLATE <i>bt</i>	1	PC 20.00	20.00 ✓
				PC
				PC
				PC
				PC
				PC
SPECIAL NET TOTAL S\$				<u>2) 3,540.00</u>
LABOUR :				
TO KNOCK AND STRAIGHTEN REAR END PANEL, REAR CHASSIS MEMBERS, REAR CROSS MEMBER. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				400 500.00
SPRAY PAINT TAILGATE, REAR END PANEL, REAR STEP PANEL				400 500.00
REMOVE AND REFIX REAR WOODEN PLATFORM				380 480.00
TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBERS & REALIGN				450 600.00
RUST PROOF AFFECTED AREAS				40 50.00
LABOUR TOTAL S\$				<u>3) 1670.00 2,140.00</u>

Main Office:

Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/104
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088854-2

Estimate

17/10/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 136440
Veh # :- GBB1037D
Veh Model :- MITSUBISHI FB70BB1SRDEA
Estimate# :- CK419845
Claim # :-
ACC. Date :- 14/10/19
Terms :- C.O.D Days
Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

8,128.17

GST @ 7 %

568.97

AMOUNT DUE S\$

8,697.14

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PARTS 2448.17
2) S/NBT 3540.00
3) LABOUR 1670.00
7658.17
- 1531.63 less 20%
6126.54.

Lump sum \$ 6100.00

Please advice.

Thank You

Buat work.

Rajan
Hp 90010068

8 days

4/5

29/10/19 @ 1100

Returning after repair

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

17/10/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- GBB1037D

Veh Model :- MITSUBISHI FB70BB1SRDEA

Estimate# :- CK419845

Claim # :-

ACC. Date :- 14/10/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE <i>bt</i>	1 PC	2,641.80	2,641.80
2.	TAILGATE STICKER - MITSUBISHI <i>ner</i>	1 PC	139.70	139.70
3.	TAILGATE LOCK LATCH LH <i>bt</i>	1 PC	79.85	79.85
4.	TAILGATE HINGE LH <i>bt</i>	1 PC	112.38	112.38
5.	TAIL LAMP ASSY LH <i>Crm</i>	1 PC	232.10	232.10
6.	REAR CHASSIS MEMBER RH (REPAIR) <i>R</i>	1 PC		
7.	REAR CROSS MEMBER (REPAIR) <i>R</i>	1 PC		
8.	REAR NUMBER PLATE BRACKET <i>bt</i>	1 SET	58.40	58.40
LIST TOTAL S\$				3,264.23
25% DISCOUNT S\$				-816.06
				2,448.17
SPECIAL NET ITEMS :				
1.	TAILGATE STICKER - 60KM/H <i>na</i>	1 PC	10.00	10.00
2.	TAILGATE STICKER - 13 PAX <i>na</i>	1 PC	10.00	10.00
3.	REAR STEP PANEL <i>repair</i>	1 PC	300.00	300.00 X
4.	REAR WOODEN PLATFORM <i>? price</i>	1 SET	3,200.00	3,200.00
5.	REAR NUMBER PLATE <i>bt</i>	1 PC	20.00	20.00
SPECIAL NET TOTAL S\$				3,540.00
LABOUR :				
TO KNOCK AND STRAIGHTEN REAR END PANEL, REAR CHASSIS MEMBERS, REAR CROSS MEMBER. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				400 500.00
SPRAY PAINT TAILGATE, REAR END PANEL, REAR STEP PANEL				400 500.00
REMOVE AND REFIX REAR WOODEN PLATFORM				380 480.00
TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBERS & REALIGN				450 600.00
RUST PROOF AFFECTED AREAS				40 60.00
LABOUR TOTAL S\$				2,140.00

Estimate

17/10/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 136440
Veh # :- GBB1037D
Veh Model :- MITSUBISHI FB70BB1SRDEA
Estimate# :- CK419845
Claim # :-
ACC. Date :- 14/10/19
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088854-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

8,128.17

GST @ 7 %

568.97

AMOUNT DUE S\$

8,697.14

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

UAG Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairer
Signature
Date

Rajan
Hp 90010068
8 days
4s
29/10/19 @1100
Returning after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019		18 Oct 2019 09:55 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YYC TRANSPORT PTE LTD, Co. Reg. No.: 200917054K								
Main Claimant:	SIAC PTE LTD, Co. Reg. No.: 199100842R								
Vehicle Reg. No.:	GBB1037D	Date of Loss:	14/10/2019 21:00 - :59 [135 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204917C02	Policy/Cover Note No.:	DMB1SN30708019000						
Vehicle Reg. No. (Insured):	PC8348P	Policy No. (Claimant):	5110234579						
		Excess:	S\$1,000.00						
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6399 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/10/2019]								
Driver/Custodian (Insured):	ZHANG QIANG (35 / Male), NRIC: G2594811X Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (13/12/2019): Alert - Adj Mandate Approved (S\$0.00) - GBB1037D - Claim Handler: Ong Chin Kiat									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB1037D (SNM19D204917C02)
[PC8348P]
TP
SIAC PTE LTD
Oct 14 2019 9:00PM
[YYC TRANSPORT PTE LTD]
Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/01/20 14:08	General View	 Load JPG	☒
2	13/01/20 14:08	General View	 Load JPG	☒
3	13/01/20 14:08	General View	 Load JPG	☒
4	13/01/20 14:08	General View	 Load JPG	☒
5	13/01/20 14:08	General View	 Load JPG	☒
6	13/01/20 14:08	General View	 Load JPG	☒
7	13/01/20 14:08	General View	 Load JPG	☒
8	13/01/20 14:08	General View	 Load JPG	☒
9	13/01/20 14:08	General View	 Load JPG	☒
10	13/01/20 14:08	General View	 Load JPG	☒
11	13/01/20 14:08	General View	 Load JPG	☒
12	13/01/20 14:08	General View	 Load JPG	☒
13	13/01/20 14:08	General View	 Load JPG	☒
14	13/01/20 14:08	General View	 Load JPG	☒
15	13/01/20 14:08	General View	 Load JPG	☒
16	13/01/20 14:08	General View	 Load JPG	☒
17	13/01/20 14:08	General View	 Load JPG	☒
18	13/01/20 14:08	General View	 Load JPG	☒
19	13/01/20 14:08	General View	 Load JPG	☒
20	13/01/20 14:08	General View	 Load JPG	☒
21	13/01/20 14:08	General View	 Load JPG	☒
22	13/01/20 14:08	General View	 Load JPG	☒
23	13/01/20 14:08	General View	 Load JPG	☒
24	13/01/20 14:08	General View	 Load JPG	☒
25	13/01/20 14:08	General View	 Load JPG	☒
26	13/01/20 14:08	General View	 Load JPG	☒
27	13/01/20 14:08	General View	 Load JPG	☒
28	13/01/20 14:08	General View	 Load JPG	☒
29	13/01/20 14:08	General View	 Load JPG	☒
30	13/01/20 14:08	General View	 Load JPG	☒
31	13/01/20 14:08	General View	 Load JPG	☒
32	13/01/20 14:08	General View	 Load JPG	☒
33	13/01/20 14:08	General View	 Load JPG	☒
34	13/01/20 14:08	General View	 Load JPG	☒
35	13/01/20 14:08	General View	 Load JPG	☒
36	13/01/20 14:08	General View	 Load JPG	☒
37	13/01/20 14:08	General View	 Load JPG	☒
38	13/01/20 14:08	General View	 Load JPG	☒
39	13/01/20 14:08	General View	 Load JPG	☒
40	13/01/20 14:08	General View	 Load JPG	☒
41	13/01/20 14:08	General View	 Load JPG	☒
42	13/01/20 14:08	General View	 Load JPG	☒
43	13/01/20 14:08	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	13/01/20 14:08	General View	 Load JPG	☒
45	13/01/20 14:08	General View	 Load JPG	☒
46	13/01/20 14:08	General View	 Load JPG	☒
47	13/01/20 14:08	General View	 Load JPG	☒
48	13/01/20 14:08	General View	 Load JPG	☒
49	13/01/20 14:08	General View	 Load JPG	☒
50	13/01/20 14:13	After Repair Photo	 Load JPG	☒
51	13/01/20 14:13	After Repair Photo	 Load JPG	☒
52	13/01/20 14:13	After Repair Photo	 Load JPG	☒
53	13/01/20 14:13	After Repair Photo	 Load JPG	☒
54	13/01/20 14:13	After Repair Photo	 Load JPG	☒
55	13/01/20 14:13	After Repair Photo	 Load JPG	☒
56	13/01/20 14:13	After Repair Photo	 Load JPG	☒
57	13/01/20 14:13	After Repair Photo	 Load JPG	☒
58	13/01/20 14:13	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/10/19 09:54	Estimate	 Load PDF	
2	18/10/19 09:54	INSO PCB348P GIA REPORT	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	06/12/19 18:58	Accident Statement	 Load HTM	
2	06/12/19 18:59	Accident Statement	 Load HTM	
3	06/12/19 19:00	Accident Statement	 Load HTM	
4	06/12/19 19:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	15/10/19 12:26	Accident Photo	 Load JPG	☒
2	15/10/19 12:26	Accident Photo	 Load JPG	☒
3	15/10/19 12:26	Accident Photo	 Load JPG	☒
4	15/10/19 12:26	Accident Photo	 Load JPG	☒
5	15/10/19 12:26	Accident Photo	 Load JPG	☒
6	15/10/19 12:26	Accident Photo	 Load JPG	☒
7	15/10/19 12:26	Accident Photo	 Load JPG	☒
8	15/10/19 12:26	Accident Photo	 Load JPG	☒
9	15/10/19 12:26	Driving License	 Load JPG	☒
10	15/10/19 12:26	Accident Photo	 Load JPG	☒
11	15/10/19 12:26	Accident Photo	 Load JPG	☒
12	15/10/19 12:26	Accident Photo	 Load JPG	☒
13	15/10/19 12:26	Accident Photo	 Load JPG	☒
14	15/10/19 12:26	Accident Photo	 Load JPG	☒
15	15/10/19 12:26	Accident Photo	 Load JPG	☒
16	15/10/19 12:26	Accident Photo	 Load JPG	☒
17	15/10/19 12:26	Accident Photo	 Load JPG	☒
18	15/10/19 12:26	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	15/10/19 12:20	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19018398/R1YF3Q2

Date: 14/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30708019000
Claimant Vehicle No :	GBB1037D	Insured Vehicle No :	PC8348P
Date of Loss:	14/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D204917C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB1037D	Engine No:	4M42A57918
Make & Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Chassis No:	FB70BBA10498
Reg. Date:	02/07/2008 (Man. Year: 2008)	Odometer:	818569 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C (D)
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Yokohama 0 mm	Rear Right Side:	Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,988.17	5,688.17	300.00	5.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,670.00	470.00	21.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,128.17	7,358.17	770.00	9.47
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	8,128.17	5,000.00	3,128.17	38.49
+ GST 7.00/7.00% (S\$)	568.97	350.00	218.97	38.49
Nett Amount (S\$)	8,697.14	5,350.00	3,347.14	38.49

INSPECTION

Date of Assignment:	18/10/2019	
Date Inspected:	29/10/2019 Inspected At:	Mova Automotive Pte Ltd (FAN YOUNG BRANCH) 15 Fan Young Road, CNG Singapore Centre Singapore 629792
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 14 Jan 2020)
Parts:	N/A	MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB1037D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,641.80 FL	*2,641.80 FL
2	1		*TAILGATE STICKER-MITSUBISHI	Necessary	139.70 FL	*139.70 FL
3	1		*TAILGATE LOCK LATCH -LH	Bent	79.85 FL	*79.85 FL
4	1		*TAILGATE HINGE LH	Bent	112.38 FL	*112.38 FL
5	1		*TAIL LAMP ASSY LH	Cracked	232.10 FL	*232.10 FL
6	1		*REAR CHASSIS MEMEBER RH (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR CROSS MEMBER (NPA)	Repair	0.00 FL	*- FL
8	1		*SET REAR NUMBER PLATE BRACKET	Bent	58.40 FL	*58.40 FL
9	1		*TAILGATE STICKER -60KM/H	Necessary	10.00 FS	*10.00 FS
10	1		*TAILGATE STICKER -13 PAX	Necessary	10.00 FS	*10.00 FS
11	1		*REAR STEP PANEL	Repair	300.00 FS	*- FS
12	1		*SET REAR WOODEN PLATFORM	Cracked	3,200.00 FS	*3,200.00 FS
13	1		*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,804.23	6,504.23
- List Item Discount on L Items 25.00/25.00% (S\$)	816.06	816.06
Total Parts (S\$)	5,988.17	5,688.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK AND STRAIGHTEN REAR END PANEL ,REAR CHASSIS MEMBERS ,REAR CROSS MEMBER .REMOVE AND REPLACE ACCIDENT DAMAGED PARTS .REALIGN ALL CONNECTION	New	500.00	400.00
2	SPRAY PAINT TAILGATE ,REAR END PANEL ,REAR STEP PANEL	New	500.00	400.00
3	REMOVE AND REFIX REAR WOODEN PLATFORM	New	480.00	380.00
4	TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBERS & REALIGN	New	600.00	450.00
5	RUST PROOF AFFECTED AREAS	New	60.00	40.00
Gross Labour Cost (\$\$)			2,140.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >