

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53134**
Date Estimated : **21/11/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Ng Song Herng
38 Jalan Dermawan

Singapore 668983

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ3128J	WBAJG12040EE74913	29/03/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak.	853.00		853.00
--	--------	--	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# BLIND RIVET	0.95	4.00		3.80 <i>net</i>
# BLIND RIVET	0.95	2.00		1.90 <i>net</i>
# FILLISTER HEAD SCREW TS5X20	0.95	10.00		9.50 <i>net</i>
# EXPANDING NUT	0.92	10.00		9.21 <i>net</i>
# BONNET	1,654.00	1.00		1,654.00 <i>bt</i>
# CROSSLINK FRT	124.40	1.00		124.40 <i>bt</i>
# LH OPEN GRID (X LINE PDC)	95.05	1.00		95.05 <i>dis</i>
# EMBLEM GROMMET	0.85	2.00		1.70 <i>net</i>
# LH BOTTOM ADAPTER	83.50	1.00		83.50 <i>Rept</i>
# UNDERBONNET SCREEN	199.25	1.00		199.25 <i>Rept</i>
# EXPANDING RIVET BLACK	1.40	10.00		14.00 <i>net</i>
# CONDENSER AIR CONDITIONING WITH DRI	977.00	1.00		977.00 <i>Rept</i>
# ULTRASONIC SENSOR BLACK	248.70	1.00		248.70 <i>net</i>

SUPPLEMENTARY ITEMS

Total Labour :	853.00
Total Parts :	3,422.01
Total Labour & Parts :	4,275.01