

INS. CASE OWNER:

CC6 /AIG1901

8420, E Kt.

LKK:  
IDAC:

Surveyor:

STEVE

DOI:

12/10/19

Date / Time:

12/10/19

Registered in Merimen:

12/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ 6832U

Claim No.:

Name of Insured:

LEE HAN PM Anthony

Policy No.:

12001V632E

Insured Tel No.:

HP:

Make / Model:

MITSUBISHI

Excess Sec II :S\$

D.O.A.:

12/10/19

Place of Accident:

KPE TMS Lmy

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO )

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Gmj. 5006U

SLQ 6832U

SJM 2507Y



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

14/12/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

4/5 S\$ 1,350

( 3 days)

Reduction:

41 %

Email

Call

FINAL SETTLEMENT

Date/Time:

27/12/19

Confirm with:

Winnie

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

26

Repair Cost:

CAL(IST)

S\$ 1,444.50

Loss of Rental (LOR):

S\$ 32

( 3 days)

x \$100

Loss of Use (LOU):

S\$ -

(\$ - x - days)

Loss of Income (LOI):

S\$ -

(\$ - x - days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

(Tick only one)

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 1,767.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1,767.50

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

1) Claim status:

Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

COPY SENT  
10/1/2020

APP. REC. BY

Steve

REF: AIG

## ASSIGNMENT

From:

Date

17.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 7507Y

at Workshop m/s: Tan Lim

at 1 Defu Lane 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJM 7507Y

Yr Regn:

15/1/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Impreza

c.c 1498

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

130080

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JFI 6E 3K SS96 003694

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

41

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/10/19

D.O.I.

17/10/19

Survey held at

Tan Lim

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-71K

CLIS \$1250 (Pd \$956 / 411.)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Probe

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Rep. Format:

Lump Sum / B.I. /

Phoebe



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No.: M2-8922054-2

AIGAsia Insured's Veh No: SLQ6832U

Date of Accident: 12 October 2019

Steve (LKK)

mt AL

17/10/19

83228813

3 chg

L/S

Mr Quek Chee Wei

Date: 14 October 2019

Ry AL SM

Estimate To Repair SJM7507Y - SUBARU IMPREZA 4DR 1.5R AWD 4AT ABS A

Chassis No: JF1GE3KS59G003694

SlNo	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper / 00	\$ 588.80
02	1 pc	rear reinforcement / 00	\$ 208.80
03	2 ps	rear bumper reflector @ \$21.60 x NA	\$ 43.20
04	1 pc	rear bumper tow cover / CR4	\$ 16.00
05	16 ps	rear bumper fastener clips @ \$2.40 / 00	\$ 38.40
		Less 20 %	\$ 895.00
			\$ 179.00
			\$ 716.00
		<u>SPECIAL NETT ITEMS</u>	
06	1 set	rear bumper parking sensor / SHD	\$ 450.00
			\$ 450.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00
02		To check electrical lighting concerned.	\$ 60.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,140.00
		Total	\$ 2,306.00

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1- 777.94

N- 290

L- 770

1657.94

L/S- 1325.63

= 1350



陳林摩呀私人有限公司  
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLQ6832U

Date of Accident : 12 October 2019

1 Defu Lane 6 Singapore 539365

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Quek Chee Wei

Date : 14 October 2019

Estimate To Repair SJM7507Y - SUBARU IMPREZA 4DR 1.5R AWD 4AT ABS A

Chassis No : JF1GE3KS59G003694

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper ✓ DD	\$ 588.60
02	1 pc	rear reinforcement ?	\$ 208.80
03	2 ps	rear bumper reflector @ \$21.60 X	\$ 43.20
04	1 pc	rear bumper tow cover ✓ CR4	\$ 16.00
05	16 ps 1 set	rear bumper fastener clips @ \$2.40	\$ 30/ 38.40
			\$ 895.00
		Less 20 %	\$ 179.00
			\$ 716.00
		<u>SPECIAL NETT ITEMS</u>	
06	1 set	rear bumper parking sensor ✓ Shd	\$ 450.00 200
			\$ 450.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00 20
02		To check electrical lighting concerned.	\$ 60.00 30
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00 300
04		Putty and spray painting of the affected portion.	\$ 500.00 380
			\$ 1,140.00
		Total	\$ 2,306.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 698J

**Vehicle Details**

Vehicle No.: SJM7507Y  
Vehicle to be Exported: No  
Intended Deregistration Date: 12 Oct 2019  
Vehicle Make: SUBARU  
Vehicle Model: IMPREZA 4DR 1.5R AWD 4AT ABS AIRBAG  
Primary Colour: Silver  
Manufacturing Year: 2008  
Engine No.: EL15D616372  
Chassis No.: JF1GE3KS59G003694  
Maximum Power Output: 79.0 kW (105 bhp)  
Open Market Value: \$13,863.00  
Original Registration Date: 15 Jan 2009  
First Registration Date: 15 Jan 2009  
Transfer Count: 0  
Actual ARF Paid: \$13,863.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 14 Jan 2024  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$13,024.00  
COE Rebate Amount: \$11,084.00  
**Total Rebate Amount: \$11,084.00**

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Oct 2019

OK

Quek Chee Wei  
c/o 1 Defu Lane 5  
Singapore 539365

Your Ref: SLQ6832Q  
Our Ref: TP012102019 (SJM7507Y)

**WITHOUT PREJUDICE**

AIG Asia Pacific Insurance Pte Ltd  
C/o LKK Auto Consultants Pte Ltd  
Motor Claims Department  
Attention: Ms Khanchna

Dear Sir/Madam

**ACCIDENT INVOLVING SJM7507Y & SLQ6832U AT PIE TOWARDS CITY BEFORE  
PIE EXIT ON 12 OCTOBER 2019**

I refer to the above-mentioned accident.

I confirmed acceptance on your offer of **S\$1,767.50 (inclusive of GST)** in full and final settlement of my property damaged claim.

I hereby authorize that the said payment is to be issued in my repairer's favour, Messrs Tan Lim Motor Pte Ltd within fourteen (14) days or upon receipt of the duly signed discharge voucher.

Your attention and prompt action in this matter is greatly appreciated.

Yours sincerely,

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Quek Chue Wei ("the third party claimant")  
of Block 45B Edgelyfield Plains #08-11 (S) 828712 (address),  
owner of SJM7507Y (vehicle no.) hereby authorize  
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SJM7507Y that was  
damaged pursuant to the accident which occurred on 12/10/2019 (date) along  
KPE towards City before PIE exit (location)  
involving vehicle no/s SLQ68324 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment furtherto settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 12 day of Oct (month) 20 19 (year)

  
Signed by "the third party claimant"

  
Signed by "the workshop"

"The contents of this document apply to vehicle  
damages only. All personal injuries and  
damages arising therefrom are excluded from  
its scope and application of this document."

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Friday, 3 January 2020 9:12 AM  
**To:** Winnie Tan  
**Cc:** Admin A  
**Subject:** RE: TLM Ref: TP012102019; LKK Ref: TBA; Accident involving SJM7507Y (TLM) & SLQ6832U (AIG) on 12.10.2019  
**Attachments:** AIG DV.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Winnie Tan <[winnie.tan@tlmotor.com.sg](mailto:winnie.tan@tlmotor.com.sg)>

**Sent:** Friday, 27 December 2019 9:34 AM

**To:** Khanchna (LKK Auto) <[khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** TLM Ref: TP012102019; LKK Ref: TBA; Accident involving SJM7507Y (TLM) & SLQ6832U (AIG) on 12.10.2019

Our ref: TP012102019 (SJM7507Y)

Your ref: TBA

### WITHOUT PREJUDICE

Hi Khanchna,

Good morning.



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.  
Attn : Loh, Chee-HengYour Ref : 3250353250SG  
Our Ref : CC6/AIG19018420/EKB3  
Date : 30 Dec 2019**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SLQ6832U & SJM7507Y ON 12/10/2019**

Refer to the above accident.

The accident occurred when 3 vehicle chain collision, Insured vehicle is second vehicle (BOLA 28). We have clarified with the Ol on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLQ6832U) and third party claimant (vehicle no. SJM7507Y).

Summary of offer made to workshop Tan Lim Motor Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 2,467.42?	\$ 1,444.50
Loss of Rental (w/GST) (3 days x \$100)	\$ 321.00	\$ 321.00
LTA Search Fee	\$ 2.00	\$ 2.00
<b>TOTAL</b>	<b>\$ 2,790.42?</b>	<b>\$ 1,767.50</b>

Amount of claim at **Liability 100%** \$ 1,767.50

Enclose herewith the relevant supporting documents for your perusal.

\*\* 3 days recommendation for repair

For your approval please.

Regards,  
Khanchna Pothuraj  
LKK Auto Consultants Pte Ltd

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co.Reg No. 200412212G GST Reg. No. 20-0412212G  
A Member of **MS&AD** INSURANCE GROUP

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

**DRIVESHIELD - PREMIER  
Comprehensive**

Certificate No. P 90303734 DMA

Excess : SGD500

Windscreen Excess : SGD100

1. **Index Mark and Registration Number of Vehicle**  
SJM7507Y
2. **Name of Policyholder**  
Quek Chee Wei
3. **Effective Date of the Commencement of Insurance for the purposes of the Act**  
15/01/2019
4. **Date of Expiry of Insurance**  
14/01/2020
5. **Persons or Classes of Persons entitled to drive\***  
Quek Chee Wei

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6. Limitations as to Use \***

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 189) and Chapter 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

**MSIG Insurance (Singapore) Pte. Ltd.**

Approved Insurers

Michael W. Gauray  
Chief Executive Officer

## Print Received Message

This mail is associated with :

**\*SJM7507Y (3250353250SG)**  
**[SLQ6832U]**  
TP  
QUEK CHEE WEI  
Oct 12 2019 12:00PM  
[LEE CHAN FAI ANTHONY]  
Tan Lim Motor Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 02/01/2020 14:07 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$1767.50) - SJM7507Y - Claim Handler: Loh, Chee-Heng

Approved:1767.50.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019 <a href="#">Edit Reg</a>		17 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,350.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,350.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LEE CHAN FAI ANTHONY</b> , ID: S7827983D									
Main Claimant: <b>QUEK CHEE WEI</b> , ID: S7144698J									
Vehicle Reg. No.: <b>SJM7507Y</b>		Date of Loss: 12/10/2019 12:00 - :59 <b>128 Months and 27 Days From LTA Reg Date (Man Yr)</b>							
Claim Type: <b>TP / 3250353250SG</b>		Policy/Cover Note No.: 1700026734 (Comprehensive) Coverage: 19/07/2019 - 18/07/2020							
Vehicle Reg. No. (Insured): <b>SLQ6832U</b>		Policy No. (Claimant): P90303734DMA							
Excess:									
Repairer: <b>Tan Lim Motor Pte Ltd (Defu)</b> 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com									
Claimant's Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 30/10/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (02/01/2020): Alert - Adj Mandate Approved (S\$1767.50) - SJM7507Y - Claim Handler: Loh, Chee-H...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJM7507Y (3250353250SG)  
[SLQ6832U]  
TP  
QUEK CHEE WEI  
Oct 12 2019 12:00PM  
[LEE CHAN FAI ANTHONY]  
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
Assessment Reports															1 per page		<input type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	30/12/19 09:01	Adjuster Immediate Advice													Load HTM					
Photos/Images															3 per page		<input type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
2	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
3	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
4	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
5	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
6	30/10/19 10:58	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>				
7	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
8	30/10/19 10:58	Chassis Number													Load JPG	<input checked="" type="checkbox"/>				
9	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
10	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
11	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
12	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
13	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
14	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
15	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
16	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
17	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
18	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
19	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
20	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
21	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
22	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
23	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
24	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
25	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
26	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
27	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
28	30/10/19 10:58	General View													Load JPG	<input checked="" type="checkbox"/>				
29	30/10/19 10:58	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
30	30/10/19 10:58	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
31	30/10/19 10:58	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
32	30/10/19 10:58	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>				
33	30/10/19 10:58	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>				
34	30/10/19 10:58	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>				
35	30/10/19 10:58	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>				
36	30/10/19 10:58	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	30/10/19 10:58	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 17:30	TP ESTIMATE- MARKED		<input type="checkbox"/>
2	25/10/19 09:56	TP GIA REPORT		<input type="checkbox"/>
3	04/12/19 10:30	EMAIL TO OI		<input type="checkbox"/>
4	12/12/19 15:56	TP ESTIMATE MARKED (FINAL)		<input type="checkbox"/>
5	12/12/19 15:56	LOD, FINAL TAX INVOICE, LTA SEARCH FEE, RENTAL SUPPORTING DOCS, ATA		<input type="checkbox"/>
6	14/01/20 10:16	WORKSHOP INVOICE		<input type="checkbox"/>
7	14/01/20 10:16	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
8	14/01/20 10:16	Release Voucher		<input type="checkbox"/>
9	14/01/20 10:16	RENTAL RECEIPT		<input type="checkbox"/>
10	14/01/20 10:16	LOD		<input type="checkbox"/>
11	14/01/20 10:16	GIA SEARCH		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/10/19 09:42	OI GIA REPORT		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ6832U (Insd veh)	Model:	SUBARU IMPREZA 1.5 (A)
	SJM7507Y (TP veh)		
Date of Accident:	12/10/2019		

Global Sum Settlement	:	[ ] Yes	[ X ] No
Repair Estimate	:	\$	2,467.42
Final Repair Cost	:	\$	1,444.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	321.00 3 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,767.50
Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 1,767.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

14 Jan  
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19018420/EKA3Q2

Date: 14/01/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700026734  
 Claimant: SJM7507Y Insured Vehicle No: SLQ6832U  
 Vehicle No: SJM7507Y Date of Loss: 12/10/2019 Nature of Claim: TP Claim No: 3250353250SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJM7507Y  
 Make & Model: SUBARU IMPREZA, 1.5 (A) Engine No: EL15D616372  
 Reg. Date: 15/01/2009 (Man. Year: 2008) Chassis No: JF1GE3KS59G003694  
 Colour: Silver Odometer: 130080 km  
 Engine Capacity: 1498 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,166.00	927.04	238.96	20.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	730.00	410.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,306.00</b>	<b>1,657.04</b>	<b>648.96</b>	<b>28.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,350.00</b>		
(S\$)	2,306.00	1,350.00	956.00	41.46
<b>+ GST 7.00/7.00% (S\$)</b>	<b>161.42</b>	<b>94.50</b>	<b>66.92</b>	<b>41.46</b>
<b>Nett Amount (S\$)</b>	<b>2,467.42</b>	<b>1,444.50</b>	<b>1,022.92</b>	<b>41.46</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		<b>321.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,767.50</b>		

## INSPECTION

Date of Assignment: 17/10/2019  
 Date Inspected: 17/10/2019 Inspected At: Tan Lim Motor Pte Ltd (Defu)  
 1 Defu Lane 6  
 Singapore 539365

Estimated Period of Repair: 3.0 days



---

**Adjuster:** CHEN TSUE YEE**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	588.60 FL	*654.00 FL
2	1		*REAR REINFORCEMENT	Dented	208.80 FL	*208.80 FL
3	1		*REAR BUMPER REFLECTOR	Not Necessary	43.20 FL	*- FL
4	1		*REAR BUMPER TOW COVER	Crushed	16.00 FL	*16.00 FL
5	1		*SET REAR BUMPER FASTENER CLIPS	Necessary	38.40 FL	*30.00 FL
6	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,345.00</b>	<b>1,108.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>179.00</b>	<b>181.76</b>
<b>Total Parts (\$\$)</b>	<b>1,166.00</b>	<b>927.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	20.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	380.00
Gross Labour Cost (\$\$)			<b>1,140.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >