



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

NG BOON SHING
BLK 679B JURONG WEST CENTRAL 1 #15-06
SINGAPORE 642679

Attention : THE OWNER
Contact : 93465776

Estimate : ES006823

Date : 18/10/2019
Vehicle Num. : SGE6414R
Make/Model : TOYOTA COROLLA 1.6-2006
Chassis/Eng# : MR053ZEC107115669/3ZZ4554097
Accident Date : 17/10/2019
Claim No. :
Reference :
Policy No. :

Not Notified
11/10/19
Money After Paint
4-5 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	BOOT LID	Bu 885.30	✓
2.	1	BOOT LID LOCK	Na 149.30	✓
3.	2	BOOT LID REFLECTOR	193.27 Su 386.54	x
4.	2	TAIL LAMP	389.45 Su 778.90	?
5.	4	TAIL LAMP CLIP	6.00 Bu 24.00	?
6.	2	TAIL LAMP LOWER PANEL	108.30 Bu 216.60	✓
7.	1	REAR END PANEL		760.80 ?
8.	1	REAR END PANEL TOP GARNISH		178.10 ?
9.	1	BOOT WEATHERSTRIP	Su 191.00	x
10.	1	REAR BUMPER	Bu 587.75	✓
11.	6	REAR BUMPER CLIP	6.50 Na 39.00	✓
12.	2	REAR BUMPER BRACKET	74.40 Na 148.80	?
13.	2	REAR BUMPER SIDE RETAINER	68.90 Dis 137.80	✓

List TotalS\$:	4,483.89
25.00% Discount S\$:	1,120.97
	3,362.92

SPECIAL NETT ITEMS :				
1.	1	COROLLA EMBLEM	Na 55.80	✓
2.	1	ALTIS EMBLEM	Na 51.20	✓
3.	1	1.6 E EMBLEM	Na 63.35	✓
4.	1	VVTI EMBLEM	Na 49.80	✓
5.	1	REVERSE SENSOR	Na 280.00	200%

Special Nett Total S\$:	500.15
--------------------------	--------

LABOUR : RUST PROOFING TREATMENT	100.00 ?
-------------------------------------	----------

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

NG BOON SHING
BLK 679B JURONG WEST CENTRAL 1 #15-06
SINGAPORE 642679

Attention : THE OWNER
Contact : 93465776

Estimate : ES006823

Date : 18/10/2019
Vehicle Num. : SGE6414R
Make/Model : TOYOTA COROLLA 1.6-2006
Chassis/Eng# : MR053ZEC107115669/3ZZ4554097
Accident Date : 17/10/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHANGE TAIL LAMP AND CHECK WIRING		2d 65.00
		SPRAY PAINT DAMAGED AREA AFFECTED		7cd 1,100.00
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME, REAR FLOOR PANEL AND CHANGE ALL NECESSARY		
		PARTS		1,100.00 ?
		Labour Total S\$:		2,365.00

SingDollars : Six Thousand Two Hundred Twenty-Eight & Cents Seven Only


COMPLETE VMS PTE LTD

Total S\$: 6,228.07
=====

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun