

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



CONFIDENTIAL

Our ref: PIO/MR/2019/111
Your ref: ACS.11161.19.INJ.GN.ts
DATE: 04 JULY 2019

Tel: 6355 3000
Fax: 6861 2344

A C SYED & PARTNERS
101A UPPER CROSS STREET
#13-23 PEOPLE'S PARK CENTRE
SINGAPORE 058358

CERTIFIED BY
Dr Chua Ying Xian
MR 16572G
MBBS(S), MPH, GDFM, MMed(FM)
DOCTOR IN-CHARGE
PIONEER POLYCLINIC

MEDICAL REPORT OF MR ABDUL RAHMAN ABU BAKAR, M / 24 YRS
NRIC NO: S 9441104 A

The above-mentioned is a 24 year old Malay gentleman who presented to our clinic on the 17th January 2019 for right groin pain following a road traffic accident on 16th January 2019. Patient claims that he hit a curb while riding a motorbike which resulted in him landing on this right groin region. He denied any hip pain, neck pain or any neurological symptoms. He was wearing a helmet and denied head injury.

On examination, he was neurologically intact without any evidence of severe head injury. There was mild tenderness at the neck of the femur of the right hip. There was full range of movement of the right hip without any skin changes or deformity. Examination of this testes, penis, heart and lungs were unremarkable. The sensation and power of his upper and lower limb is intact.

Xray of the pelvis and right hip:

No bony injury demonstrated. The bones are in satisfactory position.

He was given symptomatic management as attached with 3 days of medical certification.

Thank you.

Regards



DR TEO HON WEI
FAMILY PHYSICIAN
PIONEER POLYCLINIC
NATIONAL UNIVERSITY POLYCLINICS


**National University
Polyclinics**

A member of the NUHS

UEN: 53358682L

GST Reg No: 200910555Z

TAX INVOICE



ABDUL RAHMAN ABU BAKAR
684A JURONG WEST STREET 64
#10-103
SINGAPORE 641684

MRN: S9441104A
CLINIC: PIONEER POLYCLINIC
BILL DATE: 05/07/2019 14:57
BILL NO: 2A19136770
TERMS: IMMEDIATE

SERVICES RENDERED	UNIT	GROSS(\$)	DISCOUNT(\$)	AMT PAYABLE(\$)
REGISTRATION				
Medical Report Fees (REF:PIO/MR/2019/111)	1	100.00	0.00	100.00
Total Charges		100.00		
Discount			0.00	
Amount Payable Before Tax				100.00
7% GST				7.00
Amount Payable After Tax				107.00
TOTAL AMOUNT PAYABLE				107.00
PAYMENT BY				
CHEQUE (CHQ NO: UOB 453664) - A C SYED & PARTNERS			05/07/2019	107.00
TOTAL DUE AFTER PAYMENT				0.00

ADDITIONAL INFORMATION

Medicines, goods and services sold are non-refundable and non-exchangeable
^ 3rd party claimable

SERVED BY: NUR FARINA AHMAD FUAZ
05/07/2019



S9441104A



2A19136770

National University Polyclinics	
National University Polyclinics A member of the NUHS	Pioneer Polyclinic 26 Jurong West Street 61 Singapore 648201
RECEIVED 19 APR 2019 BRAS BASAH BRANCH	
MEDICAL CERTIFICATE	ORIGINAL PIO19004371
Name : ABDUL RAHMAN ABU BAKAR	NRIC : S9441104A
Type of Medical Leave granted : OUTPATIENT SICK LEAVE The above name is unfit for duty for a period of 3 day(s) from 17/01/2019 to 19/01/2019 inclusive. The certificate is not valid for absence from court attendance. The above named attended Examination/Treatment from 02:26 PM to --	
Remarks : For enquiries, please call 63553000	
17/01/2019	Dr. TEO HON WEI (60380E)
Date	Issued By
	Location
	Signature

National University Polyclinics National University Polyclinics A member of the NUHS		Pioneer Polyclinic 26 Jurang West Street 61 Singapore 648201		RECEIVED 29 APR 2019	
MEDICAL CERTIFICATE		ORIGINAL		PIO19004371	
Name : ABDUL RAHMAN ABU BAKAR :		NRIC : S9441104A		BRAS BASAH BRANCH	
Type of Medical Leave granted : OUTPATIENT SICK LEAVE The above name is unfit for duty for a period of 3 day(s) from 17/01/2019 to 19/01/2019 inclusive The certificate is not valid for absence from court attendance. The above named attended Examination/Treatment from 02:26 PM to --					
Remarks : For enquiries, please call 63553000					
17/01/2019		Dr. TEO HON WEI (60380E)		PIO	
Date		Issued By		Location	
				Signature	

Krazy Throttle Motors & Trading Pte Ltd
5 Soon Lee St (Pioneer Point)
#06-21, Singapore 627607
9103 4407

INVOICE

620

Bill To:

Abdul Rahman
Ktm duke 200
FBK 1860 X

Date: Jan 31, 2019

Payment Terms: Cash

Due Date: Jan 31, 2019

Balance Due: \$0.00

Item	Quantity	Rate	Amount
JG541235 KTM Clutch Cover <i>mis</i> ✓	1	\$75.00	\$75.00 ✓
JG561200 KTM Gear Shifter Assly <i>scr</i> ✓	1	\$50.00	\$50.00 ✓
JG601204 Radiator Assly <i>X no damage</i> ✓	1	\$120.00	\$120.00 <i>ysu</i> ✓
JG601237 Radiator Fan <i>X no damage</i> ✓	1	\$70.00	\$70.00 <i>ysu</i> ✓
JG121038 Fork Leg Assly LH <i>lt</i> ✓	1	\$420.00	\$420.00 ✓
JU121007 Fork Leg Assly RH <i>lt</i> ✓	1	\$420.00	\$420.00 ✓
JU121054 Top Triple Clamp (Lower) <i>lt</i> ✓	1	\$200.00	\$200.00 ✓
JG151031 Handlebar <i>lt</i> ✓	1	\$70.00	\$70.00 ✓
JG113024 Foot R. Bracket Front R/S <i>scr</i> ✓	1	\$35.00	\$35.00 ✓
52JU0217 Tank Cover Top - Elec Orange <i>scr</i> ✓	1	\$100.00	\$100.00 ✓
56JG134X Cover Fuel Tank RHS S.Black <i>scr</i> ✓	1	\$30.00	\$30.00 ✓
JG73025C Mask Spoiler R/S Orange <i>scr</i> ✓	1	\$25.00	\$25.00 ✓
JG73015C Mask Spoiler L/S Orange <i>scr</i> ✓	1	\$25.00	\$25.00 ✓
56JG05X3 Front Fender E. Black <i>scr</i> ✓	1	\$60.00	\$60.00 ✓
36JU0016 Kit Belly Pan Assly <i>scr</i> ✓	1	\$50.00	\$50.00 ✓
36JU0080 Front Wheel Cpl. <i>lt</i> ✓	1	\$280.00	\$280.00 ✓
JP131818 Front Brake Disc <i>scr</i> ✓	1	\$70.00	\$70.00 ✓
JG131038 Tyre Front <i>scr</i> ✓	1	\$110.00	\$110.00 ✓
JG131245 Tyre Rear <i>(no damage photo)</i> ✓	1	\$145.00	\$145.00 <i>ysu</i> ✓
JG131826 Assembly Master Cylinder Front <i>(no damage photo)</i> ✓	1	\$80.00	\$80.00 <i>ysu</i> ✓
JG401041 Head Light (MY-14) <i>(no damage photo)</i> ✓	1	\$110.00	\$110.00 <i>ysu</i> ✓
DT401002 Flasher Cpl. Re. R/S Fr. L/s <i>(no damage photo)</i> ✓	1	\$30.00	\$30.00 <i>ysu</i> ✓
JG402401 Speedometer <i>(no damage photo)</i> ✓	1	\$240.00	\$240.00 <i>ysu</i> ✓
labour Cost	1	\$350.00	\$350.00 <i>300</i> ✓

2020

10%

1818

1818 + 00

300 - 00

2118.00

Subtotal:	\$3,165.00
Discounts (5%):	\$158.25
Total:	\$3,006.75
Amount Paid:	\$3,006.75

Cash Paid



THROTTLE MOTOR
TRADING PTE LTD
UEN: 201826687M
No.5, Soon Lee Street (Pioneer Point)
#06-21, Singapore - 627 607

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2019		18 Oct 2019 14:55 Edit Adj Rpt	S\$2,118.00 Edit Estimates	S\$2,118.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	ABDUL RAHMAN ABU BAKAR, ID: S9441104A		
Vehicle Reg. No.:	FBK1860X	Date of Loss:	16/01/2019 00:00 - :59 [45 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19010415	Policy/Cover Note No.:	MC00015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHD3985Y	Policy No. (Claimant):	5100304797
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (18/10/2019): Alert - Adj Mandate Approved (S\$0.00) - FBK1860X - Claim Handler: Priya
- III_SG (21/08/2019): Cancellation of Assignment: FBK1860X

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBK1860X (MCT19010415)**
[SHD3985Y]

TP

ABDUL RAHMAN ABU BAKAR

Jan 16 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#)

Documentation			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 11:40	Letter of Demand from Third Party From: TP BI - Reg. No: FBK1860X, Claimant: ABDUL RAHMAN ABU BAKAR	Load PDF	
2	23/08/19 12:03	SAS2536701-SHD3985Y	Load PDF	
3	18/10/19 17:38	damage photos	Load PDF	
4	19/10/19 14:16	Singapore Accident Statement TP SAS FBK1860X	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/12/19 09:05	LETTER	Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/09/19 23:15	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	19/01/19 11:25	Accident Photo	Load JPG	☒
2	19/01/19 11:25	Accident Photo	Load JPG	☒
3	19/01/19 11:25	Accident Photo	Load JPG	☒
4	19/01/19 11:25	Accident Photo	Load JPG	☒
5	19/01/19 11:25	Accident Photo	Load JPG	☒
6	19/01/19 11:25	Accident Photo	Load JPG	☒
7	19/01/19 11:25	Accident Photo	Load JPG	☒
8	19/01/19 11:25	Accident Photo	Load JPG	☒
9	19/01/19 11:25	Accident Photo	Load JPG	☒
10	19/01/19 11:25	Accident Photo	Load JPG	☒
11	19/01/19 11:25	Accident Photo	Load JPG	☒
12	19/01/19 11:25	Accident Photo	Load JPG	☒
13	19/01/19 11:25	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	19/01/19 11:45	Sketch Plan	Load TIF	
2	19/01/19 11:45	Sketch Plan #2	Load JPG	☒
3	19/01/19 11:45	Common Statement	Load TIF	
4	19/01/19 11:45	Common Statement	Load TIF	
5	19/01/19 11:45	Common Statement	Load TIF	
6	19/01/19 11:45	Common Statement	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS1/III19018505/R1TD3S2

Date: 31/12/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBK1860X	Insured Vehicle No :	SHD3985Y
Date of Loss:	16/01/2019	Nature of Claim:	TP
		Claim No:	MCT19010415

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK1860X	Engine No:	0590613062
Make & Model:	KTM 200 DUKE, 200cc	Chassis No:	VBKJUC407FC035905
Reg. Date:	13/04/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,674.25	1,818.00	856.25	32.02
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	332.50	300.00	32.50	9.77
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,006.75	2,118.00	888.75	29.56

INSPECTION

Date of Assignment:	18/10/2019	
Date Inspected:	18/10/2019	Inspected At: Krazy Throttle Motors & Trading Pte Ltd 5 Soon Lee St, #06-21, Singapore 627607
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/31/2019

Adjuster Report

NOTE: THE ASSESSMENT OF DAMAGES BASING ON THE DAMAGED PROFILE. TP REPORTED THAT THERE IS NO CONTACT. INSURED DRIVER WAS CHARGED "INCONSIDERATE DURING UNDER SECTION 65(B) OF THE ROAD TRAFFIC ACT CHAPTER 276"

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Dec 2019)	
Parts:	N/A	KTM 200 DUKE 200cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK1860X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*KTM CLUTCH COVER	Missing	75.00 FL	*75.00 FL
2	1		*KTM GEAR SHIFTER ASSLY	Scratched	50.00 FL	*50.00 FL
3	1		*RADIATOR ASSY	Serviceable	120.00 FL	*- FL
4	1		*RADIATOR FAN	Serviceable	70.00 FL	*- FL
5	1		*FORK LEG ASSLY LH	Bent	420.00 FL	*420.00 FL
6	1		*FORK LEG ASSLY RH	Bent	420.00 FL	*420.00 FL
7	1		*TOP TRIPLE CLAMP (LOWER)	Bent	200.00 FL	*200.00 FL
8	1		*HANDLEBAR	Bent	70.00 FL	*70.00 FL
9	1		*FOOT R. BRACKET FRONT R/S	Scratched	35.00 FL	*35.00 FL
10	1		*TANK COVER TOP - ELEC ORANGE	Scratched	100.00 FL	*100.00 FL
11	1		*COVER FUEL TANK RHS S.BLACK	Scratched	30.00 FL	*30.00 FL
12	1		*MASK SPOILER R/S ORANGE	Cracked	25.00 FL	*25.00 FL
13	1		*MASK SPOILER L/S ORANGE	Cracked	25.00 FL	*25.00 FL
14	1		*FRONT FENDER E.BLACK	Scratched	60.00 FL	*60.00 FL
15	1		*KIT BELLY PAN ASSLY	Scratched	50.00 FL	*50.00 FL
16	1		*FRONT WHEEL CPL.	Bent	280.00 FL	*280.00 FL
17	1		*FRONT BRAKE DISC	Scratched	70.00 FL	*70.00 FL
18	1		*TYRE FRONT	Cut	110.00 FL	*110.00 FL
19	1		*TYRE REAR	Serviceable	145.00 FL	*- FL
20	1		*ASSEMBLY MASTER CYLINDER FRONT	Serviceable	80.00 FL	*- FL
21	1		*HEAD LIGHT (MY-14)	Serviceable	110.00 FL	*- FL
22	1		*FLASHER CPL. RE. R/S FR. L/S	Serviceable	30.00 FL	*- FL
23	1		*SPEEDOMETER	Serviceable	240.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	2,815.00	2,020.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	140.75	202.00
Total Parts (\$\$)	2,674.25	1,818.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR COST.	New	350.00	300.00
Gross Labour Cost (S\$)			350.00	300.00
- 5.00/0.00% Labour Discount (S\$)			17.50	0.00
Gross Labour after Discount (S\$)			332.50	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >