

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM19018532/Dps3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Date: 16-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SDB 9833K	Veh. Inspected	FBC 8525K	
	Policy No.	P1950966	Coverage (\$)	0.00	
	Claim No.	S9M023DR	Excess (\$)	0.00	
	Assign From		Assign Date	21/10/2019	
2. Vehicle Particulars & Condition					
	Make & Model	SUZUKI DRZ400	c.c	398	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	JS1B8111200109048	Colour	BLACK	
	Odometer	8958	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/70 R17	BRIDGESTONE	2 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/60 R17	BRIDGESTONE	2 mm	
	L/H Rear Tyre			mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/10/2019	Inspection Date	21/10/2019	
	Survey held at	SG 98 MOTOR PTE LTD			
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a.					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				