



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/03/2020

Survey Details:

Date of loss	21-Oct-19
Date of appointment	21-Oct-19
Date of survey	21-Oct-19
Location of survey	SG 98 MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	FBC 8525K
Make and Model	SUZUKI DRZ 400
Date of registration	16/7/2008
Excess	
Market Value	\$9,000
Parf Rebate	\$6,156
Nett Loss	\$2,844

Repair details:

Initial Estimate	\$ 6,805.70
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,590.20
Check items (estimate)	\$ -
Labour	\$ 330.00
Total	\$ 2,920.20
Lump Sum(if applicable)	\$ 2,300.00
Number of days for repair	3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID came out from house parking lot and collided with third party who was on main driveway. PIR against OID.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$	2,300.00
Loss of use	\$	90.00 (3days x \$30.00)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees		NIL
Others (Towing Fee)	\$	35.00
Proposed Total	\$	2,425.00