

Motor Intelligence Automo Pte Ltd

13 Kaki Bukit Road 4, #01-20

Bartley Biz Centre, Singapore 417807

Tel : 6281 0087 Fax : 6281 0187

Email : sales@mia.com.sg

Vehicle No.: SGY 4455 E

Date: 18-Oct-19

Make/ Model: ALFA ROMEO

Owner : Dares Automotive Pte Ltd

Dear Sirs,

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>DESCRIPTION:</u>	<u>AMOUNT(\$\$)</u>
	<u>List Items</u>	
1	Front door -R/H ✓ BT	\$ 3,567.40 1250.80
1	Front door lock X SVC	\$ 325.00
1	Front door regulator motor X SVC	\$ 956.00
1	Front door rubber X SVC	\$ 560.00
1	Front door side mirror X SVC (R)	\$ 925.00
		\$ 6,333.40
	Discount 20%	\$ 1,266.68
		\$ 5,066.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total cost of parts : \$ 5,066.72

<u>S/N.</u>	<u>Labour Charges</u>	
1	To remove, refit doors fittings, replace damaged parts and transfer all fittings	\$ 180.00
2	To apply undercoating.	\$ 100.00
3	Panel beating.	\$ 1,000.00
4	To re-spray painting on the affected areas. 1.5 + side mirror cover M/H	\$ 800.00
		\$ 2,080.00

L/S repair
Resurvey after paint
without prejudice
2 Day
2.00 pm
Hock Ann
85311883
Hock Ann @ lkk.com
21/10/19

Grand Total : \$ 7,146.72