

ASS. REC. BY:

REP: CS/AGI19018546/Dsdbm Special Instruction:

Surveyor: Sykin

ASSIGNMENT (Office)

From (Person): Ivy Rattien of AGI Date/Time: 2/11/2014 @ 2:03pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJJ 6775L Insured: SLX5049J

at Workshop n/s: Tan Lim Motor Tel: 68885151

of 1 Defy tone 6

Policy No: _____ Claim No: C10004351 / JM

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/10/2014
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment: _____

Date/Time: 2:32pm @ 2/11/14 Person Contacted: William Vehicle: IN/OUT

| Date/Time | Action/Instruction | Estimated |
|-----------|--------------------|-----------|
| | SJJ 6775L - X | / |
| | SLX 5049 J - X | |
| | | |
| | | |
| | | |
| | | |

ASS. REG. BY:

REF:

ASSIGNMENT

COE 2023 Sept.

From: _____ Date: _____

Veh No: 8556775L Yr Regn: Sept/2008

Estimated Cost: _____

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To inspect Vehicle No: _____

Make: Toyota wish c.c. 1794

at Workshop m/s _____

Colour: Grey A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 200094 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: 1Z23117860

Policy No. _____

C/No: 5TDER12W103000302

Claims No. _____

Gen. Cond: Good Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/65 R15

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Bal. or Market Value: _____

Front

Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A. 19/10/2019

D.O.I. 21/10/2019

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at Tan Lim Motor Repair

CA / REV / REP. / 24 HRS

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| | Budget Direct SLX 60495 |
| | MV 25K |
| | LIA 13K |
| | NL 12K |
| | RECEIVED 02 JAN 2020 |
| 31/12/2019 | Insured with Wei Shing L/S 3450/- with 4 days of rev (\$3,854.70 Red - 53%) |

Date/Time, File Pass to? 02/01/20

1) Typical : Prel. Report : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

3 + RS. \$ _____

Photos _____

Other _____

ADD Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Exp. Format: _____

Lump Sum / T.P.: \$ 3,450/- US

TOTAL 250

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 21 October 2019 2:23 PM
To: Admin-D (LKKAuto)
Cc: SUR; Julie Mangubat
Subject: TPPD Survey: Claim ref:C10004351/JM || OI-SLX5049J (Red) TP- SJJ6775L || Est:0.00 || Tan Lim Motor

Hi Team,

We would like to arrange TP survey for SJJ6775L.

Workshop information:

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365

O. +65 68 58 5151

F. +65 6858 0877

Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111

Claims +65 6221 2199

Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924

budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: caymen@tlmotor.com.sg <caymen@tlmotor.com.sg>
Sent: Monday, 21 October 2019 11:50 AM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>
Cc: 'Tan Lim Mtr- William' <wei.shong@tlmotor.com.sg>
Subject: RE: Third party survey - SJJ6775L Your insured: SLX5049J DOA: 19.10.2019 || C10004351

Dear Ivy,

We would like to choose LKK.

Please arrange survey asap as vehicle is in.

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place all programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: caymen@tlmotor.com.sg <caymen@tlmotor.com.sg>
Sent: Monday, 21 October 2019 9:38 AM
To: Claims <claims@budgetdirect.com.sg>
Cc: 'Tan Lim Mtr- William' <wei.shong@tlmotor.com.sg>
Subject: Third party survey - SJJ6775L Your insured: SLX5049J DOA: 19.10.2019

Without Prejudice

Your ref: - SLX5049J

Our ref: - SJJ6775L

DOA: 19.10.2019

Dear Sir/Mdm,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and also let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favorable reply.

**** Please arrange survey asap as vehicle is grounded.**

Thank you.

Regards,



Caymen
caymen@tlmotor.com.sg

O. +65 68 58 5151
F. +65 6858 0877

Tan Lim Motor Pte I
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 933I

Vehicle Details

Vehicle No.: SJJ6775L
Vehicle to be Exported: No
Intended Deregistration Date: 19 Oct 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 AUTO
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: 1ZZ3117860
Chassis No.: JTDER12W103000302
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,803.00
Original Registration Date: 23 Sep 2008
First Registration Date: 23 Sep 2008
Transfer Count: 2
Actual ARF Paid: \$18,803.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Sep 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$16,689.00
COE Rebate Amount: \$13,100.00
Total Rebate Amount: \$13,100.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------|
| Date Of Report | 19/10/2019 15:59 |
| Date Of Accident | 19/10/2019 10:10 |
| Exact Location Of Accident | DRIVEWAY OF FLORAVALE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJJ6775L |
| Insured/Policyholder | |
| Name Of Registered Owner | ROMELLY BIN RAHMAT |
| NRIC No | S8329933I |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-91890529 |
| Alternative Phone No | OFFICE-91890529 |

Vehicle Particulars

| | |
|--|-----------------|
| Manufacturer | TOYOTA |
| Model | WISH-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5104704766 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | ROMELLY BIN RAHMAT |
| NRIC No | S8329933I |
| Date Of Birth | 27/09/1983 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 15/10/2008 |
| Driving Experience | 11 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91890529 |
| Fax Number | |
| Contact Number | OFFICE-91890529 |
| Email Address | NOEMAIL |

| | |
|---|---------------------------------|
| Address | BLOCK 185 JELEBU ROAD #04-22 |
| Postcode | 670185 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - - - |
| Insurance Company of Driver's Own Vehicle | - - - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other information

| | |
|---|---------------------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : PASSENGER GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

On 19.10.2019 at 1010hrs, I was on my way dropping a female passenger to Floravale at Westwood Avenue. As I was on the drive way to alight her, I stopped due to a bus was doing a reversing in front of me. Suddenly, a hard bang from behind. A car (B: SLX5049J) entered from the left side made a right turn and hit onto the rear of my car. The impact was great that my head hit the headrest and my right knee hit the dashboard (lower). My car damaged on its rear left portion. Vehicle A (SJJ6775L): 1 female passengers on board. Vehicle B (SLX5049J): Unknown passenger on board.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------------|
| Vehicle Registration Number | SLX5049J |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | ANUJ LAKHANPAL |
| NRIC/Passport Number | |
| Contact Number | 91892976 |
| Address | |



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AGI Insured's Veh No : SLX5049J
Date of Accident : 19 October 2019

Mr Romelly Bin Rahmat

Date : 21 October 2019

Estimate To Repair SJJ6775L - Toyota Wish 1.8 A
Chassis No : JTDER12W103000302

| S/No | Quantity | Description | Amount |
|------|----------|--|----------------------------|
| 08 | | <u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion. 1440.00 | \$ 1,100.00 \$ 2,720.00 |
| | | Total | \$ 7,304.70 |
| | | | 4348.70 |
| | | 21/10/2019 @ 1615hr Not Author L/sum 4 days ngan LKK Auto | L/S 3450/- |
| | | | 600/- |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19018546/Dsd3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 07-01-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | SLX 5049J | Veh. Inspected | SJJ 6775L |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10004351/JM | Excess (\$) | 0.00 |
| Assign From | IVY RATILLA | Assign Date | 21/10/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|------------|
| Make & Model | TOYOTA WISH | c.c | 1794 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | JTDER12W103000302 | Colour | GREY |
| Odometer | 200094 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 195/65 R15 | PIRELLI | 5 mm |
| L/H Front Tyre | 195/65 R15 | PIRELLI | 5 mm |
| R/H Rear Tyre | 195/65 R15 | PIRELLI | 5 mm |
| L/H Rear Tyre | 195/65 R15 | PIRELLI | 5 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|-----------------------|-----------------|------------|
| Accident Date | 19/10/2019 | Inspection Date | 21/10/2019 |
| Survey held at | 1 DEFU LANE 6 | | |
| Repairer | TAN LIM MOTOR PTE LTD | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 6775L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|--------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | DISTORTED / DENTED | 515.00 | 515.00 |
| 1 | N/S REAR BUMPER SIDE RETAINER | SERVICEABLE | 68.00 | - |
| 1 | N/S REAR BUMPER SIDE HOLDER | SERVICEABLE | 58.00 | - |
| 8 | REAR BUMPER FASTENER CLIP @\$3.50 | SERVICEABLE | 28.00 | - |
| 1 | N/S REAR BUMPER END SPLASHIELD COVER | NOT NECESSARY | 75.00 | - |
| 2 | REAR BUMPER BRACKET @\$98.00 | SERVICEABLE | 196.00 | - |
| 1 | N/S REAR BUMPER REFLECTOR | NOT NECESSARY | 85.00 | - |
| 1 | REAR END PANEL INNER TRIM | NOT NECESSARY | 285.00 | - |
| 1 | TAILGATE LID | DENTED / BENT | 1,280.00 | 1,280.00 |
| 1 | TAILGATE LID CENTRE LOGO BADGE | NECESSARY | 75.00 | 75.00 |
| 1 | TAILGATE LID WEATHERSTRIP | SERVICEABLE | 303.00 | - |
| 1 | TAILGATE LID TOP SPOILER | MOUNTING BROKEN | 1,050.00 | 1,050.00 |
| 1 | REAR END PANEL OUTER | NOT NECESSARY | 465.00 | - |
| 1 | REAR END PANEL INNER TRIM | NOT NECESSARY | 285.00 | - |
| 1 | N/S REAR LAMP | BROKEN | 420.00 | 420.00 |
| 2 | REAR WINDSCREEN SIDE RUBBER SEAL @\$35.80 | NECESSARY | 71.60 | 71.60 |
| | LESS 25% DISCOUNT | | -1,314.90 | -852.90 |
| | | | 3,944.70 | 2,558.70 |
| SPECIAL NETT ITEMS | | | | |
| 1 | TAILGATE LID ACCESSORY BADGE (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | SET REAR BUMPER PARKING SENSOR (SN) | SHORTED | 400.00 | 220.00 |
| 1 | SET REAR WINDSCREEN SEALANT (SN) | NECESSARY | 120.00 | 40.00 |
| 1 | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NECESSARY | 70.00 | 40.00 |
| | | | 640.00 | 350.00 |
| LABOUR | | | | |
| | TO REINSTALL OF REAR BUMPER PARKING SENSOR. | | 80.00 | 40.00 |
| | TO REMOVE AND REFIT REAR WINDSCREEN GLASS. | | 140.00 | 120.00 |
| | TO RUST-PROOFING OF THE AFFECTED AREAS. | | 160.00 | 40.00 |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 40.00 | 30.00 |
| | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | | 100.00 | 60.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------|---------------------------|-------------------|
| | TO REMOVE AND REINSTALL TAILGATE LID TOP SPOILER. | | 250.00 | 50.00 |
| | PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. | | 850.00 | 500.00 |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 1,100.00 | 600.00 |
| | | | 2,720.00 | 1,440.00 |
| | GRAND TOTAL | | 7,304.70 | 4,348.70 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,450.00 |

Report Ref No. CS/AGI19018546/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.