

28. REC BY:

REF: CS/MSG 19018566 / H4f3d2

Other instructions

Surveyors

HOCK AND

ASSIGNMENT (Office)

From (Person)

Final Food Writing

ed

MSLG

Date/Time:

21-10-19 14.36.17

Estimated Cost

Bill 162

$$OD(TP)WS/TPRES/ODRES/EVA/INV/MV/CS$$

To Inspect Vehicle No.

SY 4780E

Injured:

SGH 3129B

Workshop n/3

E-CARD Auto Service

Tel:

93225982 / 82393100

of

B1K51 144.000 | #01-29

Policy No.

28750214 Qmx

Claim No:

Sam Insard:

Excerpt:

Make of Veh:

(Client's Record)

DOA 18-10-17

CA / REV / REP. / REV 24 HRS

Date/Time

21-10-19 4391.2

Persons Contacted

Be more

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SS4 4780E - NA MSG R1015462/24 DON - 8/10/2019
	SG4 3927B - VN MSG R1015462/24 DUA - 13/10/2019

ASSIGNMENT

From: _____ Date: 22.10.2019

Estimated Cost: _____

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJY 4780E

at Workshop n/s: E-car Auto Services

at: 51 Ubi Avenue 1 # 01-29

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 14y

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJY 4780E Yr Regn: 7/09/2010

Type: ☒ Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: E-carroll 9 Antis 1.6 A7 c.c 1598

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 19/092 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EE106167728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / 5/Rim / STD A/Rim or

Tyre Size: F: 195/65/R15

R: 195/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Yokohama	Rear	Yokohama
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm	
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm	
D.O.A. <u>18/10/19</u>		D.O.A. <u>22/10/19</u>	

Survey held at: E-car

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SJY4780E vehicle finished at 4/ump \$7200 SJY 4780E Estimated cost Agree by workshop ms.sally person # do dissent -> (all given 1kth & mv - 17900 prove)
	PV - 10908 (Red: 6217.34, 66%)
	NV - 6900
	RECEIVED 00 NOV 2019

Date/Time, File Pass to?

1) 7/11 Typist

Date/Time, File Return to?

2) _____

☐ Prel. Report

☒ Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:	140
Transportation	
S + R	
Phone	
Other	11
TOTAL	161

Pop. Form: TP

Lump Sum: 3200

**E-CARE AUTO SERVICES PTE LTD**

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Motor Claim Department

Tel: 6220 9644 Fax: 62257402

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJY4780E**MODEL : TOYOTA COROLLA ALTIS 1.6 AUTO**

POLICY NO : A28927339MKF

CHASSIS NO : MR053ZEE106167728

YEAR OF MANUFACTURE : 2010

DATE / TIME OF ACCIDENT: 18/10/2019 Time: 19:15PM ALONG BARTLEY RD BEFORE BARTLEY MRT

THIRD PARTY VEHICLE NO: SGH3929B

Date: 21/10/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Net	Amount
		SS		SS
1 Rear bumper	CRG 1 ✓	697.40		697.40 488.30 ✓
2 Rear bumper side retainer LH /RH	21H only 2 ✓	77.00		154.00 58 ✓
3 Rear bumper reflector LH/RH	SVC 2 X ✓	56.76		113.52
4 Rear bumper sponge	CRG 1 ✓	171.27		171.27 137.80 ✓
5 Rear bumper reinforcement	1 X RPT ✓			
6 Rear reinforcement inner bracket LH/RH	21H only 2 ✓	96.80	BT	193.60 55.60 ✓
7 Rear end panel	BT 1 ✓	654.50		654.50 445.80 ✓
8 Rear end panel center bracket	1 X ✓			
9 Rear end panel center garnish inner	CRG 1 ✓	222.97		222.97 148.70 ✓
10 Rear duct assy LH/RH	SVC 2 X ✓	171.16		342.32
11 Rear Bootlid	(R) SVC 1 X ✓	901.56		901.56
12 Rear Bootlid lock	1 ✓	117.48		117.48 117.48 ✓
13 Rear Bootlid lamp RH/LH	SVC 2 X ✓	214.50		429.00
14 Rear fender lamp LH/RH	21H only CRG 2 ✓	456.50		913.00 220.25 ✓
15 Bootlid 'TOYOTA' Logo	acc 1 ✓	66.00		66.00 49.20 ✓
16 Emblem 'ELEGANCE'	acc 1 ✓	74.25		74.25 40.55 ✓
17 Emblem 'corolla'	acc 1 ✓	74.25		74.25 38.90 ✓
18 Emblem 'Altis'	acc 1 ✓	72.49		72.49 43.20 ✓
19 Bootlid Weatherstrip	CRG 1 ✓	209.00		209.00 155.60 ✓
20 Rear Board Cover Inner	acc 1 ✓	324.50		324.50 188.70 ✓
21 Spare tyre compartment panel	(R) SVC 1 X ✓	968.99		968.99

Sub-Total: 6,072.44

Total Parts 6,072.44

Special Nett Items

1	Anti-rust coating	nec	✓	1	80.00	80.00	40	✓
2	Rear end panel sealant	nec	✓	1	80.00	80.00	40	✓
3	Rear bumper sensor (set)	short	✓	1	284.90	284.90	200	✓
4	Rear bumper clip (set)	nec	✓	20	6.00	120.00	30	✓
						<u>564.90</u>		

Total Parts: 6,637.34**Labour Charges For Rear Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,200.00	1000	✓
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00	900	✓
3	Provide skill labour to disconnect and check electrical wiring	100.00	30	✓
4	Remove and replace rear bumper sensor	100.00	40	✓
5	Remove and refit rear end panel lining and garnish to facilitate repair	100.00	60	✓
6	To mount vehicle on to chassis alignment bench	280.00		

Total Labour:

	2,780.00
Total Parts & Labour:	9,417.34
GST 7%	659.21
Grand Total:	<u>10,076.55</u>

Estimate Repair Duration 5 Days

Page : 2 of 2

Remain Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name : _____
 Company : _____
 Date : _____
 Time : _____
 Contact : _____
 Email : _____

WCAAS Consultants hence notify the Repairer of the following:

- To survey by the Repairer spray painting
- To display damaged part(s) during survey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Email : _____

Parts = 2179.78

Parts less 25%

1634.83

S. nett 310

Labour 2030

3974.83

L/s less 20%

3179.86

Total L/s Amount → \$ 3200.4

2/5 repair
 without prejudice
 Hoche Ann
 85311883
 2-30pm
 Hoche Ann @ Kelle Auto.com

5 day
 resurvey After paint

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Thursday, 7 November, 2019 8:46 AM
To: E-Care Auto
Cc: Denise Tay (LKKAuto); Bernard Kee
Subject: RE: Finalize -Accident Involving (Our Vehicle SJY4780E (MSIG) against Vehicle SGH3929B (MSIG) (Our ref: 609075)

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear sally ,

Good day, o.k will be process base on finalized total amount COR \$ 3200 lump sump and DOR 5 days close.

Noted: All finalized document > LOA ,LOD,DV,LTA need send to MISG claims dept.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: E-Care Auto [mailto:info_ecare@yahoo.com]
Sent: Wednesday, 6 November, 2019 3:03 PM
To: Hock Ann (LKK Auto)
Cc: Denise Tay (LKKAuto); Bernard Kee; E-Care Auto
Subject: Re: Finalize -Accident Involving (Our Vehicle SJY4780E (MSIG) against Vehicle SGH3929B (MSIG) (Our ref: 609075)

Hi Hock Ann,

We accepted finalize amount @ \$3200.00 Lump Sum.

Thank you.

Best Regards,

Sally Chan

E-Care Auto Services Pte Ltd

51, Ubi Ave 1,

#01-29 Paya Ubi Industrial Park

Singapore 408933.

Tel: +65 6841 8892 Phone: 8239 3100

On Friday, 1 November 2019, 08:36:09 am GMT+8, Hock Ann (LKK Auto) <hockann@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear sally ,

Good day, will check estimate adjustment before finalized with yours.

Will updated amount asap .

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2019		21 Oct 2019 16:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SITI MASRURAH BINTE KARIM KHAN SURATTEE, ID: 58624945F								
Main Claimant:	E-KARZ RENTAL PTE LTD, Co. Reg. No.: 201608381M								
Vehicle Reg. No.:	SJY4780E	Date of Loss:	18/10/2019 19:00 - :59 [109 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	28750214QMX (TP, Fire & Theft) Coverage: 30/05/2016 - 08/06/2020						
Vehicle Reg. No. (Insured):	SGH3929B	Policy No. (Claimant):							
		Excess:							
Repairer:	E-Care Auto Services Pte Ltd (HQ) Block 51, Ubi Ave 1, #01-29, Paya Ubi Ind Pk, 408933 Ubi - Tel: 9388 5988								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/10/2019]								
Driver/Custodian (Insured):	KARIM BIN OMAR KHAN SURATTEE (58 / Male), NRIC: S1429647F Email:								
Adj Asg. Remarks:	on WP, Liab: clear. Agree on SJE. Contact: Sally @ 8239 3100. (Please arrange survey on 22/10/2019 at 11am).								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

381M

SJY4780E

No

20 Oct 2019

TOYOTA

COROLLA ALTIS 1.6 AUTO

White

2010

3ZZ4974936

MR053ZEE106167728

80.0 kW (107 bhp)

\$16,716.00

07 Sep 2010

07 Sep 2010

2

\$16,716.00

Yes

06 Sep 2020

\$8,358.00

06 Sep 2020

A - Car (1600cc & below)

10

\$29,000.00

\$2,550.00

\$10,908.00

- 8358

The information contained herein is correct as at 20 Oct 2019

DOA = 18/10/19

OK

Balance 11 months

Depreciation = 10500 years

$10500 \div 12 = 875$

MV - 17900

PV - 10908

PV - 6900

$9625 + 8358$

$= 17983$



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!



Direct Owner



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

< Back (1 2) Next >

Sort by Date Posted

20 results/page

21 vehicles

TOYOTA ALTIS

3

	Model	Price	Depreciation	Eng Cap	Mileage	Veh Type	
Search Selection	TOYOTA ALTIS	Any	Any	2010	Any	Any	Available
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$33,800	\$6,750 /yr	25-Jan-2010	1,598 cc	93,000 km	Sedan Available
	Super Low Genuine Mileage Done. Well Maintained, Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade-In, Insurance And Scrap Services...						
	Posted: 29-Oct-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	Toyota Corolla Altis 1.6A Elegance	\$20,888	\$15,170 /yr	18-Aug-2010	1,598 cc	140,000 km	Sedan Available
	Very Well Maintained By Lady Owner! Always Parked Indoors & Hands Wash By Owner. Genuine Low Mileage, Powerful & Responsive Engine! Perfect Conditions For Renewal Of COE & Still Come With 6 Months Warranty! Graded 'B' For Trust Certified Quality Pre-Owned L...						
	Posted: 29-Oct-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	Toyota Corolla Altis 1.6A	\$18,000	\$11,870 /yr	13-Aug-2010	1,598 cc	135,000 km	Sedan Available
	New Arrival! Low Mileage Clocked Annually! Very Hint Condition! Interior/Exterior Good Maintain! Perfect Dashboard! Powerful/Responsive Engine! Ideal For Short Term Usage And Future Coe Renewal! Trade In/ Loan Available.Viewing By Appointment Only!						
	300 VR Cars Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	Posted: 29-Oct-2019						
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$33,800	\$6,550 /yr	01-Feb-2010	1,598 cc	126,394 km	Sedan Available
	Can Pay 10 Yrs COE. Most Reliable Japanese Sedan Altis Ideally For Daily Drives Yet Fuel Efficient, Under Usage Low Mileage. Fully Done Up To Showroom Unit Standard, Don't Hesitate Anymore. New Paintwork, New Tyres. Priced To Sell, See To Believe. No Gimmicks Pricing.						
	Posted: 29-Oct-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Corolla Altis 1.6A (New 5-yr COE) \$33,800 \$6,750 /yr 09-Feb-2010 1,598 cc 120,700 km Sedan Available

2 Owners, Well Maintained, Easy Loan Available.

Posted: 29-Oct-2019

Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 10-yr COE) \$47,800 \$4,780 /yr 15-Jan-2010 1,598 cc - Sedan Available

5 Years COE Available! AA Trust Certified Quality Pre-Owned Vehicle! No Further Repair Needed. Very Well Maintained By Previous Owner! The Most Popular Sedan For Work/Leisure And Across The Causeway That Sit Comfortably For Everyone With Generous Legroom Space!

AA Trust Automotive

Posted: 29-Oct-2019

Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Toyota Corolla Altis 1.6A (New 10-yr COE) \$49,800 \$4,980 /yr 15-Mar-2010 1,598 cc 140,000 km Sedan Available



Renew 10 Years COE And Full Loan Available. Well Kept By Previous Owner. High Trade In Available. Act Fast And Call Now To Fix An Appointment Before It's Gone. Don't Miss This Gem!

Posted: 19-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,800 \$6,950 /yr 02-Mar-2010 1,598 cc 132,701 km Sedan Available

10 Yrs Coe At 47800 Respectively, All Wear And Tears Done Recently, No Repairs Needed, Kindly Contact Us Or Visit Us At Our Showrooms. Buy And Sell With A Strictly Accredited Company At AKK WHEELS PTE LTD. Where Quality Service Really Matters.

Posted: 19-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A \$16,800 \$12,210 /yr 30-Jun-2010 1,598 cc 123,444 km Sedan Available

100% Loan Available. We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

Posted: 19-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,888 \$6,970 /yr 09-Apr-2010 1,598 cc 86,500 km Sedan Available

Free 1 Normal Servicing Upon Purchased! Up To 1 Year Warranty For Engine And Gearbox! 100% Loan Approval Rate! Good Conditions On Both Interior And Exterior. Comes With 5 Years COE. Call Us Now To Book A Breezy And Smooth Test Drive On This Unit With Our Fr...

Posted: 17-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Save on petrol with DBS Esso card!

Enjoy huge petrol savings of up to 21%, interest-free 0% Instalment Payment Plan for Motor Insurance and Road Tax, and 1-year annual fee waiver. Find out more

Find out more!



Toyota Corolla Altis 1.6A \$19,500 \$13,180 /yr 25-Aug-2010 1,598 cc 44,269 km Sedan Available

Posted: 16-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$32,800 \$6,550 /yr 04-Jan-2010 1,598 cc 151,000 km Sedan Available

Comes With New Cushion. New Coat Of Paint. Servicing Done Up And Really To Go. 100% Loan Available. High Trade In. Call Our Friendly Sales Representative Now!

ADMIN (2994) Pte Ltd

Posted: 15-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A \$16,388 \$10,720 /yr 27-Sep-2010 1,598 cc 208,000 km Sedan Available

1 Owner! No Admin Fee! Car Rental/Dealers Welcome! Low Deprec Road Tax Till 26 Mar 2020! Pay \$16,388 Now, Get Back Minimum PARF \$8,340 From LTA + Car Body \$2000 About 11 Months Later! Depre Only \$731 Per Month! (i.e. \$16,388 - \$8,340 - \$2000 = \$6,048...

Posted: 14-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 10-yr COE) \$49,800 \$4,980 /yr 05-Jan-2010 1,598 cc - Sedan Available

New 10 Years COE, New Paintwork, Very Well Maintained. Immaculate Condition, No Repair Needed, View To Believe, High Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now!

Posted: 14-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 10-yr COE) \$49,800 \$4,980 /yr 25-Jan-2010 1,598 cc - Sedan Available

Ideal For Short Term Usage. Well Maintained! Well Known Reliable And Fuel Efficiency Vehicle! Flexible Loan Arrangement! Trade In Welcomed! Hurry Don't Miss Out This Awesome Vehicle! Call Us Today To Find Out More!

Posted: 13-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,800 \$6,950 /yr 22-Jan-2010 1,598 cc 164,213 km Sedan Available

Very Well Kept Interior, Accident-Free, Road Tax Till Jan 2020, Don't Miss. High Loan, Trade In Welcome.

Posted: 08-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota

Toyota Corolla Altis 1.6A (New 5-yr COE) \$30,800 \$6,150 /yr 27-Jan-2010 1,598 cc - Sedan Available

n Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

ADMIN (2994) Pte Ltd



Posted: 03-Oct-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, 1998 Toyota



Toyota Corolla Altis 1.6A (New 10-yr COE) \$46,800 \$4,680 /yr 29-Mar-2010 1,598 cc 117,000 km Sedan Available

Toyota's Best Selling Petrol Efficient Sedan! New Paintwork! Low Mileage! Brand New Road Tax! Perfect For COE Renewal! Perfect For Grab/Gojek Drivers! Superbly Maintained By Previous Owner. Loan Available. Trade In Welcome. Call/SMS/WhatsApp For A Viewing And...

Posted: 27-Sep-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$33,000 \$5,590 /yr 01-Mar-2010 1,598 cc Sedan Available

Excellent Exterior And Interior Condition! Cheapest Deal In Town! Well Maintained With No Repairs Needed! STA/VICOM/AA Evaluation Friendly, Welcome Trade-in. Bank Loan And In House Loan Supported.

Posted: 25-Sep-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota



Toyota Corolla Altis 1.6A \$16,818 N/A 26-Feb-2010 1,598 cc 122,676 km Sedan Available

Just Arrived! Excellent Condition Assured And Peace Of Mind. Very Well Maintained, Trade In Welcome, Act Fast Before It's Gone! 100% In House Loan Available. View To Believe! Don't Miss, Call Today!

Posted: 14-Sep-2019 Tags: 2010 Toyota Corolla, 2010 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Eng Cap Mileage Veh Type

For old advertisements, view Expired ads

< Back (1 2) Next >

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car dealership for parallel import cars. Toyota, Honda, Nissan, Mitsubishi is 3000. There are plenty of cars for sale from many brands, sedans cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchbacks, to COE cars & OPC cars. You can also buy from a car auction, book up car loans, financial services, low mileage cars, car brands, car hire & car insurance. Find buy used TOYOTA ALTIS, TOYOTA ALTIS Singapore, used TOYOTA ALTIS Singapore, used TOYOTA ALTIS, used vehicles Singapore or even buy used TOYOTA ALTIS Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, review, car performance parts, car discovery, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or against the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2019 09:17
Date Of Accident	18/10/2019 19:15
Exact Location Of Accident	BARTLEY RD BEFORE BARTLEY MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY4780E
Insured/Policyholder	
Name Of Registered Owner	E-KARZ RENTAL PTE LTD
Co Reg No	201608381M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93885988
Alternative Phone No	OFFICE-93885988

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	A28927339MKF
Cover Note Number	

Driver

Name of Driver	HANSEL KAO SZE HAO (GAO SHIHAO HANSEL)
NRIC No	S7730041D
Date Of Birth	07/10/1977
Occupation	OUTDOOR
Date Of Driving Pass	16/02/2004
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92227992
Fax Number	
Contact Number	OFFICE-92227992
Email Address	NOEMAIL

Address	BLK 77 BEDOK NORTH ROAD #06-208
Postcode	460077
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS IT WAS CONGESTED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZED THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. THERE WERE 3 VEHICLES INVOLVED IN THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH3929B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KARIM BIN OMAR KHAN SURATTEE
NRIC/Passport Number	S1429647F
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGB7071E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver MUHAMMAD FAZRI BIN SABARI

NRIC/Passport Number S8105247F

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name HANSEL KAO SZE HAO (GAO SHIHAO HANSEL)

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SJY4780E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/TIN No.:

Accident Sketch Plan

SKETCH PLAN

Handwritten notes on the sketch plan grid:

- On the left side, vertically: *Barrelled*
- In the center, vertically: *A*, *B*, *C* (each inside a small box)
- On the right side:
 - A SJY 4780E*
 - B. HAD SJY 93*
 - C. SJY 021E*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

[A large diagonal line is drawn across the remaining lines of this section.]

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GRATAC SL-114-11/10/01, V2

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**E-CARE AUTO SERVICES PTE LTD**

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Motor Claim Department

Tel: 6220 9644 Fax: 62257402

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJY4780E**MODEL : TOYOTA COROLLA ALTIS 1.6 AUTO****POLICY NO : A28927339MKF****CHASSIS NO : MR053ZEE106167728****YEAR OF MANUFACTURE : 2010****DATE / TIME OF ACCIDENT: 18/10/2019 Time: 19:15PM ALONG BARTLEY RD BEFORE BARTLEY MRT****THIRD PARTY VEHICLE NO: SGH3929B**

Date: 21/10/2019

Page: 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Net	Amount
		S\$		S\$
1 Rear bumper	CRA 1✓	697.40		697.40 488.30 ✓
2 Rear bumper side retainer LH/RH 2/H only	acc 21✓	77.00		154.00 50 ✓
3 Rear bumper reflector LH/RH	SVC 2 X	56.76		113.52
4 Rear bumper sponge	CRA 1✓	171.27		171.27 137.80 ✓
5 Rear bumper reinforcement	1 X RPT			
6 Rear reinforcement inner bracket LH/RH 2/H only	21✓	96.80	BT	193.60 55.60 ✓
7 Rear end panel	BT 1✓	654.50		654.50 445.80 ✓
8 Rear end panel center bracket	SVC 1 X			
9 Rear end panel center garnish inner	CRA 1✓	222.97		222.97 148.70 ✓
10 Rear duct assy LH/RH	SVC 2 X	171.16		342.32
11 Rear Bootlid	(R) SVC 1 X	901.56		901.56
12 Rear Bootlid lock	Jm 1✓	117.48		117.48 117.48 ✓
13 Rear Bootlid lamp RH/LH	SVC 2 X	214.50		429.00
14 Rear fender lamp LH/RH 2/H only	CRA 21	456.50		456.50 220.25 ✓
15 Bootlid 'TOYOTA' Logo	acc 1✓	66.00		66.00
16 Emblem 'ELEGANCE'	acc 1✓	74.25		74.25 40.15 ✓
17 Emblem 'corolla'	acc 1✓	74.25		74.25 38.90 ✓
18 Emblem 'Altis'	acc 1✓	72.49		72.49 43.20 ✓
19 Bootlid Weatherstrip	CRA 1✓	209.00		209.00 155.60 ✓
20 Rear Board Cover Inner	MIS 1✓	324.50		324.50 188.70 ✓
21 Spare tyre compartment panel	(R) SVC 1 X	968.99		968.99

Sub-Total: 6,072.44

Total Parts 6,072.44

Special Nett Items

1	Anti-rust coating	ncc	✓	80.00	80.00 40 ✓
2	Rear end panel sealant	ncc	✓	80.00	80.00 40 ✓
3	Rear bumper sensor (set)	short	✓	284.90	284.90 200 ✓
4	Rear bumper clip (set)	ncc	✓	6.00	120.00 30 ✓
					564.90

Total Parts: 6,637.34

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	4.5 ps	1200.00 900 ✓
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	4 ps	1,000.00 800 ✓
3	Provide skill labour to disconnect and check electrical wiring		100.00 30 ✓
4	Remove and replace rear bumper sensor		100.00 20 ✓
5	Remove and refit rear end panel lining and garnish to facilitate repair		100.00 30 ✓
6	To mount vehicle on to chassis alignment bench		280.00 X

Total Labour:

	2,780.00
Total Parts & Labour:	9,417.34
GST 7%	659.21
Grand Total:	10,076.55

Estimate Repair Duration

5 Days

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name :
Compan :
Date :
Time :
Contact :
Email :

LK&A Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Email :

Parts =	2179.78
Parts less	25 %
	1634.83
S.nett	310
Labour	1780
	3724.83
L/s less	20 %
	2979.86
Total L/s Amount	\$ 3000

30/10/19 repair without prejudice Hoek Ann 85311883 2-30pm Hoek Ann @ H&A Auto.com 5 day resurvey After paint

Puts - 2179.78

250%
1634.83

net → 310

labur → 1780

3724.83

Sally Chan - 200%

2929.86

Stk 14098

↓

\$ 3000 114



E-CARE AUTO SERVICES PTE LTD
 51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933
 Tel: +65 68418892 Hotline: +65 97223678
 GST Reg. No.: 20102442D

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581
 Attn: Motor Claim Department
 Tel: 6220 9644 Fax: 62257402
 DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJY4780E
MODEL: TOYOTA COROLLA ALTIS 1.6 AUTO
POLICY NO: A28927339MKF

Date: 21/10/2019
 Page: 1 of 2

CHASSIS NO: MR053ZEE106167728
YEAR OF MANUFACTURE: 2010

DATE / TIME OF ACCIDENT: 18/10/2019 Time: 19:15PM ALONG BARTLEY RD BEFORE BARTLEY MRT
THIRD PARTY VEHICLE NO: SGH3929B

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Net	Amount
		SS		SS
1 Rear bumper	CRA 1✓	697.40		
2 Rear bumper side retainer LH /RH 1/H only	acc 21✓	77.00		697.40 488.30
3 Rear bumper reflector LH/RH	SVC 2 X	56.76		164.00 50
4 Rear bumper sponge	CRA 1✓	171.27		113.52
5 Rear bumper reinforcement	1XRPT			171.27 137.80
6 Rear reinforcement inner bracket LH/RH 4/H only	BT 1✓	96.80	BT	
7 Rear end panel	1 X	654.50		193.60 55.60
8 Rear end panel center bracket	CRA 1✓	222.97		654.50 445.80
9 Rear end panel center garnish inner	SVC 2 X	171.16		
10 Rear duct assy LH/RH	(R) SVC 1 X	901.56		222.97 148.70
11 Rear Bootlid	Jm 1✓	117.48		171.16
12 Rear Bootlid lock	SVC 2 X	214.50		901.56
13 Rear Bootlid lamp RH/LH	CRA 21	456.50		117.48 117.48
14 Rear fender lamp LH/RH 2/H only	acc 1✓	66.00		428.00
15 Bootlid 'TOYOTA' Logo	acc 1✓	74.25		456.50 388.50 Δ
16 Emblem 'ELEGANCE'	acc 1✓	74.25		66.00 39.60
17 Emblem 'corolla'	acc 1✓	74.25		74.25 40.125
18 Emblem 'Altis'	acc 1✓	72.49		74.25 38.190
19 Bootlid Weathership	CRA 1✓	209.00		72.49 43.20
20 Rear Board Cover Inner	MIS 1✓	324.50		209.00 155.60
21 Spare tyre compartment panel	(R) SVC 1 X	968.99		324.50 188.70

Sub-Total: 6,072.44

Total Parts 6,072.44

Δ - Less 2570

**E-CARE AUTO SERVICES PTE LTD**

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Motor Claim Department

Tel: 6220 9644 Fax: 62257402

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJY4780E**MODEL : TOYOTA COROLLA ALTIS 1.6 AUTO****POLICY NO : A28927339MKF****CHASSIS NO : MR053ZEE106167728****YEAR OF MANUFACTURE : 2010****DATE / TIME OF ACCIDENT: 18/10/2019 Time: 19:15PM ALONG BARTLEY RD BEFORE BARTLEY MRT****THIRD PARTY VEHICLE NO: SGH3929B**

Date: 21/10/2019

Page: 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Net	Amount
		S\$		S\$
1 Rear bumper	CRB 1 ✓	697.40		697.40
2 Rear bumper side retainer LH/RH 2/H only 21 ✓		77.00		154.00
3 Rear bumper reflector LH/RH	SVC 2 X	56.76		113.52
4 Rear bumper sponge	CRB 1 ✓	171.27		171.27
5 Rear bumper reinforcement	1 X RPT			
6 Rear reinforcement inner bracket LH/RH 2/H only 21 ✓		96.80	6+	193.60
7 Rear end panel	BT 1 ✓	654.50		654.50
8 Rear end panel center bracket	1 X			
9 Rear end panel center garnish inner	CRB 1 ✓	222.97		222.97
10 Rear duct assy LH/RH	SVC 2 X	171.16		342.32
11 Rear Bootlid	(R) SVC 1 X	901.56		901.56
12 Rear Bootlid lock	1 X	117.48		117.48
13 Rear Bootlid lamp RH/LH	SVC 2 X	214.50		429.00
14 Rear fender lamp LH/RH 2/H only	CRB 2 X	456.50		913.00
15 Bootlid 'TOYOTA' Logo	rec 1 ✓	66.00		66.00
16 Emblem 'ELEGANCE'	rec 1 ✓	74.25		74.25
17 Emblem 'corolla'	rec 1 ✓	74.25		74.25
18 Emblem 'Altis'	rec 1 ✓	72.49		72.49
19 Bootlid Weatherstrip	CRB 1 ✓	209.00		209.00
20 Rear Board Cover inner	MIS 1 ✓	324.50		324.50
21 Spare tyre compartment panel	(R) SVC 1 X	968.99		968.99

Sub-Total: 6,072.44

Total Parts: 6,072.44

3314-41

- 25%

2485.80

Special Nati Items

- | | | | | |
|---|--------------------------|------------|------|--------|
| 1 | Anti-rust coating | rec | ✓ 1 | 80.00 |
| 2 | Rear end panel sealant | rec | ✓ 1 | 80.00 |
| 3 | Rear bumper sensor (set) | short | ✓ 1 | 284.00 |
| 4 | Rear bumper clip | cost 7 rec | ✓ 20 | 6.00 |

~~80.00~~ 40
~~80.00~~ 40
~~284.00~~ 200
~~120.00~~ 30
584.00

Total Parts: 6,637.34

310

Labour Charges For Rear Portion

- | | | |
|---|--|--------|
| 1 | Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. | 4.5 ps |
| 2 | Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities | 4 ps |
| 3 | Provide skill labour to disconnect and check electrical wiring | |
| 4 | Remove and replace rear bumper sensor | |
| 5 | Remove and refit rear end panel lining and garnish to facilitate repair | |
| 6 | To mount vehicle on to chassis alignment bench | |

~~1,280.00~~ 900
~~1,000.00~~ 800
~~100.00~~ 30
~~100.00~~ 20
~~100.00~~ 30
~~280.00~~ X

1780

Total Labour:

2,780.00

Total Parts & Labour:

9,417.34

GST 7%

659.21

Grand Total:

10,076.55

Estimate Repair Duration

5 Days

Page : 2 of 2

Remark Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name _____
 Company _____
 Date _____
 Time _____
 Contact _____
 Email _____

S : \$ 2485.80
 S/N : \$ 310.00
 L : \$ 1780.00
\$ 4575.80
 20%
\$ 3660.00 ✓

L/S repair
 without pre-judice
 Hoyle Ann
 85311883
 2:30pm
 Hoyle Ann @ Mike Auto.com
 5 day
 respray After paint

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2019		21 Oct 2019 16:17 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SITI MASRURAH BINTE KARIM KHAN SURATTEE, ID: S8624945F								
Main Claimant:	E-KARZ RENTAL PTE LTD, Co. Reg. No.: 201608381M								
Vehicle Reg. No.:	SJY4780E	Date of Loss:	18/10/2019 19:00 - :59 [109 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 609075	Policy/Cover Note No.:	28750214 (TP, Fire & Theft) Coverage: 09/06/2019 - 08/06/2020						
Vehicle Reg. No. (Insured):	SGH3929B	Policy No. (Claimant):							
		Excess:							
Repairer:	E-Care Auto Services Pte Ltd (HQ) Block 51, Ubi Ave 1, #01-29, Paya Ubi Ind Pk, 408933 Ubi - Tel: 9388 5988								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 22/10/2019]								
Driver/Custodian (Insured):	KARIM BIN OMAR KHAN SURATTEE (58 / Male) , NRIC: S1429647F Email:								
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Contact: Sally @ 8239 3100. (Please arrange survey on 22/10/2019 at 11am).								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY4780E (609075)
 [SGH3929B]
 TP
 E-KARZ RENTAL PTE LTD
 Oct 18 2019 7:00PM
 [SITI MASRURAH BINTE KARIM KHAN SURATTEE]
 E-Care Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	23/10/19 14:04	Chassis Number						Load JPG	☒
2	23/10/19 14:04	Odometer Reading						Load JPG	☒
3	23/10/19 14:04	General View						Load JPG	☒
4	23/10/19 14:04	General View						Load JPG	☒
5	23/10/19 14:04	General View						Load JPG	☒
6	23/10/19 14:04	General View						Load JPG	☒
7	23/10/19 14:04	General View						Load JPG	☒
8	23/10/19 14:04	General View						Load JPG	☒
9	23/10/19 14:04	General View						Load JPG	☒
10	23/10/19 14:04	General View						Load JPG	☒
11	23/10/19 14:04	General View						Load JPG	☒
12	23/10/19 14:05	General View						Load JPG	☒
13	23/10/19 14:05	General View						Load JPG	☒
14	23/10/19 14:05	General View						Load JPG	☒
15	23/10/19 14:05	General View						Load JPG	☒
16	23/10/19 14:05	General View						Load JPG	☒
17	23/10/19 14:05	General View						Load JPG	☒
18	23/10/19 14:05	General View						Load JPG	☒
19	23/10/19 14:05	General View						Load JPG	☒
20	23/10/19 14:05	General View						Load JPG	☒
21	23/10/19 14:05	General View						Load JPG	☒
22	23/10/19 14:05	General View						Load JPG	☒
23	23/10/19 14:05	General View						Load JPG	☒
24	23/10/19 14:05	General View						Load JPG	☒
25	23/10/19 14:05	General View						Load JPG	☒
26	23/10/19 14:05	General View						Load JPG	☒
27	23/10/19 14:05	General View						Load JPG	☒
28	23/10/19 14:05	General View						Load JPG	☒
29	23/10/19 14:05	General View						Load JPG	☒
30	23/10/19 14:05	General View						Load JPG	☒
31	23/10/19 14:05	General View						Load JPG	☒
32	23/10/19 14:05	General View						Load JPG	☒
33	23/10/19 14:05	General View						Load JPG	☒
34	23/10/19 14:05	General View						Load JPG	☒
35	23/10/19 14:05	General View						Load JPG	☒
36	23/10/19 14:05	General View						Load JPG	☒
37	23/10/19 14:05	General View						Load JPG	☒
38	23/10/19 14:05	General View						Load JPG	☒
39	23/10/19 14:05	General View						Load JPG	☒
40	23/10/19 14:06	General View						Load JPG	☒
41	23/10/19 14:06	General View						Load JPG	☒
42	23/10/19 14:06	General View						Load JPG	☒
43	23/10/19 14:06	General View						Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	23/10/19 14:06	General View		☒
45	23/10/19 14:06	General View		☒
46	23/10/19 14:06	General View		☒
47	23/10/19 14:06	General View		☒
48	23/10/19 14:06	General View		☒
49	23/10/19 14:06	General View		☒
50	23/10/19 14:06	General View		☒
51	23/10/19 14:06	General View		☒
52	23/10/19 14:06	General View		☒
53	23/10/19 14:06	General View		☒
54	23/10/19 14:06	General View		☒
55	23/10/19 14:06	General View		☒
56	23/10/19 14:06	General View		☒
57	23/10/19 14:06	General View		☒
58	23/10/19 14:06	General View		☒
59	23/10/19 14:06	General View		☒
60	23/10/19 14:06	General View		☒
61	23/10/19 14:06	General View		☒
62	23/10/19 14:06	General View		☒
63	23/10/19 14:06	General View		☒
64	23/10/19 14:06	General View		☒
65	23/10/19 14:06	General View		☒
66	23/10/19 14:06	General View		☒
67	23/10/19 14:06	General View		☒
68	23/10/19 14:06	General View		☒
69	23/10/19 14:06	General View		☒
70	23/10/19 14:06	General View		☒
71	23/10/19 14:06	General View		☒
72	23/10/19 14:06	General View		☒
73	23/10/19 14:06	General View		☒
74	23/10/19 14:07	Reinspection Photo		☒
75	23/10/19 14:07	Reinspection Photo		☒
76	23/10/19 14:07	Reinspection Photo		☒
77	23/10/19 14:07	Reinspection Photo		☒
78	23/10/19 14:07	Reinspection Photo		☒
79	23/10/19 14:07	Reinspection Photo		☒
80	23/10/19 14:07	Reinspection Photo		☒
81	23/10/19 14:07	Reinspection Photo		☒
82	23/10/19 14:07	Reinspection Photo		☒
83	23/10/19 14:07	Reinspection Photo		☒
84	23/10/19 14:07	Reinspection Photo		☒
85	23/10/19 14:07	Reinspection Photo		☒
86	23/10/19 14:07	Reinspection Photo		☒
87	23/10/19 14:07	Reinspection Photo		☒
88	23/10/19 14:07	Reinspection Photo		☒
89	23/10/19 14:07	Reinspection Photo		☒
90	23/10/19 14:07	Reinspection Photo		☒
91	23/10/19 14:07	Reinspection Photo		☒
92	23/10/19 14:07	Reinspection Photo		☒
93	23/10/19 14:07	Reinspection Photo		☒
94	23/10/19 14:07	Reinspection Photo		☒
95	23/10/19 14:07	Reinspection Photo		☒
96	23/10/19 14:07	Reinspection Photo		☒
97	23/10/19 14:07	Reinspection Photo		☒
98	23/10/19 14:07	Reinspection Photo		☒
99	30/10/19 15:14	After Repair Photo		☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	30/10/19 15:14	After Repair Photo		Load JPG	☒
101	30/10/19 15:14	After Repair Photo		Load JPG	☒
102	30/10/19 15:14	After Repair Photo		Load JPG	☒
103	30/10/19 15:14	After Repair Photo		Load JPG	☒
104	30/10/19 15:14	After Repair Photo		Load JPG	☒
105	30/10/19 15:14	After Repair Photo		Load JPG	☒
106	30/10/19 15:14	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/10/19 15:09	OI ACCIDENT REPORT		Load PDF	
2	21/10/19 15:09	TP SJY4780E E-REPORT		Load PDF	
3	21/10/19 15:09	PRI		Load PDF	
4	21/10/19 15:22	Agree on SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018566/HTF3E2

Date: 12/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28750214

Claimant

Vehicle No: SJY4780E

Insured Vehicle No: SGH3929B

Date of Loss: 18/10/2019

Nature of Claim: TP

Claim No: 609075

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY4780E

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4974936

Reg. Date: 07/09/2010 (Man. Year: 2010)

Chassis No: MR053ZEE106167728

Colour: White

Odometer: 191092 km

Engine Capacity: 1598 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 5 mm

Rear Left Side:

Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,557.34	1,904.83	4,652.51	70.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,820.00	1,040.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,417.34	3,724.83	5,692.51	60.45
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,417.34	3,200.00	6,217.34	66.02
+ GST 7.00/7.00% (S\$)	659.21	224.00	435.21	66.02
Nett Amount (S\$)	10,076.55	3,424.00	6,652.55	66.02

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 22/10/2019 Inspected At:

E-Care Auto Services Pte Ltd (HQ)
Block 51, Ubi Ave 1, #01-29, Paya Ubi
Ind Pk
Singapore 408933

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY4780E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	697.40 F	*488.30 FL
2	1		*REAR BUMPER SIDE RETAINER LH / RH	N/S Necessary	154.00 F	*50.00 FL
3	2		*REAR BUMPER REFLECTOR LH / RH	Serviceable	113.52 F	*- FL
4	1		*REAR BUMPER SPONGE	Cracked	171.27 F	*137.80 FL
5	1		*REAR BUMPER REINFORCEMENT (NPA)	Repeated	0.00 F	*- FL
6	1		*REAR REINFORCEMENT INNER BRACKET LH / RH	N/S Bent	193.60 F	*55.60 FL
7	1		*REAR END PANEL	Bent	654.50 F	*445.80 FL
8	1		*REAR END PANEL CENTER BRACKET (NPA)	Serviceable	0.00 F	*- FL
9	2		*REAR DUCT ASSY LH / RH	Serviceable	171.16 F	*- FL
10	1		*REAR BOOTLID	Serviceable	901.56 F	*- FL
11	1		*REAR BOOTLID LOCK	Jammed	117.48 F	*117.48 FL
12	2		*REAR BOOTLID LAMP RH / LH	Serviceable	429.00 F	*- FL
13	1		*REAR FENDER LAMP LH / RH	N/S Crushed	456.50 F	*220.25 FL
14	1		*BOOTLID TOYOTA LOGO	Necessary	66.00 F	*49.20 FL
15	1		*EMBLEM ELEGANCE	Necessary	74.25 F	*40.25 FL
16	1		*EMBLEM COROLLA	Necessary	74.25 F	*38.90 FL
17	1		*EMBLEM ALTIS	Necessary	72.49 F	*43.20 FL
18	1		*BOOTLID WEATHERSTRIP	Crushed	209.00 F	*155.60 FL
19	1		*REAR BOARD COVER INNER	Missing	324.50 F	*188.70 FL
20	1		*SPARE TYRE COMPARTMENT PANEL	Serviceable	968.99 F	*- FL
21	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*SET REAR BUMPER SENSOR	Shorted	284.90 FS	*200.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
24	1		*REAR END PANEL CENTER GARNISH INNER	Crushed	222.97 F	*148.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 6,557.34 2,449.78
 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00 544.95

Total Parts (S\$) 6,557.34 1,904.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ANTI-RUST COATING	New	80.00	40.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,200.00	900.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,000.00	800.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	100.00	30.00
5	REMOVE AND REPLACE REAR BUMPER SENSOR	New	100.00	20.00
6	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	100.00	30.00
7	TO MOUNT VEHICLE ON TO CHASSIS ALIGNMENT BENCH	New	280.00	0.00
Gross Labour Cost (S\$)			2,860.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >