

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

Not Authorized  
21/10/18  
2/5 #8000/  
Gdy. take photo after up.

VEHICLE NO :SGY 800T

| QTY   | PARTICULAR                                     |                 |                         |
|-------|------------------------------------------------|-----------------|-------------------------|
| 1 PCS | FRONT DOOR O/S                                 | 945.50          | 20/200                  |
| 1 PCS | FRONT DOOR OUTER HANDLE O/S                    |                 | SCU \$1,650.00          |
| 1 PCS | FRONT DOOR INNER LOCK O/S                      |                 | SCU \$366.50 X          |
| 1 PCS | FRONT DOOR INNER RUBBER LOWER O/S              | 115.30          | SCU \$399.20 X          |
| 1 SET | FRONT DOOR FRAME STICKER O/S                   | 68.20           | SCU \$211.20            |
| 1 PCS | FRONT DOOR MIRROR ASSY O/S                     | 550.50          | SCU \$105.00            |
| 1 PCS | FRONT DOOR MIRROR COVER O/S                    | 50.20           | CR/AGE \$1,020.00       |
| 1 PCS | REAR DOOR O/S                                  | 921.20          | SCU \$145.00            |
| 1 PCS | REAR DOOR OUTER HANDLE O/S                     | 248.50          | SCU \$1,450.00          |
| 1 PCS | REAR DOOR INNER LOCK O/S                       | 311.20          | CR/AGE \$366.50         |
| 1 PCS | REAR DOOR INNER RUBBER O/S                     | 115.20          | 20/200 \$399.20         |
| 1 SET | REAR DOOR FRAME STICKER O/S                    | 68.20           | SCU \$215.20            |
| 1 PCS | REAR DOOR INNER TRIM BOARD O/S                 | 491.20          | SCU \$105.00            |
| 1 PCS | REAR DOOR GLASS REGULATOR                      |                 | SCU \$688.20            |
| 1 PCS | REAR DOOR GLASS REGULATOR MOTOR O/S            | complete 428.20 | SCU \$311.20 X          |
| 2 PCS | REAR DOOR HINGES @\$195.00                     | 65x2=130        | SCU \$450.50            |
| 1 PCS | REAR DOOR CHECKER O/S                          | 62.20           | SCU \$390.00            |
| 1 PCS | REAR FENDER O/S                                | 1021.20         | SCU \$125.00            |
| 1 PCS | REAR FENDER INNER TRIM BOARD O/S               |                 | SCU \$1,280.50          |
| 1 PCS | REAR FENDER GLASS O/S                          | 725.50          | SCU \$615.00 X          |
| 1 PCS | REAR FENDER SPLASH SHIELD O/S                  |                 | SCU \$850.00            |
| 1 PCS | REAR BUMPER                                    | 1050.20         | SCU \$148.20            |
| 1 PCS | REAR BUMPER SIDE HOLDER O/S                    |                 | SCU \$1,250.00          |
| 1 SET | REAR BUMPER CLIPS                              |                 | SCU \$66.50             |
| 1 PCS | TAILLAMP O/S                                   |                 | SCU \$50.00             |
| 1 PCS | REAR SHOCK ABSORBER O/S                        | 315.30          | SCU \$450.50 X          |
| 1 PCS | REAR WHEEL HUB BEARING O/S                     | 450.50          | SCU \$392.50            |
| 1 PCS | REAR AXLE BEAM                                 |                 | SCU \$685.10            |
| 1 PCS | ROCKER PANEL GARNISH O/S                       |                 | SCU \$1,685.00 X        |
|       |                                                | 8329.60         | SCU \$665.00 X          |
|       |                                                | 6663.68         | \$16,536.00             |
|       | S.NETT                                         |                 |                         |
| 1 SET | DOOR VISOR o/s                                 |                 | SCU \$120.00 80         |
| 1 PCS | REAR FENDER GLASS SEALANT O/S                  |                 | SCU \$50.00 40          |
| 1 PCS | REAR SPORT RIM O/S                             |                 | 20/200 \$1,050.00 480   |
| 1 PCS | REAR TYRE O/S                                  |                 | CR/AGE \$200.00 602 120 |
| 1 SET | REAR BUMPER REVERSE SENSOR                     |                 | SCU \$250.00 X          |
|       | LABOUR CHARGES                                 |                 |                         |
|       | TO CHECK WIRING                                |                 | \$80.00 20              |
|       | TO DISMANTLE & REFIX REAR REVERSE SENSOR       |                 | \$80.00 50              |
|       | TO DISMANTLE & REFIX CUSHION UPHOLTSTERY       |                 | \$120.00 80             |
|       | TO TRANSFER BOTH O/S DOOR MECHANISM            |                 | \$180.00 120            |
|       | TO CONDUCT WHEEL ALIGNEMENT                    |                 | \$120.00 60             |
|       | TO DISMANTLE & REPLACING REAR UNDERCARRIAGE    |                 | \$380.00 250            |
|       | TO DISMANTLE & REPLACING REAR FENDER GLASS O/S |                 | \$120.00 100            |
|       | TO SPRAY RUST PROOFING                         |                 | \$150.00 90             |

LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

\$1,280.00 850  
\$1,600.00 1000  
TOTAL \$22,316.00

1000368  
P002

KK Auto Consultants hence notified  
of the following  
part(s) and/or  
subject to the following  
conditions and  
terms of  
the contract.