



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel:6702 4282 Fax:6702 4202

TPAIG
VIC

KMHDI41CMEU129409.

Page No. 1

Vehicle No. SKN2910G HYUNDAI ELANTRA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BONNET		1602.50	+
2	FRONT BONNET HINGE LH & RH @\$121.00	new	242.00	+
1	FRONT BONNET LOCK		185.70	+
1	FRONT BUMPER	Rehd	721.40	495
2	FRONT BUMPER SIDE RETAINER LH & RH @\$65.80	new	131.60	70
2	FRONT BUMPER SIDE BRACKET LH & RH @\$70.30	new	140.60	+
2	FRONT BUMPER FOGLAMP COVER LH & RH @\$211.00	new	422.00	+
1	FRONT BUMPER SPONGE	emlet	152.20	+
1	FRONT BUMPER REINFORCEMENT	new	715.20	+
1	FRONT BUMPER LOWER AIR GRILLE		410.20	+
2	FRONT HEADLAMP LH & RH @\$1482.30	Btt Cntd	3688.80	1482.30
2	FRONT HEADLAMP BRACKET LH & RH @\$152.30	new	304.60	+
1	FRONT GRILLE LOGO	new	71.00	+
1	FRONT CHROME GRILLE	Cntd	460.20	336
2	FRONT FENDER LH & RH @\$456.20		912.40	+
2	FRONT FENDER INNER SHEILD LH & RH @\$146.3		292.60	+
1	FRONT SUPPORT PANEL	new	959.30	+
1	FRONT RADIATOR		658.00	+
1	FRONT A/C CONDENSER		856.00	+
1	REAR BOOTLID	Distd	1188.70	+
1	REAR BOOTLID LOGO	new	61.00	+
2	REAR BOOTLID LAMP LH & RH @\$355.00	LH ut, RH Cntd	710.00	+
1	REAR BOOTLID LOCK	Dmgd	210.00	+
1	REAR BOOTLID INNER TRIM BOARD	Cntd	290.00	+
1	REAR BOOTLID WEATHERTRIP	ut	125.80	+
1	REAR BOOTLID HINGE LH & RH @\$189.60	Btt	379.20	234
1	REAR BUMPER	Distd	953.70	489
1	REAR BUMPER LOWER	Rehd	241.00	+
2	REAR BUMPER SIDE RETAINER LH & RH @\$79.00	new	158.00	70
2	REAR BUMPER BRACKET LH & RH @\$82.60	new	165.20	+
1	REAR BUMPER REINFORCEMENT	Cntd	441.10	346
1	REAR BUMPER REINFORCEMENT BRACKET	Btt	176.90	+
1	REAR BUMPER UNDER COVER	new	81.00	+
1	REAR BUMPER INNER KEYLESS SENSOR	Cntd	228.00	85
1	REAR BUMPER INNER SPONGE	new	162.80	+
1	REAR BUMPER MUD FLAP LH & RH @\$75.20	new	150.40	+
2	REAR TAILLAMP LH & RH @\$729.60	LH Cntd, RH Cntd	1459.20	727
1	REAR END PANEL	Rehd	485.90	+
1	REAR END PANEL TOP GARNISH	Rehd	203.10	+
1	REAR FENDER INNER TRIM BOARD LH & RH @\$549.20	torn	1098.40	535
2	REAR FENDER LH & RH @\$771.50	new	1543.00	+
1	REAR SPARE TYRE PANEL	new	982.00	+
1	REAR SPARE TYRE PANEL TOP COVER	Rehd	280.00	+
1	REAR SPARE TYRE PANEL SEALANT	new	450.00	200(SW)

908490
7267.92

SPECIAL NETT ITEMS

1 SET	FRONT CAR PLATE WITH HOLDER	calc
1 SET	FRONT BUMPER CLIPS	re
1 SET	FRONT FENDER COWLING CLIPS	re -
1	REVERSE SENSOR	200.00
1	REVERSE CAMERA	re re
1 SET	REAR BUMPER CLIPS	re
1 SET	REAR CAR PLATE WITH HOLDER	calc
1	REAR END PANEL SEALANT	re
1 SET	REAR END PANEL TOP GARNISH CLIPS	re
1	COOLANT	the re

less	20%	25150.70	
		5030.14	20%
		20120.56	
		70.00	60
		80.00	30
		100.00	+
		280.00	200
		350.00	+
		100.00	70
		70.00	60
		100.00	60
		80.00	10
		100.00	+
Total Parts		21380.56	

450



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SKN2910G HYUNDAI ELANTRA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	1000
3	To remove and refix wiring at damaged areas	100.00	60
4	To perform anti rust treatment on affected areas	200.00	60
5	To remove and replace reverse sensors and check for proper functions	120.00	50
6	To remove and refix rear boot mechanism	150.00	60
7	To top up coolant	120.00	x
8	To tuff coat	100.00	60
	Labour Total :	3990.00	
	TOTAL (PARTS & LABOUR):	25370.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/c 21/10/19.

10 Days

total 16407.52

L/S: 7k (Nett Value) ✓

10 Days ✓