LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4

Singapore 038986

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Josey Loh Date: 22 Oct 2019

Preliminary Advice

Insured Vehicle No : SLC8840G

TP Vehicle No : SKV814Y Accident Date : 17/10/2019

Make : KIA FORTE K3 Assignment Date : 22/10/2019

Date of Inspection : 21/10/2019 Est. Duration of Repair : 9 days

Inspection At : Elite Automotive Pte Ltd (HQ)

280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands

Singapore 757322

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront and rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,474.10
Revised Amount	:S\$	11,001.60
Check Items (Estimated)	:S\$	4,829.40
Total	:S\$	15,831.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.