



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19018658/Atd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMB 65Z	Veh. Inspected	FV 8060L
Policy No.		Coverage (\$)	0.00
Claim No.	D19/3484/SMRT	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	21/10/2019

2. Vehicle Particulars & Condition

Make & Model	KAWASAKI KRR	c.c	148
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	KR150KA55124	Colour	BLACK
Odometer	121884	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/80 R17	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/80 R17	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/05/2019	Inspection Date	26/11/2019
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**