

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 October 2019

To : LKK

By Fax: 6256-4315

Attn: *Buyer*

Tel:

VEHICLE NO : JQH 1173

Yamaha LC 135

ACCIDENT DATE: 27 September 2019

Description	Qty	Quotation \$
1 Handle Bar <i>2x4</i>	1	135.00 <i>✓</i>
2 Head Lamp <i>Cut</i>	1	280.00 <i>✓</i>
3 Head Lamp Cover <i>Cut</i>	1	180.00 <i>✓</i>
4 Front Cover <i>Cut</i>	1	145.00 <i>✓</i>
5 Front Signal LH <i>broken</i>	1	65.00 <i>✓</i>
6 Leg Shield <i>cut</i>	1	135.00 <i>X</i>
7 Front Mudguard <i>run</i>	1	250.00 <i>X</i>
8 Fork Under Bracket <i>2 Down</i>	1	135.00 <i>✓</i>
9 Front Fork <i>2x down (1st)</i>	1 set	480.00 <i>✓</i>
10 Front LH Side Fairing <i>broken</i>	1	135.00 <i>✓</i>
11 Gear Pedal <i>NH</i>	1	65.00 <i>X</i>
12 Front Footrest <i>NH</i>	1	75.00 <i>X</i>
13 Footrest Rubber <i>NH</i>	1	55.00 <i>X</i>
14 Mirror <i>broken ops</i>	1 set	135.00 <i>✓</i>
15 Brake Lever <i>Cut</i>	1	65.00 <i>✓</i>
16 Front RH Fairing <i>Cut</i>	1	155.00 <i>✓</i>
17 Exhaust Guard <i>Cut</i>	1	185.00 <i>✓</i>
18 Pillion Grip <i>Cut</i>	1	65.00 <i>✓</i>
19 Rear RH Footrest <i>Cut</i>	1	78.00 <i>✓</i>
20 Meter Cover <i>2x NH</i>	1	210.00 <i>X</i>
21 LH Fairing Inner Garnish <i>Cut</i>	1	158.00 <i>✓</i>
22 Front Rim <i>run</i>	1	325.00 <i>X</i>

Sub-Total 3,511.00

Less 10% 351.10

Sub-Total 3,159.90

23) Radiator Assy - *350.00 ✓*
4/1/2020

VEHICLE NO : JQH 1173

Yamaha LC 135

Nett Items

- 1 Front number plate - 1 set *NLG*
- 2 Rear number plate *NLG*
- 3 Towing fee *NLG*
- 4 Remove & replace necessary parts, align & etc
- 5 Remove & replace fork assy, rim & top up fork oil
- 6 Supply body decal sticker

25.00 *15/-*
15.00 *X -*
40.00 *X*
~~280.00~~ *200/-*
~~150.00~~ *80/-*
~~120.00~~ *80/-*

Sub-Total

630.00

Nett Total

3,789.90

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you

S9 MOTOR TRADING PTE LTD

LG

22/10/2019 @ 1600pm

Nbt Andro

2/Sum 4 days

ya

LKK Andro

LKK & Consultants - hence notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check Sum insured.