72/03/2002 -					
ASS. REC. BY	7:	REF: (S/A61	190187001 1	Ay f3 Spe	cial Instruction:
Surveyor :	Adrian		MENT (Office	e) (9	
From (Person). Ivy Ratilla	of	AG1	Asset Transfer	Date/Time; 21.10.19 4.24p.m
Estimated To	st:		Bill to:		Date/Time;
OD TPIN	S/TP RES/OD R	ES/EVA/INV/M	DIII (0		
To Inspect Vo	ehicle No:	22 9457C	7 7 CB	Insured:	sks 19152
at Workshop	m/s N-51 Au	ometive			67410510
of 2 kaki	Bukit Ava	2-901-18		lei:_	07410510
Policy No:			CI.: N	C IOAn	217
Sum Insured:				C 10004	1564
Make of Veh			Excess:		
(Client's Record				I	0.0.A.
CA / REV	/ REP. / REV 241	IRS			
Date/Time:	410.19 53 op. w	Person Contacte	. Zi Tih		H.O.D. Endorsement:
			30.	· · · · · · · · Ve	hicle IN JOUT
Date/Time	Action/Instruction	(V) Estim	ate.		
	SLZ 94570	- ×			
	SKS 1915Z -	CC 3/ AIG 150	65837/RW3	92 DI	0A-05704/2015
		<u> </u>		1	14 + 05/04/ 2019
	<u> </u>				
· · · · · ·	 				

ASSI	CINIT	1/1	GN	•
433	T X	VII	1,18	
LALJIJA	· · ·	1		-

From: Date: 23.10.2019	Veh No: SLZ5457C . Yr Regn: 2018 / May.
Estimated Cost:	Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLZ 9457C	Make: Toysta Sients c.c 1496. Colour Black A/C: Insured/Std/NI/NA
at Workshop m/s N-51 Autonom	
of 2 kgri Burt Ave 2 401-18	Sp.Reading (25699, T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: NHP 170724399 .
Claims No.	Gen. Conde Good) Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed Leaked Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 185 (60 R15
(Policy Condition)	R: 185/60R15.
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOIYOKO or Habilead
Bal. or Market Value:	Front Rear R/Bal 06 mm R/Bal. 06 mm
IDAC Accident Rport: Consistent? : Yes or No	7
GIA / PR Seen: Consistent? : Yes or No	D.O.A. D.O.I. 23/10/19
Est. Repairs: days Res.: Yes or No	2/5/
Lum Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S U/O / Rooftop or
CA / REV / REP. / 24 HRS	
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
TP Budget Direct.	•
0	
mv: 781c Pv:40.96	
Net 1 37.11c.	
45 \$24,500 = (Red:	524183-65,49%)
	, , , , , , , , , , , , , , , , , , , ,
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 18
- Final Papart	Resurvey No. of Trip: 4 Survey Fee:
Date/Time, File Return to?	Transportation:
2) 27/4/20 Typist Add Fe	ee: : Site Insp (\$)S+RSSI
	: Interview (\$) Photos
Rep Former:	:Tech. Invs (\$) Others
(1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	:Weelend (%
	TOTAL

Summer Lee (LKK Auto)

From:

Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Sent:

Tuesday, 22 October, 2019 4:22 PM

To: Cc: Admin-D (LKKAuto) SUR; Julie Mangubat

Subject:

TPPD Survey: Claim ref:C10004367/JM || OI- SKS1915Z (Black) TP- SLZ9457C ||

Est:0.00 || N-51

Attachments:

9457.pdf

Hi Team,

We would like to arrange TP PRS for SLZ9457C please. They have chosen Mr. Adrian Ling to survey the vehicle.

Please confirm.

Thank you.

Regards,

Ivy Ratilla Executive, Claims Admin

T +65 6540 2185 F +65 6725 0853 E <u>ivy.r@budgetdirect.com.sg</u>



Trusted Service Award

Customer Care +65 6221 2111 Claims +65 6221 2199 Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924 budgetdirect.com.sq



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **<u>Budget</u> <u>Direct Insurance</u>**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Chio Ziting <ziting@n51.com.sg> Sent: Tuesday, 22 October 2019 12:05 PM To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Subject: Re: SLZ9457C & SKS1915Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2

WORKING DAYS | | C10004367

Dear Sir / Madam,

We appoint your surveyor Mr Adrian Ling - LKK

Please see attached.

Thank you.

Regards, Zi Ting N-51 Automotive Pte Ltd Office: 6842 0051 Fax: 6741 0510

www.n51.com.sq

From: Chio Ziting < ziting@n51.com.sg
Sent: Tuesday, 22 October 2019 10:52 AM
To: Claims < claims@budgetdirect.com.sg

Subject: SLZ9457C & SKS1915Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING

DAYS

Dear Sir/Madam,

As per above subject,

Please refer to attachment and:-

Kindly propose / provide your 10 surveyors	
Thank you.	
Regards,	
Zi Ting	
N-51 Automotive Pte Ltd	
Office: 6842 0051	
Fax: 6741 0510	
www.n51.com.sg	
)

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

- ~		-		1				7/1	- 0	۱'n	т
- (•7	.,		и I		va.	TΕ	W			и
	-			_	_		_	-			

 Date Of Report
 21/10/2019 16:46

 Date Of Accident
 20/10/2019 23:00

Exact Location Of Accident JUNC OF YIO CHU KANG RD / LENTOR RD

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ9457C

Insured/Policyholder

Name Of Registered Owner GRAB RENTALS PTE LTD

Co Reg No 201617200G Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-31388644

Vehicle Particulars

Manufacturer TOYOTA

Model SIENTA HYBRID-1.5 X CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number A29114756MKF

Cover Note Number

Driver

Name of Driver LEONG POW CHING

 NRIC No
 \$1800453D

 Date Of Birth
 31/12/1950

 Occupation
 OUTDOOR

 Date Of Driving Pass
 04/04/1979

Driving Experience 40 YEARS AND 6 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-91464240

Fax Number

Contact Number

EMail Address NOEMAIL

Address

BLK 437 YISHUN AVE 6 #04-2066

Postcode

760437

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - LESSEE

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: NOT APPLICABLE

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

ANG MO KIO POLICE DIVISIONAL HQ (F DIVISION)

ROAD: 51 ANG MO KIO AVENUE 9, POSTCODE: 569929, COUNTRY:

Police Station Address

SINGAPORE TEL NO: 1800-2180000 - FAX NO: 64814246

Police Station Contact

NO

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO. F/20191021/7032

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

SD CARD WITH WORKSHOP

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKS1915Z

Vehicle Make/Model/Colour

VOLKSWAGEN / JETTA

Details Of Properties

VEH B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

97321806

Page 2 of 27

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEONG POW CHING

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLZ9457C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

(DRIVER)

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Oriver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

ETCH PLAN			
I YIO CHU KANG ROAD			
→			
→		A	SLZ 9417
		В	sksiais z
ANTBI	4-		
1	-		
LESTICE ROAD			
CRIBE CIRCUMSTANCES OF THE ACCIDENT			
REFER TO POLICE READS 7/2019/03/ 4032	10		
	alus		
	21/10/2	2019	
	7 1-1		
	3.51	TM	
	******	The same of the sa	mida ili ili ili ili ili ili ili ili ili il
	- The state of the		

Policyholder's Signature Date & Time: Driver's Signardy (If driver's not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Police Report





1 of 2

POLICE REPORT (NP299)

Police Station Of Origin Ang Mo Kio Division HQ 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No:1800-2180000

Report No. F/20191021/7032

Date/Time Report Made	Vide Report No.		Station Diary No			
21/10/2019 14:32				4		
Name Of Informant	Address					
LEONG POW CHING	APT BLK	437 YISH	UN AVENUE 6 #0	4-2066		
	SINGAPORE 760437					
ID Type / ID No.	Contact N	lo.				
NRIC NO / S1800453D	Home/Office: Mobile:					
	98558319					
Nationality	Email Add	dress				
SINGAPORE CITIZEN	shirleyjon	g80@gma	il.com -			
Occupation	Sex	Age	Date of Birth	Race		
PART-TIME TAXI DRIVER	Female	68	31/12/1950	Chinese		
Institution/School Name	Language English	•				
Date/Time Of Incident	Location Of Incident					
20/10/2019 23:00 - 20/10/2019 23:30	LENTOR	ROAD				

Brief details.

On 20th October 2019 around 2300h, I was waiting at the T-Junction turning right into Lentor Road. I began turning right when the traffic light turned red. Suddenly, a vehicle beat the red light and hit my vehicle. As I was not feeling well from the impact, I went to seek medical attention for my injuries. I was given 3 days medical leave.

Subjects Involved Victim	
Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 21/10/2019 14:32
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Police Report





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20191021/7032

Person Name	LEONG POW CHING			
ID Type	NRIC NO	ID No	S1800453D	
Gender	Female	Age	68	
Race	Chinese	Language	English	
Occupation	PART-TIME TAXI DRIVER	Address Type		
Address	APT BLK 437 YISHUN AVENUE 6 #04-2066 SINGAPORE 760437	Mobile No	98558319	
Is Informant A Victim?	Yes			
Person Name	LEONG POW CHING (Inform	ant)		


Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 21/10/2019 14:32
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	200G	
Mahrie Daville		
Vehicle No.:	SLZ9457C	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	23 Oct 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	SIENTA HYBRID 7-SEATER 1.5X CVT	
Primary Colour:	Black	
Manufacturing Year:	2018	
Engine No.:	1NZ8531357	
Chassis No.:	NHP1707124399	
Maximum Power Output:	73.0 kW (97 bhp)	
Open Market Value:	\$22,683.00	
Original Registration Date:	23 May 2018	
First Registration Date:	23 May 2018	
Transfer Count:	1	
Actual ARF Paid:	\$13,757.00	
Intended PARER (Interestal Section 1994)		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	22 May 2028	
PARF Rebate Amount:	\$10,317.00	
Interiera (99) : Ruba (630) (chiis		
COE Expiry Date:	22 May 2028	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$38,200.00	
COE Rebate Amount:	\$30,560.00	
Total Rebate Amount:	\$40,877.00	

The information contained herein is correct as at 23 Oct 2019



Compare [4] el Type: Petrol-Electric

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

TP Bridget Direct. Yome

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019 Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng#: NHP1707124399/1NZ8531357

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON COMPRESSOR Me M	1	2755.00	2,755.00 ×
AIRCON CONDENSER Bet	1	1138.00	1,138.00
AIRCON CONDENSER ALUMINIUM PIPE F HE NEC	1	677.00	677.00 ×
AIRCON CONDENSER SUCTION PIPE	1	484.00	484.00 +
CENTER PILLAR LH	1	364.00	364.00 +
DASHBOARD (LOWER) 7 Deld	1	596.00	596.00
DASHBOARD (TOP)	1	791.00	791.00
DASHBOARD GLOVE COMPARTMENT	1	317.00	317.00
DASHBOARD INSTRUMENT PANEL Z	1	690.00	690.00
DASHBOARD REINFORCEMENT	1	577.00	577.00 /
FAN COWLING ME ME	1	281.00	281.00 X
FRONT BONNET	1	656.00	656.00
FRONT BONNET HINGES L/R 7 Me m	2	67.00	134.00
FRONT BONNET MECHANISM LOCK	1	97.00	97.00 X
FRONT BRACE PANEL Best	1	128.00	128.00
FRONT BUMPER Dela	1	581.90	581.90
FRONT BUMPER FOGLAMP GARNISH L/R	2	156.50	313.00
FRONT BUMPER GRILLE	1	840.00	840.00

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

FRONT BUMPER LOWER LID DISULD	1	293.00	293.00
FRONT BUMPER SIDE RETAINER L/R	2	67.50	135.00
FRONT BUMPER SPONGE CAULD	1	137.50	137.50
FRONT BUMPER TOP RIBBER MOULDING MEN	1	62.50	62.50 🗶
FRONT BUMPER UNDER COVER TOTAL	1	125.00	125.00
FRONT ENGINE CROSSMEMBER Best	<u>I</u>	1618.00	1,618.00
FRONT ENGINE CROSSMEMBER SIDE RAIL L/R 14 n	2	297.00	594.00 +
FRONT ENGINE UNDER COVER LH tom	Ĭ	125.00	125.00
FRONT ENGINE UNDER COVER RH ton	1	125.00	125.00
FRONT FENDER 'HYBRID' EMBLEM L/R	2	59.00	118,00 59
FRONT FENDER INNER SHIELD L/R +OIN	2	167.00	334.00
FRONT HEADLAMP L/R Cruld	2	978.00	1,956.00
FRONT HEADLAMP TOP PANEL LH	1	135.70	135.70 +
FRONT KNUCKLE ARM BEARING L/R	2	107.00	214.00
FRONT KNUCKLE ARM L/R Por	2	404.00	808.00
FRONT LH ABS SENSOR	1	379.00	379.00 ~
FRONT LH CHASSIS MEMBER OUTER PANEL	Ī	229.00	229.00 +
FRONT LH DOOR Distorted.	1	1112.00	1,112.00

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

	4.		
FRONT LH DOOR CHECKER Best	1	125.00	125.00
FRONT LH DOOR FRAME OUTER GARNISH (VERTICAL)	1	93.00	93.00
FRONT LH DOOR FRAME OUTER MOULDING RIVET	10	12.00	120.00
FRONT LH DOOR GLASS CHANNEL	1	133.00	133.00 /
FRONT LH DOOR GLASS CHANNEL WEATHER STRIP	1	133.00	133.00
FRONT LH DOOR GLASS OUTER MOULDING	1	77.00	77.00
FRONT LH DOOR GLASS REGULATOR	1	183.00	183.00
FRONT LH DOOR GLASS REGULATOR MOTOR , Le N	1	575.00	575.00 +
FRONT LH DOOR HINGE (LOWER) ?	1	67.00	67.00
FRONT LH DOOR HINGE (TOP)	1	67.00	67.00
FRONT LH DOOR INNER RUBBER GUIDE STOPPER	2	15.00	30.00
FRONT LH DOOR INNER SPEAKER (m)	1	375.80	375.80
FRONT LH DOOR INNER TRIM BOARD	1	1077.00	711 (1,017.08)
FRONT LH DOOR MECHANISM LOCK	1	657.00	373 657.00
FRONT LH DOOR PILLAR (CENTER)	1	395.00	395.00 X
FRONT LH DOOR PILLAR (INNER)	1	387.00	387.00 +
FRONT LH DOOR PILLAR (OUTER) Device	1	387.00	387.00
FRONT LH DOOR PILLAR INNER GARNISH Dela	1	98.00	98.00

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

	6		
FRONT LH DOOR WEATHER STRIP W	1	271.00	271.00
FRONT LH DRIVE SHAFT 3ext	1	1336.00	1,336.00
FRONT LH FENDER Distorted	1	551.00	551.00
FRONT LH FENDER INNER PANEL	1	574.00	574.00 ×.
FRONT LH FENDER INNER SHIELD (VERTICAL)	1	79.30	79.30
FRONT LH FENDER QUATER GARNISH Could.	1	58.50	58.50
FRONT LOWER ARM L/R Best	2	497.00	994.00 🗸
FRONT SHOCK ABSORBER L/R Bet	2	417.00	834.00
FRONT SHOCK ABSORBER TOP MOUNTING L/R	2	115.00	230.00
FRONT STABILIZER BAR Best	1	315.00	315.00
FRONT STABILIZER LINK L/R	2	107.00	214.00
FRONT STEERING RACK AND PINION BUT	1	1587.00	1,587.00
FRONT SUPPORT PANEL Buckerd	1	1097.00	1,097.00
FRONT TIE ROD END L/R LIT SENT	2	107.00	214.00 107
FRONT WHEEL HOUSING LH Review	1	574.00	574.00 X
FRONT WHEEL HUB CAP L/R HT PMC	2	174.00	100(SN3)48.00
FRONT WHEEL L/R Lit Bent	2	200.00	400,00 200
FRONT WINDSCREEN PILLAR GARNISH LH H	1	197.00	197.00 \

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Λ \)		
FRONT WIPER GARNISH	1	625.00	625.00
FRONT WIPER GARNISH SIDE COVER LH	1	49.00	49.00
RADIATOR (AUTO) Not NEW	1	2135.00	2,135.00 ×
REAR AXLE Best	1	1933.00	1,933.00
REAR BUMPER Deland	1	950.00	485 950.00
REAR BUMPER END SEAL COVER LH	1	124.00	124.00 🗡
REAR BUMPER REFLECTOR GARNISH LH &	1	90.00	90.00
REAR BUMPER SIDE RETAINER L/R LH Pod	2	90.00	180.00
REAR LH DOOR Distorted.	1	979.00	979.00
REAR LH DOOR CENTER HINGE NA MA	1	127.00	127.00 \(\)
REAR LH DOOR CENTER WEATHER STRIP (VERTICAL)	1	77.00	77.00 +
REAR LH DOOR FRAME OUTER GARNISH (FRONT) (VERTICAL)	1	95.00	95.00 F
REAR LH DOOR FRAME OUTER GARNISH (REAR) (VERTICAL)	1	93.00	93.00
REAR LH DOOR GLASS OUTER MOULDING MM	1	89.00	89.00 ×
REAR LH DOOR GLASS REGULATOR Dond	1	183.00	183.00
REAR LH DOOR GLASS REGULATOR MOTOR	1	575.00	575.00 ×
REAR LH DOOR INNER RUBBER STOPPER MM	2	15.00	30.00
REAR LH DOOR INNER TRIM BOARD De ford	1	1017.00	779 1,017.00
			117

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

REAR LH DOOR LOWER MECHANISM LOCK Dunch	1	575.00	575.00
REAR LH DOOR LOWER ROLLER HINGE Best	1	167.00	167.00
REAR LH DOOR LOWER ROLLER HINGE LOCK HE M	1	298.00	298.00 ×
DEAD AND DOOR MECHANISM LOCK (EDONT) ?	1	571.00	571.00×
REAR LH DOOR MECHANISM LOCK (REAR)	1	971.00	971.00 X
REAR LH DOOR PROTECTOR W	1	225.00	225.00
REAR LH DOOR UPPER ROLLER HINGE Best	1	107.00	107.00
REAR LH DOOR WEATHER STRIP Lt	Ĭ	165.00	165.00
REAR LH FENDER Dented	1	757.00	757.00
REAR LH FENDER ARCH GARNISH LAT	1	107.00	107.00
REAR LH FENDER INNER SHIELD HE ML	+ 1	53.00	53.00 X
REAR LH SHOCK ABSORBER BENT	1	168.00	168.00
REAR LH SLIDING DOOR ELECTROMOTIVE MOTOR Dand	1	2098.00	2,098.00
REAR LH WHEEL Ne M	1	321.00	321.00
REAR LH WHEEL BEARING	32332	671.00	671.00
REAR LH WHEEL CAP	24249 1	174.00	174.00
REAR TAILLAMP LH Not Now	1	425.00	425.00 +
20 24	SN: 200		

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Subtota	l before discount		51,978.20
Percentage discount 25%			12,994.55
	Sub-total 1	-	38,983.65
FRONT BUMPER CLIPS - SET HW	1	80.00	80,00 30
FRONT FENDER INNER SHIELD CLIPS L/R - SET du	2	40.00	80.0060
FRONT LH DOOR FRAME OUTER GARNISH (VERTICAL) CLIPS - SET	1	30.00	30,00/0
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50,06 30
FRONT TYRE L/R We M	2	350.00	700.00 🔀
FRONT WINDSCREEN PILLAR GARNISH CLIPS LH - SET	1	50.00	50.00 X
FRONT WINDSCREEN SEALANT HER	1	80.00	80.00 +
FRONT WIPER GARNISH CLIPS - SET NW	1	50.00	50.00 3
REAR BUMPER CLIPS - SET NW	1	80.00	89,86 30
REAR LH DOOR INNER TRIM BOARD CLIPS - SET NW	1	50.00	59.06 30
REAR LH DOOR PROTECTOR CLIPS - SET New	1	30.00	30.00 /0
REAR LH FENDER ARCH GARNISH CLIPS - SET	1 240	20.00	20.00 10
REAR LH FENDER INNER SHIELD CLIPS - SET 人んし M	1	50.00	50.00 X
REAR LH TYRE AR M	1	350.00	350.00

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No.: +65 6842 0051 Fax No.: +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Contact: 66550005-GRAB 91464240

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code: CLM15673

Date in: 21/10/2019

Vehicle Num.: SLZ9457C

Model: TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng#: NHP1707124399/1NZ8531357

1,700.00	Subtotal before discount	
0.00		Percentage discount 0%
1,700.00	Sub-total 2	
40,683.65	Parts-total	

LABOUR	5 1	
LABOUR		
To remove, change air con parts, vacuums, refill air con gas.		149.00 120
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)		89.86 30.
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.		100.00 70
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.		480.00 450
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.		400.00 300
To road test driving, check and resetting wheel alignments system.		149.06 80
To remove, reinstall petrol tank. (to FR)		80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140,00 100
To remove front scat, dismantle. (Allowing to repair, align seat rest frame and seat base.)		140.00 ×
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	100 E.	160.00
To remove, change dashboard fascia and transfer where necessary.	5930	409.06 220
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		2,400.00 1800
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and realign body structure, body alignments and damaged consistent to the accident.	told: 30619	3,200.00 2400
To apply anti-rust chemical on repaired and replaced panel.	h S 74-1-	149.60 120
Labour Total	18 Days	8,000.00

Parts & Labour Total

48,683.65