

Supervisor: GQ ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong of SMD Date/Time: 23.10.19 10.029.11

meriman

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGZ 108D Insured: SJY 8563P

at Workshop m/s Auto Wheels motorworks Tel: 97684247

of NO 1 Bukit Batok Crescent #02-40

Policy No: DMMTPRO1014346 Claim No: (MMD)1904966

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/10/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS mp' H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23/10/19 10.11.am Person Contacted: Louis Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	<u>SGZ 108D - X</u>
	<u>SJY 8563P - X</u>
<u>24/10/19</u>	<u>Send preli revised via meriman</u>
<u>31/10/19</u>	<u>LS \$4450 confirmed by email (Ref 16144.26, 7870)</u>

Ameyur

Gal

REF: SMO

ASSIGNMENT

(-2021)

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Auto wheels

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: ~~\$400k~~ 46k

IDAC Accident Rport. \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S68108D Yr Regn: 23 Apr 2011

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes c.c. 1796

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 102136 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD20744827048111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255 / 35 ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 23-10-19

Survey held at W/S 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COB: 37314 \$15k/year

RECEIVED 01 NOV 2019

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 31/10 - typist

Report Format: Merimen

Lump Sum / I.B.I.: (\$ 4450/-)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

- Add Fee:  : Site Insp (\$ )
- : Interview (\$ )
- : Tech. Invs (\$ )
- : Weekend (\$ )

TOTAL

450
11
461

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	GNOH PAU LOONG	Date:	24 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SJY8563P	Accident Date	: 19/10/2019
TP Vehicle No	: SGZ108D	Assignment Date	: 23/10/2019
Make	: MERCEDES-BENZ E200	Est. Duration of Repair	: 4
Date of Inspection	: 23/10/2019		
Inspection At	: AUTO WHEELS		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,594.26
Revised Amount	:S\$	6,877.54
Check Items (Estimated)	:S\$	1,782.09
Total	:S\$	8,659.63
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Oct 2019		23 Oct 2019 10:02 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: **ANG LAY KHENG**, ID: S7418727G, Tel: +6583555060, Email: CHUAMARKUS.0804@GMAIL.COM

Main Claimant: **TAN YEA FEN**, ID: S7869339H

Vehicle Reg. No.: **SGZ108D** Date of Loss: 19/10/2019 15:00 - :59

Claim Type: **TP / CMTD1904966** Policy/Cover Note No.: D19MTPV01014346  
(Comprehensive)

Vehicle Reg. No. (Insured): **SJY8563P** Policy No. (Claimant):  
Excess:

Repairer: **Auto Wheels Motorworks Pte Ltd (HQ)** No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247

Handling Insurer: **Sompo Insurance Singapore Pte. Ltd. (HQ)** - Tel: 6461 6555 ... [Handled by **GNOH PAU LOONG** - 63295217]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 04/11/2019]

Driver/Custodian (Insured): **ANG LAY KHENG (50 / Male)**, NRIC: S7418727G, Tel: +6583555060 Email: CHUAMARKUS.0804@GMAIL.COM

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 31 October 2019 3:48 PM  
**To:** louisongautowheels@yahoo.com; Guo Qiang (LKKAuto); SUR  
**Subject:** RE: Finalize for vehicle SGZ108D lumpsum \$5,500/- with 4 rep

Dear Louis,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to SOMPO INSURANCE

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Louis Ong <louisongautowheels@yahoo.com>  
**Sent:** Thursday, 31 October 2019 2:22 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: Finalize for vehicle SGZ108D lumpsum \$5,500/- with 4 rep

Hi Veron,

Amount confirmed.

Thanks

Auto Wheels Motorworks PTE LTD  
Louis Ong  
91928963

On Thu, 31 Oct 2019 at 12:04, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Louis,

WITHOUT PREJUDICE

Offer Lump Sum \$4450 @ 4 working days.

PARTS-\$4770 (less 10%)=\$4293

LABOUR-\$1270

TOTAL-\$5563 (less 20%)=\$4450.40

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Louis Ong <louisongautowheels@yahoo.com>

**Sent:** Wednesday, 30 October 2019 8:08 PM

**To:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>

**Subject:** Finalize for vehicle SGZ108D lumpsum \$5,500/- with 4 repair days.

Hi Guo Qiang,

The above attachment is the finalize and after paint photos.

Can help to finalize for vehicle SGZ108D lumpsum \$5,500/- with 4 repair days.

No Supplementary.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

## ▶ Mercedes Benz e200 Used Vehicle List (14 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Mercedes-Benz E-Class E200 CGI Coupe</b>	\$45,900	\$15,790 /yr	11-Jan-2011	1,796 cc	117,000 km	Prem Roy Motoring	Available
80% Loan Of The Car Price Available. 10 Year COE Renewal With 84 Months Loan Option Available. Consignment Unit, Whatsapp For Viewing Options. Well Maintained Unit. Office No. - 66028046 Prem Roy - 84684000   PRM Admin - 98896985							
<b>Mercedes-Benz E-Class E200 CGI</b>	\$44,555	\$14,330 /yr	14-Jan-2011	1,796 cc	-	DC Motors Pte Ltd	Available
One Of The Highest OMV Around, Lowest Depreciation, Most Repair And Parts Changed, Smooth Engine & Gearbox, High Trade In And High Loan Available, Guarantee Buy Back At \$30500 On The Very Last Day. Office No. - 66942711 Clement - 90258033							
<b>Mercedes-Benz E-Class E200 CGI Coupe</b>	\$49,000	\$16,820 /yr	28-Jan-2011	1,796 cc	149,000 km	STI Auto Trading	Available
Trade In And Loan Available. Office No. - 64892855 Richard - 96712965							
<b>Mercedes-Benz E-Class E200 CGI Cabriolet</b>	\$58,000	\$18,810 /yr	03-Jun-2011	1,796 cc	111,000 km	Bavarian Marques Pte Ltd	Available
Immaculate Iridium Silver Metallic E250 CGI Cabriolet For Sale! Contrasted With A Beautiful Sporty Red Interior With Full Leather Seats. Exceptional Upkeep & Maintenance By Careful Lady Owner. Full Se... Office No. - 67178811 Jeremiah - 98807671   Shawn - 88188544   Eugene - 81333924   Qai - 88148478							
<b>Mercedes-Benz E-Class E200 CGI Elegance</b>	\$49,500	\$14,360 /yr	23-Jun-2011	1,796 cc	97,000 km	Euro-Asia Motor	Available
Rare Find! 1 Owner With Authentic Low Mileage! Can Be Verified At C&C. Very Safe Buy. Must View! A Vehicle Not To Be Missed! Office No. - 65150595 Alexis Ong - 90275656   Alan Tan - 85338552   Keith - 97367333   Darren Tan - 93223322							
<b>Mercedes-Benz E-Class E200 CGI</b>	\$48,088	\$12,580 /yr	28-Jun-2011	1,796 cc	146,000 km	Creed Automotive LLP	Available
Consignment Unit. 1 Owner Cycle And Carriage Unit. Beautifully Maintained And Taken Care Inside Out. As Good As Almost New Car Condition. High Paper Value. Flexible Loan Schemes Available. Trade In We... Office No. - 96190677 Jason - 88479094   Jake Toh - 96190677   Sean - 97767865							
<b>Mercedes-Benz E-Class E200 CGI</b>	\$55,800	\$17,540 /yr	14-Jul-2011	1,796 cc	210,800 km	Car Search	Available
Extremely Well Maintained By Owner! Serviced And Maintained Regularly! Popular Mercedes Sedan Equipped With A Refined And Powerful 1.8L Turbo Engine Giving You A Powerful Daily Drive! Powerful Yet Fue... Office No. - 62620728 Ken - 93388994   Jack - 91416611   Rachel - 91126538   Justin - 91827511							
<b>Mercedes-Benz E-Class E200 CGI</b>	\$49,988	\$13,920 /yr	25-Jul-2011	1,796 cc	131,000 km	Cycle & Carriage.Fulco Motor Dealer	Available
Original Condition. Low Interest At 2.28%, Well Maintained And Trade In Welcome. Don't Miss This Deal! Contact Us Via Call/SMS To Arrange A Viewing Today! Office No. - 67468117 Paul Yong - 97694879   Alan Ng - 96710232							
<b>Mercedes-Benz E-Class E200 CGI Avantgarde</b>	\$45,800	\$14,040 /yr	26-Jul-2011	1,796 cc	152,051 km	Lake View Credit Pte Ltd	Available
Owner Consignment, E200 Avantgarde Edition! Amazing Low Mileage Clocked Of 15200km Annually. Confirm No Other Repairs Needed. Ideal For Future COE Renewal, Road Tax Till Jan 20. New Car Number. 100% A... Office No. - 67499895							



2019/10/23

Tong Hoe - 96433160 | Mr How - 97279995

**Mercedes-Benz E-Class E200 \$62,800** \$21,150 /yr 28-Jul-2011 1,796 cc - Leco Prestige **Available**  
**CGI**

Road Tax Till Jul 2019. Original Condition. Low Interest Rate Financing And Insurance Can Be Arranged. Call For Viewing.

Office No. - 64740566

Edison - 97277767 | Alvin Lem - 90021980 | Patrick Gong - 97127361 | Freddy Ang - 83777777

**Mercedes-Benz E-Class E200 \$50,000** \$14,020 /yr 05-Aug-2011 1,796 cc 127,058 km General Leasing Pte Ltd **Available**  
**CGI**

Office No. - 68441818

Vincent Lim - 91195688 | Steve - 98229717

**Mercedes-Benz E-Class E200 \$48,800** \$12,410 /yr 06-Sep-2011 1,796 cc 119,339 km Car (S) Pte Ltd **Available**  
**CGI**

1 Owner All The Way. From Cycle And Carriage. Beautifully Maintained And Taken Care Inside Out. As Good As Almost New Car Condition. High Paper Value. Accident Free, Safe Buy. Loan Schemes Available. ...

Office No. - 63863322

Song - 97654355 | Bond - 94389996 | Alan Goh - 91805058

**Mercedes-Benz E-Class E200 \$58,700** \$16,100 /yr 18-Oct-2011 1,796 cc 119,000 km Hua Hong Motoring **Available**  
**Avantgarde**

7G Avantgarde Model, Just Done Servicing. 100% Accident Free, Tip Top Engine And Gearbox Condition. C&C Unit! No Repairs Needed, View To Believe Its Genuine Tip Top Condition, Accident-Free, In-House ...

Office No. - -

Randy Chan - 96949339 | Terence - 81608080

**Mercedes-Benz E-Class E200 \$53,800** \$13,220 /yr 23-Nov-2011 1,796 cc 141,000 km Imperium Car Motor Pte **Available**  
**Ltd**

Bank And In House Full Loan Available. Brand New Paintwork. 100% Accident Free. No Repairs Needed. 6 Months Certified Pre Owned Car Warranty Will Be Provided. Trade In Welcome. Kindly Contact Our Sale...

Office No. - 65572663

Melvin Teo - 87870008 | Eugene Lim - 92725924

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	339H
Vehicle No.:	SGZ108D
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 CGI A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	27186030059983
Chassis No.:	WDD2074482F048111
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$52,361.00
Original Registration Date:	23 Apr 2011
First Registration Date:	23 Apr 2011
Transfer Count:	2
Actual ARF Paid:	\$52,361.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2021
PARF Rebate Amount:	\$28,798.00

COE Expiry Date:	22 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$56,801.00
COE Rebate Amount:	\$8,516.00
<b>Total Rebate Amount:</b>	<b>\$37,314.00</b>

The information contained herein is correct as at 23 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.


### ACCIDENT STATEMENT

Date Of Report	22/10/2019 16:19
Date Of Accident	19/10/2019 15:20
Exact Location Of Accident	SLIP ROAD OF PUNNGOL EAST TOWARDS PUNNGOL CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ108D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN YEA FEN
NRIC No	S7869339H
Email Address	ABBY_YF@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98002416
Alternative Phone No	OTHERS-98002416
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	E200 CGI A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00000008
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN YEA FEN
NRIC No	S7869339H
Date Of Birth	07/12/1978
Occupation	INDOOR
Date Of Driving Pass	18/07/2008
Driving Experience	11 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98002416
Fax Number	
Contact Number	OTHERS-98002416
Email Address	ABBY_YF@HOTMAIL.COM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR FROM PUNJIBOL EAST TURN TO PUNJIBOL CENTRAL  
 I HAVE STOP BEFORE TURN TO MAIN ROAD (PUNJIBOL CENTRAL)  
 THIRD PARTY (S. J. S. S. S. S.) BANG ON MY CAR FROM BEHIND

fmm

Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.	<input type="checkbox"/>	- Reporting Only
	<input type="checkbox"/>	- Claim OD
	<input type="checkbox"/>	- Claim TP
	<input checked="" type="checkbox"/>	- Claim OD/ TP at other workshop

DECLARATION  
 I/WE declare the foregoing particulars are true in every respect.

*fmm*  
 Policyholder's signature  
 Date & Time  
 22 06 2019  
 4.08 PM

*fmm*  
 Driver's Signature  
 (if driver not the policyholder)  
 Date & Time  
 22 06 2019  
 4.08 PM

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 Nric/Fin No.

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA  
#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)  
Email: louisongautowheels@yahoo.com

## ESTIMATE

DESCRIPTION	QTY	LIST PRICE
<b>PARTS</b>		
BOOTLID / DD	1	\$2,453.20 ? 2365
BOOTLID CHROME MOULDING X NH	1	\$345.10 X
BOOTLID LAMP X NH	2	\$1,378.40 X
REAR EMBLEM / MCL.	1	\$74.20 48
BOOTLID LOCK X NH	1	\$364.20 X
TAILLAMP X	2	\$1,692.60 X
<b>REPAIR</b>		
TAILLAMP PANEL	2	
REAR BUMPER / CRA	1	\$2,207.30 ? 1377
REAR BUMPER CLIPS / MCL.	10	\$50.00 -
REAR BUMPER RETAINER X	2	\$244.60 X
REAR BUMPER RETAINER PLATE X NH	2	\$122.40 X
REAR BUMPER CENTRE BRACKET X NH	1	\$287.40
REAR BUMPER BRACKET X	2	\$366.40
REAR BUMPER DIFFUSER	1	\$875.40 ? 384
TOWING COVER / cut	1	\$88.50 bc
REAR REINFORCEMENT X	1	\$786.40
REAR BUMPER SPONGE X NH	1	\$342.10
END PANEL TOP GARNISH X	1	\$322.10
REAR WEATHERSTRIP X	1	\$298.50
END PANEL X repair	1	\$1,235.70
SPARE TYRE PANEL (FIBER) X NH	1	\$601.30
<b>REPAIR</b>		
SPARE TYRE SIDE PANEL	2	
SPARE TYRE UNDER COVER X NH	1	\$365.30
SPARE TYRE UNDER COVER CLIPS X	10	\$50.00
REVERSE SENSOR / DM 257.00	1	\$1,028.80 ? 257.2
REVERSE SENSOR HOLDER / MCL.	4	\$224.80

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)

Email: louisongautowheels@yahoo.com

## ESTIMATE

REAR EXHAUST PIPE MUFFLER	X	1	\$1,721.50
REAR EXHAUST PIPE FINISHER	X	1	\$343.10
REAR EXHAUST PIPE GASKET	X	1	\$65.30
REAR EXHAUST MOUNTING	X	2	\$172.60
REAR SMART BOOTLID KEY SENSOR ASSY	XX	1	\$564.20

TOTAL: \$18,671.40  
DISCOUNT 10%: \$1,867.14  
\$16,804.26

4545.2  
4090.68

## S/NET

REAR NUMBER PLATE	X	PRICE	\$150.00
END PANEL SEALANT	X		\$80.00
			<u>\$230.00</u>

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA  
#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)  
Email: louisongautowheels@yahoo.com

## ESTIMATE

LABOUR	PRICE	
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$1,600.00	500
TO RESPRAY BOOTLID	\$300.00	200
TO RESPRAY REAR BUMPER	\$300.00	200
TO RESPRAY END PANEL	\$300.00	200
TO RESPRAY SPARE TYRE PANEL	\$300.00	X NN
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$100.00	30
TO REMOVE AND REFIT BOOTLID COMPONENT FOR FACILITATE REPAIR	\$150.00	40
TO REMOVE AND REFIT REAR TRIMING FOR FACILITATE REPAIR	\$150.00	60
TO REMOVE AND REFIT REVERSE SENSOR	\$150.00	40
TO RESET AND DIAGNOSE TO ORIGINAL SETTING	\$150.00	X
SUNDARIES	\$60.00	X NN
RUST PROOFING	\$80.00	X
<b>TOTAL:</b>	<b>\$3,640.00</b>	1270
	20674.26	
<b>TOTAL:</b>	<b>\$20,594.26</b>	
7% GST:	\$1,441.60	5360.68
	<b>\$22,035.86</b>	

*[Handwritten signature]*  
24/10/19

4 Days. 20%: 4250

lumpsum repair

After repair photos.

Guo Qiang - 8288 0282

ckk

23/10/19.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA  
R02 40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)  
Email: louisongautowheels@yahoo.com

ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID / DD	1	/\$2,453.20 ?
BOOTLID CHROME MOULDING X	1	X \$345.10
BOOTLID LAMP X	2	X \$1,378.40
REAR EMBLEM / MEC.	1	/\$74.20
BOOTLID LOCK X	1	X \$364.20
TAILLAMP X	2	X \$1,692.60
TAILLAMP PANEL	2	REPAIR
REAR BUMPER / CBA	1	/\$2,207.30 ?
REAR BUMPER CLIPS / MEC.	10	/\$50.00
REAR BUMPER RETAINER X	2	X \$244.60
REAR BUMPER RETAINER PLATE X	2	X \$122.40
REAR BUMPER CENTRE BRACKET ?	1	X \$287.40
REAR BUMPER BRACKET X	2	X \$366.40
REAR BUMPER DIFFUSER	1	/\$875.40 ?
TOWING COVER / cut ee.	1	/\$88.50
REAR REINFORCEMENT ?	1	X \$786.40
REAR BUMPER SPONGE ?	1	X \$342.10
LND PANEL TOP GARNISH X	1	X \$322.10
REAR WEATHERSTRIP X	1	X \$298.50
END PANEL X repair.	1	X \$1,235.70
SPARE TYRE PANEL (FIBER) X	1	X \$601.30
SPARE TYRE SIDE PANEL	2	REPAIR
SPARE TYRE UNDER COVER X	1	X \$365.30
SPARE TYRE UNDER COVER CLIPS X	10	X \$50.00
REVERSE SENSOR / Om	1	/\$1,028.80 ? 257.20
REVERSE SENSOR HOLDER / MEC.	4	/\$224.80

6,230.60



# AUTO WHEELS

MOTORWORKS PTE LTD

NO.1 BUKIT BATOK CRESCENT WCEGA PLAZA  
#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)  
Email: louisongautowheels@yahoo.com

### ESTIMATE

REAR EXHAUST PIPE MUFFLER	X	1	X	\$1,721.50
REAR EXHAUST PIPE FINISHER	X	1	X	\$343.10
REAR EXHAUST PIPE GASKET	X	1	X	\$65.30
REAR EXHAUST MOUNTING	X	2	X	\$172.60
REAR SMART BOOTLID KEY SENSOR ASSY	X	1	X	\$564.20

TOTAL:	\$18,671.40
DISCOUNT 10%:	\$1,867.14
	<u>\$16,804.26</u>

6,230.60  
10%  
5,607.54

### S/NET

REAR NUMBER PLATE	X
END PANEL SEALANT	X

PRICE	
X	\$150.00
X	\$80.00
	<u>\$230.00</u>

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA  
#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 22/10/2019  
VEHICLE NO: SGZ108D  
MODEL: MERCEDES E200  
YEAR: 2011  
ACCIDENT DATE: 19/10/2019  
TYPE OF CLAIM: TP  
CLAIM ADVISOR: LOUIS (91928963)  
Email: louisongautowheels@yahoo.com

ENTIRETY

LABOUR	PRICE	
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$1,600.00	500
TO RESPRAY BOOTLID	\$300.00	200
TO RESPRAY REAR BUMPER	\$300.00	200
TO RESPRAY END PANEL	\$300.00	200
TO RESPRAY SPARE TYRE PANEL	\$300.00	X
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$100.00	30
TO REMOVE AND REFIT BOOTLID COMPONENT FOR FACILITATE REPAIR	\$150.00	40
TO REMOVE AND REFIT REAR TRIMING FOR FACILITATE REPAIR	\$150.00	60
TO REMOVE AND REFIT REVERSE SENSOR	\$150.00	40
TO RESET AND DIAGNOSE TO ORIGINAL SETTING	\$150.00	X
SUNDARIES	\$60.00	X
RUST PROOFING	\$80.00	X
<b>TOTAL:</b>	<b>\$3,640.00</b>	<b>1,270</b>
<b>TOTAL:</b>	<b>\$20,594.26</b>	<b>T: 6,877.54</b>
<b>7% GST:</b>	<b>\$1,441.60</b>	<b>LS: \$5,500</b>
	<b>\$22,035.86</b>	

4 Days.  
Lumpsum repair  
After repair photos  
Gno @iang - 8288 0282  
ckk  
23/10/19.  
(4) days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/SMO19018732/GVF3N2  
**Date:** 05/11/2019

**REFERENCE**

<b>Handling Insurer:</b>	Sompo Insurance Singapore Pte. Ltd.	<b>Policy No:</b>	D19MTPV01014346
<b>Claimant Vehicle No :</b>	SGZ108D	<b>Insured Vehicle No :</b>	SJY8563P
<b>Date of Loss:</b>	19/10/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	CMTD1904966

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SGZ108D	<b>Engine No:</b>	27186030059983
<b>Make &amp; Model:</b>	MERCEDES-BENZ E200, 1.8 CGI (A)	<b>Chassis No:</b>	WDD2074482F048111
<b>Reg. Date:</b>	23/04/2011 (Man. Year: 2010)	<b>Odometer:</b>	102136 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	1796 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	255/35ZR18	<b>Rear Tyre Size:</b>	255/35ZR18
<b>Front Left Side:</b>	Michelin 6 mm	<b>Rear Left Side:</b>	Michelin 6 mm
<b>Front Right Side:</b>	Michelin 6 mm	<b>Rear Right Side:</b>	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,094.26	4,293.00	12,801.26	74.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,270.00	2,310.00	64.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,674.26</b>	<b>5,563.00</b>	<b>15,111.26</b>	<b>73.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,450.00</b>		
<b>(S\$)</b>	20,674.26	4,450.00	16,224.26	78.48
<b>+ GST 7.00/7.00% (S\$)</b>	1,447.20	311.50	1,135.70	78.48
<b>Nett Amount (S\$)</b>	<b>22,121.46</b>	<b>4,761.50</b>	<b>17,359.96</b>	<b>78.48</b>

**INSPECTION**

<b>Date of Assignment:</b>	23/10/2019	
<b>Date Inspected:</b>	23/10/2019	<b>Inspected At:</b>
		Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA Singapore 658064

**Estimated Period of Repair:** 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Nov 2019)	
<b>Parts:</b>	N/A	MERCEDES-BENZ E200 1.8 CGI (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGZ108D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Dented	2,453.20 FL	*2,365.00 FL
2	1	*BOOTLID CHROME MOULDING	Not Necessary	345.10 FL	*- FL
3	2	*BOOTLID LAMP	Not Necessary	1,378.40 FL	*- FL
4	1	*REAR EMBLEM	Necessary	74.20 FL	*48.00 FL
5	1	*BOOTLID LOCK	Not Necessary	364.20 FL	*- FL
6	2	*TAILLAMP	Not Necessary	1,692.60 FL	*- FL
7	2	*TAILLAMP PANEL (NPA)	Repair	0.00 FL	*- FL
8	1	*REAR BUMPER	Cracked	2,207.30 FL	*1,377.00 FL
9	10	*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	2	*REAR BUMPER RETAINER	Not Necessary	244.60 FL	*- FL
11	2	*REAR BUMPER RETAINER PLATE	Not Necessary	122.40 FL	*- FL
12	1	*REAR BUMPER CENTRE BRACKET	Not Necessary	287.40 FL	*- FL
13	2	*REAR BUMPER BRACKET	Not Necessary	366.40 FL	*- FL
14	1	*REAR BUMPER DIFFUSER	Deformed	875.40 FL	*384.00 FL
15	1	*TOWING COVER	Cut	88.50 FL	*64.00 FL
16	1	*REAR REINFORCEMENT	Not Necessary	786.40 FL	*- FL
17	1	*REAR BUMPER SPONGE	Not Necessary	342.10 FL	*- FL
18	1	*END PANEL TOP GARNISH	Not Necessary	322.10 FL	*- FL
19	1	*REAR WEATHERSTRIP	Not Necessary	298.50 FL	*- FL
20	1	*END PANEL	Repair	1,235.70 FL	*- FL
21	1	*SPARE TYRE PANEL (FIBER)	Not Necessary	601.30 FL	*- FL
22	2	*SPARE TYRE SIDE PANEL (NPA)	Repair	0.00 FL	*- FL
23	1	*SPARE TRYE UNDER COVER	Not Necessary	365.30 FL	*- FL
24	10	*SPARE TRYE UNDER COVER CLIPS	Not Necessary	50.00 FL	*- FL
25	1	*REVERSE SENSOR (4 Pcs)	Damaged (1 Pc only)	1,028.80 FL	*257.20 FL
26	4	*REVERSE SENSOR HOLDER	Necessary	224.80 FL	*224.80 FL
27	1	*REAR EXHAUST PIPE MUFFLER	Not Necessary	1,721.50 FL	*- FL
28	1	*REAR EXHAUST PIPE FINISHER	Not Necessary	343.10 FL	*- FL
29	1	*REAR EXHAUST PIPE GASKET	Not Necessary	65.30 FL	*- FL
30	2	*REAR EXHAUST MOUNTING	Not Necessary	172.60 FL	*- FL
31	1	*REAR SMART BOOTLID KEY SENSOR ASSY	Not Necessary	564.20 FL	*- FL
32	1	*REAR NUMBER PLATE	Not Necessary	150.00 FS	*- FS
33	1	*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1	*SUNDARIES	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>18,961.40</b>	<b>4,770.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,867.14</b>	<b>477.00</b>
<b>Total Parts (\$\$)</b>	<b>17,094.26</b>	<b>4,293.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR FACILITATE REPAIR-REAR PORTION	New	1,600.00	500.00
2	TO RESPRAY BOOTLID	New	300.00	200.00
3	TO RESPRAY REAR BUMPER	New	300.00	200.00
4	TO RESPRAY END PANEL	New	300.00	200.00
5	TO RESPRAY SPARE TYRE PANEL	New	300.00	0.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	30.00
7	TO REMOVE AND REFIT BOOTLID COMPONENT FOR FACILITATE REPAIR	New	150.00	40.00
8	TO REMOVE AND REFIT REAR TRIMING FOR FACILITATE REPAIR	New	150.00	60.00
9	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	40.00
10	TO RESET AND DIAGNOSE TO ORIGINAL SETTING	New	150.00	0.00
11	RUST PROOFING	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,580.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;