

# TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6280 8927 FAX: 6280 4205

Vehicle No: GBG5699R  
 Model No. Toyota Dyna  
 Chassis no. \*

Accident Date : 18/10/2019  
 Owner : Guan Lee Vegetables & Fruits Pte Ltd  
 Date of Estimate : 22/10/2019

## Estimate for Accident Vehicle No. GBG5699R

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Front door rh <i>bt</i> ✓	1	\$658.90	\$658.90
2 Front door hinge rh ?	1	\$64.20	\$64.20
3 Front door hinge lower rh ?	1	\$64.20	\$64.20
4 Front door inner board rh ?	1	\$358.90	\$358.90
5 Front door weatherstrip rh <i>nu</i> ✓	1	\$114.50	\$114.50
6 Front door inner lock rh <i>Jan</i> ✓	1	\$198.00	\$198.00
7 Front door lower rubber <i>nu</i> ✓	1	\$85.00	\$85.00
8 Front door regulator gear rh ?	1	\$144.50	\$144.50
9 Front door regulator motor rh ?	1	\$190.00	\$190.00
10 Front door outer handle rh ✗	1	\$98.00	\$98.00
11 Front door channel rh ✗	1	\$132.00	\$132.00
12 Front wheel arch panel garnish rh ✗	1	\$110.00	\$110.00
13 Front windscreen pillar A - repair	1	\$278.50	\$0.00
14 Front driver floor panel - repair	1	\$312.50	\$0.00
15 Front step garnish rh <i>ca</i> ✓	1	\$142.00	\$142.00
16 Cabin rear panel - repair	1	\$0.00	\$0.00
17 Rear platform frame rh - repair ✗	1	\$0.00	\$0.00
		Bal c/d	\$2,360.20
		Add 15%	\$354.03
		<b>Sub-Total</b>	<b>\$2,714.23</b>

<u>Special Nett Items</u>	Qty	Unit Price	Total Amount
1 Front door company address sticker rh <i>nu</i> ✓	1	\$450.00	<del>\$450.00</del> <i>200</i>
2 Front door LTA sticker rh <i>nu</i> ✓	1	\$40.00	\$40.00
		<b>Sub-Total =</b>	<b>\$490.00</b>
		<b>Total cost for parts =</b>	<b>\$490.00</b>

**Labour charges**

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting - cabin rear panel, front door rh
- 3 Apply putty and anti-corrosion to affected parts.
- 4 Wiring / bulb checking
- 5 Transfer door mechanisms rh

500	<del>480</del>	\$1,050.00
	450	\$550.00
		\$20.00
		\$30.00
60		\$100.00
		<hr/>
		\$1,750.00
		<hr/>

Total parts	=	\$3,204.23
Total labour	=	\$1,750.00
Total Amount	=	<hr/>
		\$4,954.23
		<hr/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
Hp 90010068  
4 days  
4/3  
23/10/19 @ 1110  
EXCESS: 3000  
REVERT  
Revy after repair