From (Person Estimated Co	Hazalysu	Ble buhim:	INC Bill to:	Def	e/Time:	Del rolando	s.aspm
	The second secon	RES/EVA/INV/M					
To Inspect V	chicle No:	abf	4456L	Insured:	SFK	372ID	-
at Workshop	m/s	Rico	60	Tel:	918	8064	
of	-8 kerlei &	Bullit Are 4 #	02-24				
Policy No:_			Claim No	: · MT/	066780	001	
Sum Insured	2		Excess				
Make of Veh				D.	O.A	11110/2019	10
(Client's Recor	71)						
CA / REV	/ REP. / REV 2	4 HRS			H.O.D. Endo	002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	-
CA / REV  Date/Time;	/ REP. / REV 2	14 HRS Person Contac	cted: Shenne	NeVeb		002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	7.5
CA / REV  Date/Time:  Date/Time	/ REP. / REV 2	1000	·			002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	
Date/Time;_	/ REP. / REV 2	ion Patricial (	·			002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	7.
Date/Time;_	PREP. / REV 2	ion Patricial (	·			002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	
Date/Time;_	PREP. / REV 2	ion Palmall L	·			002/41/7/2015 10 10 10 10 10 10 10 10 10 10 10 10 10	

### Nivitha (LKK Auto)

From:

MTSurvey < MTSurvey@income.com.sg>

Sent:

Tuesday, 22 October 2019 5:25 PM

To:

assignments; Admin-D (LKKAuto)

Subject:

FW: PRI Arrangement for GBF 4456 L; MT/1066780-001

Attachments:

PRI Arrangement.pdf

Dear LKK,

Please follow-up to survey the vehicle as it was assigned to you before.

Thank you.

#### Warmest Regards

### Hazalysa Bte Ibrahim Admin Assistant Motor Department T+65 6430 7902

www.income.com.sg











At Income, we are 'In with You' on Performance, Growth. Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers



From: Enquiry [mailto:claims@rico60.com]
Sent: Tuesday, 22 October 2019 11:48 AM

To: MTCL@income.com.sg; MTSurvey < MTSurvey@income.com.sg >; mtreg@income.com.sg; NTUC Income Motor

Dept <motor@income.com.sg>

Subject: PRI Arrangement for GBF 4456 L

Hi All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – GBF 4456 L Your Insured – SFK 3721 D DOA – 11/10/2019

Thank you.

Best Regards, Shanelle Lim



### RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

### Shiau Chan (LKKAuto)

From:

MTSurvey <MTSurvey@income.com.sg>

Sent:

Friday, 1 November 2019 11:42 AM

To:

Shiau Chan (LKKAuto)

Subject:

RE: PRI Arrangement for GBF 4456 L; MT/1066780-001

OIC is Thio Tse Kiat\*\*

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Friday, 1 November 2019 11:39 AM

To: MTSurvey < MTSurvey@income.com.sg>; assignments < assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: PRI Arrangement for GBF 4456 L; MT/1066780-001

Dear Sir/Madam,

May I know who is officer-in-charge of above mentioned.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com> Sent: Wednesday, 23 October 2019 11:19 AM

To: 'MTSurvey' <MTSurvey@income.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: PRI Arrangement for GBF 4456 L; MT/1066780-001

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

### **G.NIVITHA**

#### LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MTSurvey [mailto:MTSurvey@income.com.sg]

Sent: Tuesday, 22 October 2019 5:25 PM

New Cars

Post an Ad-

Used Car

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

### Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself. Advertise it for sale at just \$58, list till sold.

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Ways of Selling

Advertiser Login

35

Family 2nd Car, Loss Missourmental Lander program Translations, Accident Festi Direct Owner Starks.



Sort by Date Posted ▼ 20 results/page 2 vehicles Toyota Regius Veh Type All types Reg Date 2016 to 2016 Eng Cap Any Depre Any depre Price Any price OMV Anv Gear Any Gear Past Owners Any Fuel Any fuel Mileage Any • ▼ Location Any Status Available Scheme All schemes Dealer Any Dealer Category All categories 0 Status Eng Cap Mileage Veh Type Make & Model Price Depreciation Reg Date 51.229 km Van Available Toyota Regius Ace 3.0A \$51,800 \$7,880 /yr 18-May-2016 2,982 cc Fuel Type: Diesel Owner.Genuine Low Mileage! Hiace Auto 5 Door! Guaranteed The Best Condition! High Loan Available! As Good As Brand New Vehicle. Do Not Hesitate To WhatsApp Or Call Our Friendly Sales Consultant For More Information! Posted: 20-Oct-2019 Tags: 2016 Toyota Regius, 2016 toyota regius, Toyota Regius, toyota regius, Toyota, Regius, regius, Used Toyota \$52,800 \$7,700 /yr 31-Aug-2016 2,982 cc 100.800 km Van Available Toyota Regius Ace 3.0M Fuel Type: Diesel 1 Owner, Full Loan Trade In Welcome, Please Call Us Now For Viewing! Call Us Now! ABWIN (1994) Pte Ltd Tags: 2016 Toyota Regius, 2016 toyota regius, Toyota Regius, toyota regius, Toyota, Regius, Ingius, Used Toyota Posted: 02-Sep-2019 Reg Date Mileage Veh Type Make & Model Price Depreciation Eng Cap 20 ▼ results/page For old advertisements, view Expired ads

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons. SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car ideas, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Regius, Toyota Regius Singapore, used Toyota Regius, used vehicles Singapore or even buy used Toyota Regius Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

#### Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement © 2004-2019 sgCarMart. All rights reserved.

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

(	)			
J		N	14	

Vehicle Owner Particulars	and the same of th	
Owner ID Type:	Business	
Owner ID: Vehicle Details	792K	
Vehicle No.:	GBF4456L	
Vehicle to be Exported:	No	
Intended Deregistration Date:	22 Oct 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	REGIUS ACE DX 3.0 M	
Primary Colour:	White	
Manufacturing Year:	2016	
Engine No.:	1KD2607788	
Chassis No.:	KDH2010195320	
Maximum Power Output:		
Open Market Value:	\$30,819.00	
Original Registration Date:	21 Oct 2016	
First Registration Date:	21 Oct 2016	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$1,541.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	20 Oct 2026	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
PQP Paid:	\$44,265.00	
COE Rebate Amount:	\$30,952.00	
Total Rebate Amount:	\$30,952.00	

The information contained herein is correct as at 22 Oct 2019

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	14/10/2019 15:21
Date Of Accident	11/10/2019 18:00
Exact Location Of Accident	CANBERRA LINK TOWARDS SEMBAWANG WAY
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	GBF4456L
sured/Policyholder	
Name Of Registered Owner	MING XIN TRADING (1997)
Co Reg No	52858792K
Email Address	SALES@MIA.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65525955
Vehicle Particulars	
Manufacturer	тоуота
Model	TOYOTA REQRUS ACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085187163-02
Cover Note Number	
Driver	
Name of Driver	TOH KIAN TENG
NRIC No	S0809728C

15/03/1950 Date Of Birth OUTDOOR Occupation 31/01/2011 Date Of Driving Pass

8 YEARS AND 8 MONTHS **Driving Experience** 

MALE Gender

(LOCAL) +65-81509182 Mobile Number

Fax Number

Contact Number

SALES@MIA.COM.SG EMail Address

Address

APT BLK 636 YISHUN STREET 61 #03-108

Postcode

760636

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

as any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Vas there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SFK3721D

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Force must be completed by the Policyholdes and/or the Authorised Driver
- information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation:
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (G/A) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims:
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sized outside of Singapore, for one or more of the above Purposes
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

ING XIN FO

BA Admirati, 194-1776
Food Xchange & Admirator, Sengapore 757437
Fac 6562 5965 (2-9 www.) Fax 6562 0981 Driver's Signature (if griver is not the policyholder)

Date & Time

Name

NRIC/FIN No.

SKETCH PLAN

(A) GBF4456L (B) SFK3721D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

We declare the Green Factor of Target To an every respect. "AL ME MIN T

Tel 1552 5855 ( 3 lines ) Fax: 6552 600 ( Date & Time

nel's Signature Repor Name NRC/FIN NO



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24 Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com

Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM: MAKE & MODEL: MILEAGE: TYRE: GBF 4456 L
TOYOTA HIACE

MAL

L/SH 4700

Sliding

	TYRE: CHASSIS NUM:		2/591	7
	Chashs item	2/10	7/2/2	4
N:	DESCRIPTION - PARTS	5/ (0//) orv	PRICE	11
B PILLAR (RH)	P X	1	545.20	×
DE AND DOOR (RH)	005 —	1	1645-10	-
REAR DOOR HANDLE (F	RH) 177	1		×
DEAR DOOR HANDLE L	OCK CYLINDER (RH) 4 1 X	1		X
DEAD DOOR CLASS MO		1		×
6 REAR DOOR INNER LOC		1		×
REAR DOOR INNER LOC	1. 10	1	399.50	
		1	2/140	1
8 REAR DOOR INNER LOC	CK CATCH BOTTOM (RH) 7/4 X	1		1
9 REAR DOOR INNER LOO		1		X
10 REAR DOOR STOPPER		59.00		X
11 REAR DOOR STOPPER I	- 1	1		- ^
12 REAR DOOR SIDE GAR		1		X
13 REAR DOOR SIDE GAR		1		X
14 REAR DOOR INNER HA		1		×
15 REAR DOOR INNER HA		1		7
20	NDLE LOCK SWITCH (RH) 17 X	1		
17 REAR DOOR INNER BO		1	288.W	-
18 REAR DOOR CHECKER	R(RH) VSX	1		- 3
19 REAR DOOR HINGE (UI	PPER & LOWER) (RH)	2		- 3
20 REAR DOOR HINGE CE	ENTER (RH) 711X	1		
21 REAR DOOR TRACK TO	OP (RH)	1		
22 REAR DOOR TRACK BO	OTTOM (RH)	1		1
23 REAR DOOR TRACK ST	TOPPER TOP (RH) $\eta$	1		)
24 REAR DOOR TRACK ST	TOPPER BOTTOM (RH) $7/1$	1		)
25 REAR DOOR TRACK W	~ .	2		_
26 REAR DOOR WEATHER	RSTRIP (RH)	1		
27 REAR DOOR INNER WI	EATHERSTRIP (RH) A X	1		
28 REAR DOOR STEP PAN	EL (RH) / X	1		1
29 ROCKER PANEL (RH)	n.x	1		
30 REAR FENDER (RH)	Bert/00 -	1	1645-10	2.
31 REAR FENDER GLASS		1	855.10	-
DEAD FENDER CLASS		1		
32 REAR FENDER OLASS 33 REAR FENDER INNER	A	1		
34 REAR FENDER DOOR		1		
35 REAR FENDER DOOR		1		
TAIL LAMP (PH)	SCN/NIC X	1	348.20	
TAIL LAMP PANEL (RI	A 2 3 5	1	-19 00	
FLOOD PANEL	R×	1		
DEAD ARSORRED (RH		1		-
39 REAR LOWER ARM (R	A	1		-

	211		1		
REAR KNUCKLE (RH)			1		
REAR KNUCKLE BEARING (RH)	11 X		1		
REAR BEARING HUB (RH)	112		1		
44 RÉAR AXLE	NIX				
		CTIDECTA!		s	-
	25-2	SUBTOTAL			
	157	25% LESS 10%		S	
	3624.75	PARTS TOTAL	OTV	S	DICE.
SPEC	IAL NETT		QTY		RICE
1 B PILLAR SEALANT	MMX		1	S	120.00
2 REAR DOOR GLASS SEALANT	ru 50		1	S	120.00
REAR DOOR GLASS STICKER (RH)	11 X		1	S	800.00
4 REAR DOOR INNER BOARD CLIPS	m 30		20	S	200.00
5 REAR DOOR STEP PANEL SEALANT	11 ×		1	S	120.00
6 ROCKER PANEL SEALANT	NIX		1	S	120.00
7 REAR FENDER GLASS STICKER (RH)	11 X		1	S	800.00
8 REAR FENDER SEALANT	nn X		1	S	120.00
9 REAR FENDER GLASS SEALANT	· M 50		1	S	120.00
10 REAR FENDER INNER BOARD CLIPS	ハイメ		20	s	200.00
11 TAIL LAMP CLIPS	118		2	S	40.00
12 FLOOR PANEL SEALANT	11 X		1	S	120.00
12 120011.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1					
	SPEC	IAL NETT TOTAL		S	2,880.00
LAI	BOUR		QTY	1	PRICE
1 TO RNR ACCIDENT DAMAGE PARTS, 0	CUT/WELD, KNOCK&REA	LIGN 1000	1	S	3,000.00
2 TO PUTTY AND RESPRAY ACCIDENT	AFFECTED AREA	800	1	S	1,500.00
3 TO RUST PROOF ACCIDENT AFFECTE	D AREA	80	1	S	250.00
4 TO RNR REAR DOOR GLASS		100	1	s	400.00
5 TO RNR REAR FENDER GLASS		100	1	s	400.00
6 TO RNR UNDERCARRIAGE SYSTEM		11人	1	s	250.00
7 TO CHECK WHEEL ALIGNMENT		60	1	s	250.00
8 TO RNR UPHOLSTERY,GARNISH AND	ATTACHMENT PARTS	NIX	1	s	400.00
The state of the s		40	1	s	800.00
9 TO RNR DOOR MECHANISM 10 TO CHECK WIRING LAYOUT AND TA	IL LAMP FUNCTION	20	1	s	150.00
10 TO CHECK WIRING LAYOUT AND TA		111	1	s	250.00
TO DO DIACNOSIS AND RESET REPE	ROGRAM OR CODING FA	ULT CODE. 11 X	1	s	400.00
	**************************************	XNN	1	s	100.00
13 TO DO WATER LEAK TEST.	O ASSIST WORK LOAD	NAX	1	s	350.00
14 TO CLEAN AND VACUUM GLASSES T					
the Renain	Consultants hence notify er of the following:	TOTA	AL.	s	8,500.0
To ma union	petore, after spray painting	GRAND TOTAL CO	2550		11,380.0
_ DESC. 100	ally subject to confirmation				
Trini party	survey is on a "Without Prejudice" basis	2 7	6242	~	
	nodification(s) is allowed stary item(s) must be resurveyed and		-120-	30	
is subject t	o final approval from Insurance Compan	5,~	130	22	1567
	ed by Repairer	L-9	C661	100	11.59
Signature:			99	1.75	
1395			2	12	•



05-11-2019

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19018774/Uqd3n2

73 BRAS BASAH ROAD Date:

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

ATTN: THIO TSE KIAT Code: INC

1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFK 3721D	Veh. Inspected	GBF 4456L		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	MT/1066780-001	Excess (\$)	0.00		
	Assign From	HAZALYSA BTE IBRAHIM	Assign Date	22/10/2019		
_		Vehicle Par	ticulars & Condition	AND MANAGEMENT OF THE PARTY.		

2.		Vehicle Partic	culars & Condition	
	Make & Model	TOYOTA REGIUS ACE DX (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2010195320	Colour	WHITE
	Odometer	137874 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		

	General	GOOD		and the same of th		
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm		
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm		
	R/H Rear Tyre	195 R15	YOKOHAMA	6 mm		
$\vdash$	I /H Rear Tyre	195 R15	YOKOHAMA	6 mm		

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5.			General Information				
	Accident Date	11/10/2019	Inspect Date / Time	23/10/2019 ( 04:02 PM )			
	Survey held at	RICO 60 AUTO SERVICES PTE LTD					
		8 KAKI BUKIT AVEN #02-24 PREMIER @ SINGAPORE 415875	KAKI BUKIT				
5a.			Remarks				
	A)THE INSPECTION	ON WAS CONDUCTED	ON A"WITHOUT PREJUDICE" BASIS CTIONS, WE HAVE NOT AUTHORISE	S. ED REPAIRS.			
100	1=/		E. Ut- Davis of Banair				

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4456L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	B PILLAR (RH)	TO REPAIR SEE LABOUR	545.50	
1	SLIDING DOOR (RH)	DISTORTED	1,645.10	1,645.10
1	REAR DOOR HANDLE (RH) (NPA)	NOT NECESSARY	-	
1	REAR DOOR HANDLE LOCK CYLINDER(RH) (NPA)	NOT NECESSARY		1 23
- 1	REAR DOOR GLASS MOULDING (RH) (NPA)	NOT NECESSARY		
1	REAR DOOR INNER LOCK TOP (RH) (NPA)	NOT NECESSARY		
1	REAR DOOR INNER LOCK BOTTOM (RH)	DAMAGED / SHORTED	399.50	399.50
1	REAR DOOR INNER LOCK CATCH TOP (RH) (NPA)	NOT NECESSARY	-	
1	REAR DOOR INNER LOCK CATCH BOTTOM (RH) (NPA)	NOT NECESSARY	1	
1	REAR DOOR STOPPER TOP (RH) (NPA)	NOT NECESSARY	N N N N N N N N N N N N N N N N N N N	
1	REAR DOOR STOPPER BOTTOM (RH) (NPA)	NOT NECESSARY	-	
1	REAR DOOR SIDE GARNISH TOP (RH) (NPA)	NO SUCH PARTS		
	REAR DOOR SIDE GARNISH BOTTOM (RH) (NPA)	NO SUCH PARTS		
4	REAR DOOR INNER HANDLE (RH) (NPA)	NOT NECESSARY	2	
	REAR DOOR INNER HANDLE GARNISH (RH) (NPA)	NOT NECESSARY	25	
-	REAR DOOR INNER HANDLE LOCK SWITCH (RH) (NPA)	NOT NECESSARY		
	REAR DOOR INNER BOARD (RH)	TORN	288.20	288.2
	REAR DOOR CHECKER (RH) (NPA)	NO SUCH PARTS		
	REAR DOOR HINGE (UPPER & LOWER) (RH) (NPA)	NOT NECESSARY		
	REAR DOOR HINGE CENTER (RH) (NPA)	NOT NECESSARY		-
	REAR DOOR TRACK TOP (RH) (NPA)	NOT NECESSARY		
	REAR DOOR TRACK BOTTOM (RH) (NPA)	NOT NECESSARY	15	
	REAR DOOR TRACK STOPPER TOP (RH) (NPA)	NOT NECESSARY	100	-
	REAR DOOR TRACK STOPPER BOTTOM (RH) (NPA)	NOT NECESSARY		-
	REAR DOOR TRACK WHEEL SET (RH) (NPA)	NOT NECESSARY	85	-
	REAR DOOR WEATHERSTRIP (RH) (NPA)	NO SUCH PARTS	53	-
	REAR DOOR INNER WEATHERSTRIP (RH) (NPA)	NOT NECESSARY	10	-
	1 REAR DOOR STEP PANEL (RH) (NPA)	TO REPAIR SEE LABOUR		

Report Ref No. CS/INC19018774/Uqd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	ROCKER PANEL (RH) (NPA)	TO REPAIR SEE LABOUR		
-1	REAR FENDER (RH)	BENT / DENTED	1,645.10	1,645.10
100	REAR FENDER GLASS (RH)	SHATTERED	855.10	855.10
0.0	REAR FENDER GLASS MOULDING (RH) (NPA)	NO SUCH PARTS		8
	REAR FENDER INNER BOARD (RH) (NPA)	NOT NECESSARY	1.	8
	REAR FENDER DOOR GUIDE (RH) (NPA)	NOT NECESSARY		
	REAR FENDER DOOR GUIDE END (RH) (NPA)	NOT NECESSARY		
	TAIL LAMP (RH) (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	348.20	
1	TAIL LAMP PANEL (RH) (NPA)	NOT NECESSARY		
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR		
1	REAR ABSORBER (RH) (NPA)	NOT NECESSARY		
	REAR LOWER ARM (RH) (NPA)	NOT NECESSARY		
	REAR KNUCKLE (RH) (NPA)	NOT NECESSARY		1
	REAR KNUCKLE BEARING (RH) (NPA)	NOT NECESSARY		
1	REAR BEARING HUB (RH) (NPA)	NOT NECESSARY	79	1
1		NOT NECESSARY		
	LESS 25% DISCOUNT		-1,431.68	-1,208.2
			4,295.02	3,624.
	SPECIAL NETT ITEMS			
1	B PILLAR SEALANT (SN)	NOT NECESSARY	120.00	
1	REAR DOOR GLASS SEALANT (SN)	NECESSARY	120.00	50.0
	REAR DOOR GLASS STICKER (RH) (SN)	NOT NECESSARY	800.00	
20	REAR DOOR INNER BOARD CLIPS (SN)	NECESSARY	200.00	30.0
	REAR DOOR STEP PANEL SEALANT (SN)	NOT NECESSARY	120.00	
	ROCKER PANEL SEALANT (SN)	NOT NECESSARY	120.00	
- 9	REAR FENDER GLASS STICKER (RH)(SN)	NOT NECESSARY	800.00	P
- 8	REAR FENDER SEALANT (SN)	NOT NECESSARY	120.0	
	REAR FENDER GLASS SEALANT (SN)	NECESSARY	120.0	50.
20	REAR FENDER INNER BOARD CLIPS (SN)	NOT NECESSARY	200.0	0
	TAIL LAMP CLIPS (SN)	NOT NECESSARY	40.0	0

Report Ref No. CS/INC19018774/Uqd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FLOOR PANEL SEALANT (SN)	NOT NECESSARY	120.00	
			2,880.00	130.00
	LABOUR			
	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK & REALIGN. INCLUSIVE OF THE REPAIR OF B PILLAR (RH), REAR DOOR STEP PANEL (RH), ROCKER PANEL (RH) AND FLOOR PANEL.		3,000.00	1,000.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,500.00	800.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		250.00	80.00
	TO RNR REAR DOOR GLASS.		400.00	100.00
	TO RNR REAR FENDER GLASS.		400.00	100.00
	TO RNR UNDERCARRIAGE SYSTEM.	NOT NECESSARY	250.00	
	TO CHECK WHEEL ALIGNMENT.		250.00	60.00
	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	400.00	
	TO RNR DOOR MECHANISM.		800.00	
	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION.		150.00	20.00
	TO RNR TYRE AND WHEEL BALANCING.	NOT NECESSARY	250.00	
	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	400.00	
	TO DO WATER LEAK TEST.	NOT NECESSARY	100.00	
	TO CLEAN AND VACUUM GLASSES TO ASSIST WORK LOAD.	NOT NECESSARY	350.00	
			8,500.00	2,200.00
	GRAND TOTAL		15,675.02	5,954.75

RECOMMENDED COST OF LUMP SUM REPAIRS	4,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC19018774/Uqd3n2

**CHUA KANG SENG** 

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.