

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

22/10/2019

Date / Time: 22/10/2019

Registered in Merimen: 23/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. SKV 7415U

Claim No. : 9322786243SG

Name of Insured TAN PHECK SING

Policy No. :

Insured Tel No. HP: +65-90256013

Make / Model : TOYOTA COROLLA ALTIS-1.6 (A)

Excess Sec II :SS D.O.A : 17/10/2019 19:40

Place of Accident : CARPARK DR WAY ALONG BLK 289C
COMPASSVALE CRES

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SGK 8298P

INSRS:
WSP: MG SOLUTION
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	SGK 8298P - X	SKV 7415U - X	STAGE	DATE / PIC
15/1/2020 - FILED PAJ To HML To LWS			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice	☒
			LTA / GIA :	☒
		Medical Bill:	☒	
		PIR:	☒	
		Mandate/Reject Instruction:	☒	
		LOD	☒	
		Payment Breakdown Form:	☒	
		Post-Repair Photos:	☒	
		Others:	☒	
PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by:				
FINALIZATION Date/Time: Confirm with: Confirm by:				
Repair Cost: SS (days) Reduction: % Email ☐ Call ☐				
FINAL SETTLEMENT Date/Time: 9/12/19 Confirm with: Su Wang Email ☒ Call ☐				
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : N/A				
Repair Cost: (w/hy) SS 2996.00 02 REMOVED HLT TP				
Loss of Rental (LOR): SS (days)				
Loss of Use (LOU): SS 500.00 (\$ 100 x 5 days)				
Loss of Income (LOI): SS (\$ x days)				
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
GIA/LTA Search SS 29.00				
Medical: SS -				
Disbursement: SS - (e.g. Tow/ Independent)				
Legal Cost SS -				
Total: SS 3525.00 Global Sum SS:				
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1: SS 3525.00 Name 1: MG Solution Pte Ltd				
Payee 2: (Strike if N.A.) SS Name 2:				
Payee 3: (Strike if N.A.) SS Name 3:				

COPY SENT
21/1/20201) Claim status: Normal/Reject/Private Settle
2) Report Format: 1P
3) Survey fee: \$320

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh. had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGK8298P- Yr Regn: 2010 May.Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.O. 1799Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 122649 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF01630A S 200108Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 22/10/19

Survey held at

MG Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>43-42800 (Red \$ 5556.16 / 661)</u>
	<u>MV: 221k</u>
	<u>PV: 14.6k</u>
	<u>Nett: 7.4k</u>

Date/Time, File Pass in?

☐

: Preli. Report

If

☐

: Final Report

Date/Time, File Pass in?

If

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Wheel Align (\$

Survey Fee: _____

Transportation: _____

I 3 + PG 3

Risks

(4km)

- 3 11

Report Format: _____

Lump Sum / LB 1: 12

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 21/10/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGK8298P	Jiale	
MODEL	: HONDA CIVIC 1.6A		
CHASSIS NO		JHMFV1630AS200108	
<u>ACCIDENT DETAILS</u>			
DATE	: 17-Oct-19		
TIME	: 1940HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Debond</i>	1	\$ 660.30	\$ 660.30
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 320.00	\$ 320.00
4	FRONT BUMPER FOGLAMP LH <i>new</i>	1	\$ 280.00	\$ 280.00
5	FRONT BUMPER FOGLAMP HOUSING LH <i>new</i>	1	\$ 120.00	\$ 120.00
6	HID HEADLAMP LH <i>ht</i>	1	\$ 989.60	\$ 989.60
7	HID HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 65.90	\$ 65.90
8	FRONT FENDER LH <i>Dented</i>	1	\$ 630.00	\$ 630.00
9	FRONT FENDER INNER COWLING LH <i>torn</i>	1	\$ 148.90	\$ 148.90
10	FRONT LOWER ARM LH <i>2</i>	1	\$ 266.00	\$ 266.00
11	FRONT KNUCKLE ARM LH	1	\$ 274.60	\$ 274.60
12	FRONT KNUCKLE ARM BEARING LH <i>NP</i>	1	\$ 138.00	\$ 138.00
13	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 342.40	\$ 342.40
14	FRONT WHEEL HUP LH	1	\$ 190.20	\$ 190.20

2492.8

199424

TOTAL PRICE \$ 4,557.70

LESS 20% \$ 911.54

SUB TOTAL PRICE \$ 3,646.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Ne</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
2	FRONT FENDER INNER COWLING CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00 ✓
3	FRONT WHEEL RIM (SET) <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00 <i>500</i>
4	FRONT TYRE LH <i>Ne Ne</i>	1	\$ 350.00	\$ 350.00 ✓

530

TOTAL \$ 1,630.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	450	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	1450	
3	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	x	
4	WIRING CHECK	\$ 100.00	30	
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 280.00	x	
6	FOUR WHEEL ALIGNMENT	\$ 120.00	80	

1010

TOTAL

\$3,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,275.16

TOTAL LABOUR COST : \$ 3,080.00

TOTAL REPAIR COST : \$ 8,355.16

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lij
n/s 22/10/19

04 Days

total: 3751.44

5/2 = 2.81c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	779E
Vehicle Details	
Vehicle No.:	SGK8298P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L 5AT
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	R18A15000278
Chassis No.:	JHMF1630AS200108
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$24,856.00
Original Registration Date:	14 May 2010
First Registration Date:	14 May 2010
Transfer Count:	0
Actual ARF Paid:	\$24,856.00
PARF Eligibility Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2020
PARF Rebate Amount:	\$12,428.00
COE Particulars	
COE Expiry Date:	13 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$2,117.00
Total Rebate Amount:	\$14,545.00

The information contained herein is correct as at 22 Oct 2019

OK



Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

[SEARCH](#)

[Price Range](#)

[Depreciation](#)

[Year Reg](#)

[Vehicle Type](#)

[Search](#)

[View All](#)

[Advanced Search](#)

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Civic 2.0A Si



[Add to Shortlist](#)

Honda Civic 1.8M VTI-5



[Add to Shortlist](#)

Honda Civic 1.8A VTI-5



[Add to Shortlist](#)

Honda Civic 1.8A VTI-5



[Add to Shortlist](#)

[Clear All](#)

[Add all to Shortlist](#)

[Back to search result](#)

CAR DETAILS

	Honda Civic 2.0A Si	Honda Civic 1.8M VTI-5	Honda Civic 1.8A VTI-5	Honda Civic 1.8A VTI-5
Price	\$19,000	\$19,500	\$30,800	\$30,850
Instalment	\$13,333	\$6,859	\$1,188	\$1,190
Registration Date	15-Dec-2009	29-Dec-2009	02-Jun-2011	14-Jun-2011
Manufactured	2008	2008	2009	2009
Mileage	-	167,000 km	76,000 km	100,027 km
Transmission	Auto	Manual	Auto	Auto
Engine Cap	1,998 cc	1,799 cc	1,799 cc	1,799 cc
Road Tax	\$1,210 /yr	\$978 /yr	\$978 /yr	\$978 /yr
Power	114.0 kW (152 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	1,312 kg	1,190 kg	1,219 kg	1,219 kg
Features	2.0L DOHC I-VTEC Engine, 5 Speed Auto, Paddle Shifter, ABS, SRS Airbags, Cruise Control.	Powerful 1.8L 16V I-VTEC Engine, 5 Speed Manual, Dual Airbags, Immobilizer, Multi-Function Steering And Climatic Aircon Control.	1.8L Powerful I-VTEC Engine, 5-Speed Automatic Transmission, ABS, Airbags, Digital Climatic Aircon Control, 4 x Discs Brakes, Paddle Shifters.	Smooth 1.8L I-VTEC E Auto Transmission With SRS Airbags. ABS Etc.
Accessories	Original Factory 16" Sports Rims, Reverse Sensors, Factory Integrated Audio System Come With Steering Control, Etc.	Factory Audio System, Sports Rims, Climate Control A/C, Leather Seats.	Newly Done Up Full Mugen Bodykit And Spoiler, Leather Seat, Sports Rim, HID Headlight, Factory Fitted Audio, Reverse Sensor, Multi Steering Control.	Good Condition, Black Back At Least \$13k W/ You Can Renew It. No Viewing.
Description	Only 2 Owners, 100% Stock Condition With No Fanciful Modifications Done, Almost Perfect Interior With Factory Fitted Black Leather, Perfect Car For COE Renewal, Buy With Or Without COE Extension Option Available, High Trade In With Attractive Interest Rates From 2.98% Onwards, 100% Loan Available Too! Price Negotiable, \$0 Admin Fee, No Cash Purchase Penalty, Call Or Sms Your Offer Today!	Well Taken Care Car, With Everything Left Stock, Many Things Done Up Ready For Renewal Of COE. Drives Smooth And Comfortable. Tyres Just Recently Replaced With A Month Ago, Renew 10 Years For Just \$5.6k Depreciation. Price Negotiable.	1 Year In House Warranty, Full Loan Available, Free Servicing, Warranty NOT By 3rd Party Workshop, Good For Short Term Drive Or Future COE Renewal, Price Stated Above Is Actual Selling Price, New Paintwork, Fully Refurbished, Accident Free, STA Or VICOM Are Welcome, Purchase Comes With Official Certificate With A Peace Of Mind, Bank & In House Loan Available, Free Grooming.	Low Depreciation, High Loan, In House Loan / Now! Call Us Now For
COE	N.A.	\$18,509	\$57,100	\$56,001
OMV	\$28,463	\$27,474	\$24,527	\$25,185
ARF	\$28,463	\$27,474	\$24,527	\$25,185
Depreciation	N.A.	N.A.	\$11,510 /yr	\$11,110 /yr
No. of Owners	2	4	2	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PAIF Car, Premium Ad Car	PAIF Car, Direct Owner Sale	PAIF Car, Low Mileage Car	PAIF Car
Availability	Available	Available	Available	Available

SELLER INFORMATION

LETTER OF AUTHORITY

Name : SUN SOON KUAN
Address : BLK 322 HUBER CENTRAL
09-00 SINGAPORE 530833
Contact No : _____

TO: AIG ASIA PACIFIC INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SGK 3298P AND SGK 745U ON 17/10/2019
AT/ALONG driveway of Blk 26 Compassvale Crescent

I/We, SUN SOON KUAN, am/are the registered owner of
motor car no. SGK 3298P

Please note that I have assigned all compensations monies due to me/us in the above said accident to M/S MG SOLUTION PTE LTD.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned accident to M/S MG SOLUTION PTE LTD and forward your settlement cheque to M/S MG SOLUTION PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant


Witness By

View Received Message

This mail is associated with :

*SGK8298P (9322786243SG)
[SKV7415U]
TP
SOH SONG NGUAN
Oct 17 2019 7:00PM
[TAN PHECK SING]
MG Solution Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **09/12/2019 09:13 AM**
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$3739.00) - SGK8298P - Claim Handler: Loh, Chee-Heng**

Approved:3739.00.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2019 Edit Reg		22 Oct 2019 00:00 Edit Adj Rpt	\$52,800.00 Edit Estimates	\$52,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN PHECK SING , ID: S7408405B								
Main Claimant:	SOH SONG NGUAN , ID: S0207779E								
Vehicle Reg. No.:	SGK8298P	Date of Loss:	17/10/2019 19:00 - :59 [113 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9322786243SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKV7415U	Policy No. (Claimant):	VPA/P0932891						
		Excess:							
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (09/12/2019): Alert - Adj Mandate Approved (\$3739.00) - SGK8298P - Claim Handler: Loh, Chee-H... - AIG_SG (24/10/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGK8298P (9322786243SG)
[SKV7415U]
TP
SOH SONG NGUAN
Oct 17 2019 7:00PM
[TAN PHECK SING]
MG Solution Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	--	--

Letters/Correspondences					1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit

Assessment Reports					1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	06/12/19 17:15	Adjuster Immediate Advice				Load HTML

Photos/Images					3 per page 3 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	14/11/19 14:37	General View				Load JPG
2	14/11/19 14:37	General View				Load JPG
3	14/11/19 14:37	General View				Load JPG
4	14/11/19 14:37	General View				Load JPG
5	14/11/19 14:37	General View				Load JPG
6	14/11/19 14:37	General View				Load JPG
7	14/11/19 14:37	General View				Load JPG
8	14/11/19 14:37	General View				Load JPG
9	14/11/19 14:37	General View				Load JPG
10	14/11/19 14:37	General View				Load JPG
11	14/11/19 14:37	General View				Load JPG
12	14/11/19 14:37	General View				Load JPG
13	14/11/19 14:37	General View				Load JPG
14	14/11/19 14:37	General View				Load JPG
15	14/11/19 14:37	General View				Load JPG

Documentation					1 per page 1 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	25/10/19 16:41	TP GIA REPORT				Load PDF
2	06/12/19 13:25	LOD				Load PDF
3	06/12/19 13:25	GIA SEARCH FEE				Load PDF
4	15/01/20 10:23	TP ESTIMATE - MARKED (FINAL)				Load PDF
5	21/01/20 19:31	Authorisation to Act				Load PDF
6	21/01/20 19:31	Release Voucher				Load PDF
7	30/01/20 10:44	WORKSHOP INVOICE				Load PDF
8	30/01/20 10:46	LETTER TO OI				Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKV7415U (Insd veh)	Model:	HONDA CIVIC 1.8 L 5AT (A)
	SGK8298P (TP veh)		
Date of Accident:	17/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	8,941.09
Final Repair Cost	:	\$	2,996.00
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	29.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,525.00

5.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	MG Solution Pte Ltd	:	\$ 3,525.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

30 Jan

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19018787/ADA3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SGK8298P

Insured Vehicle No : SKV7415U

Date of Loss: 17/10/2019

Nature of Claim: TP

Claim No: 9322786243SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGK8298P

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Engine No: R18A15000278

Reg. Date: 14/05/2010 (Man. Year: 2009)

Chassis No: JHMFD1630AS200108

Colour: Silver

Odometer: 122649 km

Engine Capacity: 1799 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,276.16	2,544.24	2,731.92	51.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,010.00	2,070.00	67.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,356.16	3,554.24	4,801.92	57.47
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	8,356.16	2,800.00	5,556.16	66.49
+ GST 7.00/7.00% (S\$)	584.93	196.00	388.93	66.49
Nett Amount (S\$)	8,941.09	2,996.00	5,945.09	66.49
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,525.00		

INSPECTION

Date of Assignment: 22/10/2019

Date Inspected: 22/10/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	660.30 FL	*660.30 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	131.80 FL	*64.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	320.00 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP LH	Not Necessary	280.00 FL	*- FL
5	1		*FRONT BUMPER FOGLAMP HOUSING LH	Not Necessary	120.00 FL	*- FL
6	1		*HID HEADLAMP LH	Cut	989.60 FL	*989.60 FL
7	1		*HID HEADLAMP LOWER BRACKET LH	Not Necessary	65.90 FL	*- FL
8	1		*FRONT FENDER LH	Dented	630.00 FL	*630.00 FL
9	1		*FRONT FENDER INNER COWLING LH	Torn	148.90 FL	*148.90 FL
10	1		*FRONT LOWER ARM LH	Not Necessary	266.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM LH	Not Necessary	274.60 FL	*- FL
12	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	138.00 FL	*- FL
13	1		*FRONT SHOCK ABSORBER LH	Not Necessary	342.40 FL	*- FL
14	1		*FRONT WHEEL HUP LH	Not Necessary	190.20 FL	*- FL
15	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
16	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	20.00 FS	*20.00 FS
17	1		*SET FRONT WHEEL RIM	Cut	1,200.00 FS	*500.00 FS
18	1		*FRONT TYRE LH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,187.70	3,042.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	911.54	498.56
Total Parts (\$\$)	5,276.16	2,544.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	450.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	450.00
3	REMOVE AND REFIX FRONT WINDSCREEN	New	180.00	0.00
4	WIRING CHECK	New	100.00	30.00
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	280.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			3,080.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >