

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 21/10/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGK8298P	Jiale	
MODEL	: HONDA CIVIC 1.6A		
CHASSIS NO		JHMF D1630 AS200108	
<u>ACCIDENT DETAILS</u>		DATE	: 17-Oct-19
		TIME	: 1940HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehanded</i>	1	\$ 660.30	\$ 660.30
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 320.00	\$ 320.00
4	FRONT BUMPER FOGLAMP LH <i>new</i>	1	\$ 280.00	\$ 280.00
5	FRONT BUMPER FOGLAMP HOUSING LH <i>new</i>	1	\$ 120.00	\$ 120.00
6	HID HEADLAMP LH <i>6t</i>	1	\$ 989.60	\$ 989.60
7	HID HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 65.90	\$ 65.90
8	FRONT FENDER LH <i>Dented</i>	1	\$ 630.00	\$ 630.00
9	FRONT FENDER INNER COWLING LH <i>torn</i>	1	\$ 148.90	\$ 148.90
10	FRONT LOWER ARM LH <i>2</i>	1	\$ 266.00	\$ 266.00
11	FRONT KNUCKLE ARM LH	1	\$ 274.60	\$ 274.60
12	FRONT KNUCKLE ARM BEARING LH <i>HP</i>	1	\$ 138.00	\$ 138.00
13	FRONT SHOCK ABSORBER LH <i>M</i>	1	\$ 342.40	\$ 342.40
14	FRONT WHEEL HUP LH <i>✓</i>	1	\$ 190.20	\$ 190.20

2926.80

TOTAL PRICE \$ 4,557.70

LESS 20% \$ 911.54

2341.44

SUB TOTAL PRICE \$ 3,646.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Ne</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
2	FRONT FENDER INNER COWLING CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00 <i>✓</i>
3	FRONT WHEEL RIM (SET) <i>ut</i>	1	\$ 1,200.00	\$ 1,200.00 <i>450</i>
4	FRONT TYRE LH <i>Ne Ne</i>	1	\$ 350.00	\$ 350.00 <i>x</i>

500 TOTAL \$ 1,630.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>400</i>	
3	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	<i>x</i>	
4	WIRING CHECK	\$ 100.00	<i>30</i>	
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 280.00	<i>x</i>	
6	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>	

TOTAL

\$3,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,276.16
 TOTAL LABOUR COST : \$ 3,080.00
 TOTAL REPAIR COST : \$ 8,356.16

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :
 NO OF DAYS :

FAX :

Adrian Ly
n/s 22/10/19

04 Days

total: 3751.44

1/2 : 31c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: