

S9 MOTOR TRADING PTE LTD

Blk 4001 Ang Mo Kio Industrial Park 1

#01-21 Singapore 569622

Office Tel: 6452 4898 / Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

24/10/2019

LKK - Mr. Bryan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Re: VCA 3937 - Tanaka LC 135-VI

- 1) Head lamp - \$320.00 NH X
- 2) Handle Bar - \$115.00 NH X
- 3) Handle Bar Bracket - \$95.00 NH X
- 4) Handle Grip x 2 - \$160 (2 pcs) NH X
- 5) Balancer - 1 set - ~~\$160~~ Cnt ✓
- 6) Fork Under-bracket - \$180.00 Dm ✓
- 7) Fork tube x 2 pc - \$480.00 / set NH / Ashok ✓
- 8) Cone bearing - \$120 / set Dm ✓
- 9) Front Rim - \$320.00 NH X
- 10) Brake lever - \$65.00 Cnt NH X
- 11) Gear pedal - \$65.00 NH ✓
- 12) Leg Shield - LH - \$125.00 ~~to be replaced~~ NH ✓
- 13) Front Mudguard - \$250.00 broken ✓
- 14) Front Panel - \$185.00 Cnt ✓
- 15) Front LH Fainting - \$195.00 Cnt ✓
- 16) Centre leg shield - \$150.00 money deposit ✓
- 17) Rear LH Fainting - \$165.00 Cnt ✓

S9 MOTOR TRADING PTE LTD

Blk 4001 Ang Mo Kio Industrial Park 1

#01-21 Singapore 569622


Office Tel: 6452 4898 / Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

- 18) Rear - Box - @ 280.00 (Mutt) Int ✓
- 19) Front Box - @ 135.00 ✓
- 20) Foot rest - ~~88~~ @ 65.00 ✓
- 21) Foot rest Bracket - @ 135.00 ✓
- 22) Foot rest - Rubbr - 1 set - ~~88~~ @ 80.00/ea NH ✓

Nett Items:

- 1) Towing fee - @ 40.00 NH
- (2) Remove & Replace necessary parts
align & etc. - ~~250.00~~ 180/-
- 3) Remove & Replace Fork, Assy,
To top fork oil - @ ~~120.00~~ 80/-
- 4) Re align body alignment - @ ~~190.00~~ 50/-

23/10/2019 4:45pm

JKK Adv