

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 16375

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1269/2019/NS
Date : 21-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SLS 4727 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Serene Ching Li-Ling
Address : 159 Lorong Kismis
Singapore 598082
Telephone : HP +65 97338723
Type of Claim : ~~Third Party Claims~~ *OP claims*
Policy No. : 1800057221
Vehicle No : **SMA 575 Z**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : May-18
Engine No : DAX 032647
Chassis No : WAUZZZF2J213644
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Oct-19
Place of Accident : Lorong Kismis (Outside Bukit Timah Pri Sch)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 575 Z

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1000	
3	To respray front bumper, front lower spoiler, rhs front fender and both front wheel arch trims.	\$ 4,000.00 1600	2 x 550 = 1100 Arch trim x 2
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	250 x 2 = 500
TOTAL LABOUR CHARGES		: <u>\$ 7,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 575 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$ 2,364.00	+
2	FRONT BUMPER FIXING PARTS	\$ 244.00	+
3	FRONT BUMPER SECURING STRIP - RH	\$ 34.00	+
4	FRONT BUMPER CLOSING ELEMENT - RH	\$ 101.00	+
5	FRONT BUMPER SPOILER	\$ 685.00	+
6	FRONT BUMPER UNDERRUN BAR	\$ 431.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 519.00	+
8	FRONT BUMPER END CAP - RH	\$ 83.00	+
9	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	+
10	FRONT FENDER - RH <i>Dented</i>	\$ 1,301.00	✓ 1040.80
11	FRONT FENDER BRACE - RH <i>Not Nec</i>	\$ 206.00	? X
12	FRONT BUMPER BRACKET - RH <i>Not Nec</i>	\$ 16.00	? X
13	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 246.00	+
14	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT <i>new</i>	\$ 35.00	+
15	WHEEL SPOILER - RH <i>new</i>	\$ 139.00	+
16	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$ 1,154.00	✓ 922.40
17	HEADLIGHT MOUNTING - RH	\$ 107.00	+
18	LED HEADLIGHT - RH	\$ 7,227.00	+
19	LIFT CYLINDER - RH	\$ 128.00	+
20	SUNDRIES <i>Nec.</i>	\$ 300.00	? ✓ 22.24
TOTAL SPARE PARTS		\$ 15,354.00	
TOTAL LABOUR CHARGES		\$ 7,472.00	
GRAND TOTAL		\$ 22,826.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Adrian Ly

Surveyed Date

: 23/10/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

not authorized, 04 pages

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant