

ASS. REC. BY:

REF: CS/FCI 19018376/UVf3"

Special Instruction:

Sender: MARCUS

ASSIGNMENT (Office)

CWS

From (Person): Jason Tan

of

FCI

Date/Time: 12:17pm 24/10/2014

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No:

JRY 8369

Insured:

SHA 4049J

at Workshop m/s

Fastech Auto

Tel:

67465405.

of

1 Kuki Bukit Ave 6 #01-46

Policy No:

Claim No:

D19006729 MPFH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2014

CA / REV / RHP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:29pm 24/10/14

Person Contacted:

Jason

Vehicle IN OUT

Date/Time

Action/Instruction

Ismauld /

JRY 8369 - X

SHA 4049 J - CS/FCI 1801264/RWD/line

D.O.A. 17/10/2013

24/10/14

Informed FCI pending workshop cost by email

18/11/14

Email preli revised to FCI

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: JR48369
 at Workshop m/s M.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection. 500
 Bal. or Market Value: RM 33k.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: JR48369 Yr Regn: 3, 07
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota Innova c.c. 1998
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 183128 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PN111NV4008610881
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/55-R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/10/19 D.O.I. 24/10/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
all
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>18/11/19</u>	<u>2/5 @ 10,000 confirmed with Alan (Red 18,861, 650)</u>
	<u>mv: RM 33,500f</u>

RECEIVED 19 NOV 2019

Date/Time, File Pass to? ☐ : Prel. Report ☐ : Final Report
 Days Of Repair: 7
 Resurvey No. of Trip: 3
 Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$)
☐ : Tech. Invs (\$) ☐ : WAF (\$)
 Report Format: CWS
 Lump Sum / R.R.: 10,000/-
 Survey Fee: 170 + 270
 Transportation: 50
 S + RS: 50 + 50 + 50
 Photos: 181
 Other: 580
 Total: 821



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006729MFSH

Our ref: CS/FCI19018876/Uvf3

DATE: 18/11/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO JRY 8369


We thank for your instruction on 24/10/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 24/10/2019 at the premises of M/s FASTECH AUTO PTE LTD

Workshop Estimate Amount	: S\$28,861.00
Revised Estimate Amount	: S\$10,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	22-10-2019	Our Ref No.	D19006729MFSH
Accident Date	21-10-2019	Claim Type.	Third Party
Insured Vehicle	SHA4049J	Third Party Vehicle.	JRY8369
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY		
Contact Person.	LINA		
Contact No.	67465405/ 0	Fax No.	67458520
Survey Type	WITHOUT PREJUDICE: NO ESTIMATE GIVEN , NO DIRECT SETTLEMENT		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JASON TEA CHEE KIAT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 18 November 2019 4:33 PM
To: 'CWS Motor Claims'; jasontea@msfirstcapital.com.sg
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1-JRY 8369
Attachments: JRY 8369 PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle JRY 8369
Date of survey: 24/10/2019
Number of days (estimated) : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 25 October 2019 9:23 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; jasontea@msfirstcapital.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1-JRY 8369

Dear Sir/Madam,

Kindly forward copy of SHA 4049J GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 24 October 2019 2:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1-JRY 8369

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JRY 8369 on 23/10/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Thursday, 24 October 2019 12:32 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 24 October 2019 12:17 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19006729MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 24 October 2019 2:02 PM
To: 'CWS Motor Claims'
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1-JRY 8369

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JRY 8369 on 23/10/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 24 October 2019 12:32 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006729MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 24 October 2019 12:17 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006729MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)


Updated on: October 03, 2019

RM 386/month

RM 29,800

2006 Toyota Innova 2.0 G (A) ALL IN GOOD CONDITION

Updated on: October 03, 2019

[Dealer](#) [Perak » Sitiawan »](#)


Seller Information

[Dealer](#)
[Perak » Sitiawan »](#)

Key details

[Registration Card](#) [View](#)
[Car type](#) [Used Car](#)
[Make](#) [Toyota](#)
[Model](#) [Innova](#)
[Variant](#) [G](#)
[Year](#) [2006](#)
[Engine Capacity](#) [1998 cc](#)
[Transmission](#) [Automatic](#)
[Seat Capacity](#) [8](#)
[Mileage](#) [85 - 90K](#)
[Colour](#) [White](#)
[View All 467 Cars From This Seller](#)

Seller's comments

Say Carlist.my for the best deal

GAMMA USED CARS & JKL AUTO TRADING
The Name That You Can TRUST
and RELIABLE In Automobile Industry.

NOBODY SELL USED CAR LIKE US

@@@ WHY YOU MUST BUY FROM US ???
>>> CARS ARE INSPECTED

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)

Updated on: September 05, 2019

RM 408/month

RM 31,500

Seller Information

2007 Toyota Innova 2.0 G (A)

Updated on: September 05, 2019

 Dealer
  Penang » Ayer Itam »

 Dealer

 Penang » Ayer Itam

Key details

	Car type	Used Car
	Make	Toyota
	Model	Innova
	Variant	G
	Year	2007
	Engine Capacity	1998 cc
	Transmission	Automatic
	Seat Capacity	8
	Mileage	125 - 130K
	Colour	Gold



Seller's comments

Say Carlist.my for the best deal

Toyota Innova 2.0G

- Year 2007
- Low mileage
- ABS brake system
- SRS airbags
- Leather seats
- Reverse camera
- Rear aircon
- Chrome handle
- Walnut panel
- 15" sport rims

Mastertan Auto Sdn Bhd



SIJIL PEMILIKAN KENDERAAN

AA5658Y

JABATAN PENGANGKUTAN JALAN

No Pendaftaran	: JRY8369
No ID	: 810222018345
Nama Pemunya Berdaftar	: AM CHH SIONG
Alamat	: 58131/6, JLN PTROKAK SENGKARANG 83200 BATU PAHAT JOHOR
No Chassis No. Enjin	: PN11NV4003610881 / 1TR0348189
Buatan/Nama Model	: TOYOTA / INNOVA 2.0 G (A)
Kemungkinan Enjin	: 1988
Dehan Bekar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: PERSENDERIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat	: MOTOKAR PELBAGAI UTILITI / 2007
Tarikh Pendaftaran	: 29/03/2007
B D M/B. G. K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -

Participant AW CHI SIONG KAMPUNG PARIT BOTAK MUKIM 10 SENGGARANG 83200 JOHOR	Certificate No.	: TVP-81510598-J4
	Account No.	: V0030229
	Agent Name	: SOGOMAS AUTO
	Product Type	: Private Car - Private Use
	Period of Takaful from 02/05/2019 To 01/05/2020 (both Dates Inclusive). Any subsequent period for which the Participant shall pay and the Takaful Operator shall agree to accept a renewal contribution.	

NRIC No	: 810222-01-8345	Business Reg No	:		Vehicle Estimated Value	RM	42000.00
Business/Occupation	: Executive	Other ID No	:		Gross Contribution	RM	1313.77
Vehicle Information					Less: No Claim Discount 38.33%	RM	503.57
JPJ Document No	:	Log Book No	: NIL		Windscreen (RM1,000.00)	RM	150.00
Vehicle Reg No	: JRY8369				Legal liability to passengers (driver's liability)	RM	67.80
Make	: TOYOTA				Legal liability to passenger for act of negligence	RM	7.50
Model	: INNOVA NA	Cover Type	: Comprehensive			RM	1035.50
Engine No	: 1TR6348189	Vehicle Type	: Private Car		Add : Service Tax 6.00 %	RM	62.13
Chassis No	: PN111NV4008610881	License Type	: Normal Vehicle		Stamp Duty	RM	10.00
Year of Manufacture	: 2007	Use For	: Private Use				
Cubic Capacity	: 1998				TOTAL AMOUNT DUE	RM	1107.63
Seating Capacity	: 8						
Financial Interest	: NIL				Excess All Claims	RM	0.00
Authorised Driver							
1	AW CHI SIONG	810222-01-8345					
2	ANY AUTHORISED DRIVER						

Subject to the following warranties, endorsements and clauses incorporated herein and forming part of the Policy.

Clause Code	Clause Name
B001	EXCESS ALL CLAIMS
M003	SANCTION LIMITATION AND EXCLUSION CLAUSE
N002	INFORMATION ON ePOLICY
M004	IMPORTANT NOTICE
B089	WINDSCREEN GLASS
B072	LEGAL LIABILITY OF PASSENGERS FOR ACTS OF NEGLIGENCE
M007	MINIMUM CONTRIBUTION
B087	AGREED VALUE CLAUSE

MEMO

INFORMATION ON ePOLICY

In line with our Group's strategy to promote usage of technology and to help preserve the country's natural resources, we no longer print the full policy/certificate wording. You may view and print the above policy/certificate wording at our website www.etiqa.com.my. Printout may also be obtained from our offices nationwide.

SANCTION LIMITATION AND EXCLUSION CLAUSE

This takaful certificate shall not provide cover and the Company shall not be liable to pay any claim or provide any benefit hereunder to the extent that the provision of such cover, payment of such claim, or provision of such benefit would expose the Company to any Sanction, prohibition or restriction under the CISAD Act or United Nations resolutions or trade or economic sanctions, laws or regulations of the European Union, United Kingdom.

Wef 1 Jan 2014, prohibition or restriction under the CISAD Act is replaced by laws or regulations of United States of America

MINIMUM CONTRIBUTION

The Certificate is subject to RM50.00 minimum contribution.



Visit www.etiqa.com.my or our nearest branch to obtain the full policy wordings.
Help preserve the country's natural resources.



CERTIFICATE OF TAKAFUL

Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)
 Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
 Motor Vehicles (Third Party Risks & Compensation) Rules 1960 (Republic of Singapore)
 Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam

MOTOR - PRIVATE CAR	Comprehensive	RM	42,000.00
MX1 -- Private Car - Private Use	Excess All Claims	RM	0.00

Index Mark and Vehicle Registration No.

Certificate No.

JRY8369

TVP-81510598-J4

Name of Participant

AW CHI SIONG

Effective Date of the Commencement of Takaful for the purpose of the Regulations, Ordinance or Enactment

Date of Expiry of Takaful

02/05/2019

01/05/2020

Persons or Classes of Persons entitled to drive

- (a) The Certificateholder
 (b) Any other person who is driving on the Certificateholder's order or with his permission.

Limitations as to use

Use only for social, domestic and pleasure purposes and for the Certificateholder's business.

The Certificateholder does not cover use for hire or reward, racing, pace-making, reliability trial, speedtesting the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Limitation rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.

I / We certify that the Certificate to which this Certificate relates is issued in accordance with the provision of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

For and behalf of
 Etiqa General Takaful
 Berhad



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/10/2019 10:01	Vide Report No.: F/20191021/0070	Station Diary No.: 30
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: AW CHI SIONG			Address: MALAYSIA JH KAMPUNG PARIT BOTAK MUKIM 10 83200 SENGGARANG JOHO	
ID Type / ID No.: FIN NO / F8428573X			Contact No.: Home/Office:	Mobile: 93955564
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 38	Date of Birth: 22/02/1981	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Construction Worker			Driving Licence Information: Class:	
			Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/10/2019 13:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 SENGKANG EAST WAY ANCHORVALE ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRY8369	Car	TOYOTA	INNOVA	Silver	Totally Damaged	0
SHA4049J	Car	HYUNDAI	AVANTE	Blue	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Driver			
Name	AW CHI SIONG	ID No.	F8428573X
Related Vehicle	JRY8369 (Car)	Contact No.	93955564
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/10/2019	Date Discharge	22/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious
Driver			
Name	CHUA KWAN CHENG	ID No.	S7508194D
Related Vehicle	SHA4049J (Car)	Contact No.	96915179
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/10/2019 at about 1340hrs, while I was driving my Malaysian registered vehicle bearing vehicle number JRY8369 along the second lane of Sengkang East Way, I had stopped my vehicle at the junction of Sengkang East Way and Anchorvale Road as the traffic light was red.

Later at about 1345hrs, as the traffic light turned green, I moved off. While my vehicle was entering the said cross junction, out of sudden I saw a blue coloured Taxi bearing vehicle registered number SHA4049J which came out from Anchorvale Road and appeared in front of vehicle. As it was sudden, I was unable to stop in time. As a result, there was a collision between the front portion of my vehicle and right portion of the said Taxi. Upon the collision, I came out of my vehicle and approached the Taxi driver. The Taxi driver apologies to me and admitted that he had beat the red light. Subsequently, ambulance and Traffic police arrived at scene. I was conveyed to Sengkang General Hospital and received 03 days of MC. I had sustained pain on my chest and neck due to the collision. I also wish to state that the front portion of my vehicle was badly damage due to the collision.

That is all.



**SINGAPORE
POLICE FORCE**



T/20191022/2025

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20191022/2025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sr Staff Sgt MOHAMAD AZHAR BIN ABDUL
AZIZ

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168



Signature

Singapore Police Force

Signature Of Informant:


S10+6

Date/Time:
22/10/2019 10:01

Classification Of Case:

21/10/2019 1:45 PM

OWNER CONVEY BY AMBULANCE,
ADMITTED TO HOSPITAL



③

②

①

ANCHORAGE RD
(ANCHORAGE ST)



TRY 8369

SENGKANG EAST WAY TOWARD
JALAN KAYU

SENGKANG EAST WAY
(SENGKANG EAST RD)



FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: JRY 8369

QTY	PARTICULAR	
1 PCS	BONNET	739.10
1 PCS	BONNET OUTER CHROME MOULDING	165.30
2 PCS	BONNET HINGES @\$66.50	
1 PCS	BONNET RUBBER SEAL	
1 PCS	BONNET LOCK	
1 SET	BONNET INSULATOR CLIPS	
1 PCS	FRONT BUNPER	573.10
2 PCS	FRONT BUMPER SIDE RETAINERS @\$66.50	
1 PCS	FRONT BUMPER CENTRE GRILLE	145.30
1 PCS	FRONT BUMPER LOWER SKIRTING	480.00
1 PCS	FRONT BUMPER REINFORCEMENT	339.10
2 PCS	FRONT BUMPER BRACKETS @\$115.00	65.00
2 PCS	FRONT BUMPER FOG LAMPS @\$450.00	325.00
1 SET	FRONT BUMPER CLIPS	
1 PCS	FRONT GRILLE	
1 PCS	FRONT GRILLE LOGO	48.50
1 PCS	FRONT SUPPORT PANEL	
1 PCS	FRONT BRACE PANEL	151.00
1 PCS	RADIATOR	979.10
1 PCS	RADIATOR FAN ASSY	610.10
1 PCS	A/C CONDENSER	
1 PCS	A/C CONDENSER FAN ASSY	605.00
2 PCS	A/C CONDENSER BRACKETS @25.00	
1 SET	HEADLAMPS @\$650.00	508.50 x 2 = 1017.00
1 PCS	RADIATOR SPARE TANK	
1 PCS	BATTERY BRACKET	
2 PCS	FRONT FENDERS @\$622.30	462.50
2 PCS	FRONT FENDER INNERSHIELD @\$215.00	181.10 x 2 = 362.20
1 SET	FRONT FENDER INNERSHIELD CLIPS	
1 PCS	AIR CLEANER BOX ASSY	725.50
2 PCS	HORN UNIT @\$105.00	
2 PCS	HEADLAMP PANELS @\$699.00	
1 PCS	POWER STEERING PUMP	950.30
1 PCS	ALTERNATOR ASSY	1150.00
1 PCS	ALTERNATOR FAN BELT	
1 PCS	FRONT WINDSCREEN	1221.10
1 PCS	FRONT WINDSCREEN MOULDING	
1 PCS	FRONT DOOR N/S	
1 PCS	FRONT DOOR PROTECTOR N/S	
1 PCS	AIR CON COMPRESSOR	
1 PCS	WIPER WASHER TANK	

S.NETT

1 PCS	FRONT LICENCE PLATE
1 PCS	BATTERY
1 BOL	RADIATOR COOLANT

not Authorized
26/11
28/10/18
1/5 *10,000/
th. ph. other sp -
7dy.

Buc	\$839.10	
S20	\$287.30	
nlscnt	\$133.00	1pc
11	\$39.00	X
11	\$145.50	
11	\$30.00	X
11	\$673.10	
sub/cn	\$133.00	
11	\$188.20	
11	\$680.00	
11	\$437.10	
nlscnt	\$230.00	1pc
nlscnt	\$900.00	1pc
11	\$45.00	
S20	\$362.10	
11	\$85.50	
11	\$519.30	
11	\$221.90	
sub/cn	\$1,455.10	
cn/11	\$686.50	
11	\$1,163.90	
cn/11	\$650.50	
11	\$50.00	X
S20	\$1,300.00	
11	\$88.20	X
11	\$105.00	X
nlscnt	\$1,244.60	1pc
nlscnt	\$430.00	
11	\$50.00	
cn	\$877.20	
11	\$210.00	X
11	\$1,398.00	X
sub/cn	\$1,860.00	
sub/cn	\$1,995.00	
cn	\$148.00	5025.11
cn	\$866.20	
11	\$142.00	
11	\$915.20	X
11	\$188.50	X
11	\$2,150.00	X
11	\$266.00	X
	\$24,151.00	

cn	\$20.00	14
S20	\$200.00	X
11	\$50.00	30

1334650
1000987

1 PCS	FRONT WINDSCREEN SEALANT			121	\$50.00	40
	LABOUR CHARGES					
	TO CHECK WIRING				\$80.00	30
	TO REFILL AIR CON GAS				\$150.00	100
	TO DISMANTLE & REFIX FRONT WINDSCREEN				\$150.00	120
	TO CONDUCT WHEEL ALIGNMENT			11	\$100.00	X
	TO SPRAY RUST PROOFING				\$150.00	90
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE			11	\$380.00	X
	TO MOUNT VEHICLE ON CAR O-LINER			11	\$380.00	X
	LABOUR FOR PANEL BEATING & REPLACING PARTS				\$1,500.00	900
	TO PUTTY & SPRAY PAINTING				\$1,500.00	1200
				TOTAL	\$28,861.00	

2524

I hereby certify that I have notified
 the following:
 1. The relevant authorities.
 2. The relevant insurance company.
 3. The relevant police station.
 4. The relevant fire station.
 5. The relevant hospital.
 6. The relevant ambulance.
 7. The relevant police station.
 8. The relevant fire station.
 9. The relevant hospital.
 10. The relevant ambulance.

I hereby certify that I have notified
 the following:
 1. The relevant authorities.
 2. The relevant insurance company.
 3. The relevant police station.
 4. The relevant fire station.
 5. The relevant hospital.
 6. The relevant ambulance.

I hereby certify that I have notified
 the following:
 1. The relevant authorities.
 2. The relevant insurance company.
 3. The relevant police station.
 4. The relevant fire station.
 5. The relevant hospital.
 6. The relevant ambulance.

I hereby certify that I have notified
 the following:
 1. The relevant authorities.
 2. The relevant insurance company.
 3. The relevant police station.
 4. The relevant fire station.
 5. The relevant hospital.
 6. The relevant ambulance.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018876/Uvf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4049J	Veh. Inspected	JRY 8369	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006729MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	24/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA INNOVA (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	PN111NV4008610881	Colour	SILVER	
Odometer	183128	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	MICHELIN	6 mm	
L/H Front Tyre	215/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/10/2019	Inspection Date	24/10/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRY 8369

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	839.10	739.10
1	BONNET OUTER CHROME MOULDING	BROKEN	267.30	165.30
2	BONNET HINGES @\$66.50	N/S BENT	133.00	66.50
1	BONNET RUBBER SEAL	NOT NECESSARY	39.00	-
1	BONNET LOCK	TWISTED	145.50	145.50
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	30.00	-
1	FRONT BUMPER	DISTORTED	673.10	573.10
2	FRONT BUMPER SIDE RETAINERS @\$66.50	BENT / CRACKED	133.00	133.00
1	FRONT BUMPER CENTRE GRILLE	DISTORTED	188.20	145.30
1	FRONT BUMPER LOWER SKIRTING	DISTORTED	680.00	480.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	437.10	339.10
2	FRONT BUMPER BRACKETS @\$115.00	N/S BENT	230.00	65.00
2	FRONT BUMPER FOG LAMPS @\$450.00	N/S CRACKED	900.00	325.00
1	SET FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT GRILLE	BROKEN	362.10	362.10
1	FRONT GRILLE LOGO	NECESSARY	65.50	48.50
1	FRONT SUPPORT PANEL	BENT	519.30	519.30
1	FRONT BRACE PANEL	TWISTED	221.90	151.00
1	RADIATOR	BENT / PUNCTURE	1,455.10	939.10
1	RADIATOR FAN ASSY	CRACKED / JAMMED	688.50	610.10
1	A/C CONDENSER	DISTORTED	1,163.90	1,163.90
1	A/C CONDENSER FAN ASSY	CRACKED / JAMMED	650.50	605.00
2	A/C CONDENSER BRACKETS @\$25.00	NOT NECESSARY	50.00	-
2	HEADLAMPS @\$650.00	BROKEN	1,300.00	1,017.00
1	RADIATOR SPARE TANK	NOT NECESSARY	88.20	-
1	BATTERY BRACKET	NOT NECESSARY	105.00	-
2	FRONT FENDERS @\$622.30	N/S BUCKLED	1,244.60	462.50
2	FRONT FENDER INNERSHIELD @\$215.00	DEFORMED / TORN	430.00	362.20
1	SET FRONT FENDER INNERSHIELD CLIPS	NECESSARY	50.00	50.00

Report Ref No. CS/FCI19018876/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CLEANER BOX ASSY	CRACKED	877.20	725.50
2	HORN UNIT @\$105.00	NOT NECESSARY	210.00	-
2	HEADLAMP PANELS @\$699.00	TO REPAIR SEE LABOUR	1,398.00	-
1	POWER STEERING PUMP	BENT / JAMMED	1,860.00	950.30
1	ALTERNATOR ASSY	BENT / JAMMED	1,995.00	1,150.00
1	FRONT WINDSCREEN	CRACKED	866.20	866.20
1	FRONT WINDSCREEN MOULDING	NECESSARY	142.00	142.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	915.20	-
1	FRONT DOOR PROTECTOR N/S	NOT NECESSARY	188.50	-
1	AIR CON COMPRESSOR	SERVICEABLE	2,150.00	-
1	WIPER WASHER TANK	NOT NECESSARY	266.00	-
	LESS 25% DISCOUNT		-	-3,336.65
			24,003.00	10,009.95
	<u>SPECIAL NETT ITEMS</u>			
1	ALTERNATOR FAN BELT (50%)(SN)	CUT	148.00	74.00
1	FRONT LICENCE PLATE (SN)	CRACKED	20.00	14.00
1	BATTERY (SN)	SERVICEABLE	200.00	-
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			468.00	158.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN.		150.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		150.00	90.00
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF HEADLAMP PANELS AND FRONT DOOR N/S.		1,500.00	900.00

Report Ref No. CS/FCI19018876/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			4,390.00	2,440.00
GRAND TOTAL			28,861.00	12,607.95

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00
---	--	--	-----------

Report Ref No. CS/FC119018876/Uvf3n2

MARKET VALUE: RM 33,500.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.