

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

22/10/2019

Owner: ANC MOTORING PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR8275J

1pc	front bonnet	R1	\$ 892.30	✓
2pcs	front bonnet hinge @\$65.80	D14	\$ 131.60	✓
1pc	front bonnet inner lock	R1	\$ 87.70	✓
1pc	front bonnet inner lock bracket	R1	\$ 95.20	✓
1pc	front bonnet inner cardboard	reform	\$ 185.00	✓
8pcs	front bonnet inner cardboard clip @\$5.00	m	\$ 40.00	✓
2pcs	front bonnet inner centre rubber @\$85.50	cm	\$ 171.00	✓
2pcs	front bonnet inner side rubber @\$80.50	NIS cm	\$ 161.00	✓
1pc	front bonnet lock side garnish	cm	\$ 85.00	✓
2pcs	front headlamp @\$1559.40	nty Bro	\$ 3,118.80	✓
2pcs	front headlamp lower bracket @\$35.00	cm	\$ 70.00	✓
2pcs	front headlamp top bracket @\$28.85	cm	\$ 57.70	✓
1pc	front centre grille base	cm	\$ 542.20	✓
1pc	front centre grille outer garnish	cm	\$ 385.00	✓
1pc	front centre grille chrome	cm	\$ 108.00	✓
1pc	front centre grille "HONDA" logo	nty	\$ 58.85	✓
1pc	front bumper	R1	\$ 927.50	✓
2pcs	front bumper side retainer @\$31.70	D11	\$ 63.40	✓
1pc	front bumper grille	cm	\$ 260.00	✓
1pc	front bumper lower spoiler	D11	\$ 351.00	✓
20pcs	front bumper clip @\$5.00	m	\$ 100.00	✓
1pc	front bumper reinforcement	R1	\$ 321.50	✓
2pcs	front bumper reinforcement garnish @\$65.25	D11	\$ 130.50	✓
2pcs	front bumper fog lamp @\$285.85		\$ 571.70	?
2pcs	front bumper fog lamp base @\$80.25		\$ 160.50	?
2pcs	front bumper fog lamp garnish @\$185.85		\$ 371.70	?
1pc	front support panel	R1	\$ 676.20	✓
1pc	front support panel top garnish	cm	\$ 95.00	✓
2pcs	front support panel side garnish @\$75.85	cm	\$ 151.70	✓
1pc	front air con condenser	R1	\$ 668.10	✓
1pc	front air con condenser pipe 1		\$ 180.50	?
1pc	front air con condenser pipe 2		\$ 190.50	?
1pc	front air con condenser cowling		\$ 185.80	?
1pc	front air con condenser cowling motor		\$ 385.25	?
1pc	front air con condenser cowling motor fan		\$ 120.50	?
1pc	front radiator	R1	\$ 1,250.60	✓
1pc	front radiator top hose		\$ 85.20	?
1pc	front radiator lower hose		\$ 92.50	?
	balance c/f		\$ 13,529.00	



India
Kenneth
23/10/19

Not Authorised
L1 Sy B7
Recovery After Repair
7 - days

輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

22/10/2019

Owner: ANC MOTORING PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR8275J

balance b/f		\$ 13,529.00	
1pc	front radiator cowling	\$ 185.50	✓
1pc	front radiator cowling motor	\$ 350.50	✓
1pc	front radiator cowling motor fan	\$ 135.50	✓
1pc	front radiator spare tank	\$ 185.25	✓
1pc	front manifold	\$ 1,250.50	✓
2pcs	front horn @\$95.00	\$ 190.00	✓
1pc	front wiper garnish	\$ 385.20	✓
2pcs	front wiper garnish side rubber @\$85.50	\$ 171.00	✓
1pc	front wiper tank	\$ 281.50	✓
1pc	front wiper tank arm	\$ 125.00	✓
1pc	front air chamber	\$ 123.25	✓
2pcs	front fender @\$580.00	\$ 1,160.00	✓
2pcs	front fender protector @\$195.00	\$ 390.00	✓
2pcs	front fender "HYBRID" emblem @\$65.50	\$ 131.00	✓
2pcs	front fender inner shield @\$195.00	\$ 390.00	✗
20pcs	front fender inner shield clip @\$5.00	\$ 100.00	✗
		\$ 19,083.20	
less 20%		\$ 3,816.64	
		\$ 15,266.56	
remover & refit radiator & air-con condenser		\$ 250.00	100d
towing		\$ 100.00	✓
alignment		\$ 60.00	✓
wiring		\$ 250.00	30d
tuffkote		\$ 280.00	120d
spray painting		\$ 1,600.00	1100d
labour charges		\$ 1,600.00	800d
Total			
		\$ 19,406.56	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____