

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4 , #03-50 , Premier @ KB , Singapore 415875

Tel : 62459655 / 8653 6483 (Xiang) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com

TP INS : AXA

Veh No. : SJX 549 P

Veh Model : Toyota Vois

No. List items

- 1 Rear Bumper
- 2 Rear Bumper Side Retainer RH
- 3 Tail lamp RH
- 4 Rear Fender RH
- 5 Rear Fender Inner cowling RH
- 6 Rear Shock Absorber RH
- 7 Rear Wheel Hub With Bearing RH
- 8 Rear Axle

QTY

Amount

1	1	\$ 476.50	✓
1	1	\$ 98.50	X
1	1	\$ 451.30	X
1	1	\$ 775.00	X
1	1	\$ 107.00	?
1	1	\$ 151.20	?
1	1	\$ 571.75	?
1	1	\$ 1,776.75	?

Sub-Total : \$4408

Less 25%

Total : \$3306

S/N

- Rear Bumper Clips
Rear Fender Inner Cowling Clips
Rear Sport Rim RH
Rear Tyre RH

1Set	1	\$ 50.00	✓
1Set	1	\$ 50.00	X
1	1	\$ 500.00	400
1	1	\$ 400.00	600 1200

S/N Total : \$1000

Labour

- Wire Check
R&R Rear Undercarriage
R&R Rear Reverse Sensor
Tuff Coat
Labour
Painting

\$ 50.00	20
\$ 250.00	?
\$ 50.00	40
\$ 100.00	X
\$ 1,000.00	300
\$ 1,000.00	400

Labour Total : \$2450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not signed
24/10/19
24/10/19