



Final Report

Estimate No. : **b1 53198**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Lim Kai Seong
4E Lim Ah Pin Road

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 547853

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ586G	WBA6V12090ED0567	27/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good rear bumper and rear right fender including to remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00 ✓
To respray rear bumper and rear right fender.	1,730.00	0	1,730.00 ✓
To check steering geometry and conduct wheel alignment accordance with BMW specifications. (1x).	531.00	0	531.00 ✓
To replace rear right wheel rim including balancing.	94.00	0	94.00 ✓
# To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 7.5X17 MULTI SPK 547 ✓	921.70	1.00	0	921.70

Total Labour :	4,285.00
Total Parts :	921.70
Total Labour & Parts :	5,206.70 ✓
GST @7%:	364.47
Grand Total :	5,571.17

LOSS OF USE = \$60 X 4 DAYS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W/ GST Reg. No. M2-0020061-X



Supplementary

Estimate No. : **b1 53198**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Lim Kai Seong
4E Lim Ah Pin Road

Singapore 547853

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ586G	WBA6V12090ED0567	27/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To check electrical wiring systems and lightings at the rear section for proper function. ✓ <i>REC</i>	150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	150.00
Total Parts :	
Total Labour & Parts :	150.00

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax 64796601
64796624

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature:

Date:

GST REG. NO : M2 - 0020081

24 OCT 2019

E S T I M A T E

Estimate No. : b1 53198
Date Estimated : 24/10/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Lim Kai Seong
4E Lim Ah Pin Road

Singapore 547853

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ586G	WBA6V12090ED05675	27/12/2018	216i GT	0

DESCRIPTION

Replace rear bumper and remove attachment etc include repair (P-H/L) on damage area

VALUE

2,125.00

Spray painting rear bumper and right rear side fender

1,923.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

531.00

To replace tyre and wheel rim including balancing. (1x) right rear

94.00

Sundries.

150.00

Total Labour 1: 4,823.00

DESCRIPTION

ALLOY RIM 7.5X17 MULTI SPK 547 CM
HUB CAP WITH CHROME EDGE X
RR BUMPER RH SIDE GUIDE X
LEFT PROTECT X
RIGHT PROTECT X
REAR BUMPER PANEL PRIMED (LINES PDC X R

QTY	PRIC	VALUE
1	921.70	921.70
1	28.95	28.95
1	61.35	61.35
1	11.20	11.20
1	11.20	11.20
1	1,045.45	1,045.45

Total Parts : 2,079.85

Star (LKK) ML 14/12 2/12/19, 11:30am
4 dy
P/P
Ry BeL SPY

Labour 1	:	4,823.00
Parts	:	2,079.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	483.20
Grand Total	:	7,386.05

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **