

CC3/A1G19018933/Axd3n2

ASSIGNMENT

Merimen

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: 1800074627
 Claims No: _____
 Sum Insured: _____ Excess: 30/-
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Est. Repairs: 3 days Res: Yes or No
 Turn Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SY868M Reg: 2018 June
 Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or

Make: Audi Q5 CC: 1984
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 18936 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/Nr: WAU222FY1J2136493

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 235/55R19
 R: 235/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: 2/9/19 D.O.I: 24/10/19

Survey held at Premium

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD 9/19
	SY868M - CS1C119016/1A/Axd3
	12/11/2019
25/10/19	Revert via merimen
29/10/19	@ 15:03 pm mandate approved by victor koh via merimen
29/10/19	@ 15:28 pm informed CIA to Lee Sang (repair) via email.

RECEIVED 24 MAR 2020

18/20 Final dig \$6449.76 (Red 5948.24, 489) confirmed by email

Date/Time, File Path: ☐ : Preli. Report

ly: ☐ : Final Report

Date/Time, File Path: ☐ : Final Report

24/3 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp 15

☐ : Interview 15

☐ : Tech Insp 15

☐ : Other 15

Survey Fee

Transportation

S + P2 11

Other

Any

200

11

211

Page 2 of 2
 6449.76

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Oct 2019

Preliminary Advice

Vehicle No	: SJY868M	Accident Date	: 02/09/2019
Make	: AUDI Q5 SPORT	Policy No.	: 1800074627
Assignment Date	: 25/10/2019	Excess	: S\$0.00
Date of Inspection	: 24/10/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,398.00
Revised Amount	:S\$	6,118.50
Check Items (Estimated)	:S\$	513.00
Total	:S\$	6,631.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	72,426.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107,574.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

View Received Message

This mail is associated with :

***SJY868M (9101906277SG)**

OD

Sep 2 2019 4:50PM

[OMNITITAN VENTURE PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/02/2020 15:36 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6449.76) - SJY868M - Claim Handler: Chan, Yoke Shi

Approved:6449.76:

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 29 October 2019 3:28 pm
To: Claims
Cc: SUR
Subject: SJY 868M OD (AIG) Date of Loss - 02/09/2019

Hi All,

As instructed by our client, please proceed to repair the insured vehicle **SJY 868M (Excess S 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (ON BEHALF OF VERON)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SJY868M (91019062775G)**

OD

Sep 2 2019 4:50PM

[OMNITITAN VENTURE PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 29/10/2019 15:03 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6118.50) - SJY868M - Claim Handler: Chan, Yoke Shi

Approved:6118.50:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 25 October 2019 4:52 PM
To: Veron Chen (LKKAUTO); SUR
Cc: 'Claims'
Subject: RE: SJY 868M-DOA: 2/9/2019 (AIG OD)
Attachments: SJY 868 M - 02092019 ADDENDUM.PDF

Dear all,

Attached is the amended GIA report.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 25 October 2019 3:14 PM
To: 'Chang Chee Sing' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: (nora.khai@premiumauto.com.sg) <nora.khai@premiumauto.com.sg>
Subject: SJY 868M-DOA: 2/9/2019 (AIG OD)

Dear Tony,

Kindly assist.

- OD claim # SJY868M # verify on driver's name and make necessary

From: Chan, Yoke Shi

To: Claims, SUR

Cc: Lim, Sheng Yang, Parthiban, Theerthan, Mohd Rizal, Nur Mariah Huibrechts

Sent: 25/10/2019 3:01:42 PM

Dear Team,

Please assist to verify and check the correct driver's name and assist to file addendum.

Driver

Name of Driver

YIP MUN

Thank you

Regards,

Chan Yoke Shi

AIG

Express Claim Adjuster,

Singapore- Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1012102

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 25 October 2019 5:01 PM
To: 'Chan, Yoke Shi'; Claims; SUR
Cc: Lim, Sheng Yang; Parthiban, Theerthan; Mohd Rizal, Nur Mariah Huibrechts
Subject: RE: - OD claim # SJY868M # verify on driver's name and make necessary addendum
Attachments: SJY 868 M - 02092019 ADDENDUM.PDF

Dear Yoke Shi,

Addendum uploaded in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Yoke Shi <yokeshi.chan@aig.com>
Sent: Friday, 25 October 2019 3:02 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: Lim, Sheng Yang <ShengYang.Lim@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Mohd Rizal, Nur Mariah Huibrechts <NurMariahHuibrechts.MohdRizal@aig.com>
Subject: - OD claim # SJY868M # verify on driver's name and make necessary addendum



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면
첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-11-01 15:01 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

- OD claim # SJY868M # verify on driver's name and make necessa...

From: Chan, Yoke Shi
To: Claims, SUR
Cc: Lim, Sheng Yang, Parthiban, Theerthan, Mohd Rizal, Nur Mariah Hulbrechts
Sent: 25/10/2019 3:01:42 PM

Dear Team,

Please assist to verify and check the correct driver's name and assist to file addendum.

Driver

Name of Driver	YIP MUN
----------------	---------

Thank you

Regards,

Chan Yoke Shi
AIG
Express Claim Adjuster,
Singapore- Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 18 February 2020 4:48 PM
To: Boo seng yak; Carrine Leong; Chang Chee Sing; jlayee.yap@premiumauto.com.sg; SUR; (nora.khai@premiumauto.com.sg)
Subject: RE: FINAL REVISION SJY868M - OD CHINA - SURVEYED 24 OCT 19

Dear Mr Boo,

Confirm repair cost of \$6449.76 before GST @ 3 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Saturday, 18 January 2020 5:20 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jlayee.yap@premiumauto.com.sg

Subject: FINAL REVISION SJY868M - OD CHINA - SURVEYED 24 OCT 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$6449.76 @ 3 days. Please revise labour rate frog AIG to China Taiping.

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	491C
Vehicle Details	
Vehicle No.:	SJY868M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	DAX033136
Chassis No.:	WAUZZZFY1J2136493
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$44,968.00
Original Registration Date:	27 Jun 2018
First Registration Date:	27 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$54,956.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2028
PARF Rebate Amount:	\$41,217.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,000.00
COE Rebate Amount:	\$31,209.00
Total Rebate Amount:	\$72,426.00

The information contained herein is correct as at 25 Oct 2019

OK

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6724 0010 Fax (65) 6724 0030
 Operating Hours : Monday to Friday, 09:00 – 17:00
 UEN: S60500020 / GST Reg. No.: M400617721

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA119117974 Vehicle Registration No: SJY868M
 Name (as shown in NRIC) : YIP MUN NRIC/FIN/Passport No : S6903944H
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : 10 UBI CRESCENT #106-100 Singapore: 408564
 Contact (Tel) : _____ Mobile No.: 90100928
 Email Address : MUN@omnititan.com.sg
 Date of Accident : 02/09/2019 Time of Accident : 16:50
 Place of Accident : DUNMAN ROAD
 Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

CONVERT CLAIM TO OD CLAIM

Policyholder / Driver's Signature
 Date: _____



TONY FOONG
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #28-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0050
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S665500200 / GST Reg. No.: M800017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA 112117174-02 Vehicle Registration No: SDT 868 W
Name(as shown in NRIC) : YIP SOCK MUN NRIC/FIN/Passport No : S6903944 H
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 10 UBI CRESCENT # 06-100 Singapore(478544)
Contact (Tel) : _____ Mobile No. : 96100928
Email Address : YIPMUN@gmail.com
Date of Accident : 02/09/2014 Time of Accident : 16:50
Place of Accident : DUNMAN ROAD
Insurance Company : AIU

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To change driver's name from YIP MUN to YIP SOCK MUN

Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name: Gay Fong
NRIC/FIN No.: G20421071
Date: 25/10/14

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11317

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1090/2019/NS
Date : 10-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Omnititan Venture Pte Ltd
Address : 8 Amber Road
#10-04
Singapore 439853
Telephone : HP +65 90100928
Type of Claim : Own Damage Claim
Policy No. : 1800074627
Vehicle No : **SJY 868 M**
Model Code : Audi Q5 SPORT 2.0 TFSI QU
Model / Year : 27/6/2018
Engine No : DAX 033136
Chassis No : WAUZZZF1J2136493
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-19
Place of Accident : Dunman Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJY 868 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 ¹⁶⁰⁰ 500.800 ⁸⁸⁸	⁸⁸⁸
3	To respray rear upper bumper, rear lower bumper and both rear wheel arch trims.	\$ 3,000.00 ¹⁶⁰⁰	^{2 x 550 = 1100} ^{Arch Trim x 02 = 250 x 2 = 500}
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓ ⁵⁰⁰
SUB TOTAL LABOUR CHARGES		: \$ 4,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 868 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER <i>Repair</i>	\$ 1,571.00	+
2	REAR BUMPER - LOWER <i>3 replaced</i>	\$ 1,077.00	✓ 861.60
3	REAR BUMPER SPOILER	\$ 754.00	✓ 602.80
4	REAR BUMPER TOWING EYE COVER - LH / RH <i>2 new 2 replaced</i>	\$ 69.00	34.50 X
5	REAR BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 86.00	+
6	REAR BUMPER TRIM - RH <i>blue new</i>	\$ 213.00	? X
7	TAIL LIGHT - RH <i>cracked</i>	\$ 627.00	✓ 501.60
8	BOOT LID CONTROL UNIT	\$ 387.00	+
9	REAR BUMPER CARRIER	\$ 831.00	+
10	REAR BUMPER HOLDING STRAP	\$ 151.00	✓ 130.80
11	REAR BUMPER GUIDE SECTION - RH	\$ 76.00	+
12	REAR BUMPER FOAM FILLER PIECE - RH	\$ 56.00	+
13	REAR PARKING AID SENSOR	2 \$ 462.00	+
14	REAR PARKING AID SENSOR SEAL RING	4 \$ 12.00	+
15	REAR WHEEL COVER - LH / RH <i>new</i>	2 \$ 974.00	✓ 779.20
16	SUNDRIES <i>Real</i>	\$ 300.00	? 31.76
TOTAL SPARE PARTS		: \$ 7,646.00	
TOTAL LABOUR CHARGES		: \$ 4,752.00	
GRAND TOTAL		: <u>\$ 12,398.00</u>	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 24/10/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11317

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1090/2019/NS
Date : 10-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Hi Adrian

3 days - ok - jb - 20 Jan 20

Please revise labour - NOT AIG

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Omnititan Venture Pte Ltd
Address : 8 Amber Road
#10-04
Singapore 439853
Telephone : HP +65 90100928
Type of Claim : Own Damage Claim
Policy No. : 1800074627
Vehicle No : **SJY 868 M**
Model Code : Audi Q5 SPORT 2.0 TFSI QU
Model / Year : 27/6/2018
Engine No : DAX 033136
Chassis No : WAUZZZF1J2136493
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-19
Place of Accident : Dunman Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJY 868 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 800.00
3	Top respray rear upper bumper, rear lower bumper and both rear wheel arch trims.		\$ 3,000.00	\$ 2,200.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		:	<u>\$ 4,752.00</u>	<u>\$ 3,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 868 M

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	REAR BUMPER - UPPER	\$ 1,571.00	
2	REAR BUMPER - LOWER	\$ 1,077.00	\$ 861.60
3	REAR BUMPER SPOILER	\$ 754.00	\$ 602.80
4	REAR BUMPER TOWING EYE COVER - LH / RH	2 \$ 69.00	
5	REAR BUMPER CLOSING ELEMENT - RH	\$ 86.00	
6	REAR BUMPER TRIM - RH	\$ 213.00	
7	TAIL LIGHT - RH	\$ 627.00	\$ 501.60
8	BOOT LID CONTROL UNIT	\$ 387.00	
9	REAR BUMPER CARRIER	\$ 831.00	
10	REAR BUMPER HOLDING STRAP	\$ 151.00	\$ 120.80
11	REAR BUMPER GUIDE SECTION - RH	\$ 76.00	
12	REAR BUMPER FOAM FILLER PIECE - RH	\$ 56.00	
13	REAR PARKING AID SENSOR	2 \$ 462.00	
14	REAR PARKING AID SENSOR SEAL RING	4 \$ 12.00	
15	REAR WHEEL COVER - LH / RH	2 \$ 974.00	\$ 779.20
16	SUNDRIES	\$ 300.00	\$ 31.76
TOTAL SPARE PARTS		\$ 7,646.00	\$ 2,897.76
TOTAL LABOUR CHARGES		\$ 4,752.00	\$ 3,552.00
GRAND TOTAL		\$ 12,398.00	\$ 6,449.76

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Yr Ref: SJY 868 M

Norah Khai

6768 9911

6841 1183

Nora.khai@premiumauto.com.sg

Body & Paint Dept

PA/OD/1090/2019/NH

From

Telephone +65 -

Telefax +65 -

Mobile +65 -

Our Dept

Email

23-Mar-2020

Date

Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SJY 868 M, Audi Q5 SPORT 2.0 TFSI QU S-TRONIC.

With reference to the above-mentioned vehicle, no. **SJY 868 M**, claimant, **Omnititan Venture Private Limited**, please find the related document per attached.

1. A copy of the Original invoice no. 85014991 – S\$ 6,901.24.
2. A copy of the Discharge Voucher duly signed by client.

Premium Automobiles Pte Ltd.

Showroom

9 Leng Kee Road

Singapore 159090

Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres

55 Ubi Rd 1

Singapore 408699

Telephone (65) 6336 2323

Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG Insurance – SJY 868 M

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6366 2323
Main Telefax 6641 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:21

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014991 Date : 19/03/2020 Order : SJY0868M Term : 30	Account: A0006 (T - 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Regn No: SJY0868M (V 37734) Model: Q5 SPORT 2.0 TFSI qu S tronic You have been assisted by :- UB-Tony Foong (33)		Regn Date: 27/06/2018 Chassis: WAUZZZ2FY1J2136493 Mileage: 20126 Engine: DAX 033136	WIP No.: 11317 Dept: U

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	800.00	1.00	800.00
S	BODYWORK	M: TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A80A807527 GRU	(SK)COVER Less 020%	1.00	1077.00	861.60
X	A80A807434B TB2	(SK)SPOILER Less 020%	1.00	753.50	602.80
X	A80A945070	(SK)TAILLIGHT Less 020%	1.00	627.00	501.60
X	A80A807329B	(SK)STRAP AP Less 020%	1.00	151.00	120.80
X	A80A853817A GRU	(SK)COVER Less 020%	1.00	487.00	389.60
X	A80A853818A GRU	(SK)COVER Less 020%	1.00	487.00	389.60
X	ALSTOM2Y68	SUNDRIES Less 020%	1.00	39.70	31.76

Parts 2,897.76
Labour 0.00
Sublet 3,552.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,449.76

7% GST 451.48

Grand Total 6,901.24



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJY868M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1090/2019/TF
21 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 SPORT 2.0 TFSI qu S tronic
Vehicle Chassis No. : WAUZZZF1J2136493
Vehicle Regn No. : SJY868M
Vehicle Mileage : 20126KM
Vehicle Owner : Omnititan Venture Private Limited
Certificate No : 1800074627
Own Damage Excess : Waiver
Accident Date : 2 September 2019
Place : Dunman Road
Repair Cost : \$ 6,901.24
WIP No. : 11317
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6586 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6386 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


2019

Omnititan Venture Private Limited
10 Ubi Crescent #06-100 Ubi Techpark Lobby E
Singapore 408564
Tel: 67428479 Fax: 67421420
Email: phiten@omnititan.com.sg
Co. Reg. / GST No. 200404491C

DISCHARGE VOUCHER - AIG - SJY868M

Omnititan Venture Private Limited
10 Ubi Crescent #06-100 Ubi Techpark Lobby E
Singapore 408564
Tel: 67428479 Fax: 67421420
Email: phiten@omnititan.com.sg
Co. Reg. / GST No. 200404491C

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019		25 Oct 2019 08:41 Edit Adj Rpt	S\$6,449.76 Edit Estimates	S\$6,449.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	OMNITITAN VENTURE PTE LTD, Co. Reg. No.: 200404491C, Tel: +6590100928			
Vehicle Reg. No.:	SJY868M	Date of Loss:	02/09/2019 16:00 - :59 [14 Months and 6 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 9101906277SG	Policy/Cover Note No.:	1800074627 (Comprehensive)	
		Excess:	S\$0.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/11/2019]			
Driver/Custodian:	YIP MUN (50 / Female), NRIC: S6903944H, Tel: +6590100928 Email: YIPMUN@GMAIL.COM			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (18/02/2020): Alert - Adj Mandate Approved (S\$6449.76) - SJY868M - Claim Handler: Chan, Yoke S...
- AIG_SG (29/10/2019): Alert - Adj Mandate Approved (S\$6118.50) - SJY868M - Claim Handler: Chan, Yoke S...
- AIG_SG (29/10/2019): SJY868M / OD / 02/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY868M (9101906277SG)**
OD
Sep 2 2019 4:50PM
[OMNITITAN VENTURE PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 09:46	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 09:36	General View	Load JPG	☒
2	25/10/19 09:36	General View	Load JPG	☒
3	25/10/19 09:36	General View	Load JPG	☒
4	25/10/19 09:36	General View	Load JPG	☒
5	25/10/19 09:36	General View	Load JPG	☒
6	25/10/19 09:36	General View	Load JPG	☒
7	25/10/19 09:36	General View	Load JPG	☒
8	25/10/19 09:36	General View	Load JPG	☒
9	25/10/19 09:36	General View	Load JPG	☒
10	25/10/19 09:36	General View	Load JPG	☒
11	25/10/19 09:36	General View	Load JPG	☒
12	25/10/19 09:36	General View	Load JPG	☒
13	25/10/19 09:36	General View	Load JPG	☒
14	25/10/19 09:36	General View	Load JPG	☒
15	22/01/20 16:03	Reinspection Photo	Load JPG	☒
16	22/01/20 16:03	Reinspection Photo	Load JPG	☒
17	22/01/20 16:03	Reinspection Photo	Load JPG	☒
18	22/01/20 16:03	Reinspection Photo	Load JPG	☒
19	22/01/20 16:03	Reinspection Photo	Load JPG	☒
20	22/01/20 16:03	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 09:47	Singapore Accident Statement	Load PDF	
2	25/10/19 09:47	Certificate of Insurance	Load PDF	
3	25/10/19 09:47	Driver's Driving License	Load PDF	
4	25/10/19 09:47	MARK ESTIMATE	Load PDF	
5	25/10/19 16:54	ADDENDUM GIA REPORT	Load PDF	
6	22/01/20 16:07	FINAL MARKING	Load PDF	
7	26/03/20 13:20	WORKSHOP INVOICE	Load PDF	
8	26/03/20 13:21	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/10/19 20:30	Addendum Sheet	Load JPG	☒
2	25/10/19 16:48	Addendum Sheet	Load JPG	☒
3	06/12/19 18:24	Accident Statement	Load HTM	
4	06/12/19 18:25	Accident Statement	Load HTM	

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=864062&extid=3211... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19018933/AVD3N2

Date: 26/03/2020

REFERENCE

Insured/Claimant:	OMNITITAN VENTURE PTE LTD	Policy No:	1800074627	
Date of Loss:	02/09/2019	Nature of Claim:	OD	Claim No: 9101906277SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY868M		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX033136
Reg. Date:	27/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF1J2136493
Colour:	Black	Odometer:	18936 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,646.00	2,897.76	4,748.24	62.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	3,552.00	1,200.00	25.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,398.00	6,449.76	5,948.24	47.98
+ GST 7.00/7.00% (S\$)	867.86	451.48	416.38	47.98
Nett Amount (S\$)	13,265.86	6,901.24	6,364.62	47.98

INSPECTION

Date of Assignment:	25/10/2019		
Date Inspected:	24/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-UPPER	Repair	1,571.00 FS	*- FS
2	1		*REAR BUMPER-LOWER	Deformed	1,077.00 FS	*861.60 FS
3	1		*REAR BUMPER SPOILER	Deformed	754.00 FS	*602.80 FS
4	2		*REAR BUMPER TOWING EYE COVER-LH/RH	Not Necessary	69.00 FS	*- FS
5	1		*REAR BUMPER CLOSING ELEMENT-RH	Not Necessary	86.00 FS	*- FS
6	1		*REAR BUMPER TRIM-RH	Not Necessary	213.00 FS	*- FS
7	1		*TAIL LIGHT-RH	Cracked	627.00 FS	*501.60 FS
8	1		*BOOT LID CONTROL UNIT	Not Necessary	387.00 FS	*- FS
9	1		*REAR BUMPER CARRIER	Not Necessary	831.00 FS	*- FS
10	1		*REAR BUMPER HOLDING STRAP	Necessary	151.00 FS	*120.80 FS
11	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	76.00 FS	*- FS
12	1		*REAR BUMPER FOAM FILLER PIECE-RH	Not Necessary	56.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR	Not Necessary	462.00 FS	*- FS
14	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
15	2		*REAR WHEEL COVER-LH/RH	Necessary	974.00 FS	*779.20 FS
16	1		*SUNDRIES	Necessary	300.00 FS	*31.76 FS
Total Parts (\$\$)					7,646.00	2,897.76

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	2,200.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,752.00	3,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >