

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:21

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014991 Date : 19/03/2020 Order : SJY0868M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SJY0868M (V 37734) Regn Date: 27/06/2018 Mileage: 20126 WIP No.: 11317

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF1J2136493 Engine: DAX 033136 Dept: u

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	800.00	1.00	800.00
S	BODYWORK	M: TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A80A807527 GRU	(SK) COVER Less 020%	1.00	1077.00	861.60
X	A80A807434B TB2	(SK) SPOILER Less 020%	1.00	753.50	602.80
X	A80A945070	(SK) TAILLIGHT Less 020%	1.00	627.00	501.60
X	A80A807329B	(SK) STRAP AP Less 020%	1.00	151.00	120.80
X	A80A853817A GRU	(SK) COVER Less 020%	1.00	487.00	389.60
X	A80A853818A GRU	(SK) COVER Less 020%	1.00	487.00	389.60
X	ALSTOM2Y8S	SUNDRIES Less 020%	1.00	39.70	31.76

Parts 2,897.76
Labour 0.00
Sublet 3,552.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,449.76

7% GST 451.48

Grand Total 6,901.24



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: **SJY868M**

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1090/2019/TF
21 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 SPORT 2.0 TFSI qu S tronic
Vehicle Chassis No. : WAUZZZF1J2136493
Vehicle Regn No. : **SJY868M**
Vehicle Mileage : 20126KM
Vehicle Owner : Omnititan Venture Private Limited
Certificate No : 1800074627
Own Damage Excess : Waiver
Accident Date : 2 September 2019
Place : Dunman Road
Repair Cost : \$ 6,901.24
WIP No. : 11317
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


20/11

Omnititan Venture Private Limited
10 Ubi Crescent #06-100 Ubi Techpark Lobby E
Singapore 408564
Tel: 67428479 Fax: 67421420
Email: phiten@omnititan.com.sg
Co. Reg./GST No. 200404491C

DISCHARGE VOUCHER - AIG - SJY868M

Omnititan Venture Private Limited
10 Ubi Crescent #06-100 Ubi Techpark Lobby E
Singapore 408564
Tel: 67428479 Fax: 67421420
Email: phiten@omnititan.com.sg
Co. Reg./GST No. 200404491C