

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KMH DU41BR9U713067.

LIM HAN CHAI
BLK 641 YISHUN ST 61
#11-206
S 760641

TP Budget Direct
Xiao Chan.

Date :31.10.2019
Vehicle No :SJP 1636 G
Make/Model :HYUNDAI AVANTE
Accident date :19.10.2019

No	DESCRIPTION	Qty	Amount (\$S)
----	-------------	-----	--------------

List Items

1	Rear windscreen rubber <i>new</i>	1	\$ 69.1 <i>+</i>
2	Rear bumper <i>Rebuilt</i>	1	\$ 613.8 <i>447</i>
3	Rear bumper side holder @ \$41.80 <i>new RH</i>	2	\$ 83.6 <i>41.80</i>
4	Rear bumper reinforcement <i>new</i>	1	\$ 327.8 <i>+</i>
5	Rear bumper clips (1 set) <i>new</i>	1	\$ 66 <i>30</i>
6	Rear RH lamp <i>caulced</i>	1	\$ 283.8 <i>✓</i>
7	Rear end panel <i>Rebuilt</i>	1	\$ 332.2 <i>✓</i>
8	Rear RH fender <i>Repair</i>	1	\$ 1030.7 <i>+</i>
9	Rear RH fender inner trim <i>new</i>	1	\$ 151.8 <i>+</i>
			\$ 2958.8
Less 20% Disc			\$ 591.76
Total			\$ 2367.04

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>new</i>	\$ 380 <i>X</i>
Total		\$ 380

Labour Cost

1	To supply rear windscreen sealant <i>new</i>	\$ 50 <i>X</i>
2	To supply rear end panel inner sealant <i>new</i>	\$ 200 <i>60</i>
3	Remove & reinstall rear windscreen	\$ 150 <i>X</i>
4	Remove & reinstall reverse sensor	\$ 150 <i>50</i>
5	Remove ,replace & repair consistent to the accident	\$ 1200 <i>600</i>
6	Respray painting	\$ 1000 <i>600</i>
7	Tuff kote	\$ 100 <i>60</i>
Total		\$ 2850

Grand Total \$ 5597.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2277.84

h/s: 1.8K

04 Days

21c