

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO.: 35766600C

16-03-2020

Date of Accident: 23-10-2019

OUR REF : SLH 3505G/T/19

Lim Tong Teck
Blk 213B Compassvale Lane
#13-264
Singapore 542213

Lick-Morrens

Dat. In/ant: 06/01/2020 to 08/01/2020

LICK - HISO Tong

ESTIMATE BILL ON VEH. NO. : SLH 3505G

MODEL : NISSAN NOTE

CHASSIS NO: IN1TBAE12Z0982829

NETT ITEM

Rear Bumper Fascia

414

DD/Oe

~~600.00~~

600.00

Less Discount 10%:

60.00

540.00

23/3/20

SPECIAL NETT ITEM

Reverse Sensor With Control Unit

or

5u 380.00 X

LABOUR CHARGE

To respray affected areas

405

450.00

To renew damaged parts, straighten & repair & aligned all parts

200

400.00

1.770.00

GST 7% :

123.90

AMOUNT DUE:

1,893.90

Not Authorized
Lal
L/S \$ 7500
2 days.

p-414
102
p-37260
L-600.00
972.60
778.