

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

### # SUPPLEMENTARY ITEMS

|                                 |           |
|---------------------------------|-----------|
| Total Labour :                  | 7,918.00  |
| Total Parts :                   | 2,613.40  |
| Total Labour & Parts :          | 10,531.40 |
| Deduction for Excess :          | 1,500.00  |
| Total Repair Costs less Excess: | 9,031.40  |
| GST @7%:                        | 632.20    |
| Grand Total :                   | 9,663.60  |

| DATE              | WARRANTY DAYS |
|-------------------|---------------|
| 19/11/19          | 7             |
| FAX TO            |               |
| FAX NO            |               |
| FAX TO            |               |
| FAX NO            |               |
| FAX TO            |               |
| FAX NO            |               |
| COMPLAINT         |               |
| DATE              |               |
| PLEASE PRINT NAME |               |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 53192**  
Date Estimated : **24/10/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Ong Hwee Leng**  
**105 Prince Charles Crescent**  
**#12-17**

**Singapore 159019**

**- ACCOUNT - 66**  
**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

| REGN. NO.                                                                                                                                                                                                                                                                               | CHASSIS NO.            | REGN. DATE        | MODEL            | MILEAGE  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------|------------------|----------|
| <b>SLU4288H</b>                                                                                                                                                                                                                                                                         | <b>WBA8E32050A0202</b> | <b>16/11/2017</b> | <b>318iA/4Dr</b> | <b>0</b> |
| ACCOUNT:                                                                                                                                                                                                                                                                                |                        |                   |                  |          |
| DESCRIPTION                                                                                                                                                                                                                                                                             | ORIGINAL PRICE         | DISC. %           | NETT             |          |
| To replace front right door, front right fender, front right wheel housing cover and right side skirting etc including to make good rear right door, rear bumper and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job. | 2,975.00               | 0                 | 2,975.00         |          |
| To respray front right door, front right fender, rear right door, rear bumper and right side skirting etc.                                                                                                                                                                              | 3,992.00               | 0                 | 3,992.00         |          |
| To carry out body cavity preservation.                                                                                                                                                                                                                                                  | 200.00                 | 0                 | 200.00           |          |
| To check steering geometry and conduct wheel alignment according to BMW specification                                                                                                                                                                                                   | 451.00                 | 0                 | 451.00           |          |
| To check electrical wiring systems at the front section for proper function including adjustments of headlights.                                                                                                                                                                        | 150.00                 | 0                 | 150.00           |          |
| Sundries.                                                                                                                                                                                                                                                                               | 150.00                 | 0                 | 150.00           |          |

| DESCRIPTION                         | UNIT PRICE | QTY  | DISC. % | NETT     |
|-------------------------------------|------------|------|---------|----------|
| #                                   |            |      |         |          |
| # EXPANDING NUT                     | 2.10       | 4.00 | 0       | 8.40     |
| FRT RH DOOR                         | 1,267.50   | 1.00 | 0       | 1,267.50 |
| FRT RH SIDE PANEL                   | 702.65     | 1.00 | 0       | 702.65   |
| # MODEL LETTERING SIDE (SPORT LINE) | 46.30      | 1.00 | 0       | 46.30    |
| # RIVET                             | 0.50       | 6.00 | 0       | 3.00     |
| FRT DOOR WEATHERSTRIP               | 140.70     | 1.00 | 0       | 140.70   |
| # FRT RH WHEEL HOUSING COVER        | 117.15     | 1.00 | 0       | 117.15   |
| RH SILL TRIM PRIMED                 | 322.45     | 1.00 | 0       | 322.45   |
| # EXPANDING NUT 7X7 MM              | 1.05       | 5.00 | 0       | 5.25     |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 53192**  
Date Estimated : **24/10/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Ong Hwee Leng**  
**105 Prince Charles Crescent**  
**#12-17**

**Singapore 159019**

**- ACCOUNT - 66**  
**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

|                 |                        |                   |                  |          |
|-----------------|------------------------|-------------------|------------------|----------|
| REGN. NO.       | CHASSIS NO.            | REGN. DATE        | MODEL            | MILEAGE  |
| <b>SLU4288H</b> | <b>WBA8E32050A0202</b> | <b>16/11/2017</b> | <b>318iA/4Dr</b> | <b>0</b> |

| DESCRIPTION | ACCOUNT:       |  | DISC. % | NETT |
|-------------|----------------|--|---------|------|
|             | ORIGINAL PRICE |  |         |      |

| DESCRIPTION                         | UNIT PRICE | QTY  | DISC. % | NETT   |
|-------------------------------------|------------|------|---------|--------|
| #                                   |            |      |         |        |
| # EXPANDING NUT                     | 2.10       | 4.00 | 0       | 8.40   |
| # MODEL LETTERING SIDE (SPORT LINE) | 46.30      | 1.00 | 0       | 46.30  |
| # RIVET                             | 0.50       | 6.00 | 0       | 3.00   |
| # FRT RH WHEEL HOUSING COVER        | 117.15     | 1.00 | 0       | 117.15 |
| # EXPANDING NUT 7X7 MM              | 1.05       | 5.00 | 0       | 5.25   |

### # SUPPLEMENTARY ITEMS

|                        |        |
|------------------------|--------|
| Total Labour :         |        |
| Total Parts :          | 180.10 |
| Total Labour & Parts : | 180.10 |