

/ SS. REC. BY:

REF

CS/MSG/10017042/RIVF3N2

Special Instruction:

Surveyor

RASH

ASSIGNMENT (Office)

From (Person):

Kwot Woon Choo

of

MSG

Date/Time:

29.10.19 8.42a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 42884

Insured:

at Workshop m/s

Performance

Tel:

63190172 / 63190174

of

203 Alexandra Road

Policy No:

291051355

Claim No:

608802

Sum Insured:

Excess:

\$1500.00

Make of Veh:

D.O.A

15.10.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29.10.19

10.39am

Person Contacted:

Chua

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 42884 - N13A1 MSG 191018207 / 4

D.O.A - 15/10/2019

30/10/19

Revert via merimen

30/10/19

Recd approved \$10,312.15 from Chen How by merimen

30/10/19

Informed mr Chua c/A ex \$1500 by email

26/11/19

Final fig \$10,531.40 confirmed by email (Ref 5964.60, 361)

19

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Kwok Woon Choo	Date:	20 Nov 2019

Preliminary Advice

Vehicle No	: SLU4288H	Accident Date	: 15/10/2019
Make	: BMW 318i	Policy No.	: 29051355
Assignment Date	: 29/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 29/10/2019	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,496.00 (incl.supplementary \$180.10)
Revised Amount	:S\$	10,531.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,531.40 (incl.supplementary \$180.10)
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	116,000.00
COE / PARF Rebate	:S\$	72,575.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,425.00

Remarks

☒ The vehicle is economical for repair.

☐ The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSiG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 30 Oct 2019

Preliminary Advice

Vehicle No	: SLU4288H	Accident Date	: 15/10/2019
Make	: BMW 318i	Policy No.	: 29051355
Assignment Date	: 29/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 29/10/2019	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,315.90
Revised Amount	:S\$	10,312.15
Check Items (Estimated)	:S\$	1,484.75
Total	:S\$	11,796.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	116,000.00
COE / PARF Rebate	:S\$	72,575.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,425.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2019		29 Oct 2019 08:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONG HWEE LENG, ID: S1827200H, Tel: +6598220618								
Vehicle Reg. No.:	SLU4288H	Date of Loss:	15/10/2019 22:00 - :59 [33 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 608802	Policy/Cover Note No.:	29051355 (Comprehensive) Coverage: 16/11/2018 - 15/11/2019						
		Excess:	S\$1,500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/10/2019]								
Driver/Custodian:	WALTER KONG (21 / Male), NRIC: S9811701F, Tel: +6596192672 Email: walter.98.kong@gmail.com								
Adj Asg. Remarks:	Car in 29/10/19. Survey & revert. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail 									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLU4288H (608802)**

OD

Oct 15 2019 10:00PM

[ONG HWEE LENG]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 26/11/2019 11:35 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10531.40) - SLU4288H - Claim Handler: Kwok Woon Choo

Approved:10531.40.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 30 October 2019 3:33 PM
To: Chua Kee Sin; SUR
Subject: SLU 4288H-DOA: 15/10/2019 (MSIG OD)

Dear Mr Chua,

As instructed by our client , please proceed to repair the **insured vehicle SLU 4288H (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLU4288H (608802)**

OD

Oct 15 2019 10:00PM

[ONG HWEE LENG]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 30/10/2019 15:25 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10312.15) - SLU4288H - Claim Handler: Kwok Woon Choo

Approved:10312.15.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 26 November 2019 12:31 PM
To: Sharon Heng L K; Rasul (LKKAUTO); SUR
Cc: Toh Jing Xuan; Bernard Wan Chong Huat
Subject: RE: OD CLAIM FINAL REPORT - SLU4288H

Dear Sharon,

Confirmed amount \$10,531.40 before excess \$1500 and GST

7 working days.

Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Tuesday, 19 November 2019 5:46 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; Bernard Wan Chong Huat <bernard.wan@simedarby.com.sg>
Subject: OD CLAIM FINAL REPORT - SLU4288H

Dear Rasul

For your perusal :

Labor	\$ 7918.00
Parts	\$ 2613.40
Total	\$10531.40
Excess	\$ 1500.00

Note : 7 working days.

Please reply me directly.

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Tuesday, 19 November, 2019 3:41 PM

To: Sharon Heng L K

Subject: Message from KM_C458

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	200H
Vehicle Details	
Vehicle No.:	SLU4288H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318i LED NAV SHAD. LIGHT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	F0491782B38B15A
Chassis No.:	WBA8E32050A020271
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,419.00
Original Registration Date:	16 Nov 2017
First Registration Date:	16 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$35,187.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2027
PARF Rebate Amount:	\$26,390.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$46,185.00
Total Rebate Amount:	\$72,575.00

The information contained herein is correct as at 30 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/10/2019 17:11
Date Of Accident 15/10/2019 22:15
Exact Location Of Accident CHANGHI AIRPORT T3 B1 SECTION 2 CARPARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU4288H
Insured/Policyholder
Name Of Registered Owner ONG HWEE LENG
NRIC No S1827200H
Email Address JESS6729@YAHOO.COM
Mobile Phone No (LOCAL) +65-98220618
Alternative Phone No OTHERS-86192672

Vehicle Particulars

Manufacturer BMW
Model 318i
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number B 29051355 SMP
Cover Note Number

Driver

Name of Driver WALTER KONG
NRIC No S9811701F
Date Of Birth 06/04/1998
Occupation INDOOR
Date Of Driving Pass 27/12/2018
Driving Experience 0 YEAR AND 9 MONTH
Gender MALE
Mobile Number (LOCAL) +65-86192672
Fax Number
Contact Number OTHERS-98220618
Email Address WALTER.98.KONG@GMAIL.COM

Address	105 PRINCE CHARLES CRESCENT #12-17
Postcode	159019
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN2326U
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE LAY
NRIC/Passport Number	S2580863J
Contact Number	94751920
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

CHANCE! AIRPORT 1/3 B1 SIGNAGE 2 CARPARK



A) SLU 4288H

B) SMN 2326V

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A signalled his intentions to exit his parking lot and checked ~~checked~~ ~~checked~~ for oncoming cars before exiting the lot. Due to the vehicle parked at a close proximity to his left, he paid more attention to that vehicle and did not notice B moving the hand towards him (A) as he was exiting his lot. As a result, B collided into the ^{front} right door area of A's vehicle. After the initial impact, B continued (?) accelerating and "poked" a second time, stopping just one away from pillar C. B became slightly mounted (?) onto A and A's front-right door ~~could not~~ was obstructed from opening. To settle the issue without inconveniencing other road users, A directed his vehicle away from B and stopped at a clear area.

Upon inspection of the damages, A noticed the front-right door had dents and a loose rubber seal at the front of the door. There were some scratches too from the better maneuver to clear the road. B's vehicle front-left portion (below the wheel) came slightly undrained/loose. As it was A's first experience in ~~such~~ any vehicular accident, many calls were made to render help while he discussed and exchanged particulars with B. A and B agreed to call it a day by fixing their own vehicles and not pursuing any action further right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6/10/19 1356

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A signalled his intentions to exit his parking lot and checked for oncoming cars before exiting the lot. Due to the vehicle parked at a close proximity to his left, he paid more attention to that vehicle and did not notice B making the bend towards him (A) as he was exiting his lot. As a result, B collided onto the front-right door area of A's vehicle. After the initial impact, B continued accelerating and "pushed" a second time, stopping just cm away from pillar C. B became slightly mounted onto A and A's front-right door was obstructed from opening. To settle the issue without inconveniencing other road users, A directed his vehicle away from B and stopped at a clear area.

Upon inspection of the damages, A noticed the front-right door had dents and a loose rubber seal at the front of the door. There were some scratches too from the latter manoeuvre to clear the road. B's vehicle front-left portion (before the wheel) came slightly undone/loose. As it was A's first experience in any vehicular accident, many calls were made to render help while he discussed and exchanged particulars with B. A and B agreed to call it a day by fixing their own vehicles and not pursuing any action for the night.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

260, Karpang Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53192
Date Estimated : 24/10/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ong Hwee Leng
105 Prince Charles Crescent
#12-17

Singapore 159019

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A020271	16/11/2017	318iA/4Dr	0

DESCRIPTION

VALUE

Replace right front fender, front right door, right lower side skirting include remove attachment etc repairs on accident damage area

✓ 2975 5,100.00

Spray painting front bumper, right front side fender, both right door and right lower side skirting

✓ 3992 4,436.00

To carry out body cavity preservation.
(2 panel).

✓ 200 236.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

✓ 457 531.00

To replace tyre and wheel rim including balancing. (1x).
right front

X 94.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

✓ 150 171.00

Sundries. *nu*

✓ ? 150.00

Total Labour 1: 10,724.00

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 8JX19 M DOUBLE SPK 442 *XSVL*

1 1,690.05 1,690.05

HUB CAP WITH CHROME EDGE (BMW) *XSVL*

1 28.95 28.95

FRT RH DOOR *st*

1 1,267.50 1,267.50

FRT RH SIDE PANEL *bt*

1 702.65 702.65

FRT RH 2 SIDE PANEL BRACKET *nu* *XAN*

1 34.95 34.95

FRT RH 1 SIDE PANEL BRACKET *nu* *XAN*

1 34.95 34.95

FRT RH 3 SIDE PANEL BRACKET *nu* *XAN*

1 34.95 34.95

FRT RH DOOR BRAKE *nu* *XAN*

1 77.20 77.20

Window lifter *?* *XAN*

1 315.85 315.85

FRT RH DOOR OUTER MOULDING *?* *XAN*

1 84.35 84.35

FRT RH DOOR INSIDE CHANNEL SEALING *?* *XAN*

1 71.70 71.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M UST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kangkong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53192
Date Estimated : 24/10/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A020271	16/11/2017	318iA/4Dr	0

DESCRIPTION	QTY	PRIC	VALUE
FRT DOOR WEATHERSTRIP <i>Ne /</i>	1	140.70	140.70
FRT RH SEALING WINDOW FRAME INTERIO <i>? X SUC</i>	1	61.15	61.15
FRT RH DOOR WINDOW GUIDE <i>? X SUC</i>	1	104.85	104.85
FRT DOOR EDGE PROTECTION <i>? X SUC</i>	1	169.40	169.40
SUPPORTING LEDGE RH <i>? X</i>	1	18.85	18.85
SUPPORTING LEDGE RH <i>? X</i>	1	36.25	36.25
SUPPORTING LEDGE RH <i>? X</i>	1	37.75	37.75
SUPPORTING LEDGE RH <i>? X</i>	1	37.55	37.55
RH SILL TRIM PRIMED <i>de /</i>	1	322.45	322.45
FRT RH DRIVE FOR WINDOW LIFTER <i>? X SUC</i>	1	319.85	319.85

Total Parts : 5,591.90

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Signature
3/10/19

Claims ☒ 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/10/19 @ 1515 Excess S\$ 1500Surveyor's Name Rene Sign _____Surveyor's Tel 90010068 Authorised Yes ☒ No ☐

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

16,496

Labour 1	:	10,724.00
Parts	:	5,591.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,142.11
Grand Total	:	17,458.01

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796626 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 53192**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A020271	16/11/2017	318iA/4Dr	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53192**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A020271	16/11/2017	318iA/4Dr	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770160, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796626 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 53192**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A020271	16/11/2017	318iA/4Dr	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.5(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

Performance Motors Limited

A member of the Sino Dairy Group
Co. Reg. No. 197401550W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53192**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Ong Hwee Leng
105 Prince Charles Crescent
#12-17

Singapore 159019

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A0202	16/11/2017	318iA/4Dr	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace front right door, front right fender, front right wheel housing cover and right side skirting etc including to make good rear right door, rear bumper and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,975.00	0	2,975.00	
To respray front right door, front right fender, rear right door, rear bumper and right side skirting etc.	3,992.00	0	3,992.00	
To carry out body cavity preservation.	200.00	0	200.00	
To check steering geometry and conduct wheel alignment according to BMW specification	451.00	0	451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00	
Sundries.	150.00	0	150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# EXPANDING NUT	2.10	4.00	0	8.40
FRT RH DOOR	1,267.50	1.00	0	1,267.50
FRT RH SIDE PANEL	702.65	1.00	0	702.65
# MODEL LETTERING SIDE (SPORT LINE)	46.30	1.00	0	46.30
# RIVET	0.50	6.00	0	3.00
FRT DOOR WEATHERSTRIP	140.70	1.00	0	140.70
# FRT RH WHEEL HOUSING COVER	117.15	1.00	0	117.15
RH SILL TRIM PRIMED	322.45	1.00	0	322.45
# EXPANDING NUT 7X7 MM	1.05	5.00	0	5.25



SUPPLEMENTARY ITEMS

Total Labour :	7,918.00
Total Parts :	2,613.40
Total Labour & Parts :	10,531.40
Deduction for Excess :	1,500.00
Total Repair Costs less Excess:	9,031.40
GST @7%:	632.20
Grand Total :	9,663.60

[illegible]

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0000061-X



Supplementary

Estimate No. : **b1 53192**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Ong Hwee Leng
105 Prince Charles Crescent
#12-17

Singapore 159019

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4288H	WBA8E32050A0202	16/11/2017	318iA/4Dr	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>na</i>	2.10	4.00	0	8.40
# MODEL LETTERING SIDE (SPORT LINE) <i>na</i>	46.30	1.00	0	46.30
# RIVET <i>na</i>	0.50	6.00	0	3.00
# FRT RH WHEEL HOUSING COVER <i>at</i>	117.15	1.00	0	117.15
# EXPANDING NUT 7X7 MM <i>na</i>	1.05	5.00	0	5.25

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	180.10
Total Labour & Parts :	180.10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19019042/R1VF3N2

Date: 27/11/2019

REFERENCE

Insured/Claimant:	ONG HWEE LENG	Policy No:	29051355	
Date of Loss:	15/10/2019	Nature of Claim:	OD	Claim No: 608802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4288H	Engine No:	F0491782B38B15A
Make & Model:	BMW 318i, 1.5 (A)	Chassis No:	WBA8E32050A020271
Reg. Date:	16/11/2017 (Man. Year: 2017)	Odometer:	20471 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$116,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,922.00	2,763.40	3,158.60	53.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,574.00	7,768.00	2,806.00	26.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,496.00	10,531.40	5,964.60	36.16
- Excess (\$\$)	1,500.00	1,500.00	0.00	0.00
(\$\$)	14,996.00	9,031.40	5,964.60	39.77
+ GST 7.00/7.00% (\$\$)	1,049.72	632.20	417.52	39.77
Nett Amount (\$\$)	16,045.72	9,663.60	6,382.12	39.77

INSPECTION

Date of Assignment:	29/10/2019	
Date Inspected:	29/10/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
Parts:	143	BMW 318I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4288H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALLOY RIM 8JX19 M DOUBLE SPK 442	Serviceable	1,690.05 FS	*- FS
2	1		*HUB CAP WITH CHROME EDGE (BMW)	Serviceable	28.95 FS	*- FS
3	1		*FRT RH DOOR	Bent	1,267.50 FS	*1,267.50 FS
4	1		*FRT RH SIDE PANEL	Bent	702.65 FS	*702.65 FS
5	1		*FRT RH 2 SIDE PANEL BRACKET	Not Necessary	34.95 FS	*- FS
6	1		*FRT RH 1 SIDE PANEL BRACKET	Not Necessary	34.95 FS	*- FS
7	1		*FRT RH 3 SIDE PANEL BRACKET	Not Necessary	34.95 FS	*- FS
8	1		*FRT RH DOOR BRAKE	Not Necessary	77.20 FS	*- FS
9	1		*WINDOW LIFTE	Not Necessary	315.85 FS	*- FS
10	1		*FRT RH DOOR OUTER MOULDING	Not Necessary	84.35 FS	*- FS
11	1		*FRT RH DOOR INSIDE CHANNEL SEALING	Not Necessary	71.70 FS	*- FS
12	1		*FRT DOOR WEATHERSTRIP	Necessary	140.70 FS	*140.70 FS
13	1		*FRT RH SEALING WINDOW FRAME INTERIO	Serviceable	61.15 FS	*- FS
14	1		*FRT RH DOOR WINDOW GUIDE	Serviceable	104.85 FS	*- FS
15	1		*FRT DOOR EDGE PROTECTION	Serviceable	169.40 FS	*- FS
16	1		*SUPPORTING LEDGE RH	Not Necessary	18.85 FS	*- FS
17	1		*SUPPORTING LEDGE RH	Not Necessary	36.25 FS	*- FS
18	1		*SUPPORTING LEDGE RH	Not Necessary	37.75 FS	*- FS
19	1		*SUPPORTING LEDGE RH	Not Necessary	37.55 FS	*- FS
20	1		*RH SILL TRIM PRIMED	Deformed	322.45 FS	*322.45 FS
21	1		*FRT RH DRIVE FOR WINDOW LIFTER	Serviceable	319.85 FS	*- FS
22	4		*EXPANDING NUT	Necessary	8.40 FS	*8.40 FS
23	1		*MODEL LETTERING SIDE (SPORT LINE)	Necessary	46.30 FS	*46.30 FS
24	6		*RIVET	Necessary	3.00 FS	*3.00 FS
25	1		*FRT RH WHEEL HOUSING COVER	Cut	117.15 FS	*117.15 FS
26	5		*EXPANDING NUT 7X7 MM	Necessary	5.25 FS	*5.25 FS
27	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **5,922.00** **2,763.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RIGHT FRONT FENDER,FRONT RIGHT DOOR,RIGHT LOWER SIDE SKIRTING INCLUDE REMOVE ATTACHMENT ETC.REPAIRS ON ACCIDENT DAMAGE AREA	New	5,100.00	2,975.00
2	SPRAY PAINTING FRONT BUMPER,RIGHT FRONT SIDE FENDER,BOTH RIGHT DOOR AND RIGHT LOWER SIDE SKIRTING	New	4,436.00	3,992.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (2 PANEL)	New	236.00	200.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
5	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X) RIGHT FRONT	New	94.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			10,574.00	7,768.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >