



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

EQ INSURANCE COMPANY LTD

Ref: CS3/EQ19019057/Gvf3e2

5 MAXWELL ROAD #17-00 TOWER BLOCK MND
COMPLEX SINGAPORE 069110

Date: 22-04-2020



Code: EQI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLV 1136C	Veh. Inspected	SMJ 2708Y
Policy No.		Coverage (\$)	0.00
Claim No.	DM19HO02899-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	29/10/2019

2. Vehicle Particulars & Condition


Make & Model	TOYOTA NOAH	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800358327	Colour	SILVER
Odometer	51295 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	HABILEAD	6 mm
L/H Front Tyre	195/65 R15	HABILEAD	6 mm
R/H Rear Tyre	195/65 R15	HABILEAD	6 mm
L/H Rear Tyre	195/65 R15	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.



5. General Information

Accident Date	24/10/2019	Inspect Date / Time	30/10/2019 (10:30 AM)
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

Report Ref No. CS3/EQ19019057/Gvf3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.