

15/5/2010

INS. CASE#OWNER:

CC 6 /EQ11901

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

21/10/19

Date / Time:

21/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGG 1628m

Name of Insured:

LAW KIM SENG

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

21/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

0M19NU0297

Policy No.:

0MPPN19-000654

Make / Model:

Toyota

Place of Accident:

SLV

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLV 412MP

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fastech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 28(3CCU1A1)

NO or B 28, Ass. Lia : 100

Repair Cost:

\$S

18725.00

Loss of Rental (LOR):

\$S

(\$ 60 x 8 days)

Loss of Use (LOU):

\$S

(\$ 60 x 8 days)

Loss of Income (LOI):

\$S

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$S

5.00

Medical:

\$S

Disbursement:

\$S

130.00

Legal Cost

\$S

Total:

\$S

19337.00

Global Sum \$S:

19000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

\$S

19000.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT
11/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$140.00

ASS. REC. BY:

RHP:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others:

TOTAL

Report Forms:

Lump Sum / L.B.P.:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Wash end

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
when
29/10/18
4/5 * 17500 /
707.

VEHICLE NO: SLV 4125P

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID REAR LOGO 68.00
2 PCS	BOOTLID REFLECTORS @\$645.00
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID WEATHERSTRIP 188.20
1 PCS	REAR BUMPER 1245.32
1 PCS	REAR BUMPER BLACK GARNISH 288.20
2 PCS	REAR BUMPER REFLECTORS @\$90.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$165.00
1 PCS	REAR BUMPER TOP RETAINER 181.00
1 PCS	REAR BUMPER REINFORCEMENT 615.32
1 SET	REAR BUMPER CLIPS
4 PCS	REAR BUMPER PDC SENSORS @\$245.00 490
1 PCS	REAR BUMPER INNER LOCK PAD 205.30
1 PCS	REAR BUMPER INNER LOCK SENSOR 350
1 PCS	REAR END PANEL 881.75
1 PCS	REAR END PANEL GARNISH 166.50
2 PCS	TAILLAMPS @\$885.00 825 x 2 = 1650
2 PCS	REAR FENDER INNER TRIMS @\$399.00
1 PCS	REAR EXHAUST ASSY
1 PCS	FRONT BUMPER 1415.00
1 PCS	FRONT BUMPER REINFORCEMENT 366.50
1 PCS	FRONT BUMPER SIDE HOLDER O/S 145.00
1 PCS	FRONT BUMPER FOG LAMP O/S 425.00
1 PCS	FRONT BUMPER FOG LAMP GARNISH O/S 297.50
1 PCS	FRONT BUMPER CENTRE GARNISH 315
1 PCS	FRONT BUMPER LOGO
1 PCS	FRONT BUMPER INNER AUXILIARY AIR DUCT
2 PCS	FRONT GRILLES @\$305.00
2 PCS	FRONT BUMPER PDC SENSORS @\$245.00
1 PCS	FRONT BUMPER SPONGE 188.20
1 PCS	FRONT FENDER O/S 715.20
1 PCS	FRONT FENDER INNERSHIELD FRONT O/S 181.00
1 PCS	FRONT FENDER INNERSHIELD REAR O/S 182.00
1 SET	FRONT FENDER INNERSHIELD CLIPS O/S
1 PCS	FRONT INNER SIDE COOLER O/S
1 PCS	FRONT SHOCK ABSORBER O/S 576.20
1 PCS	FRONT KNUCKLE ARM O/S 845.50
1 PCS	FRONT KNUCKLE ARM BEARING O/S 325.00
1 PCS	FRONT LOWER ARM O/S 412.50
1 PCS	FRONT TORSION ARM O/S 312.20
1 PCS	FRONT STEERING RACK ASSY
1 PCS	FRONT LINKAGE O/S 166.50
1 PCS	HEADLAMP ASSY O/S 3068.40
1 PCS	HEADLAMP MODULE O/S 450.00
1 PCS	HEADLAMP BALLAST O/S

R	\$2,466.32	X
me	\$85.00	—
11	\$1,290.00	X
826	\$315.00	X
101	\$366.00	—
D.S	\$2,018.00	—
321	\$388.00	✓
11	\$180.00	X
11	\$330.00	X
cm	\$392.00	—
321	\$715.00	—
me	\$50.00	—
Shocks	\$980.00	2 p.c.s
cm	\$288.00	—
cm	\$415.00	—
body	\$1,068.00	—
101	\$348.00	—
cm	\$1,770.00	—
11	\$798.00	X
R	\$1,880.00	X
D.S	\$2,009.00	—
321	\$788.00	—
one	\$199.00	—
cm	\$488.00	—
101	\$320.00	—
101	\$381.00	—
me	\$68.00	—
101	\$145.00	—
O/S cut	\$610.00	1 p.c
shock	\$490.00	1 p.c
101	\$281.00	—
321	\$945.00	—
101	\$265.00	—
101	\$288.00	—
me	\$50.00	—
sent/	\$850.00	—
321	\$1,200.00	—
321	\$1,485.00	—
me	\$499.00	—
321	\$615.00	—
321	\$620.00	—
826	\$2,245.00	X
101	\$188.00	—
321	\$3,800.00	—
cm	\$850.00	—
11	\$680.00	X

52

1 PCS	AIR CON CONDENSER
1 PCS	RADIATOR ASSY
2 PCS	SEATBELTS @\$980.00
2 PCS	SEATBELT BUCKLES @\$650.00
1 PCS	FRONT WHEEL HUB O/S 450.00
1 PCS	FRONT SPORT RIM O/S
1 PCS	FRONT TYRE O/S
1 PCS	REAR END PANEL SEALANT
1 SET	REAR FLOOR PANEL INSULATOR
1 PCS	FRONT LICENCE PLATE W/HOLDER

11	\$980.00	X
11	\$1,120.00	X
11	\$1,960.00	X
11	\$1,300.00	X
3/4	\$815.00	✓
car/set	\$1,215.00	8005 ~
su	\$300.00	X
der	\$50.00	✓
11	\$180.00	X
set	\$50.00	405 ~
		\$44,471.32

(52)

LABOUR CHARGES

TO CHECK WIRING

TOWING CHARGE

TO DISMANTLE & REPLACING PDC SENSOR

TO TRANSFER BOOTLID MECHANISM

TO DISMANTLE & REFIX REAR EXHAUST

TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE

TO REFILL AIR CON GAS

TO RESET & REPROGRAM HEADLAMP SYSTEM

TO CONDUCT WHEEL ALIGNMENT

TO SPRAY RUST PROOFING

LABOUR FOR PANEL BEATING & REPLACING PARTS

TO PUTTY & SPRAY PAINTING

	\$80.00	30
	\$100.00	60
	\$100.00	5-0
11	\$100.00	X
	\$180.00	80
	\$380.00	150
11	\$150.00	X
	\$150.00	50
	\$120.00	60
	\$180.00	60
	\$2,200.00	1200
	\$2,500.00	1600
TOTAL	\$50,711.32	

4160

LKK Auto Consultants hence notify the Repairer of the following:

- To restore colour after spray painting
- To display damaged parts during delivery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be restored and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

18931.29

52

17884.72

22164.72

1731

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	582B
Vehicle Details	
Vehicle No.:	SLV4125P
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318I LED NAV SHAD. LIGHT
Primary Colour:	Orange
Manufacturing Year:	2017
Engine No.:	F2001814B38B15A
Chassis No.:	WBA8E36030NU81682
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,502.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$35,303.00 17657
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$26,477.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$46,822.00
Total Rebate Amount:	\$73,299.00

The information contained herein is correct as at 29 Oct 2019

OK

PRISM+1  **Lazada**
OVER 1000+ 5 STAR
RAVE REVIEWS
ON OUR GAMING
MONITORS



**#1 TOP SELLER 2019
(ELECTRONICS) ON LAZADA**

SHOP NOW

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan. Trade In Are
Welcome. 100% Deposit Refund.
For Unapproved Loan.
Classic Credit - StarAd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category 

Sort by Date Posted  20 results/page 

6 vehicles

bmw 318

Advanced Search  Submit 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 318		Any	Any	2017	Any	Any	Any	Available
	BMW 3 Series 318i Shadow Edition		\$117,000	\$12,290 /yr	30-Nov-2017	1,499 cc	20,600 km	Luxury	Available
Loan Interest At 2.28%. Warranty Till 2022. Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beau...									
Posted: 29-Oct-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									
	BMW 3 Series 318i		\$114,727	\$12,280 /yr	19-Oct-2017	1,499 cc	8,880 km	Luxury	Available
Low Depreciation, Full Loan, Bank Loan, In House Loan Are All Available Now! Call Us Now For A Viewing!									
Posted: 28-Oct-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									
	BMW 3 Series 318i Sport		\$119,800	\$12,620 /yr	28-Dec-2017	1,499 cc	25,113 km	Luxury	Available
Low Mileage, Family 2nd Car. Fully Maintain By Agent. 5 Years Agent Warranty. Body Kit With Front Lip And Boot Lip! Sporty And Elegan...									
Posted: 27-Oct-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									
	BMW 3 Series 318i Sport		\$109,800	\$12,480 /yr	24-May-2017	1,499 cc	63,535 km	Luxury	Available
Powerful Yet Economical BMW 318 Sport Sedan! Clad In Sapphire Black With Black/Red Highlight Upholstery. Come With BMW 360 Degr...									
Performance Premium Selection Limited									
Posted: 25-Oct-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									
	Merlin Motor & Engineering Works - Repair & Servicing								
Established in 1980s, Merlin Motor Works is a Singapore-based company that provides excellent automotive solutions.									
More info about this shop									
	BMW 3 Series 318i Shadow Edition		\$116,800	\$12,310 /yr	16-Nov-2017	1,499 cc	25,000 km	Luxury	Available
1 Owner Only. Agent Maintained. View To Believe. Flexible Loan Available. Call Or Visit Us Now For Further Details.									
Posted: 19-Oct-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									
	BMW 3 Series 318i Shadow Edition		\$122,688	\$12,860 /yr	28-Dec-2017	1,499 cc	14,541 km	Luxury	Available
Own The Most Impressive German Built Car For The Past Generation That Gives You The Ultimate Sheer Driving Pleasure, Great For You...									
Posted: 09-Sep-2019 Tags: 2017 BMW 318i, 2017 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW									

Compare

Save this search criteria, to get email alerts whenever a match is found.

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 31 October 2019 3:38 PM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SGG1628M (OI : EQI - DM19HO02927-JG) AND SLV4125P (TP : LKK REF - CC6/EQI19019067/Upb3) on 29.10.2019
Attachments: SGG1628M.pdf

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, October 30, 2019 5:37 PM
To: EQI PRS
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: Direct Settlement - Accident Involving SGG1628M (OI : EQI - TBA) AND SLV4125P (TP : LKK REF - CC6/EQI19019067/Upb3) on 29.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLV 4125P at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP GIA report

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	582B
Vehicle Details	
Vehicle No.:	SLV4125P
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318I LED NAV SHAD. LIGHT
Primary Colour:	Orange
Manufacturing Year:	2017
Engine No.:	F2001814B38B15A
Chassis No.:	WBA8E36030NU81682
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,502.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$35,303.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$26,477.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$46,822.00
Total Rebate Amount:	\$73,299.00

The information contained herein is correct as at 29 Oct 2019

OK

Hsiao Tong (LKKAUTO)

From: Jason <Jason@fastechauto.com.sg>
Sent: Monday, 9 March 2020 12:16 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: SLV4125P *Our Ref: CC6/EQI19019067/Upb3s2 [ACCIDENT INVOLVING SGG 1628M(EQ) / SLV 4125P/ OTHERS ON 29/10/2019]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$19,000.00(all-in) for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Sunday, March 8, 2020 4:01 PM
To: Jason <Jason@fastechauto.com.sg>
Subject: Your Ref: SLV4125P *Our Ref: CC6/EQI19019067/Upb3s2 [ACCIDENT INVOLVING SGG 1628M(EQ) / SLV 4125P/ OTHERS ON 29/10/2019]

Your Ref: **SLV4125P**
Our Ref: CC6/EQI19019067/Upb3s2

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SGG 1628M(EQ) / SLV 4125P/ OTHERS ON 29/10/2019

We refer to the above matter.

We propose settlement at a global sum of **\$19,000.00(all-in).**

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ19019067/Upa3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 23-03-2020	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGG 1628M	Veh. Inspected	SLV 4125P	
Policy No.	DMPPHQ19-002854	Coverage (\$)	0.00	
Claim No.	DM19HO02927-JG	Excess (\$)	0.00	
Assign From		Assign Date	29/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 318I (A)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8E36030NU81682	Colour	ORANGE	
Odometer	23833	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	255/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	255/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	255/40 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND FRONT O/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2019	Inspection Date	29/10/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4125P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	2,466.32	-
1	BOOTLID REAR LOGO	NECESSARY	85.00	68.00
2	BOOTLID REFLECTORS @ \$645.00	NOT NECESSARY	1,290.00	-
1	BOOTLID INNER LOCK	SERVICEABLE	315.00	-
1	BOOTLID WEATHERSTRIP	TWISTED	366.00	188.20
1	REAR BUMPER	DISTORTED	2,018.00	1,245.32
1	REAR BUMPER BLACK GARNISH	BENT	388.00	288.20
2	REAR BUMPER REFLECTORS @ \$90.00	NOT NECESSARY	180.00	-
2	REAR BUMPER SIDE HOLDERS @ \$165.00	NOT NECESSARY	330.00	-
1	REAR BUMPER TOP RETAINER	CRACKED	392.00	181.00
1	REAR BUMPER REINFORCEMENT	BENT	715.00	615.32
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
4	REAR BUMPER PDC SENSORS @ \$245.00	SHORTED 2PCS ONLY	980.00	490.00
1	REAR BUMPER INNER LOCK PAD	CRACKED	288.00	205.30
1	REAR BUMPER INNER LOCK SENSOR	CRACKED	415.00	350.00
1	REAR END PANEL	BADLY DENTED	1,068.00	881.75
1	REAR END PANEL GARNISH	TWISTED	348.00	166.50
2	TAILLAMPS @ \$885.00	CRACKED	1,770.00	1,650.00
2	REAR FENDER INNER TRIMS @ \$399.00	NOT NECESSARY	798.00	-
1	REAR EXHAUST ASSY	TO REPAIR SEE LABOUR	1,880.00	-
1	FRONT BUMPER	DISTORTED	2,009.00	1,415.00
1	FRONT BUMPER REINFORCEMENT	BENT	788.00	366.50
1	FRONT BUMPER SIDE HOLDER O/S	CRACKED	199.00	145.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	488.00	425.00
1	FRONT BUMPER FOG LAMP GARNISH O/S	TWISTED	320.00	299.50
1	FRONT BUMPER CENTRE GARNISH	TWISTED	381.00	315.00
1	FRONT BUMPER LOGO	NECESSARY	68.00	68.00
1	FRONT BUMPER INNER AUXILING AIR DUCT	TORN	145.00	145.00
2	FRONT GRILLES @ \$305.00	O/S CUT	610.00	305.00

Report Ref No. CC6/EQ119019067/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER PDC SENSORS @ \$245.00	SHORTED 1PC ONLY	490.00	245.00
1	FRONT BUMPER SPONGE	TORN	281.00	188.20
1	FRONT FENDER O/S	BUCKLED	945.00	715.20
1	FRONT FENDER INNER SHIELD FRONT O/S	TORN	265.00	181.00
1	FRONT FENDER INNER SHIELD REAR O/S	TORN	288.00	182.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT INNER SIDE COOLER O/S	BENT / PUNCTURE	850.00	850.00
1	FRONT SHOCK ABSORBER O/S	BENT	1,200.00	576.20
1	FRONT KNUCKLE ARM O/S	BENT	1,485.00	845.50
1	FRONT KUCKLE ARM BEARING O/S	NECESSARY	499.00	325.00
1	FRONT LOWER ARM O/S	BENT	615.00	412.50
1	FRONT TORSION ARM O/S	BENT	620.00	312.20
1	FRONT STEERING RACK ASSY	SERVICEABLE	2,245.00	-
1	FRONT LINKAGE O/S	TWISTED	188.00	166.50
1	HEADLAMP ASSY O/S	BROKEN	3,800.00	3,068.40
1	HEADLAMP MODULE O/S	CRACKED	850.00	450.00
1	HEADLAMP BALLAST O/S	NOT NECESSARY	680.00	-
1	AIR CON CONDENSER	NOT NECESSARY	980.00	-
1	RADAITOR ASSY	NOT NECESSARY	1,120.00	-
2	SEATBELTS @ \$980.00	NOT NECESSARY	1,960.00	-
2	SEATBELT BUCKLES @ \$650.00	NOT NECESSARY	1,300.00	-
1	FRONT WHEEL HUB O/S	BENT	815.00	450.00
1	FRONT TYRE O/S	SERVICEABLE	300.00	-
1	REAR END PANEL SEALANT	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR	NOT NECESSARY	180.00	-
	LESS 5% DISCOUNT		-	-946.56
			43,206.32	17,984.73
	SPECIAL NETT ITEMS			
1	FRONT SPORT RIM O/S (SN)	CUT / BENT	1,215.00	800.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			1,265.00	840.00

Report Ref No. CC6/EQ19019067/Upa3s2